STATE OF UTAH DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING						FORI	_	
APPLICATION FOR PERMIT TO DRILL				1. WELL NAME and Roug	NUMBER h Canyon Federal 30	-1		
2. TYPE OF WORK DRILL NEW WELL (REENTER P&A V	WELL (DEEPEN	WELL		3. FIELD OR WILDCAT WILDCAT			
<u> </u>			5. UNIT or COMMUN	NITIZATION AGRE	EMENT NAME			
6. NAME OF OPERATOR		MPANY OF UTAH, LLC			7. OPERATOR PHON	IE 435 896-1943		
8. ADDRESS OF OPERATOR	entennial Park Dr.,	Richfield, UT, 84701			9. OPERATOR E-MA	IL ons@wolvgas.com		
10. MINERAL LEASE NUMBER (FEDERAL, INDIAN, OR STATE) UTU-82536		1. MINERAL OWNERS EDERAL () INDIA		FEE	12. SURFACE OWNE	ERSHIP DIAN (STATE (FEE (
13. NAME OF SURFACE OWNER (if box 12	= 'fee')				14. SURFACE OWNE	R PHONE (if box 1	2 = 'fee')	
15. ADDRESS OF SURFACE OWNER (if box	12 = 'fee')			<u> </u>	16. SURFACE OWNE	R E-MAIL (if box 1	.2 = 'fee')	
17. INDIAN ALLOTTEE OR TRIBE NAME (if box 12 = 'INDIAN')		B. INTEND TO COMM ULTIPLE FORMATION		ION FROM	19. SLANT			
(11 BOX 12 - 11101AIV)	Y	ES (Submit Con	nmingling Applicat	ion) NO 📵	VERTICAL DIR	ECTIONAL 📵 H	ORIZONTAL (
20. LOCATION OF WELL	FOOT	AGES	QTR-QTR	SECTION	TOWNSHIP	RANGE	MERIDIAN	
LOCATION AT SURFACE	288 FNL	452 FWL	NWNW	32	17.0 S	1.0 E	S	
Top of Uppermost Producing Zone	1830 FSL	810 FEL	NESE	30	17.0 S	1.0 E	S	
At Total Depth	1830 FSL		NESE	30	17.0 S	1.0 E S		
21. COUNTY SANPETE		2. DISTANCE TO NEA	810	. ,	23. NUMBER OF ACRES IN DRILLING UNIT			
		5. DISTANCE TO NEA Applied For Drilling o		AME POOL	26. PROPOSED DEPTH MD: 12800 TVD: 12400			
27. ELEVATION - GROUND LEVEL 6171	28	B. BOND NUMBER BLI	M WYB000616		29. SOURCE OF DRILLING WATER / WATER RIGHTS APPROVAL NUMBER IF APPLICABLE 63-3169			
		АТТ	TACHMENTS					
VERIFY THE FOLLOWING	ARE ATTACHED	IN ACCORDANCE	E WITH THE U	ΓAH OIL AND	GAS CONSERVATION	ON GENERAL RU	ILES	
WELL PLAT OR MAP PREPARED BY	LICENSED SURVE	YOR OR ENGINEER	№ сом	PLETE DRILLI	LLING PLAN			
AFFIDAVIT OF STATUS OF SURFACE	OWNER AGREEM	ENT (IF FEE SURFAC	CE) FORM	FORM 5. IF OPERATOR IS OTHER THAN THE LEASE OWNER				
DIRECTIONAL SURVEY PLAN (IF DIRECTIONALLY OR HORIZONTALLY DRILLED)			№ торо	TOPOGRAPHICAL MAP				
NAME Charles Irons TITLE Senior Landman			lman		PHONE 435 896-1943			
SIGNATURE DATE 04/20/2010					EMAIL cirons@wolvgas	.com		
API NUMBER ASSIGNED 43039500030000		APPROVAL		Y	hospill			
					Permit Manager			

API Well No: 43039500030000 Received: 4/20/2010

Proposed Hole, Casing, and Cement						
String	Hole Size	Casing Size	Top (MD)	Bottom (MD)		
Cond	26	20	0	1200		Γ
Pipe	Grade	Length	Weight			Γ
	Grade J-55 Buttress	1200	106.5			Т
						Т


CONFIDENTIAL

API Well No: 43039500030000 Received: 4/20/2010

Proposed Hole, Casing, and Cement						
String	Hole Size	Casing Size	Top (MD)	Bottom (MD)		
Surf	17.5	13.375	0	4000		T
Pipe	Grade	Length	Weight			T
	Grade J-55 Buttress	4000	68.0			Ι
						T

CONFIDENTIAL

Proposed Hole, Casing, and Cement						
String	Hole Size	Casing Size	Top (MD)	Bottom (MD)		
I1	12.25	9.625	0	10100	Г	Г
Pipe	Grade	Length	Weight			
	Grade L-80 LT&C	6000	53.5			
	Grade P-110 LT&C	4100	53.5			Γ
					Г	Г



API Well No: 43039500030000 Received: 4/20/2010

Proposed Hole, Casing, and Cement					
String	Hole Size	Casing Size	Top (MD)	Bottom (MD)	
L1	8.5	5.5	0	12800	
Pipe	Grade	Length	Weight		
	Grade N-80 LT&C	4700	20.0		

CONFIDENTIAL

WOLVERINE OPERATING COMPANY OF UTAH, LLC

Energy Exploration in Partnership with the Environment



April 20, 2010

Diana Mason
Permitting—Petroleum Technician
Utah Division of Oil, Gas and Mining
P.O. Box 145801
Salt Lake City, Utah 84114-5801

Re: Application for Permit to Drill (Utah ePermit #2558)

Rough Canyon Federal 30-1 Surface location in NW/4 NW/4, Section 32, T17S, R1E, SLB&M Bottom hole location in NE/4 SE/4, Section 30, T17S, R1E, SLB&M Sanpete County, Utah

Dear Mrs. Mason:

Wolverine Operating Company of Utah, LLC (Wolverine) hereby submits this letter with the accompanying e-Permit materials, as part of the *Application for Permit to Drill* (APD) for the referenced well:

- R649-3-11 Directional Drilling Application Plat showing proposed surface location and bottom hole location;
- Letter of consent to Wolverine's directional drilling program, signed by the owners of Oil and Gas Lease #UTU-84043;

A lease of water rights from a private owner (Water Right #63-3169) will be the source for water during drilling and completion operations on this proposed well.

The proposed well is located on SITLA administered surface under Special Use Lease Application #1680. A portion of the wellbore path will cross BLM administered subsurface (off lease) in the SW4SW4 of Section 29-T17S-R1E, before entering Section 30 (Wolverine's Federal lease #UTU-82536).

This letter and the accompanying plat are also intended to serve as an application for directionally drilling the well per R649-3-11. Wolverine is the owner, or has obtained the consent of the owner, of all oil and gas within 460 feet from all points along the intended wellbore for the well. Information relating to R649-3-11 is as follows:

Operator: Wolverine Operating Company of Utah, LLC

Address: 1140 N Centennial Park Drive

Richfield, Utah 84701

DENTIAL Well: Rough Canyon Federal 30-1

Field: NA (Wildcat) Reservoir: NA (Wildcat)

County: Sanpete

Restrictive topography and to minimize surface impact Reason:


Please accept this letter as Wolverine's written request for confidential treatment of all information contained in and relating to this application and proposed well.

Thank you for consideration of this application. Please feel free to contact me or Paul Spiering of this office if you have any questions or need additional information.

Sincerely,

Charlie Irons Senior Landman

(harlie Drome











WOLVERINE GAS & OIL CORPORATION Energy Exploration in Partnership with the Environment

> ONE RIVERFRONT PLAZA 55 CAMPAU, N.W. GRAND RAPIDS, MI 49503-2616 (616) 458-1150

Directional Drilling Application Plat (R649-3-11) Rough Canyon Federal 30-1 Well Location

Date: 4/14/2010

Data Source: mjl rough canyon



April 19, 2010

Utah Division of Oil, Gas and Mining Attn: Mr. Brad Hill, Oil and Gas Permitting Manager P.O. 80x 145801 Salt Lake City, Utah 84114-5801

Re: Wolverine Gas & Oil APD #2558 of the Electronic Permitting System

Dear Mr. Hill:

The undersigned are the current lessees under federal oil and gas lease #UTU-84043 covering the W/2, SE/4 & S/2NE/4 of Section 29 & All of Section 31, T175, R1E, SLM, Sanpete County, Utah.

Wolverine Gas & Oil Corp. is planning a directional drilling program for their Rough Canyon Fed. 30-1 well that is planned to be drilled from a surface location in the NW/4NW4 of Section 32, T175, R1E with a projected bottom hole location in Section 30, T175, R1E.

As lessees under UTU-84043, we hereby consent to Wolverine's direction drilling program as required in R649-3-11 of the Utah Division of Oil, Gas & Mining rules and regulations.

Sincerely,

Burnett Oil Company

By: Burnett Oli Co., Inc., Managing General Partner

William D. Pollard

President

Pioneer Natural Resources USA, Inc.

Robert C. Hagens, Vice-President, Land

Tecovas Partners III, L.P.

By: Marsh Operating Company, General Partner

James C. Clam, President

BURNETT PLAZA - SUITE 1500 801 CHERRY STREET - UNIT #9

BURNETT OIL CO., INC.

FORT WORTH, TX 76102-6881 (817) 332-5108

SURFACE USE PLAN OF OPERATIONS

For inclusion with Application for Permit to Drill

Name of Operator: Wolverine Operating Company of Utah, LLC

Address: 1140 N. Centennial Park Drive

Richfield, Utah 84701

Rough Canyon Federal 30-1

Surface Well Location: 288' FNL & 452' FWL, (being in NW4/NW4)

Section 32, T17S, R1E, SLB&M

Sanpete County, Utah

Bottom Hole Location: 1830' FSL & 810' FEL, (being in NE4/SE4)

Section 30, T17S, R1E, SLB&M

Sanpete County, Utah

Access Road Location: Existing two-track road leads from Highway SR 28 Easterly across

the S2SE Section 1-T18S-R1W and across the W2W2 Section 6-T18S-R1E to the mouth of Rough Canyon in the SWSW Section 31-T17S-R1E. A new road is proposed to be built Northeasterly through Rough Canyon to the East line of Section 31. A Title V right-of-way application is being submitted to the Richfield BLM office covering both above existing road and new road. The portion of the lease road continuing into Section 32 will be constructed under terms of an Easement from State of Utah School and Institutional Trust Lands Administration (SITLA) and the well pad will be constructed under terms of a Special Use Lease from same.

Fee surface use is not required for construction and drilling of the referenced well and access road. State surface use is required for construction of the well pad and that portion of the access road that is situated in Section 32-T17S-R1E. Federal surface use for access is being requested with the associated Title V Right-of-Way application through the BLM – Richfield Field Office.

The dirt contractor will be provided with an approved copy of the surface use plan of operations and conditions of approval before initiating construction.

Existing Roads:

The vicinity map in the APD drawing packet shows the proposed well location east of Highway SR28 in the Sanpitch Mountain range. The closest town is Fayette, Utah (well location being 5 miles North-northeast of Fayette).

<u>Driving directions</u>: From Gunnison, Utah, travel north on SR 28, under Utah Department of Transportation (UDOT) maintenance approximately 8.5 miles to a driveway on the East side connecting the highway to a two-track road. Proceed through the gate Easterly, thence Northerly a distance of about 1.42 miles on said two-track to its terminus near the mouth of Rough Canyon. Continue Northeasterly up the narrow canyon on a to-be-constructed new road a distance of about 1.38 miles to the Section 31 east line and SITLA boundary. Continue into Section 32 on SITLA land a distance of 700+ feet to the Rough Canyon Federal 30-1 well pad.

Access Roads to be Constructed and Reconstructed:

The surface condition of the existing two-track road is not adequate to bear rig-related traffic and will require improvement. The width of the traveled way will be increased from about 8 feet+/- to 12 feet, and 8 foot wide vehicle turnouts will be constructed at strategic points to allow trucks to pass. See drawing sheets TS-01 (Type 2 Typical Section) and TS-02 in the Right-of-Way application for detail on existing road improvements. Details on

areas of construction are shown on sheets PP-01 through PP-04 of the Right-of-Way application.

From the mouth of Rough Canyon to the BLM-SITLA land boundary, a new road will need to be constructed, following the meander of the bottom of the wash, a distance of 7.295.32 linear feet (1.38 miles). Due to the tight turns and confinement of the canyon walls the traveled way of this road will need to be a minimum of 14 feet; with extra width of up to 40.2 feet on curves. The roadbed will be fortified with untreated base course and granular borrow taken from the existing community gravel pit referenced below under *Construction Materials*. See drawing sheets TS-01 (Type 1 Typical Section) and TS-02 for detail on new road construction. Details on areas of construction are shown on sheets PP-04 through PP-14 of the Right-of-Way application. Best management practices will be used in all stages of design and construction.

The continuation of the new road into Section 32 (SITLA land) to the well pad will be constructed under authority of an easement from SITLA. Details of construction for that portion of the lease road are included in the APD packet submitted herewith. The well pad will be constructed under authority of a Special Use Lease from SITLA (Application #1680) and details of pad layout and construction design are also included in the APD packet.

Total length of the improved portion of the road across BLM land is 1.42 miles. Total length of new constructed access road is 1.52 miles (being 1.38 miles across BLM land and .14 mile across SITLA land).

Road construction, operation and maintenance will be in compliance with the terms and conditions of the BLM and SITLA Conditions of Approval, the American Association of State Highway and Transportation (AASHTO) safety standards, and will meet criteria for the Manual of Uniform Traffic Control Devices (MUTCD) manual for signs.

Energy dissipating structures and silt fences will be utilized to minimize erosion that may result from the road construction.

The Operator intends to install a cattle guard in addition to the gate near where the existing two-track road enters the highway. The cattle guard will be installed in the existing fence opening and the gate will be reinstalled to the side.

All existing roads and the new road will be maintained and kept in good repair during all phases of operation. Vehicle operators will obey posted speed restrictions and observe safe speeds commensurate with road and weather conditions.

Equipment to be used in construction will consist of conventional heavy equipment, including bulldozers, scrapers, excavators, backhoes, compactors and water trucks. In the event rock blasting is necessary in excavation a certified blaster will be called in to perform the operation on an as-needed basis. All applicable regulations, including those of the Bureau of Alcohol, Tobacco and Firearms, will be followed for the use of explosive materials. No explosives will be stored on site. Boulders that are exposed by excavation, that cannot be broken up and used as aggregate, will be buried in the right-of-way, unless otherwise requested by the Authorized Officer.

Location of Existing Wells within a one-mile radius:

There are no wells (oil, gas, water, injection or disposal, producing or being drilled) within a one-mile radius of the proposed location.

Location of Existing and/or Proposed Facilities if Well is Productive:

(a) On well pad—A temporary testing facility may be constructed on this location in the event drilling is successful, consisting of treater/separator, tanks and related components. The facility would be surrounded by a dike of sufficient capacity to contain the storage capacity of the largest tank. All loading lines and valves would be located inside the berm surrounding the tank battery.

(b) Off well pad – It is not possible to know whether an off-well pad production facility would be necessary in the event of a discovery. In the event such a facility is needed a site closer to Highway SR 28 would potentially be used for collection, treating and load-out. The Operator will submit this information for approval at such time as production requirements are known.

Location and Type of Water Supply (Rivers, Creeks, Lakes, Ponds and Wells):

The Operator intends to lease water rights from a private water right owner: water right number 63-3169. This will be done by temporary change order through the Utah Division of Water Rights office in Richfield, Utah. Water will be drafted from the Sevier River at a load-out point tentatively located in the NE4 of Section 2-18S-1W, subject to

change, depending on the level of the reservoir at the time of need. Should additional water sources be pursued they will be properly permitted through the State of Utah – Division of Water Rights. The BLM will be notified of any changes in water supply.

Construction Materials:

Natural earth materials used for fill on the well pad will be taken from cuts made in construction of the pad. Imported granular borrow from an approved source will be applied to the surface of the well pad and access road where deemed necessary. The roadbed will be fortified with granular borrow taken from an existing community gravel pit that is located nearby. An application for mineral materials sale for that purpose is being submitted concurrently with this APD. If additional materials are needed they will be taken from an approved source.

Methods for Handling Waste Disposal:

The reserve pit will be used for the disposal of waste mud and drill cuttings. All borehole fluids and salts will be contained in the reserve pit. It will be located in cut material and will be lined with 12 mil minimum thickness plastic nylon reinforced liner material. The liner will overlay a felt liner pad only if sharp rock edges result from excavation. The pit liner will overlap the top of the pit walls and be covered with dirt and/or rocks to hold it in place. No trash, scrap pipe, etc. that could puncture the liner will be disposed of in the pit. Pit walls will be sloped no greater than 2:1. A minimum 2-foot freeboard will be maintained in the pit at all times during the drilling and completion operations. After evaporation of fluids, back-fill of sub-soil and compaction to prevent settling will occur within 90 days of cessation of pit use. If necessary, any remaining fluids will be pumped out of the pit and transported off site.

No chemicals subject to reporting under SARA Title III (hazardous materials) in an amount greater than 10,000 pounds will be used, produced, stored, transported, or disposed of in association with the drilling, testing, or completion of the well. Furthermore, no extremely hazardous substances, as defined in 40 CFR 355, in threshold planning quantities, will be used, produced, stored, transported, or disposed of in association with the drilling, testing, or completion of the well.

Wastewater will not be discharged on the surface at this site and the drilling of the well will not require a wastewater management plan.

All rubbish and debris will be kept in containers on the well site, and will be hauled to an approved disposal site upon completion of drilling operations and as needed during such operations. There will be no chemical disposal of any type.

Self-contained, portable toilets will be used for human waste, and the waste will be disposed at an approved human waste disposal facility. Sanitation will comply with local and state regulations.

Ancillary Facilities:

No ancillary facilities are anticipated at this time.

Well Site Layout:

Pad Location and Layout Drawings in the APD drawing packet show the proposed well site layout including location of the reserve pit and access road onto the pad, turnaround areas, parking areas, living facilities, soil material stockpiles, and the orientation of the rig with respect to the pad and other facilities. Cross section sheets in said packet show cuts and fills required for construction, and their relationship to topography. As detailed above under Methods for Handling Waste Disposal, the reserve pit will be lined and appropriate measures as described above will be taken to prevent leakage. The pit will be fenced on three sides during drilling operations and then the fourth side will be immediately fenced when the rig is moved off location.

The pad and road designs will be consistent with SITLA, UDOGM and BLM requirements.

A pre-construction meeting with responsible company representative and contractors will be conducted at the project site prior to commencement of surface-disturbing activities. The pad and road will be construction-staked (centerline and exterior boundaries) prior to this meeting.

All surface disturbing activities will be supervised by a qualified, responsible company representative who is aware of the terms and conditions of approval from the BLM under the Title V Right-of-Way, and APD, and terms and

conditions of approval from SITLA under the Easement and Special Use Lease.

All cut and fill slopes will be such that stability can be maintained for the life of the activity.

The stockpiled topsoil (first 6 inches or maximum available) will be isolated in a berm by the well pad. Topsoil will be stockpiled for reclamation in such a way as to prevent soil loss and contamination.

Water spraying may be implemented if necessary to minimize dust.

Plans for Reclamation of the Surface:

Interim Reclamation: In the event production is achieved the Operator will perform interim reclamation of the site. Interim reclamation will consist of reclamation of the reserve pit and reclamation of that portion of the well pad not needed for ongoing operations. After evaporation of fluids, the pit will be back-filled with sub-soil and/or rock and compacted to prevent settling. The pit area will be surfaced with granular borrow to render it a usable part of the well pad. All portions of the pad no longer necessary for well workover, testing or treating will be contoured to match the surrounding terrain to the best extent practicable. Stockpiled topsoil will be evenly distributed thereon, scarified and seeded as per Conditions of Approval.

<u>Final Reclamation</u>: In the event the well is a dry hole, or at such time that all production ceases and the well has been plugged and abandoned, the Operator will perform final reclamation of the site. Final reclamation will consist of reclamation of the reserve pit, the well pad and the access road as it crosses SITLA and BLM land. In the event the right-of-way across BLM land is assignable to SITLA, and such assignment is approved, reclamation of the BLM right-of-way may be partial, according to terms and conditions of said right-of-way. The Operator will comply with all Conditions of Approval for reclamation of the right-of-way.

Any accumulation of hydrocarbons in the reserve pit will be removed and recovered for sale unless it is determined by the authorized officer to be waste oil. All waste oil will be disposed of properly at approved facilities. The portion of the reserve pit liner that is exposed above the cuttings will be cut and removed from the site and disposed in an authorized landfill. After evaporation of fluids, the pit will be back-filled with subsoil and/or rock from the reserve pit stockpile and compacted to prevent settling.

Unless otherwise directed, road base material used in the construction of the access road and pad will be removed from the site and disposed in a proper manner. If the reserve pit has adequate capacity, then some or all of the road base material may be buried in the reserve pit, provided that the granular is not contaminated by oil or other waste materials. The access road will be contoured using an excavator or similar equipment, rather than simply ripping the surface.

Subsoil from the portions of the well pad that are fill will be pulled up onto the pad in order to reestablish the original slope to the best extent possible. The portions that are cut will be filled to match the original slope of the land to the best extent possible. Topsoil from the stockpile will then be evenly distributed over the entire impacted area. The entire impacted area will be scarified and seeded in late fall, using the seed mix and methods described in BLM and SITLA conditions of approval. Final reclamation will take place within 180 days after plugging date of the last well on site, depending on weather, season and other extenuating circumstances.

During the life of the project and until the site is released from liability for reclamation, the project will be inspected at least annually for noxious weeds. If invasive noxious weeds are found, the weeds will be treated to eliminate further reproduction, and treatment shall continue until the weeds have been eradicated. If noxious weeds are found, BLM and SITLA will be notified of their occurrence.

See Additional Detail on Plans for Reclamation of the Surface on Addendum to Surface Use Plan of Operations, attached hereto.

Surface Ownership:

The surface of the proposed well site and the Section 32 portion (.14 mile) of the access road is State owned and is administered by the State of Utah School and Institutional Trust Lands Administration (SITLA). The access road across Section 31-T17S-R1E, Section 6-T18S-R1E and Section 1-T18S-R1W is federally owned and is administered by the Bureau of Land Management, United States Department of Interior.

Other Information:

The topsoil (6 inches, or maximum amount present) will be stripped and removed from the well pad and stockpiled for future reclamation of the site. This topsoil shall be stockpiled separately from any other excavated materials. It will be reserved for reclamation and not utilized for any other purpose. If it is to be stockpiled for more than one year it will be seeded in the fall with a seed mix approved by the authorized officer.

Heavy equipment used to construct and rehabilitate the well pad and access road will be cleaned and/or sprayed to remove any noxious or invasive weeds and seeds, prior to entering to the project site. Any other equipment and vehicles that have been used in other locations where noxious weeds or seeds could have attached to the equipment will also be sprayed and/or cleaned.

Due to the narrow canyon, adequate truck turnouts are not possible on the new-built portion of the road. While smaller vehicles would be able to pass on the traveled surface, larger trucks would not. Flagmen with radio communication will be stationed at the upper and lower ends of Rough Canyon at all times when rig traffic is present, to prevent opposing traffic from meeting in this confined area.

In the event of a flash flood, traffic on the new road in Rough Canyon would be shut down until the flow of water ceased and the road surface could be returned to a passable condition.

All equipment and vehicles will be confined to the access road and well pad.

Western Land Services will conduct a Class III archeological survey and will submit same under separate cover to the appropriate agencies.

Western Land Services will conduct a T&E survey and prepare an EA for the proposed well site. The T&E report and EA will be submitted under separate cover to the appropriate agencies.

No stream alteration or drainage crossings are involved that require additional State or Federal approval.

All permanent structures, including pumping units, constructed or installed will be painted a flat, non-reflective color as described on page 40 of the Gold Book (Surface Operating Standards and Guidelines for Oil and Gas Exploration and Development, 4th Edition 2006). Permanent structures are defined as being on location for six months or longer. Facilities required to comply with Occupational Safety and Health Act (OSHA) shall be excluded.

Fire suppression equipment will be available to suppress any wildfires caused by construction or related activities. In the event of a wildfire the Sanpete County Fire Warden will be notified. (435) 835-2117.

Operator Certification

I hereby certify that I, or someone under my direct supervision, have inspected the drill site and access route proposed herein; that I am familiar with the conditions which currently exist; that I, or someone under my direct supervision, have full knowledge of state and Federal laws applicable to this operation; that the statements made in this APD package are, to the best of my knowledge, true and correct; and that the work associated with the operations proposed herein will be performed in conformity with this APD package and the terms and conditions under which it is approved. I also certify that I, or the company I represent, am responsible for the operations conducted under this application. These statements are subject to the provisions of 18 U.S.C. 1001 for the filing of false statements.

Executed this 14th day of April, 2010.

Signature:

Paul Spiering

Position Title:

District Land Manager

Address:

Wolverine Operating Company of Utah, LLC

1140 N. Centennial Park Drive

Richfield, Utah 84701

Telephone:

435-896-1943

Field representative (if not above signatory)

Charlie Irons, Senior Landman

Address:

1140 N Centennial Park Drive

Richfield, Utah 84701

Telephone:

435-896-1943

Agents not directly employed by the operator must submit a letter from the operator authorizing that agent to act or file this application on their behalf.

H2S Drilling Operations Plan

Wolverine Operating Company of Utah, LLC

Rough Canyon Federal 30-1

Section 30
Township 17S - Range 01E
Sanpete County, Utah

GL Elevation: 6169 feet (est. graded)

One Riverfront Plaza 55 Campau, NW Grand Rapids, Michigan 49503-2616

Table of Contents

Introduction and directions

- I. Responsibilities and Duties
 - A. All personnel
 - MEIDENTIAL B. Wellsite Supervisor (Drilling Foreman)
 - C. Rig Supervisor/Toolpusher
 - D. Safety Consultant
 - E. Drilling Manager
- II. Well Location Layout
 - A. Location
- III. Safety Procedures
 - A. Training
 - B. Operating Conditions
 - C. Warning System Response and Evacuation Plan
 - D. Emergency Rescue Procedures
 - E. Review with Local Officials
- IV. H2S Safety Equipment on Well Location
- V. Operating Procedures and Equipment
- VI. Well Ignition Procedures
 - A. Ignition Equipment
 - B. Ignition Procedures
- VII. Residents Public in Radius of Exposure
 - A. Map of area around location
- VIII. Emergency Phone Directory
 - A. Wolverine
 - B. Emergency Services Phone List
- IX. Reference Material for Hydrogen Sulfide and Sulfur Dioxide
- X. Attachments-Maps, Diagrams

Introduction

This H2S contingency plan has been prepared for the Rough Canyon Federal 30-1 well, which will be located on a state surface lease in Section 32, T17S-R01E, Sanpete County. This Plan is intended as a guide for personnel working at the well site should an accidental release of natural gas containing hydrogen sulfide occur during drilling or completion operations. Operational requirements included installation of gas monitors and safety equipment on the drill site, personnel training, and response procedures. All personnel, including anyone who may travel to location on an unscheduled basis, must review and be familiar with onsite duties as well as the safety equipment involved. For the plan to be effective, the cooperation and participation of all personnel working at the well site is required.

The location is a remote location, located approximately 2.93 miles off of Highway 28 up into Rough Canyon. Therefore exposure to H2S by the general public is very unlikely during drilling or completion operations. The prevailing wind direction is expected to be from the west is drilled.

Directions

<u>Driving directions</u>: From Gunnison, Utah, travel north on SR 28 approximately 8.5 miles to a driveway on the East side connecting the highway to a two-track road. Proceed through the gate Easterly, thence Northerly a distance of about 1.42 miles on said two-track to its terminus near the mouth of Rough Canyon. Continue Northeasterly up the narrow canyon on a to-be-constructed new road a distance of about 1.38 miles to the Section 31 east line and SITLA boundary. Continue into Section 32 on SITLA land a distance of 700+ feet to the Rough Canyon Federal 30-1 well pad.

I. <u>Duties & Responsibilities</u>

In order to assure proper execution of the contingency plan, it is essential that one person be responsible for and requisite authority for implementing the procedures outlined in this plan. The order of responsibility will be as follows:

- 1. Wolverine supervisor on location if unable to perform his/ her duties;
- 2. Alternate Wolverine representative if unable to perform his/ her duties;
- 3. Rig Supervisor/Toolpusher if unable to perform his/her duties;
- 4. Safety consultant representative if available.

A. All Personnel

- 1. Always be alert for possible H2S alarms both audible and visual.
- 2. Be familiar with location of Safe Briefing Areas (SBA) and protective breathing equipment.
- 3. Develop "wind awareness". Be aware of prevailing wind direction as well as nearby uphill areas should there be no wind.
- 4. Familiarize yourself with nearest escape routes for safe evacuation.
- 5. Should H2S alarm sound, DON'T PANIC remain calm and follow instructions of person in charge.
- 6. If the H2S alarms sound:
 - a. Essential personnel shall don the appropriate respiratory protective equipment and follow safety procedures. They will continue to wear respiratory protective equipment until the area is deemed safe (H2S concentration less than 10 PPM).
 - b. Non-essential personnel shall evacuate to the appropriate safe briefing area using escape-breathing systems. They are to wait there for further instructions from the Wolverine foreman or the designated person in charge.
 - c. Initiate rescue protocol if necessary and following training procedures.

B. Wellsite Supervisor

- 1. The Wellsite Supervisor will confirm that all personnel on location at any time are trained in H2S safety and aware of above list of duties.
- 2. The Wellsite Supervisor will ensure that all personnel observe all safety and emergency procedures.
- 3. The Wellsite Supervisor will make an effort to keep the number of personnel on location to a minimum and to ensure that only essential personnel are on location during critical operations.
- 4. Should an extreme danger condition exist, the Wellsite Supervisor will:
 - a. Assess the situation and advise all personnel by appropriate means of communication.
 - b. Be responsible for determining that the extreme danger condition is warranted and have the red flag posted at location entrance.
 - c. Go to safe briefing area. Give clear instructions relative to hazard on location and actions for personnel to follow.
 - d. Notify company and regulatory groups of current situation as required per company policy and regulatory protocol. Follow appropriate procedures for emergency services notification.
 - e. Proceed to well and supervise operations with rig supervisor. Take action to control and reduce the H2S hazard.
 - f. Ensure that essential personnel are properly protected with supplied air breathing equipment and that non-essential personnel are in a "poison gas free" area.
 - g. Authorize evacuation of any persons/residents in area surrounding the well location.
 - h. Commence any ignition procedures if ignition criteria are met.

C. Rig Supervisor/Toolpusher

- 1. If the Wellsite Supervisor is unable to perform his/her duties and an alternate Wolverine representative is also unable or unavailable to perform his/her duties, the rig supervisor will assume command of wellsite operations and all responsibilities listed above for Wellsite Supervisor.
- 2. The Rig Supervisor will ensure that all rig personnel are properly trained to work in H2S environment, fully understand the purpose of H2S alarms, and know actions to take when alarms activate. He/She will ensure that all crew personnel understand

the buddy system, safe briefing areas, and individual duties as well as emergency evacuation procedures.

- 3. Should any extreme danger operational condition arise, the Rig Supervisor shall assist the Wellsite Supervisor by:
 - a. Proceeding to the rig floor and assist in supervising rig operations.
 - b. Ensuring that only essential working personnel remain in hazardous areas.
 - c. Ensuring that all crewmembers that remain in hazardous area, wear respiratory protective equipment until notified that area is "clear" of any toxic gases.
 - d. Assigning rig crewmember or other service representative to block entrance to location. No unauthorized personnel are to be allowed entry to location.
 - e. Helping to determine hazardous "danger zones" on location using portable detection equipment, and positioning electric fans to move gas in any high concentration areas.

D. Safety Consultant

- 1. During normal operations (no H2S present), the safety consultant will be responsible for the following:
 - a. Ensuring that all wellsite safety equipment is in place and operational.
 - b. Ensuring that all wellsite personnel are familiar with location safety layout and operation of all safety equipment.
 - c. Assisting the Wellsite Supervisor in performing weekly H2S drills for location personnel.
- 2. When an operational condition is classified as extreme danger, the safety consultant will be responsible for the following:
 - a. Accounting for all wellsite personnel.
 - b. Assessing any injuries and directing first aid measures.
 - c. Ensuring that all safety and monitoring equipment are functioning properly and available.
 - d. Monitoring the safety of wellsite personnel.
 - e. Maintaining close communication with the Wellsite Supervisor.
 - f. Being prepared to assist Wellsite Supervisor with support for rig crew or other personnel using breathing equipment.
 - g. Being prepared to assist the Wellsite Supervisor with emergency procedures including possible well ignition.
 - h. Being prepared to assist with evacuation of any area residents or other personnel in the immediate area.

E. Drilling Manager

- 1. The Wolverine Drilling Manager will be responsible for notifying and maintaining contact with the company Production Manager and/or other company supervisory personnel as required.
- 2. Maintaining communication with the Wellsite Supervisor and providing any other assistance that might be required.
- 3. Travelling to wellsite if appropriate
- 4. Assisting Wellsite Supervisor with all other notifications including both company and regulatory.

II. Well Location Layout

A. Location

- An attached well site diagram depict location and rig orientation, prevailing wind direction, terrain of surrounding area, location of briefing areas, access roads, location of flare lines and pits, location of caution/danger signs, and location of wind indicators.
- If practical, the drilling rig will be situated to allow for the prevailing winds to blow across the rig toward the circulation tanks or at right angles to the lines from the BOP stack to the circulation tanks or as near this configuration as possible.
- 3. If practical, there will be 2 roads from location with one at each end of location or as dictated by prevailing winds and terrain. If an alternate road is not practical, a clearly marked footpath to a safe area will be provided. The auxiliary escape route will be kept available and passable at all times so that a shift in wind direction will not prevent escape from the location if an emergency should occur. An auxillary footpath will be provided near the western corner of the location to provide an emergency egress off the pad for foot traffic.
- 4. The entrance(s) to the location will be designed to be barricaded if necessary because of a hydrogen sulfide emergency condition.
- 5. A minimum of 2 safe briefing areas (SBA) will be designated for assembly of personnel during emergency conditions. These will be located at least 200 feet from the wellbore and in such a location that at least one area will be upwind of the well at all times. Upon recognition of an emergency situation, all personnel will be trained to assemble at the designated briefing area for instructions.
- 6. Smoking areas will be established and smoking will be allowed only at those established smoking areas.

- 7. Reliable 24-hour telephone communications will be available at the wellsite supervisor's office.
- 8. The drilling rig will have a continuous electronic H2S detection system that will be located to detect the presence of hydrogen sulfide in areas where it is most likely to appear on site. The sensor head locations will be: 1) rig floor by driller's console, 2) substructure area near the bell nipple, 3) the shale shaker, 4) the mud mixing area. Additional sensors will be positioned at the discretion of the drilling foreman. At least 1 light and 1 siren will be placed on the rig to indicate the presence of hydrogen sulfide. The light and siren will be strategically placed to be visible to all personnel on the drill site.
- 9. Equipment to indicate wind direction will be installed at prominent locations and will be visible at all times during drilling operations. At least 2 wind direction indicators (i.e. windsocks) will be placed at separate elevations (i.e. near ground level and rig floor height). At least 1 wind direction indicator will be clearly visible from all principal working areas at all times so that wind direction can be easily determined. In addition, a wind direction indicator will be provided at each of the two briefing areas if the other wind direction indicators on location are not visible from the briefing areas.
- 10. Operational danger or caution sign(s) will be displayed along all controlled accesses to the site. The sign(s) will legible and large enough to be read by all persons entering the wellsite and be placed a minimum of 200 feet but not more than 500 feet from the wellsite and at a location which allows vehicles to turn around at a safe distance prior to reaching the site.
- 11. Protective safety equipment will be available for all essential personnel. There will be five 30-minute SCBA and five air line breathing units with emergency escape cylinders located at the drilling floor or dog house, one SCBA and air line unit will be located in the derrick (for derrick man), one 30-minute SCBA per person will be located by the quarters of all personnel on location, and 30-minute SCBA and escape units will be distributed as needed near the shaker, mud tanks, and any other area where escape from an H2S contaminated area could be difficult. A safety trailer containing the compressed breathing air will be located near the well site and air lines will be run from the safety trailer to where the air line breathing units are located.

III. Safety Procedures

A. Training

When this plan is in effect, all personnel who come onto the location must be properly trained in hydrogen sulfide, nitrogen, and oxygen deficient atmospheres safety. The personnel shall carry documentation with them indicating that the training has occurred within the previous 12 months. All training will comply with federal and state regulatory guidelines. There will be a training session that reviews this site specific H2S plan and the H2S PPP (if applicable) for all personnel in each work crew on location. Training will also include weekly H2S and well control drills.

All training sessions and drills are to be recorded in the driller's log, as well as in the safety trailer logbook.

Training topics shall include at a minimum:

- 1. Hazards and characteristics of hydrogen sulfide, nitrogen, and oxygen deficient atmospheres and symptoms of exposure to these gases.
- 2. Proper use, care and limitations of respiratory protective equipment with hands-on practice.
- 3. Use of both fixed and portable toxic gas detection equipment.
- 4. Work practices to reduce chances for toxic gas exposure and procedures for confined space.
- 5. First aid for toxic gas exposure and resuscitation equipment.
- 6. The buddy system.
- 7. Emergency evacuation procedures.
- 8. A review of the contingency plan for the well.

B. Operating Conditions

A three color- flag warning system will be used to notify personnel approaching the drill site as to operating conditions on the wellsite. This system is in compliance with BLM Onshore Order 6 and follows industry standards.

Green Flag - Potential Danger

Yellow Flag - Moderate Danger

Red Flag- Extreme Danger - Do not approach if red flag is flying.

A red warning flag will be displayed when H2S is detected in excess of 10 ppm at any detection point.

The operational danger or caution signs located near the entrance to the location will be painted a high visibility red, black and white, or yellow with black lettering. They will be legible and large enough to be read by all persons entering the wellsite and will read "DANGER – POISON GAS – HYDROGEN SULFIDE" and in small lettering "Do not approach if Red Flag is Flying".

All sign(s) and, when appropriate, flag(s) will be visible to all personnel approaching the location under normal lighting and weather conditions.

Location access will be monitored and controlled during "non-routine" operations such as perforating, pressurized pumping, and well testing of potential H2S bearing formations. The number of personnel on location will be restricted to "essential" personnel only

C. Warning System Response and Evacuation Plan

When H2S is detected in excess of 10 ppm at any detection point indicating that an extreme danger condition exists, all non-essential personnel will be moved to a safe area and essential personnel (i.e., those necessary to maintain control of the well) shall don a pressure-demand type protective breathing apparatus. Once accomplished, operations may proceed.

If an H2S emergency situation arises, the Wellsite Supervisor will contact local authorities to authorize and work in coordination with them to evacuate and restrict non-essential personnel from areas near the wellsite where H2S concentration levels could potentially exceed 10 ppm. All associated regulatory agencies will then be notified as soon as possible.

D. Emergency Rescue Procedures

Well site personnel should not attempt emergency rescues unless they have been properly trained. A trained person who discovers another person overcome by hydrogen sulfide **should not attempt to rescue without donning the proper breathing equipment.** When making an emergency rescue always use the following procedures:

- 1. Don rescue breathing equipment before attempting to rescue someone.
- Remove the victim from the contaminated area to an area free of gas by traveling upwind or cross wind. Be certain that you are in a safe area before removing your breathing equipment.
- 3. If the victim is not breathing, initiate mouth-to-mouth resuscitation immediately. Follow CPR guidelines and replace mouth-to-mouth with a bag mask resuscitator if available.
- 4. Treat the victim for shock, keeping the victim warm and calm. Never leave the victim alone.
- 5. Any personnel who experience hydrogen sulfide exposure must be taken to a hospital for examination and their supervisor notified of the incident.
- 6. Their supervisor shall follow the company Emergency Preparedness plan.

E. Planning with Local Officials

Wolverine representatives will meet with local officials and apprise them of key elements of the H₂S Drilling Operations Plan.

IV. <u>H2S Safety Equipment on Well Location Procedures</u>

<u>ltem</u>	<u>Amount</u>	<u>Description</u>	
1.	1	Safety trailer with a cascade system of 10-300 cu. ft	
regulators.	bottles of compressed	I breathing air complete with high-pressu	re
2.	At least 1000 ft. fittings. This airline wil	Low-pressure airline equipped with Hanson locking Il be rigged up with manifolds to supply	
breathing air t mixing areas.	o the rig floor, substruc	cture, derrick, shale shaker area, and mu Three high-pressure refill hoses will be attached cascade systems for cylinder refill.	
3.	Twelve (12)	Scott 30-minute self-contained breathing apparatuses (SCBA).	
4.	Twelve (12)	Scott airline units with emergency escape cylinders.	
5.	One (1) audible and visual ala w alarm and 15 ppm fo	4-channel continuous electronic H2S monitors with rms. The set points for these alarms are for the high alarm.	10
•	• •	· ·	
6.	Two (2) detection units with tu	Sensidyne portable hand operated pump type bes for hydrogen sulfide and sulfur dioxid	le.
7.	One (1)	Oxygen resuscitator with spare oxygen cylinder.	
8.	One (1)	Trauma first aid kit.	
9.	One (1)	Stokes stretcher and one (1) KED	
10.	Four (4)	Windsocks.	
11.	At least one (1)	Well condition sign with 3 flag system.	
12.	Two (2)	Safe Briefing Area (SBA) signs.	
13.	One (1)	Fire blanket.	
14.	One (1)	Set air splints.	
15.	Two (2)	Electric explosion proof fans.	
16.	One (1)	Bullhorn and chalk board.	
17.	Three (3)	300 cu. ft. air bottles for the safe briefing area.	
18.	Two (2)	30# fire extinguishers.	
19.	Six (6) communication when	Battery powered voice microphones for wearing air masks.	
20.	One (1)	Battery powered combustible gas meter.	

V. Operating Procedures and Equipment

- If zones containing in excess of 100 ppm of H2S gas are encountered while drilling with air, gas, mist, other non-mud circulating mediums for aerated mud, the well will be killed with a water-based mud and mud will be used thereafter as the circulating medium for continued drilling.
- A flare system will be designed and installed to safely gather and burn H2Sbearing gas and it will be equipped with a suitable and safe means of ignition. If noncombustible gas is to be flared, the system will have a supplemental fuel to maintain ignition.
- Flare lines will be located as far from the operating site as feasible and in a manner to compensate for wind changes. The flare line(s) mouth(s) will be located not less than 150 feet from the wellbore. Flare lines will be straight unless targeted with running tees.
- 4. If SO2 is to be released as a result of flaring of H2S, portable SO2 detection equipment will be available for checking the SO2 level in the flare impact area. If the flare impact area reaches a sustained ambient threshold level of 2 ppm or greater of SO2 in air and includes any occupied residence, school, church, park, or place of business, or other area where the public could reasonably be expected to frequent, the PPP will be implemented.
- The choke manifold included as a component of the well control system will have at least one remote controlled choke with controls readily accessible to the drilling or other authorized personnel.
- 6. A rotating head will be installed and operable.
- 7. A mud-gas separator will be rigged up and manifolded to the choke and flare system.
- 8. The drilling mud will be a water-based system maintained with a pH of 10 or greater. Corrosion inhibitor additives will be in the mud. Sufficient scavenger chemicals will be available on location and will be used to scavenge or neutralize any H2S in the drilling fluid. Mud weight will be maintained as needed to control pressure in any formations encountered.
- 9. All equipment that has potential for exposure to H2S will be suitable for H2S service. The casing head and spools, blowout preventer assembly, rotating head, kill lines, choke, choke manifold and lines, valves, mud-gas separator and other related equipment will have metallurgical standards conforming to NACE MR0175/ISO 15156. Elastomers, packing, and similar inner parts exposed to H2S will be resistant at the maximum anticipated temperature of exposure. Drill strings, surface casing, intermediate casing, and BOP shear rams are exempt from these requirements.
- 10. All respiratory protective, H2S detection, and other needed safety equipment will be in place and ready for use, and all rig crews and other service personnel will be trained in its use when this plan is effective.

- 11. There will be a continuous electronic H2S detection system that will automatically activate visible and audible alarms if hydrogen sulfide is detected. The visible light will activate if 10 ppm H2S is present. The audible siren will activate if 15 ppm H2S or higher concentration is present. There will be at least four H2S sensors in place on the drilling rig. Additional alarm lights & sirens may be added to ensure that all personnel on the drill site are able to notice the alarms at any time. All H2S detection equipment will be calibrated as recommended by the manufacturer and calibration records will be maintained on location.
- 12. Both 30-minute self-contained breathing apparatuses (SCBA) and workline units with escape cylinders will be available on location. There will be sufficient numbers of this supplied air breathing equipment on location to ensure that all personnel on location have equipment available to them. All respiratory protective equipment will use nose cups to prevent fogging in temperatures below 32°F. Spectacle kits will be available for personnel that require corrective lenses when working under mask.
- 13. Electronic voice-microphones will be available for essential personnel to use when working under mask to facilitate communication.
- 14. Additional breathing equipment will be provided for non routine operations that require additional service personnel on the well location to ensure that all personnel on the well location have a dedicated supplied air respirator.
- 15. Electric explosion-proof ventilating fans (bug blowers) will be available to provide air movement in enclosed areas where gas might accumulate.
- 16. Any drill stem test performed on any formation potentially containing H2S will be done with a minimal number of personnel at the drilling site as necessary to safely operate the test equipment. Any such drill-stem test will be conducted only during daylight hours and will be a closed chamber test with no fluids allowed to flow from surface.
- 17. Any production testing of an H2S bearing formation will be done with proper wellhead and other equipment in place to allow a controlled test through separation equipment and flare as needed. Any such test would be conducted with monitoring and warning devises in place and proper safety equipment available.

VI. Well Ignition Procedures

If it should become apparent that an uncontrolled release of hydrogen sulfide to the atmosphere might endanger the health and safety of the public or well site personnel, the Wolverine Wellsite Supervisor will make a decision to ignite the well. The following procedure should be followed before attempting to ignite the well.

- A. Ignition equipment The following equipment will be available for on-site for use by the ignition team.
 - 1. Two 12 gauge flare guns with flare shells
 - 2. Two 500 ft. Fire resistant retrieval ropes

- 3. One portable combustible gas meter
- 4. Self contained breathing apparatus (SCBA) for each member of the ignition team.
- 5. One backup vehicle with communication equipment

B. Ignition Procedures

- 1. The Wellsite Supervisor will ensure that well site personnel are evacuated to a safe area upwind of the well bore prior to any ignition action.
- 2. The Wellsite Supervisor and a designated partner "buddy" backed up by well site safety personnel will comprise the ignition team. All team members will be wearing 30 minute SCBAs.
- 3. The backup crew will be positioned near a radio-equipped vehicle at a safe distance from the sour gas release. They will standby to rescue the actual team igniting the well.
- 4. The partner of the ignition team will carry a combustible gas/ hydrogen sulfide meter to continuously monitor the area in which they are working and define the perimeter of the gas cloud.
- 5. The Wellsite Supervisor will carry the flare gun and shells.
- 6. The ignition team will determine the hazardous area and establish safe working perimeters. Once this is identified the team will proceed upwind of the leak and fire into the area with flare gun. If trouble is encountered in trying to light the leak, retry to ignite by firing the flare shells at 45 and 90 angles to the gas source, but DO NOT approach closer to the leak.
- 7. After ignition, monitor for sulfur dioxide and work with the support group to restrict access to the contaminated area.

VII. Residents – Public in Radius of Exposure

Exposure to H2S by the general public is very unlikely during drilling or completion operations. The well site is located in a remote area, approximately 2.9 miles off the nearest major road. There are no permanent residents within a 1-mile radius of the well site and the 100 PPM and the 500 PPM radii of exposure for this well based on offset well parameters of 2.0 MMCFD flow rate and 0.1% H2S content are less than 2000' and 1000', respectively. The surrounding area is federally owned or STITLA land. This land may be used for recreational purposes including hunting or recreational vehicles during the drilling or completion of this well. The well pad will have controlled access during drilling.

VIII. <u>Emergency Phone Directory</u>

A. Wolverine Gas and Oil Company of Utah, LLC

Chuck Emerson (Drilling Wellsite Supervisor – Wolverine) Rig Phone 970-812-0022 Tom Zupan (Drilling Wellsite Supervisor – Wolverine) Bill Donovan (Drilling Wellsite Supervisor – Wolverine) Jack Magill (Drilling Engineer Consultant) office 308-848-3279 Cell 303-868-6408 Tony Cook (Production Forman – Wolverine) office 435-896-2956 cell 435-201-1622 truck 435-201-2871 Ed Higuera (Operations Manager - Wolverine) office 616-458-1150

Cell

616-690-0023

B. Emergency Services Phone List

1.	Sevier Valley Medical Center - Richfield, UT	435 - 896-8271
2.	Gunnison Valley Hospital, Sanpete County	435 - 528-7246
3.	Ambulance Services – Sevier County, UT	911 or 435-896-6471
4.	Ambulance Services – Sanpete County, UT	911 or 435-835-2191
5.	Sheriff Department - Sevier County, UT	911 or 435-896-6471
6.	Sheriff Department – Sanpete County, UT	911 or 435-835-2191
7.	Highway Patrol - Utah	800 - 222-0038
8.	Fire Department - Sevier County	911 or 435-896-6471
9.	Al McKee, BLM - Salt Lake City, UT (cell phone)	801- 828-7498
10	. Utah Division Oil, Gas & Mining - Salt Lake City, UT	801- 538-5277
11	. Medical Helicopter - Air Med- Salt Lake City, UT	800 - 453-0120
12	. Utah OSHA (Mark LeBlanc)	801- 530-6862
13	. Sevier Valley Medical Center - Richfield, UT	435-896-8271

C. Nearest Hospital

The nearest hospital to the site is the Gunnison Valley Hospital, located at 64 E 100 N, Gunnison, UT. A map and directions to the hospital can be found in Section X-Attachments.

IX. Reference Material for Hydrogen Sulfide and Sulfur Dioxide

If gas should be produced, it could be a mixture of Carbon Dioxide, Hydrogen Sulfide, and Methane.

TOXICITY OF VARIOUS GASES

		Specific	1	2	3
	Chemical	Gravity	Threshold	Hazardous	Lethal
Common Name	<u>Formula</u>	of Air=1	<u>Limit</u>	<u>Limit</u>	Concern
Hydrogen		ADE.			
Cyanide	HCN	0.94	10 ppm	150 ppm/hr	300 ppm
Hydrogen Sulfide	H ₂ S	1.18	10 ppm	250 ppm/hr	600 ppm
Sulfur					
Dioxide	\mathbf{SO}_2	2.21	2 ppm		1,000 ppm
Chloride	CL 1	2.45	1 ppm	4 ppm/hr	1,000 ppm
Carbon Monoxide	CO	0.97	50 ppm	400 ppm/hr	1,000 ppm
Carbon					
Dioxide	\mathbf{CO}_2	1.52	5,000 ppm	5%	10%
Methane	CH4	0.55	90,000 ppm	Combustible Above 5% in Air	

- 1. <u>Threshold</u> = Concentration at which it is believed that all workers may repeatedly be exposed, day after day, without adverse side effects.
- 2. <u>Hazardous</u> = Concentration that may cause death.
- 3. <u>Lethal</u> = Concentration that will cause death with short-term exposure.

HYDROGEN SULFIDE

GENERAL PROPERTIES

Hydrogen Sulfide itself is a colorless and transparent gas and is flammable. It is heavier than air and, hence, may accumulate in low places.

Although the slightest presence of H2S in the air is normally detectable by its characteristic "Rotten Egg"odor, it is dangerous to rely on the odor as a means of detecting excessive concentrations because the sense of smell is rapidly lost allowing lethal concentrations to be accumulated without warning. The following table indicates the poisonous nature of Hydrogen Sulfide, which is more toxic than Carbon Monoxide.

COMMON NAMES: Sour Gas, Rotten Egg Gas, Sulphurated Hydrogen, Hydrogen sulfide, Stink Damp, H2S, Acid Gas, Sweet Gas*

PHYSICAL-CHEMICAL PROPERTIES

Chemical FormulaH2S
1. Specific Gravity (Air = 1.000) 1.193 (@ 77°F)
2. ColorNone
3. Odor Compared to Rotten Eggs
4. Odor Threshold 0.13 part of 1 ppm
5. Corrosivity
6. Solubility in Water 4.0 to 1 in H2O @ 32°F
2.6 to 1 in H2O @ 68°F
7. Effects on Humans Olfactory nerves, respiratory nerves, irritates
sensitive membranes in eyes, nose, and throat.
8. Vapor Pressure
9. Explosive Limits4.3% to 46% by volume in air.
* H2S is a sweet tasting Gas, but often the word "tasting" is left out.
10. Ignition Temperature18°F (Burns with a pale blue flame)
11. Molecular Weight34.08
12. Conversion Factors
mm HG). 1 ppm = 0.00139 mg/1 of air.
13. pH3 in water

INDUSTRIAL OCCURRENCES

Hydrogen Sulfide exposures occur in certain processes in the petroleum industry, chemical plants, chemical laboratories, sulfur and gypsum mines, viscose rayon and rubber industries, tanneries, and in the manufacture of some chemicals, dyes, and pigments. It may be encountered in excavations in the swampy or filled ground. It is produced when sulfur-containing organic matter decomposes, and it can therefore be found in sewage or organic-waste treatment plants. A common sewer gas, it may find its way into utility manhole, particularly dangerous when encountered in tanks, vessels, and other enclosed spaces.

TOXIC PROPERTIES

Hydrogen Sulfide is an extremely toxic and irritating gas. Free Hydrogen Sulfide in the blood reduces its oxygen carrying capacity, thereby depressing the nervous system. Sufficiently high concentrations can cause blockage of the phrenic nerve, resulting in immediate collapse and death due to respiratory failure and asphyxiation.

Because Hydrogen Sulfide is oxidized quite rapidly to sulfates in the body, no permanent after effects occur in cases of recovery from acute exposures unless oxygen deprivation of the nervous system is prolonged. However, in cases of acute exposures, there is always the possibility that pulmonary edema may develop. It is also reported that symptoms such as nervousness, dry nonproductive coughing, nausea, headache, and insomnia, lasting up to about 3 days have occurred after acute exposures to Hydrogen Sulfide.

At low concentrations the predominant effect of Hydrogen Sulfide is on the eyes and respiratory tract. Eye irritation, conjunctivitis, pain, lacrimation, keratitis, and photophobia may persist for several days. Respiratory tract symptoms include coughing, painful breathing, and pain in the nose and throat.

There is no evidence that repeated exposures to Hydrogen Sulfide results in accumulative or systemic poisoning. Effects such as eye irritation, respiratory tract irritation, slow pulse rate, lassitude, digestive disturbances, and cold sweats may occur, but these symptoms disappear in a relatively short time after removal from the exposure. Repeated exposure to Hydrogen Sulfide does not appear to cause any increase or decrease in susceptibility to this gas.

The paralytic effect of Hydrogen Sulfide on the olfactory nerve is probably the most significant property of the gas. This paralysis may create a false sense of security. A worker can be overcome after the typical rotten-egg odor has disappeared. Rather than the characteristic Hydrogen Sulfide odor, some victims of sudden acute overexposure have reported a brief sickeningly sweet odor just prior to unconsciousness.

Subjective olfactory responses to various concentrations of Hydrogen Sulfide may be summarized as follows:

0.02 ppm	No odor
0.13 ppm	Minimal perceptible odor
0.77 ppm	Faint, but readily perceptible odor
4.60 ppm	Easily detectable, moderate odor
27.0 ppm	Strong, unpleasant odor, but not intolerable

Physiological responses to various concentrations of Hydrogen Sulfide have been reported as follows:

10 ppm	Beginning eye irritation
50-100 ppm	Slight conjunctivitis and respiratory tract irritation after 1 hour exposure
100 ppm	Coughing, eye irritation, loss of sense of smell after 2-15 minutes. Altered respiration, pain in the eyes, and drowsiness after 15-30 minutes, followed by throat irritation after 1 hour. Several hours exposure results in gradual increase in severity of these symptoms and death may occur within the next 48 hours
200-300 ppm	Marked conjunctivitis and respiratory tract irritation after 1 hour exposure
500-700 ppm	Loss of consciousness and possibly death in 30 minutes
700 ppm	Rapid unconsciousness, cessation of respiration, and death
1000-2000 ppm	Unconsciousness at once, with early cessation of respiration and death in a few minutes. Death may occur even if individual is removed to fresh air at once.

ACCEPTABLE CONCENTRATIONS

ACCEPTABLE EIGHT-HOUR TIME-WEIGHTED AVERAGE

To avoid discomfort, the Time-Weighted average concentration of Hydrogen Sulfide shall not exceed 10 ppm.

ACCEPTABLE CEILING CONCENTRATION

The acceptable concentration for protection of health for an eight-hour, f ive-day week shall be 20 ppm. Fluctuations are to occur below this concentration.

ACCEPTABLE MAXIMUM FOR PEAKS ABOVE ACCEPTABLE BASE LINE FOR CONTINUOUS EXPOSURE

A single-peak concentration not exceeding 50 ppm for a maximum of 10 minutes is allowable provided that the daily time-weighted average is not exceeded.

H₂S EQUIVALENTS

Parts per	-	Grains per
Million	Percents	100 cu. Ft.
1	0.0001	0.055
10	0.001	0.55
18	0.0018	1.0
100	0.01	5.5
1000	0.1	55.5
10000	1.0	555.5

Grains per 100 cu. Ft. = % by volume Mole 636.4 1% by volume = 10,000 ppm

SULFUR DIOXIDE

Sulfur Dioxide (SO2) is a colorless, transparent gas and is non-flammable.

Sulfur Dioxide is produced during the burning of H2S. Although SO2 is heavier than air, it will be picked up by a breeze and carried downwind at elevated temperatures. While Sulfur Dioxide is extremely irritating to the eyes and mucous membranes of the upper respiratory tract, it has exceptionally good warning powers in this respect.

CONCENTRATIONS		EFFECTS
%SO ₂	ppm	
0.0002	2	Safe for eight (8) hour exposure
0.0005	5	Pungent odor - normally a person can detect SO2 in this range.
0.0012	12	Throat irritation, coughing, constriction of the chest, tearing and smarting of the eyes.
0.015	150	So irritating that it can only be endured for a few minutes.
0.05	500	Causes a sense of suffocation, even with the first breath.

PHYSICAL PROPERTIES AND CHARACTERISTICS

Chemical Formula	.SO ₂
1. Specific Gravity	.2.212
2. Color	.None
3. Flammable	.No
4. Odor	.Characteristic, pungent, gives ample warning of its presence.
5. Corrosivity	Drynot corrosive to ordinary metals. Wetcorrosive to most common metals.
6. Allowable Concentrations	.2 ppm (ACGIH and OSHA)
7. Effects on Humans	Irritates eyes, throat and upper respiratory system

TOXIC PROPERTIES


Sulfur Dioxide is an irritating gas in its vapor form and the odor is so intensely irritating that concentrations of 3 to 5 parts per million in the air are readily detectable by the normal person. In higher concentrations, the severely irritating effect of the gas makes it unlikely that any person would be able to remain in a Sulfur Dioxide contaminated atmosphere unless they were unconscious or trapped.

Sulfur Dioxide gas is intensely irritating to the eyes, throat, and upper respiratory system. Inhalation of this gas in concentrations of 8 to 12 parts per million in air causes throat irritation, coughing, constriction of the chest, tearing and smarting of the eyes. 150 parts per million is so extremely irritating that it can be endured only for a few minutes. 500 parts per million is so acutely irritating to the upper respiratory tract that it causes a sense of suffocation, even with the first breath.

Out of numerous reported exposures to Sulfur Dioxide, there are few references that would indicate pneumonia as an after effect.

X. Attachments-Maps, Diagrams

CONFIDENTIAL






Directions to 64 E 100 N St, Gunnison, UT 84634


8.1 mi - about 13 mins

these directions start interesection of SR 28 and the two-track that leads to the well site pad, which is approximately 2.93 miles off SR 28









Part of Sections 29, 30, 31, & 32,

BASIS OF BEARINGS BASIS OF BEARING USED WAS SOOT4'11"W BETWEEN THE NORTHWEST CORNER AND THE WEST QUARTER CORNER OF SECTION 32, T.17 S., R.1 E., S.L.B. & M. S.H.L. LAT.: 3917'40.1346" (39.294481833) NAD 83 - UTM ZONE 12N NAD27 N 14270269.333 S.H.L. LONG.: -111'50'19.1882" (-111.838663389) NAD 83 - UTM ZONE 12N NAD27 E 1403356.103 B.H.L. LAT.: 3918'01.0089" (39.300280250) - UTM ZONE 12N NAD27 N 14272392.259 B.H.L. LONG.: -111'50'35.2337" (-111.843120472) - UTM ZONE 12N NAD27 E 1402114.793

PROJECT

Wolverine Operating Company of Utah, LLC.

WELL LOCATION, LOCATED AS SHOWN IN THE N.W. 1/4 OF THE N.W. 1/4 OF SECTION 32, T.17 S., R.1 E., S.L.B. & M. SANPETE COUNTY, UTAH

LEGEND

►! = SECTION CORNERS LOCATED

➤ = QUARTER SECTION CORNERS LOCATED

= REESTABLISHED SECTION CORNERS

□ = REESTABLISHED QUARTER SECTION CORNERS

= PROPOSED WELL HEAD

= PROPOSED BOTTOM HOLE LOCATION

NOTE: THE PURPOSE OF THIS SURVEY WAS TO PLAT THE ROUGH CANYON FEDERAL #30-1 LOCATION. LOCATED IN THE N.W. 1/4 OF THE N.W. 1/4 OF SECTION 32, T.17 S., R.1 E., S.L.B. & M., SANPETE COUNTY, UTAH.

BASIS OF ELEVATION

ELEVATION BASED ON N.A.V.D. 88



CERTIFICATE

THIS IS TO CERTIFY THAT THIS PLAT WAS PREPARED FROM FIELD NOTES OF ACTUAL SURVEYS MADE BY ME OR UNDER MY SUPERVISION, AND THAT THE SAME ARE TRUE AND CORRECT TO THE BEST OF MY KNOWLEDGE AND BELIEF.





Jones & DeMile Engineering

100 West - Richfield, Utah 84701 Phone (435) 896-8266 Fax (435) 896-8268 www.jonesanddemille.com

Well Location Plat for

Wolverine Operating Company of Utah, LLC.

DATE 04/08/2010		DWG.NAME 0911-082	SCALE 1"=1000'	0911-062	1
	B.S.B.	T.R.G.	T.R.G.	J	1 .
DESIGNED	SURVEYED	CHECKED	DRAWN	PROJECT NO.	SHEET NO.

Wolverine Gas & Oil Company

Rough Canyon Sanpete County, Utah Rough Canyon Federal 30-1

Wellbore #1

Plan: Design #1

Standard Planning Report

08 April, 2010

Planning Report

Database: EDM 5000.1 Single User Db

Wolverine Gas & Oil Company Company:

Project: Rough Canyon Sanpete County, Utah Site:

Rough Canyon Federal 30-1 Well:

Wellbore: Wellbore #1 Design #1 Design:

Local Co-ordinate Reference:

TVD Reference: MD Reference: North Reference:

Survey Calculation Method:

Site Sanpete County, Utah

WELL @ 0.0ft (Original Well Elev) WELL @ 0.0ft (Original Well Elev)

Grid

Minimum Curvature

Rough Canyon Project

US State Plane 1927 (Exact solution) Map System:

NAD 1927 (NADCON CONUS) Geo Datum:

Map Zone: Utah Central 4302

Mean Sea Level System Datum:

Site Sanpete County, Utah

350,273.10 ft Northing: Site Position: Latitude: 39° 17' 40.276 N 1,904,368.00 ft 111° 50' 16.454 W Easting: Longitude: From: Lat/Long 0.0 ft **Slot Radius:** 0 " -0.22 ° **Position Uncertainty: Grid Convergence:**

Well Rough Canyon Federal 30-1

Well Position +N/-S 0.0 ft Northing: 350.273.10 ft Latitude: 39° 17' 40.276 N

0.0 ft 1,904,368.00 ft +E/-W Easting: Longitude: 111° 50' 16.454 W

0.0 ft Wellhead Elevation: **Ground Level:** 0.0 ft **Position Uncertainty**

Wellbore Wellbore #1 Declination **Dip Angle** Field Strength **Magnetics Model Name** Sample Date (nT) (°) (°) User Defined 2010/04/08 0.00 0.00 0

Design Design #1 **Audit Notes: PROTOTYPE** Tie On Depth: 0.0 Version: Phase: **Vertical Section:** Depth From (TVD) +N/-S +E/-W Direction (ft) (ft) (ft) (°) 0.0 0.0 0.0 329.21

Plan Section	s									
Measured Depth (ft)	Inclination (°)	Azimuth (°)	Vertical Depth (ft)	+N/-S (ft)	+E/-W (ft)	Dogleg Rate (°/100ft)	Build Rate (°/100ft)	Turn Rate (°/100ft)	TFO (°)	Target
0.0	0.00	0.00	0.0	0.0	0.0	0.00	0.00	0.00	0.00	
1,400.0	0.00	0.00	1,400.0	0.0	0.0	0.00	0.00	0.00	0.00	
1,400.0	0.00	0.00	1,400.0	0.0	0.0	0.00	0.00	0.00	0.00	
2,506.7	16.60	329.21	2,491.3	136.8	-81.5	1.50	1.50	0.00	329.21	
10,022.1	16.60	329.21	9,693.5	1,981.2	-1,180.5	0.00	0.00	0.00	0.00	
11,128.8	0.00	0.00	10,784.7	2,118.0	-1,262.0	1.50	-1.50	0.00	180.00	
12,844.1	0.00	0.00	12,500.0	2,118.0	-1,262.0	0.00	0.00	0.00	0.00 PBHL	

Planning Report

Database: EDM 5000.1 Single User Db Wolverine Gas & Oil Company

Project: Rough Canyon
Site: Sanpete County, Utah
Well: Rough Canyon Federal 30-1

Wellbore: Wellbore #1
Design: Design #1

Local Co-ordinate Reference:

TVD Reference: MD Reference: North Reference:

Survey Calculation Method:

Site Sanpete County, Utah

WELL @ 0.0ft (Original Well Elev) WELL @ 0.0ft (Original Well Elev)

Grid

esign:	Design #1								
Planned Survey									
Measured Depth (ft)	Inclination (°)	Azimuth (°)	Vertical Depth (ft)	+N/-S (ft)	+E/-W (ft)	Vertical Section (ft)	Dogleg Rate (°/100ft)	Build Rate (°/100ft)	Turn Rate (°/100ft)
0.0 100.0 200.0 300.0 400.0	0.00 0.00 0.00 0.00 0.00	0.00 0.00 0.00 0.00 0.00	0.0 100.0 200.0 300.0 400.0	0.0 0.0 0.0 0.0 0.0	0.0 0.0 0.0 0.0 0.0 0.0	0.0 0.0 0.0 0.0 0.0	0.00 0.00 0.00 0.00 0.00	0.00 0.00 0.00 0.00 0.00	0.00 0.00 0.00 0.00 0.00
500.0	0.00	0.00	500.0	0.0	0.0	0.0	0.00	0.00	0.00
600.0	0.00	0.00	600.0	0.0	0.0	0.0	0.00	0.00	0.00
700.0	0.00	0.00	700.0	0.0	0.0	0.0	0.00	0.00	0.00
800.0	0.00	0.00	800.0	0.0	0.0	0.0	0.00	0.00	0.00
900.0	0.00	0.00	900.0	0.0	0.0	0.0	0.00	0.00	0.00
1,000.0	0.00	0.00	1,000.0	0.0	0.0	0.0	0.00	0.00	0.00
1,100.0	0.00	0.00	1,100.0	0.0	0.0	0.0	0.00	0.00	0.00
1,200.0	0.00	0.00	1,200.0	0.0	0.0	0.0	0.00	0.00	0.00
20" Casing 1,300.0 1,400.0 KOP Begin	0.00 0.00 n Build 1.50°/1	0.00 0.00	1,300.0 1,400.0	0.0 0.0	0.0 0.0	0.0 0.0	0.00 0.00	0.00 0.00	0.00 0.00
1,500.0	1.50	329.21	1,500.0	1.1	-0.7	1.3	1.50	1.50	0.00
1,600.0	3.00	329.21	1,599.9	4.5	-2.7	5.2	1.50	1.50	0.00
1,700.0	4.50	329.21	1,699.7	10.1	-6.0	11.8	1.50	1.50	0.00
1,800.0	6.00	329.21	1,799.3	18.0	-10.7	20.9	1.50	1.50	0.00
1,900.0	7.50	329.21	1,898.6	28.1	-16.7	32.7	1.50	1.50	0.00
2,000.0	9.00	329.21	1,997.5	40.4	-24.1	47.0	1.50	1.50	0.00
2,100.0	10.50	329.21	2,096.1	54.9	-32.7	64.0	1.50	1.50	0.00
2,200.0	12.00	329.21	2,194.2	71.7	-42.7	83.5	1.50	1.50	0.00
2,300.0	13.50	329.21	2,291.7	90.7	-54.0	105.5	1.50	1.50	0.00
2,400.0	15.00	329.21	2,388.6	111.8	-66.6	130.2	1.50	1.50	0.00
2,500.0	16.50	329.21	2,484.9	135.1	-80.5	157.3	1.50	1.50	0.00
2,506.7	16.60	329.21	2,491.3	136.8	-81.5	159.2	1.49	1.49	0.00
End of Buil	d 16.60° 2507	7' MD							
2,600.0	16.60	329.21	2,580.7	159.7	-95.1	185.9	0.00	0.00	0.00
2,700.0	16.60	329.21	2,676.5	184.2	-109.8	214.4	0.00	0.00	0.00
2,800.0	16.60	329.21	2,772.4	208.7	-124.4	243.0	0.00	0.00	0.00
2,900.0	16.60	329.21	2,868.2	233.3	-139.0	271.6	0.00	0.00	0.00
3,000.0	16.60	329.21	2,964.0	257.8	-153.6	300.1	0.00	0.00	0.00
3,100.0	16.60	329.21	3,059.9	282.4	-168.3	328.7	0.00	0.00	0.00
3,200.0	16.60	329.21	3,155.7	306.9	-182.9	357.3	0.00	0.00	0.00
3,300.0	16.60	329.21	3,251.5	331.5	-197.5	385.8	0.00	0.00	0.00
3,400.0	16.60	329.21	3,347.4	356.0	-212.1	414.4	0.00	0.00	0.00
3,500.0	16.60	329.21	3,443.2	380.5	-226.7	443.0	0.00	0.00	0.00
3,600.0	16.60	329.21	3,539.0	405.1	-241.4	471.5	0.00	0.00	0.00
3,700.0	16.60	329.21	3,634.8	429.6	-256.0	500.1	0.00	0.00	0.00
3,800.0	16.60	329.21	3,730.7	454.2	-270.6	528.7	0.00	0.00	0.00
3,900.0	16.60	329.21	3,826.5	478.7	-285.2	557.3	0.00	0.00	0.00
4,000.0	16.60	329.21	3,922.3	503.3	-299.9	585.8	0.00	0.00	0.00
4,081.0	16.60	329.21	4,000.0	523.1	-311.7	609.0	0.00	0.00	0.00
13 3/8" Cas 4,100.0 4,200.0	16.60 16.60	329.21 329.21	4,018.2 4,114.0	527.8 552.3	-314.5 -329.1	614.4 643.0	0.00 0.00	0.00 0.00	0.00 0.00
4,300.0	16.60	329.21	4,209.8	576.9	-343.7	671.5	0.00	0.00	0.00
4,400.0	16.60	329.21	4,305.7	601.4	-358.4	700.1	0.00	0.00	0.00
4,500.0	16.60	329.21	4,401.5	626.0	-373.0	728.7	0.00	0.00	0.00
4,600.0	16.60	329.21	4,497.3	650.5	-387.6	757.2	0.00	0.00	0.00
4,700.0	16.60	329.21	4,593.2	675.1	-402.2	785.8	0.00	0.00	0.00

Planning Report

Database: EDM 5000.1 Single User Db Wolverine Gas & Oil Company

Project: Rough Canyon
Site: Sanpete County, Utah
Well: Rough Canyon Federal 30-1

Wellbore: Wellbore #1

Design: Design #1

Local Co-ordinate Reference:

TVD Reference:
MD Reference:
North Reference:

Survey Calculation Method:

Site Sanpete County, Utah

WELL @ 0.0ft (Original Well Elev) WELL @ 0.0ft (Original Well Elev)

Grid

Design:	Design #1								
Planned Survey									
Measured Depth (ft)	Inclination (°)	Azimuth (°)	Vertical Depth (ft)	+N/-S (ft)	+E/-W (ft)	Vertical Section (ft)	Dogleg Rate (°/100ft)	Build Rate (°/100ft)	Turn Rate (°/100ft)
4,800.0	16.60	329.21	4,689.0	699.6	-416.9	814.4	0.00	0.00	0.00
4,900.0	16.60	329.21	4,784.8	724.1	-431.5	842.9	0.00	0.00	0.00
5,000.0	16.60	329.21	4,880.7	748.7	-446.1	871.5	0.00	0.00	0.00
5,100.0	16.60	329.21	4,976.5	773.2	-460.7	900.1	0.00	0.00	0.00
5,200.0	16.60	329.21	5,072.3	797.8	-475.3	928.6	0.00	0.00	0.00
5,300.0	16.60	329.21	5,168.2	822.3	-490.0	957.2	0.00	0.00	0.00
5,400.0	16.60	329.21	5,264.0	846.9	-504.6	985.8	0.00	0.00	0.00
5,500.0	16.60	329.21	5,359.8	871.4	-519.2	1,014.4	0.00	0.00	0.00
5,600.0	16.60	329.21	5,455.7	895.9	-533.8	1,042.9	0.00	0.00	0.00
5,700.0	16.60	329.21	5,551.5	920.5	-548.5	1,071.5	0.00	0.00	0.00
5,800.0	16.60	329.21	5,647.3	945.0	-563.1	1,100.1	0.00	0.00	0.00
5,900.0	16.60	329.21	5,743.2	969.6	-577.7	1,128.6	0.00	0.00	0.00
6,000.0	16.60	329.21	5,839.0	994.1	-592.3	1,157.2	0.00	0.00	0.00
6,100.0	16.60	329.21	5,934.8	1,018.7	-607.0	1,185.8	0.00	0.00	0.00
6,200.0	16.60	329.21	6,030.7	1,043.2	-621.6	1,214.3	0.00	0.00	0.00
6,300.0	16.60	329.21	6,126.5	1,067.7	-636.2	1,242.9	0.00	0.00	0.00
6,400.0	16.60	329.21	6,222.3	1,092.3	-650.8	1,271.5	0.00	0.00	0.00
6,500.0	16.60	329.21	6,318.2	1,116.8	-665.5	1,300.0	0.00	0.00	0.00
6,600.0	16.60	329.21	6,414.0	1,141.4	-680.1	1,328.6	0.00	0.00	0.00
6,700.0	16.60	329.21	6,509.8	1,165.9	-694.7	1,357.2	0.00	0.00	0.00
6,800.0	16.60	329.21	6,605.6	1,190.4	-709.3	1,385.8	0.00	0.00	0.00
6,900.0	16.60	329.21	6,701.5	1,215.0	-723.9	1,414.3	0.00	0.00	0.00
7,000.0	16.60	329.21	6,797.3	1,239.5	-738.6	1,442.9	0.00	0.00	0.00
7,100.0	16.60	329.21	6,893.1	1,264.1	-753.2	1,471.5	0.00	0.00	0.00
7,200.0	16.60	329.21	6,989.0	1,288.6	-767.8	1,500.0	0.00	0.00	0.00
7,300.0	16.60	329.21	7,084.8	1,313.2	-782.4	1,528.6	0.00	0.00	0.00
7,400.0	16.60	329.21	7,180.6	1,337.7	-797.1	1,557.2	0.00	0.00	0.00
7,500.0	16.60	329.21	7,276.5	1,362.2	-811.7	1,585.7	0.00	0.00	0.00
7,600.0	16.60	329.21	7,372.3	1,386.8	-826.3	1,614.3	0.00	0.00	0.00
7,700.0	16.60	329.21	7,468.1	1,411.3	-840.9	1,642.9	0.00	0.00	0.00
7,800.0	16.60	329.21	7,564.0	1,435.9	-855.6	1,671.4	0.00	0.00	0.00
7,900.0	16.60	329.21	7,659.8	1,460.4	-870.2	1,700.0	0.00	0.00	0.00
8,000.0	16.60	329.21	7,755.6	1,485.0	-884.8	1,728.6	0.00	0.00	0.00
8,100.0	16.60	329.21	7,851.5	1,509.5	-899.4	1,757.1	0.00	0.00	0.00
8,200.0	16.60	329.21	7,947.3	1,534.0	-914.1	1,785.7	0.00	0.00	0.00
8,300.0	16.60	329.21	8,043.1	1,558.6	-928.7	1,814.3	0.00	0.00	0.00
8,400.0	16.60	329.21	8,139.0	1,583.1	-943.3	1,842.9	0.00	0.00	0.00
8,500.0	16.60	329.21	8,234.8	1,607.7	-957.9	1,871.4	0.00	0.00	0.00
8,600.0	16.60	329.21	8,330.6	1,632.2	-972.5	1,900.0	0.00	0.00	0.00
8,700.0	16.60	329.21	8,426.5	1,656.8	-987.2	1,928.6	0.00	0.00	0.00
8,800.0	16.60	329.21	8,522.3	1,681.3	-1,001.8	1,957.1	0.00	0.00	0.00
8,900.0	16.60	329.21	8,618.1	1,705.8	-1,016.4	1,985.7	0.00	0.00	0.00
9,000.0	16.60	329.21	8,714.0	1,730.4	-1,031.0	2,014.3	0.00	0.00	0.00
9,100.0	16.60	329.21	8,809.8	1,754.9	-1,045.7	2,042.8	0.00	0.00	0.00
9,200.0	16.60	329.21	8,905.6	1,779.5	-1,060.3	2,071.4	0.00	0.00	0.00
9,300.0	16.60	329.21	9,001.5	1,804.0	-1,074.9	2,100.0	0.00	0.00	0.00
9,400.0	16.60	329.21	9,097.3	1,828.6	-1,089.5	2,128.5	0.00	0.00	0.00
9,500.0	16.60	329.21	9,193.1	1,853.1	-1,104.2	2,157.1	0.00	0.00	0.00
9,600.0	16.60	329.21	9,289.0	1,877.6	-1,118.8	2,185.7	0.00	0.00	0.00
9,700.0	16.60	329.21	9,384.8	1,902.2	-1,133.4	2,214.2	0.00	0.00	0.00
9,800.0	16.60	329.21	9,480.6	1,926.7	-1,148.0	2,242.8	0.00	0.00	0.00
9,900.0	16.60	329.21	9,576.4	1,951.3	-1,162.7	2,271.4	0.00	0.00	0.00
10,000.0	16.60	329.21	9,672.3	1,975.8	-1,177.3	2,300.0	0.00	0.00	0.00
10,022.1	16.60	329.21	9,693.5	1,981.2	-1,180.5	2,306.3	0.00	0.00	0.00

Planning Report

Database: EDM 5000.1 Single User Db Wolverine Gas & Oil Company

Project: Rough Canyon
Site: Sanpete County, Utah
Well: Rough Canyon Federal 30-1

Wellbore: Wellbore #1
Design: Design #1

Local Co-ordinate Reference:

TVD Reference: MD Reference: North Reference:

Survey Calculation Method:

Site Sanpete County, Utah

WELL @ 0.0ft (Original Well Elev) WELL @ 0.0ft (Original Well Elev)

Grid

gn:	Design #1								
nned Survey									
Measured Depth (ft)	Inclination (°)	Azimuth (°)	Vertical Depth (ft)	+N/-S (ft)	+E/-W (ft)	Vertical Section (ft)	Dogleg Rate (°/100ft)	Build Rate (°/100ft)	Turn Rate (°/100ft)
Begin Drop	1.50°/100'MD								
10,028.9	16.50	329.21	9,700.0	1,982.9	-1,181.5	2,308.2	1.49	-1.49	0.00
9 5/8" Casi	ng				11				
10,100.0 10,200.0 10,300.0 10,400.0 10,500.0	15.43 13.93 12.43 10.93 9.43	329.21 329.21 329.21 329.21 329.21	9,768.3 9,865.1 9,962.4 10,060.4 10,158.8	1,999.7 2,021.5 2,041.1 2,058.5 2,073.6	-1,191.5 -1,204.5 -1,216.2 -1,226.5 -1,235.6	2,327.8 2,353.1 2,375.9 2,396.2 2,413.8	1.50 1.50 1.50 1.50 1.50	-1.50 -1.50 -1.50 -1.50 -1.50	0.00 0.00 0.00 0.00 0.00
10,600.0 10,700.0 10,800.0 10,900.0 11,000.0	7.93 6.43 4.93 3.43 1.93	329.21 329.21 329.21 329.21 329.21	10,257.6 10,356.8 10,456.3 10,556.1 10,656.0	2,086.6 2,097.3 2,105.8 2,112.1 2,116.1	-1,243.3 -1,249.7 -1,254.8 -1,258.5 -1,260.9	2,428.9 2,441.4 2,451.3 2,458.6 2,463.3	1.50 1.50 1.50 1.50 1.50	-1.50 -1.50 -1.50 -1.50 -1.50	0.00 0.00 0.00 0.00 0.00
11,100.0 11,128.8	0.43 0.00	329.21 329.21	10,755.9 10,784.7	2,117.9 2,118.0	-1,261.9 -1,262.0	2,465.4 2,465.5	1.50 1.50	-1.50 -1.50	0.00 0.00
End of Dro			40.055.0	0.440.0	4 000 0	0.405.5	0.00	0.00	0.00
11,200.0 11,300.0 11,400.0	0.00 0.00 0.00	0.00 0.00 0.00	10,855.9 10,955.9 11,055.9	2,118.0 2,118.0 2,118.0	-1,262.0 -1,262.0 -1,262.0	2,465.5 2,465.5 2,465.5	0.00 0.00 0.00	0.00 0.00 0.00	0.00 0.00 0.00
11,500.0 11,600.0 11,700.0 11,800.0 11,900.0	0.00 0.00 0.00 0.00 0.00	0.00 0.00 0.00 0.00 0.00	11,155.9 11,255.9 11,355.9 11,455.9 11,555.9	2,118.0 2,118.0 2,118.0 2,118.0 2,118.0	-1,262.0 -1,262.0 -1,262.0 -1,262.0 -1,262.0	2,465.5 2,465.5 2,465.5 2,465.5 2,465.5	0.00 0.00 0.00 0.00 0.00	0.00 0.00 0.00 0.00 0.00	0.00 0.00 0.00 0.00 0.00
12,000.0 12,100.0 12,200.0 12,300.0 12,400.0	0.00 0.00 0.00 0.00 0.00	0.00 0.00 0.00 0.00 0.00	11,655.9 11,755.9 11,855.9 11,955.9 12,055.9	2,118.0 2,118.0 2,118.0 2,118.0 2,118.0	-1,262.0 -1,262.0 -1,262.0 -1,262.0 -1,262.0	2,465.5 2,465.5 2,465.5 2,465.5 2,465.5	0.00 0.00 0.00 0.00 0.00	0.00 0.00 0.00 0.00 0.00	0.00 0.00 0.00 0.00 0.00
12,500.0 12,600.0 12,700.0 12,800.0 12,844.0	0.00 0.00 0.00 0.00 0.00	0.00 0.00 0.00 0.00 0.00	12,155.9 12,255.9 12,355.9 12,455.9 12,499.9	2,118.0 2,118.0 2,118.0 2,118.0 2,118.0 2,118.0	-1,262.0 -1,262.0 -1,262.0 -1,262.0 -1,262.0	2,465.5 2,465.5 2,465.5 2,465.5 2,465.5	0.00 0.00 0.00 0.00 0.00	0.00 0.00 0.00 0.00 0.00	0.00 0.00 0.00 0.00 0.00
PBHL 128	44' MD								
12,844.1	0.00	0.00	12,500.0	2,118.0	-1,262.0	2,465.5	0.00	0.00	0.00

Design Targets									
Target Name - hit/miss target - Shape	Dip Angle (°)	Dip Dir. (°)	TVD (ft)	+N/-S (ft)	+E/-W (ft)	Northing (ft)	Easting (ft)	Latitude	Longitude
PBHL - plan hits target	0.00 center	0.00	12,500.0	2,118.0	-1,262.0	352,391.10	1,903,106.00	39° 18' 1.163 N	111° 50' 32.610 V

Planning Report

Database: EDM 5000.1 Single User Db Wolverine Gas & Oil Company

Project: Rough Canyon
Site: Sanpete County, Utah
Well: Rough Canyon Federal 30-1

Wellbore: Wellbore #1
Design: Design #1

Local Co-ordinate Reference:

TVD Reference:
MD Reference:
North Reference:

Survey Calculation Method:

Site Sanpete County, Utah

WELL @ 0.0ft (Original Well Elev) WELL @ 0.0ft (Original Well Elev)

Grid

Casing Points								
	Measured Depth (ft)	Vertical Depth (ft)		Name	.	Casing Diameter (")	Hole Diameter (")	
	1,200.0	1,200.0	20" Casing			20	26	
	4,081.0	4,000.0	13 3/8" Casing			13-3/8	17-1/2	
	10,028.9	9,700.0	9 5/8" Casing	< C		9-5/8	12-1/4	

Plan Annotations Measured Depth (ft)	Vertical Depth (ft)	Local Coordinates +N/-S +E/-W (ft) (ft)	Comment
1,400.0 2,506.7 10,022.1 11,128.8 12,844.0	1,400.0 2,491.3 9,693.5 10,784.7 12,499.9	0.0	2.0 End of Drop 0.00° 11129' MD

WOLVERINE OPERATING COMPANY OF UTAH, LLC

DRILLING PLAN

Rough Canyon Federal 30-1 NE/4 SE/4 Section 30, Township 17 South, Range 1 East, S.L.B & M. Sanpete County, Utah

Plan Summary:

It is planned to drill this confidential exploratory well as a directional hole to a proposed depth of 12,800 MD to test the Jurassic Twin Creek and Navajo. Well path deviation caused by subsurface geologic irregularities, plastic salts, possible loss circulation and hole instabilities are expected to be the primary drilling concerns in this area. No abnormal pressure is anticipated.

The planned location is as follows:

Surface Location: 288' FNL, 452' FWL, Section 32, T17S, R1E, S.L.B. & M. Bottom Hole Location @ Navajo 1830' FSL, 810' FEL, Section 30, T17S, R1E, S.L.B. & M.

Thirty-two inch (32") conductor will be set to approximately 60' GL, or sufficient depth to reach the Flagstaff and for Boart Longyear rig to rig up to. and then a 26" hole will be drilled to approximately 1200', through the Tertiary Colton, Flagstaff and North Horn (conglomerates/sand/limestone) and part of the Cretaceous Indianola (conglomerates/sand/silt/shales) which extends from ~350 to 2440'. Twenty- inch (20") casing will be set from surface to 1200' and cemented to surface. After drilling that section, the Boart-Longyear rig will be moved off and Patterson Rig 304 will be moved on to finish the hole.

A 17.5" hole will be drilled directionally to approximately 4000' MD, which is projected to be into the Arapien formation, using a build rate of 1.5 degrees/100' with a KOP at 1400'. At 4000' MD, or once confirmed in the Arapien, 13-3/8" casing will be set and cemented to surface. A 12.25" hole will be directionally drilled from under the 13-3/8" casing at a projected angle of 16.6 degrees to approximately 10,100 (9800' TVD). At approximately 10,000' MD, the well will be allowed to drop at 1.5 degrees/100' until reaching the projected TD of 12,800' MD.

This plan provides for 9-5/8" casing string to be set into the Twin Creek, if required to address unstable hole conditions. If unstable hole conditions are present, after drilling into the Twin Creek to approximately 10.100' MD, the well will be logged and 9-5/8" casing will be set and cemented to ~3500 (500' inside 13-3/8" casing). An 8.5" hole will be drilled to an approximate maximum depth of 12,800' MD, where the well will be logged. If warranted by logging and drilling results, a 5.5" production liner will be set and cemented from TD to inside the 9-58" casing.

Drilling activities, with the construction of the well site and setting of conductor and 20" casing, are expected to commence in during July/August 2010, or as soon as the permit is issued.

Well Name: Rough Canyon Federal 30-1

Surface Location: 288' FNL, 452' FWL, Section 32, T17S, R1E, S.L.B. & M

NW/4 of the NW/4 Section 32, T17S, R1E, S.L.B. & M.

Sanpete County, Utah

TD Bottom-Hole Location: 1830' FSL, 810' FEL, Section 30, T17S, R1E, S.L.B. & M

NE/4 of the SE/4 Section 30, T17S, R1E, S.L.B. & M.

Sanpete County, Utah

Elevations: 6171' GL (graded), 6191' KB (est.)

I. Geology:

Tops of important geologic markers and anticipated oil (O), gas (G), or water (W), content are as follows:

<u>Formation</u>	TVD Interval (KB)	MD Interval (KB)	<u>Contents</u>	Pressure Gradient
Colton	0-56'	0-56'		
Flagstaff	56-156'	56-156'		
North Horn	156-356'	156-356'		
Indianola	356-2800'	356-2830'		
Twist Gulch	2800-3863'	2830-3940'		
Arapien	3863-9765'	3940-10,100'		
Twin Creek	9765-10079	10,100-10,400	O,G,W	0.44 psi/ft
Navajo	10079'-11,900'	10,400-12,250	O, G, W	0.44 psi/ft
Proposed TD	12,400'	~12,800'		

II. Well Control:

The contracted drilling rig will have a minimum 5M BOP system. BOPE will be in place and tested as a 5M system prior to drilling out the surface casing shoe. See attached schematic of BOPE.

A. The BOPE will, as a minimum, include the following:

Wellhead Equipment (5M Min.):

BOPE Item	Flange Size and Rating
Annular Preventer	13-5/8" 5M
Double Rams (5" Pipe - top, Blind - bottom)	13-5/8" 10M
Drilling Spool w/ 2 side outlets (4" Choke Line, 4" Kill Line)	13-5/8" 10M x 13-5/8" 10M
Single Ram (Pipe)	13-5/8" 10M
DSA	13-5/8" 10M x 13-5/8" 5M
Casing Head (13-5/8" SOW w/ two 2-1/16" SSO's)	13-5/8" 5M

Auxiliary Equipment (5M Min.):

BOPE Item	
Choke Line with 2 valves (3" minimum)	
Kill Line with 2 valves and one check valve (2" Minimum)	
2 Chokes with one remotely controlled at a location readily accessible to the driller	
Upper and lower kelly cock valves with handles	

Safety Valves to fit all drill string connections in use	
Inside BOP or float sub	
Pressure gauge on choke manifold	
Fill-up line above the uppermost preventer	
Wear bushing in casing head	

- A. Choke manifold will be functionally equipped and sized at a minimum as shown on the attached diagram. All choke lines will be straight lines unless turns have tee blocks or are targeted with running tees, and all choke lines will be anchored. All valves (except chokes) in the kill line choke manifold and choke line will be full opening and allow straight through flow.
- B. System accumulator will have sufficient capacity to open the hydraulically-controlled gate valve and close all rams plus the annular preventer (3 ram system will have added 50 percent safety factor to compensate for any fluid loss in the control system or preventers) and retain a minimum pressure of 200 psi above pre-charge on the closing manifold without use of the closing unit pumps. The fluid reservoir capacity shall be double the usable fluid volume of the accumulator system capacity and the fluid level of the reservoir shall be maintained at the manufacturer's recommendations. The accumulator will have two (2) independent power sources available to close the preventers. Nitrogen bottles may be one of those sources, and if so, will have charge maintained per manufacturer's specifications.
- C. Accumulator pre-charge pressure test will be conducted prior to connecting the closing unit to the BOP stack and at least once every 6 months. The accumulator pressure will be corrected if the measured precharge pressure is found to be above or below the maximum or minimum specified limits. Only nitrogen gas will be used to precharge.
- D. Power for the closing unit pumps will be available to the unit at all times so that the pumps will automatically start when the closing valve manifold pressure has decreased to the pre-set level.
- E. Accumulator pump capacity will be such that, with the accumulator system isolated from service, the pumps will be capable of opening the hydraulically-operated gate valve (if so equipped), plus closing the annular preventer on the smallest size drill pipe to be used within 2 minutes, and retaining a minimum of 200 psi above the specified accumulator pre-charge pressure.
- F. Locking devices, either manual (i.e., hand wheels) or automatic, will be installed on the ram type preventers. A valve will be installed in the closing line as close as possible to the annular preventer to act as a locking device. This valve shall be maintained in the open position and shall be closed only when the power source for the accumulator system is inoperative.
- G. Remote controls will be readily accessible to the driller and will be capable of both opening and closing all preventers. Master controls shall be at the accumulator and shall be capable of opening and closing all preventers and the choke line valve.
- H. Well control equipment testing will be performed using clear water when the equipment is initially installed, whenever any seal subject to test pressure is broken, following related repairs, and as a minimum, every 30-day interval. The tests will apply to all related well control equipment.

Ram type preventers and associated equipment will be isolated and tested to 5000 psi. The annular preventer will be tested to 2500 psi. Pressure shall be maintained for at least 10 minutes or until requirements of test are met, whichever is longer, for all tests. A casing head valve will be open below the test plug during testing of the BOP stack. Valves will be tested from the working pressure side with all down-stream valves open. Kill line valves will be tested with the check valve held open or the ball removed.

Pipe and blind rams will be activated each trip, but not more than once a day. The annular preventers will be functionally operated at least weekly. A pit level drill will be conducted weekly for each crew. All BOPE drills and tests will be recorded in the IADC driller's log.

III. Casing and Cementing:

A. Casing Program (all new casing):

Hole Size	Casing Size	Weight	Grade	Connection	Coupling Diameter	Setting Depth, MD
36"	32", 3/8" wall	126.7	B Line Pipe	PE	NA	0-72 DF
26"	20"	106.5	J-55	BTC	21.00	0' - 1200' DF
17.5"	13.375"	68	J-55	BTC	14.375	0' - 4000' DF
12.25"	9.625"	53.5	L-80	LTC	10.625	0'-6000' DF
12.25"	9.625"	53.5	P-110	LTC	10.625	6000'-10,100' DF
8.50"	5.5"	20	N-80	LTC	6.05	8100' - 12,800' DF

32-inch conductor-set at 50 GL (72 DF

The 32" casing is used to allow drilling fluid to be diverted into hole and into tanks, as needed, by the Boart-Longyear. No design conducted on this pipe. It will be cemented with Class G neat cement, using a tremie pipe, placed in stages with a 2-inch pipe in the 32" x 36" OH annulus.

20", 106.5 #/ft, J-55 BTC casing set at 1200' DF

The 26" hole/20-inch casing section will be drilled vertically with Boart-Longyear rig. The casing design parameters are detailed below:

Burst: Worst case burst load occurs if the well experiences an influx of gas from 4000 feet TVD. Assume the casing is filled with gas. In that case, assuming a fresh water pore pressure gradient to 4000 ft TVD and a gas gradient equal to 0.1 psi/ft, maximum burst differential pressure would occur at the surface:

 $P = 0.433 \times 4000 - 0.1 \times 4000 = 1332$ psi. The selected casing, 20" 106.5#/ft J-55 BTC, has burst strength of 2410 psi. The burst design factor is: $DF_b = \frac{2410}{1332} = 1.81$, 1.81 > 1.1, therefore OK.

Collapse: Worst case collapse load occurs if the casing is evacuated. Collapse pressure attributed to fresh water pore pressure gradient is: $P = 0.433 \times 1200 = 520$ psi. The selected casing has collapse strength of 770 psi. The collapse design factor is: $DF_c = \frac{770}{520} = 1.48$, 1.48 > 1.125, therefore OK.

Tension: String weight in air is: $T=106.5\times 1200=127,800$ lb. Joint strength is 1596 kips. The tension design factor in air is: $DF_t=\frac{1596000}{127800}=12.5,12.5>1.8$, therefore OK.

Cementing Program:

20" casing will be cemented from setting depth (1200' MD DF) to surface and topped out with premium cement if necessary. Hardware will include a guide shoe, float collar, top plug, and a minimum of one centralizer per joint on the bottom three (3) casing joints. Water or other preflush fluid pumped ahead of the slurry will separate cement from the drilling fluids. Cement volumes are based on 50% excess in the openhole, 700 feet of 10.5 ppg lead cement from surface to 700 feet and 500 feet of 15.8 ppg tail cement from 700 feet to 1200 feet.

Cement: Lead: 380 sacks Varicem cement, 10.5 ppg, 4.12 cf/sx Yield.

Tail: 1015 sacks Premium cement, 15.8 ppg, 1.19 cf/sk Yield

13-3/8", 68 #/ft, J-55 BTC casing set at 4000' MD DF

The 17-1/2" hole/13-3/8" casing section will be drilled directionally drilled with Patterson Rig 304 into the top of the Arapien formation, where casing will be set and cemented to surface. The casing design parameters are detailed below:

Burst: Worst case burst load occurs if the well experiences an influx of gas from 9800 feet TVD. Assume the casing is 90% filled with gas. In that case, assuming a fresh water pore pressure gradient to 9800 ft, 9 ppg fluid inside the casing and a gas gradient equal to 0.1 psi/ft, maximum burst differential pressure would occur at the surface: $P = 0.433 \times 9800 - 0.1 \times 9800 \left(\frac{9.0}{19.25}\right) - 0.1 \times 0.9 \times 9800 = 2903$ psi. The selected casing, $13\frac{3}{6}$ 68#/ft J-55 BTC has burst strength of 3450 psi. The burst design factor is: $DF_b = \frac{3450}{2903} = 1.18$, 1.18 > 1.1, therefore OK.

Collapse: Worst case collapse load occurs if the casing is evacuated. Collapse pressure attributed to fresh water pore pressure gradient is: $P = 0.433 \times 4000 = 1732$ psi. The selected casing has collapse strength of 1950 psi. The collapse design factor is: $DF_c = \frac{1950}{1732} = 1.126$, 1.126 > 1.125, therefore OK.

Tension: String weight in air is: $T=68\times4000=272,000$ lb. Tube strength is 1069 kips. The tension design factor in air is: $DF_t=\frac{1069000}{272000}=3.93,3.93>1.8$, therefore OK.

Cementing Program:

13-3/8" casing will be cemented from setting depth (4000' MD DF) to surface in a single stage using the following mix. Hardware will include a guide shoe, float collar, top plug, and a minimum of one centralizer per joint on the bottom three (3) casing joints. Water or other preflush fluid pumped ahead of the slurry will separate cement from the drilling fluids. Cement volumes are based on 50% excess in the openhole, 3500 feet of 10 ppg lead cement from surface to 3500 feet and 500 feet of 13 ppg tail cement from 3500 to 4000 feet.

Cement: Lead: 1050 sacks Light System, 10 ppg, 3.39 cf/sx Yield
Tail: 375 sacks 50/50 Poz, 13.9 ppg, 1.57 cf/sx Yield

9-5/8", 53.5 #/ft, L-80 and P-110 LTC casing set at 10,100' MD DF (~9800' TVD)

The 12-1/4" hole/9-5/8" casing section will be drilled directionally with Patterson Rig 304 into the top of the Twin Creek formation, where 9-5/8" casing will be set cemented to inside the 13-3/8" casing. The casing design parameters are detailed below:

Burst: Worst case burst load occurs if the well experiences an influx of gas from 12,500 feet TVD. Assume the casing is filled with gas. In that case, assuming a fresh water pore pressure gradient to 12,500 ft TVD and a gas gradient equal to 0.1 psi/ft, maximum burst differential pressure would occur at the surface: $P = 0.433 \times 12500 - 0.1 \times 12500 = 4163$ psi. The selected casing, 9% 53.5% ft L-80 LTC has burst strength of 7930 psi. The burst design factor is: $DF_b = \frac{7930}{4163} = 1.90, 1.90 > 1.1$, therefore OK.

Collapse: Worst case collapse load occurs if the casing is evacuated. Collapse pressure attributed to fresh water pore pressure gradient is: $P = 0.433 \times 9800 = 4243$ psi. The selected casing has collapse strength of 6620 psi. The collapse design factor is: $DF_c = \frac{6620}{4234} = 1.564, 1.564 > 1.125$, therefore OK.

> Alternate Collapse, salt considerations: The Arapien formation contains salt stringers throughout. The salt stringers, due to creep, can apply unusually high collapse loads to the casing. Wolverine standard design for this area is to design for 1 psi/ft of depth external pressure with a fresh water gradient inside the pipe and with a minimum design factor of 1.000. Arapien is predicted to occur from 3862' to 9765' TVD.

Maximum salt induced pressure applied to the 53.5# L-80 casing occurs at 6000 ft:

 $P = 6000 - 0.433 \times 6000 = 3402 \text{ psi}$. 9\% 53.5\# L-80 has collapse strength of 6620 psi. The collapse design factor across from salts in the L-80 casing is:

$$DF_c = \frac{6620}{3402} = 1.946, 1.946 > 1.000,$$
therefore OK.

 $DF_c = \frac{6620}{3402} = 1.946$, 1.946 > 1.000, therefore OK.

Maximum potential collapse pressure occurs at TD of 9765. If there is a salt present at the base of the Arapien, and is: $P = 9765 - 0.433 \times 9765 = 5537$ pst. Switch over to 9\% 53.5\# P-110 LTC casing at 6000 ft and run that casing to TD of 9765' TVD. 91/8 53,5# P-110 has collapse strength of 7950 psi. The collapse

design factor across from salts in the P-110 casing is:
$$DF_c = \frac{7950}{5537} = 1.436, 1.436 > 1.000, \text{ therefore OK.}$$

Another maximum potential collapse pressure involves evacuating the string such as would occur if the well were swabbed below 7850 feet, the depth to the top of the liner. In this case, salt collapse load could be applied to the outside of the casing with no backup pressure on the inside of the casing. P = 7850 psi.

$$DF_c = \frac{7950}{7850} = 1.013, 1.013 > 1.000$$
, therefore OK.

Tension: String weight in air is: $T = 53.5 \times 9800 = 524,300$ lb. Joint strength is 1047 kips. The tension design factor in air is: $DF_{\rm t} = \frac{1047000}{524300} = 1.93, 1.93 > 1.8$, therefore OK.

Cementing Program:

9-5/8" casing will be cemented from setting depth 10,100' MD) to 3500' (500 feet inside casing) in a single stage using the following mix. Hardware will include a guide shoe, two shoe joints, float collar, top plug, and a minimum of one centralizer per joint on the bottom three (3) casing joints. Water or other pre-flush fluid pumped ahead of the slurry will separate cement from the drilling fluids. Cement volumes are based on 25% excess in the openhole, 6100 feet of 14.4 ppg lead cement from 3500 to 9600 feet and 500 feet of 14 ppg tail cement from 9600 to 10,100 feet.

Cement: Lead 2030 sacks Light Standard, 14.4 ppg, 1.26 cf/sx Yield

Tail: 150 sacks Class G neat cement blend, 15.8 ppg, 1.53 cf/sx Yield

5-1/2", 20 #/ft, N-80 LTC casing liner set from 8100-12,800' MD DF (7850-12500' TVD)

The 8.5" hole/5-1/2" casing section will be drilled directionally with Patterson Rig 304 through the target Navajo to TD, where the formations will be logged and evaluated. If warranted a 5-1/2" liner would be set across the prospective pay zone and cemented to inside the 9-5/8" casing. The casing design parameters are detailed below:

Burst: Worst case burst load occurs at 12,400 ft TVD, just above a packer, with a tubing leak at surface. Assume a fresh water pore pressure gradient, the well is producing from perforations at 12,500' TVD, the tubing is filled with gas and the packer fluid has a gradient of 0.465 psi/ft.

 $P = 0.433 \times 12500 - 0.1 \times 12500 + 0.465 \times 12400 - 0.433 \times 12400 = 4559$ psi. The selected casing,

 $5\frac{1}{2}$ 20#/ft N-80 LTC has burst strength of 9190 psi. The burst design factor is: $DF_0 = \frac{9190}{4559} = 2.02, 2.02 > 1.1$, therefore OK.

Collapse: Worst case collapse load occurs if the casing is evacuated. Collapse pressure attributed to fresh water pore pressure gradient is: $P = 0.433 \times 12500 = 5413$ psi. The selected casing has collapse strength of 8830 psi. The collapse design factor is: $DF_c = \frac{8830}{5413} = 1.631$, 1.631 > 1.125, therefore OK.

Tension: String weight in air is: $T = 20 \times 4700 = 94,000$ lb. Joint strength is 428 kips. The tension design factor in air is:

$$DF_{\rm t} = \frac{428000}{94000} = 4.60, 4.60 > 1.8$$
, therefore OK

Cementing Program:

This is a liner cement job. 8.5" hole will be drilled from $10,100^{\circ}$ to $12800^{\circ}MD$. The liner will be suspended from drill pipe and a liner hanger. The $5-1/2^{\circ}$ liner will be cemented over its entire length (~ 4700 feet of length from 8100° to $12800^{\circ}MD$). The $5-1/2^{\circ}$ casing will be cemented from setting depth ($12,800^{\circ}MD$) to $8100^{\circ}MD$ (overlapping the $9-5/8^{\circ}$ casing across the deep salts) in a single stage using the following mix. Hardware will include a guide shoe, two shoe joints, float collar, top plug, and a minimum of one centralizer per joint on the bottom three (3) casing joints and over the pay zones. Water or other preflush fluid pumped ahead of the slurry will separate cement from the drilling fluids.

Cement: 815 sacks Class G, 15.8 ppg, 1.53 Yield

Notes:

- a. Final casing cement volumes will be adjusted when open-hole caliper logs obtained.
- b. A minimum of 20 percent silica will be added to the cement slurry if bottom-hole temperature exceeds 230. Expected static BHT at 12,800' MD (12500' TVD) is 250 deg. F.
- Final cement slurry mix could be adjusted based vendor recommendation or vendor actually used for job.
 Cementing company has not been selected yet for this well.
- d. The BLM will be notified at least twenty-four hours prior to running and cementing the surface and production casing strings.
- e. The size, weight, grade, type of thread, number of joints, and footage of all casing run will be recorded in the driller's log. The amount and type of all cement pumped will be recorded in the driller's log.
- Adequate time will be allowed before drilling out for the cement at the casing shoe to achieve a minimum 500-psi compressive strength.
- g. All casing strings will be tested to 1500 psi before drilling out and if pressure declines by more than 10 percent in 30 minutes, corrective action will be taken.
- h. Before drilling more than 20 feet of new hole below each casing string, a pressure integrity test of the casing shoe will be performed to a minimum of the mud weight equivalent anticipated to control the pore pressure to the next casing depth or at total depth of the well.

IV. Mud Program:

Depth	Mud Weight (ppg)	Mud Type	Viscosity, s/qt	Fluid Loss
0 – 1200'	8.6 - 9.2	Fresh Water Mud	35 – 50	NC to 15 cc
1200'- 4000'	8.6- 9.0	LSND FW Mud	45 – 55	<8 cc
4000-10,100'	10.5-10.7	Salt Saturated Mud	45-50	<8 cc
10,100-12,800'	8.9-9.5	WBM, 50K chlorides	36-42	<8 cc

- A. After mudding up, slow pump rates will be taken daily and recorded in the driller's log.
- B. Visual mud monitoring equipment will be in place to detect volume changes indicating loss or gain of circulating fluid volume.
- C. Abnormal pressures are not anticipated. In the event such pressures are to be anticipated, electronic/mechanical mud monitoring equipment will be in place and include as a minimum; pit volume totalizer (PVT); stroke counter; and flow sensor.
- D. A mud test will be performed every 24 hours after mudding up to determine, as applicable: density, viscosity, gel strength, filtration, and pH.
- E. The 10M BOPE system is not required for conditions on this well and use of the trip tank is not anticipated.
- F. Gas detecting equipment will be installed in the mud return system, and hydrocarbon gas shall be monitored for pore pressure changes. The presence of Hydrogen Sulfide gas is not expected but appropriate precautions will be taken in the event that it is encountered.
- G. The need to vent combustible or noncombustible gas is not expected. If needed, a flare system designed to gather and burn all gas will be available. The flare line discharge will be located at least 150 feet from the well head and it will be positioned downwind of the prevailing wind direction. The flare line will have straight lines unless turns are targeted with running tees and it will be anchored. The flare system will have an effective method for ignition.
- H. Abnormal pressure is not expected. If abnormal pressure is to be anticipated, a mud-gas separator (gas buster) will be installed and operable beginning at a point at least 500 feet above any anticipated hydrocarbon zone of interest.

V. Evaluation:


- A. Mud Log: A mud logging unit will be in operation from a depth of approximately 1200 feet to TD. Samples will be caught, cleaned, bagged, and marked as required.
- B. Drill Stem Tests: There are no DSTs planned.
- C. Coring: There are no whole cores planned. Sidewall cores may be collected depending on log results.
- D. Wireline Logs: Wireline logs will be run as hole conditions allow from total depth to surface casing to assist in determining lithology and potential for hydrocarbon recovery. The logging tools will include: resistivity, density-neutron log, gamma ray, dip meter, and caliper.


Expected Bottom-Hole Pressure and Abnormal Conditions: VI.

- A. Hydrogen Sulfide: The presence of Hydrogen Sulfide (H₂S) gas is possible and appropriate safety procedures are to be in place before penetrating the Twin Creek Formation.
- B. Pressure: No abnormally pressured zones are expected in this well. The pore pressure gradient for all potentially productive formations is expected to be approximately 0.44 psi/ft.
- end end C. Temperature: Bottom-hole temperature at TD is expected to be approximately 250 °F.

5k BOPE Schematic

(Not to Scale)





IDAHO

BOX ELDER

JUAB

PIUTE

KANE

ARIZONA


MILLARD


BEAVER

IRON

WASHINGTON

WOLVERINE OPERATING CO. OF UTAH, L.L.C. ROUGH CANYON FEDERAL 30-1 2010





APPROVAL

RECOMMENDED FOR APPROV	/AL:
ENGINEER	DATE
APPROVED:	
	DATE

LAND ADMINISTRATION KEY

WYOMING

GRAND

SAN JUAN

WASATCH

• LOCATION

GARFIELD

WAYNE

Bureau of Land Management
State
Private


VICINITY MAP



Jones & DeMille Engineering, Inc.

1535 South 100 West Richfield, Utah 84701 Voice 435.896.8266 Fax 435.896.8268


100 West 248 East Main tah 84701 Price, Utah 84501 396.8266 Voice 435.637.8268 96.8268 Fax 435.637.8268 www.jonesanddemille.com




1A

SHEET NO.

74.48 FEET (CHORD BEARS N33°56'29"E 73.72 FEET); THENCE N19°43'00"E 56.47 FEET TO THE POINT OF TERMINATION, SAID POINT OF TERMINATION BEING LOCATED S40°29'09"E 619.23 FEET FROM THE NORTHWEST CORNER OF SAID SECTION 32.




- 1. TYPE 1 TYPICAL SECTION APPLIES FROM STA. 85+60 to STA. 165+57.4 1.52 MILES TOTAL (STA. 158+32.8 TO STA. 165+57.4 ON SITLA)
- 2. 20-FOOT WIDTH AT TURN-OUTS.
- 3. EXTRA WIDTH UP TO 40.2' TOTAL REQUIRED FOR CURVE WIDENING WHERE NOTED ON PLAN SHEETS.



TYPE 2 TYPICAL SECTION UPGRADE EXISTING ROAD

- NOTES:
 1. TYPE 2 TYPICAL SECTION APPLIES FROM STA. 10+00 to STA. 85+60 1.44 MILES
 - 20-FOOT WIDTH AT TURN OUTS.
- CROSS SLOPE DIRECTION VARIES. SLOPE DIRECTION TO MATCH SURROUNDING NATURAL SLOPE.

	NO DATE DESIGN MARS PARCECS REQUEST REMARKS NO DATE REV. BY CORR BY MYSTOLED BY	ORIGINAL SUBMISSION FOR AUTHORIZATION	AND THE STATE OF T	SCALE: DWG NAME: 15-01 DWG CHEATEU: UNWAZOU LAST 2/26/2010	Shi Seri, Robert Canton Pren Ibs. jandra-17200.cb
			DATE PROJECT DESIGNENCINEER I G 01-2010 D.R. 01-2010 AVE.	APPROVED: CHECK.	DATE CHECK 69°.
Wolverine Operating Co. of Utah, LLC	SAN	IPE	S ALT PICAL SECTIONS	ITI PROJECT	NUMBER: US I -UOZ



GRANULAR BORROW REQ'D THROUGH ENTIRE DIP TO GRADE BREAK(S).

2. CONSTRUCT DRAINAGE DITCH AS NECCESSARY TO PROVIDE POSITIVE


DRAINAGE AWAY FROM ALL DRAINAGE DIPS.


DRAINAGE DIP LOCATION STATIONS (@ CENTERLINE OF ROADWAY):


Nolverine Operating Co. of Utah, LLC ROUGH CANYON FEDERAL 30-1


SANPETE


SHEET NO. TS-02











Search all of Utah.gov »



Utah Division of Water Rights





There are no features in the query area.

Click on the back button to try again

Please direct questions and comments regarding the map server to: leeeschler@utah.gov.





Utah Division of Water Rights

| 1594 West North Temple Suite 220, P.O. Box 146300, Salt Lake City, Utah 84114-6300 | 801-538-7240 Natural Resources | Contact | Disclaimer | Privacy Policy | Accessibility Policy



State of Utah

GARY R. HERBERT Governor

GREG BELL Lieutenant Governor Office of the Governor PUBLIC LANDS POLICY COORDINATION

JOHN HARJA Director

RECEIVED MAY 2 4 2010 DIV. OF OIL, GAS & MINING

May 19, 2010

ENTIAL 2558

Gil Hunt Utah Department of Natural Resources Division of Oil, Gas and Mining 1594 West North Temple, Suite 1210 Salt Lake City, UT 84114-5801

Subject:

Rough Canyon Federal 30-1 well (wildcat) on Oil Well lease UTU-82536, Sanpete

County

RDCC Project No. 11345

Dear Mr. Hunt:

The State of Utah, through the Public Lands Policy Coordination Office (PLPCO), has reviewed this project. Utah Code (Section 63J-4-601, et. seq.) designates PLPCO as the entity responsible to coordinate the review of technical and policy actions that may affect the physical resources of the state, and to facilitate the exchange of information on those actions among federal, state, and local government agencies. As part of this process, PLPCO makes use of the Resource Development Coordinating Committee (RDCC). The RDCC includes representatives from the state agencies that are generally involved or impacted by public lands management.

Division of Air Quality

The proposed project will be subject to R307-205-5: Fugitive Dust, of the Utah Air Quality Rules, due to the fugitive dust that may be generated during soil disturbance for the project. These rules apply to construction activities that disturb an area greater than 1/4 acre in size. A permit, known as an Approval Order, is not required from the Executive Secretary of the Air Quality Board, but steps need to be taken to minimize fugitive dust, such as watering and/or chemical stabilization, providing vegetative or synthetic cover or windbreaks. A copy of the rules can be found at www.rules.utah.gov/publicat/code/r307/r307.htm.

The State of Utah appreciates the opportunity to review this proposal and we look forward to working with you on future projects. Please direct any other written questions regarding this correspondence to the Public Lands Policy Coordination Office at the address below, or call Judy Edwards at (801) 537-9023.

Sincerely,

John Harja Director 'APIWellNo:43039500030000'

Chris Fausett From:

Hill, Brad; Mason, Diana To:

Irons, Charlie; jimdavis1@utah.gov CC:

6/14/2010 11:16 AM Date:

Subject: Wolverine Operating Company of Utah APD Approval

The APD for Wolverine's Rough Canyon Federal 30-1 (API #4303950003) has been reviewed and approved by SITLA, including archaeological clearance. As a condition of this approval, the applicant must complete a special use lease for the surface use of the well pad prior to beginning drilling activities. This lease is in process and near completion.

Please let me know if you have any questions.

Thanks,

IDENTIAL Chris Fausett Resource Specialist State of Utah School and Institutional Trust Lands Administration 675 East 500 South, Suite 500 Salt Lake City, UT 84102-2818

Phone: (801) 538-5139

ON-SITE PREDRILL EVALUATION

Utah Division of Oil, Gas and Mining

Operator WOLVERINE OPERATING COMPANY OF UTAH, LLC

Well Name Rough Canyon Federal 30-1

API Number 43039500030000 APD No 2558 Field/Unit WILDCAT

Location: 1/4,1/4 NWNW Sec 32 Tw 17.0S Rng 1.0E 288 FNL 452 FWL

GPS Coord (UTM) 427743 4349587 Surface Owner

Participants

M. Jones (UDOGM), Charlie Irons (Wolverine), Kurt Higgins, Ed Bonner, and Jim Davis (SITLA), Stan Andersen (BLM), Darrin Robinson (Jones & DeMille), Glen Nebeker (Western Land Services).

Regional/Local Setting & Topography

Located in Rough Canyon in the San Pitch Mountain Range in central Utah. Northeast of Fayette, Utah approximately 4.5 miles. Access will come from the west off of Highway 28, then head northeasterly on BLM surface on an existing two-track along the valley floor that will be upgraded. This road dies out at the mouth of Rough Canyon. A new road will have to be built and maintained through Rough Canyon up the bottom of the stream channel for about 1.5 miles. Topography varies drastically along the sides of Rough Canyon along the access road and at the wellsite. The streambed topography maintains about an 8% grade along the route to the location, with a short 10% grade right at the access point onto the proposed location. The location sits on a small knoll between two drainages. The location and about the last 700 feet of access road is located on SITLA surface, with all the rest of the road and the bottom hole location being on BLM.

Surface Use Plan

Current Surface Use

Wildlfe Habitat

New Road Miles Well Pad Src Const Material Surface Formation

1.52 **Width** 310 **Length** 425 Onsite

Ancillary Facilities

It may be necessary to store some equipment (pipe, mud, vehicles) off-site at a staging area before entering the mouth of Rough Canyon due to the smaller size well pad because of topographical constraints.

Waste Management Plan Adequate?

Environmental Parameters

Affected Floodplains and/or Wetlands Y

location and access road will affect drainage of Rough Canyon in that the access road in the canyon is up the bottom of the streambed and the location will divert flow of drainages on 2 sides.

Flora / Fauna

Pinion Juniper Community.

Soil Type and Characteristics

rocky clay.

Erosion Issues Y

The material in the roadbed should impede erosion in Rough Canyon so that it is less than the current erosion. Armoring will be required at strategic points along the well pad to protect the pad fill from erosion.

6/14/2010 Page 1

Sedimentation Issues Y

Some sedimentation is possible from the disturbed areas of the pad and the access road.

Site Stability Issues N

Drainage Diverson Required? Y

both drainages (north and south side of the pad) will need to be diverted a little around the corners of the pad traveling from east to west.

Berm Required? Y

A berm will be required to keep fluids from leaving the well pad.

Erosion Sedimentation Control Required? Y

Armoring will be required at strategic points on the well pad to protect the pad from being eroded.

Paleo Survey Run? N Paleo Potental Observed? N Cultural Survey Run? Y Cultural Resources?

Reserve Pit

Site-Specific Factors	Site R	anking	
Distance to Groundwater (feet)	>200	0	
Distance to Surface Water (feet)	>1000	0	
Dist. Nearest Municipal Well (ft)	>5280	0	
Distance to Other Wells (feet)	>1320	0	
Native Soil Type	High permeability	20	
Fluid Type	TDS>5000 and	10	
Drill Cuttings	Normal Rock	0	
Annual Precipitation (inches)	10 to 20	5	
Affected Populations			
Presence Nearby Utility Conduits	Not Present	0	
	Final Score	35	1 Sensitivity Level

Characteristics / Requirements

Dugout earthen (90x140x12). Liner required.

Closed Loop Mud Required? N Liner Required? Y Liner Thickness 12 Pit Underlayment Required?

Other Observations / Comments

The BLM had a concern during the pre-site regarding the access road at about the point where the access leaves BLM and enters SITLA surface. Stan Andersen was concerned about the cut into the slope to build the access road. Stan suggested running the road on top of the knoll instead. Wolverine contends that they need to stay below a 10% grade, and to get on top of the knoll would require close to double that. SITLA was fine with the road as it was staked on their surface. Title V right-of-way application has already been submitted to the BLM. There is about 1.42 miles of upgraded existing road, and about 1.38 miles of new road to be built on BLM lands. There is about 700 feet of new road to be built on SITLA lands.

I failed to invite DWR to the pre-site meeting. I contacted Mark Farmer on 5/11/2010 with DWR, Central Region @ 801-361-3744. He said he was unfamiliar with the pre-site process, which I explained to him and told him I would take time to meet him at the location to look at it with him since I forgot to invite him. He said he would look

6/14/2010 Page 2

at a map and get back to me if their were any concerns, but based on the section, township, and range he didn't see any concerns for wildlife.

I asked Darrin Robinson about the smaller location size for this well. He said originally when they staked this well they had the section lines staked wrong which necessitated a smaller pad to keep it on SITLA surface and within the topography constraints they have to work with. Those section lines have been re-surveyed in their correct positions and gives a little more room to work with. He said Wolverine already had things rolling with the permit when this was corrected and they didn't want to start over at that point. He said that Wolverine may submit a sundry to widen the pad after the permit is issued. Neither SITLA (Jim Davis) and I could see any problem with that.

Mark Jones 5/4/2010

Evaluator Date / Time

6/14/2010 Page 3

6/14/2010

Application for Permit to Drill Statement of Basis

Utah Division of Oil, Gas and Mining

Page 1

APD NoAPI WellNoStatusWell TypeSurf OwnerCBM255843039500030000SITLAOWSNo

Operator WOLVERINE OPERATING COMPANY OF

Surface Owner-APD

Unit

UTAH, LLC

Well Name Rough Canyon Federal 30-1

Field WILDCAT Type of Work DRILL

Location NWNW 32 17S 1E S 288 FNL 452 FWL GPS Coord (UTM) 427803E 4349605N

Geologic Statement of Basis

This location is placed just to the east of the south central portion of the Gunnison Plateau area, near the extreme western edge of the Colorado Plateau physiographic province in western central Utah. Some people have characterized this area as being in the Basin and Range - Colorado Plateau transition zone. It is otherwise characterized as being astride the Sevier Overthrust Belt. The location is on state land about 5 miles north of Fayette, Utah, about 3.5 miles west southwest of the Sevier River in Sanpete County. This location falls just east of the trace of the Paxton Thrust at the north end of the Gunnison Anticline and west of the Plateau-bounding Wales-Gunnison backthrust fault. A well at this location will spud into a soil developed on the Tertiary age Colton Formation. The location is mapped as positioned in a graben valley in a generally well-faulted area. The area is in a primary valley fill recharge area near the transition to a valley fill discharge area. Aquifers with pristine to drinking water quality [400 to 600 mg/l Total Dissolved Solids (TDS)] ground water are likely to be encountered in the shallow sediments. The hole will be drilled with a fresh water and gel mud system to 4,000' TD to set the 13 3/8" surface casing. The intermediate hole will be drilled with a saturated salt mud system. It is anticipated that this mud system is designed to handle the evaporites of the Arapien Shale. Any water encountered in the Arapien Shale is likely to be of poor quality. A Division of Water Rights publication notes that aquifers in close proximity to the Arapien Shale are also likely to contain ground water with high TDS levels. A casing, cementing and drilling fluid program as proposed should be sufficient to control and isolate the poor quality ground waters expected to be encountered at that depth in a well at this location. No water rights have been filed on underground sources of water within a mile of the location.

Chris Kierst 5/18/2010 **APD Evaluator Date / Time**

Surface Statement of Basis

On-site evaluation conducted May 4, 2010. In attendance was M. Jones (UDOGM), Charlie Irons (Wolverine), Kurt Higgins, Ed Bonner, and Jim Davis (SITLA), Stan Andersen (BLM), Darrin Robinson (Jones & DeMille), Glen Nebeker (Western Land Services).

Wolverine suggested that they would have traffic control personel posted both at the mouth of Rough Canyon and at the location. DOGM recommends this control be in place during the rig move and during drilling of the well. "Heavy Truck Traffic" signs may need to be posted after the well is drilled to help warn non-suspecting motorists on this stretch of the road.

The well pad shall be armored in the drainages at corner #2 and around corner #5 to prevent erosion of the pad by storm events.

The well pad shall be bermed to prevent fluids from leaving the pad into the adjacent drainages.

If the pits have sharp rocks in them a felt liner will be required to protect the synthetic pit liner.

6/14/2010

Application for Permit to Drill Statement of Basis

Utah Division of Oil, Gas and Mining

Page 2

Mark Jones **Onsite Evaluator**

5/4/2010 **Date / Time**

Conditions of Approval / Application for Permit to Drill

Category Condition

Pits A synthetic liner with a minimum thickness of 12 mils shall be properly installed and maintained in the reserve pit. (A felt

subliner may be required if sharp rocks are found while excavating the pits. Esspecially if the pit needs to be blasted.)

Surface The well site shall be bermed to prevent fluids from leaving the pad

Surface Drainages adjacent to the proposed pad shall be diverted around the location.

Surface The reserve pit shall be fenced upon completion of drilling operations.

Surface The well pad shall be armored in the drainages at corner #2 and around corner #5 to prevent erosion of the pad by storm events.

WORKSHEET APPLICATION FOR PERMIT TO DRILL

APD RECEIVED:	4/20/2010	API NO. ASSIGNED:	43039500030000
	Rough Canyon Federa		
		ING COMPANY OF UTAH, LLC (N3035) PHONE NUMBER:	435 896-1943
CONTACT:	Charles Irons		
PROPOSED LOCATION:	NWNW 32 170S 010E	Permit Tech Review:	
SURFACE:	0288 FNL 0452 FWL	Engineering Review:	
воттом:	1830 FSL 0810 FEL	Geology Review:	
COUNTY:	SANPETE		
LATITUDE:	39.29469	LONGITUDE:	-111.83722
UTM SURF EASTINGS:	427803.00	NORTHINGS:	4349605.00
FIELD NAME:	WILDCAT	<i>)</i>	
LEASE TYPE:	1 - Federal		
LEASE NUMBER:	UTU-82536 P	PROPOSED PRODUCING FORMATION(S): NAVAJO	
SURFACE OWNER:	3 - State	COALBED METHANE:	NO
RECEIVED AND/OR REV	IEWED:	LOCATION AND SITING:	
⊭ PLAT		R649-2-3.	
▶ Bond: FEDERAL - BL	M WYB000616	Unit:	
Potash		R649-3-2. General	
Oil Shale 190-5			
Oil Shale 190-3		R649-3-3. Exception	
Oil Shale 190-13		Drilling Unit	
✓ Water Permit: 63-3		Board Cause No: R649-3-11	
RDCC Review: 2010	0-06-14 00:00:00.0	Effective Date:	
Fee Surface Agreer	nent	Siting:	
Intent to Comming		 № R649-3-11. Directional Drill	
Commingling Approv	red		
Comments: Presite	Completed		
5 - Sta 15 - D 21 - R	deral Approval - dmasc atement of Basis - bhill birectional - dmason DCC - dmason pacing - dmason	on I	

API Well No: 43039500030000



State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

Permit To Drill

Well Name: Rough Canyon Federal 30-1

API Well Number: 43039500030000 **Lease Number:** UTU-82536

Surface Owner: STATE **Approval Date:** 6/14/2010

Issued to:

WOLVERINE OPERATING COMPANY OF UTAH, LLC, 1140 N. Centennial Park Dr., Richfield, UT 84701

Authority:

Pursuant to Utah Code Ann. §40-6-1 et seq., and Utah Administrative Code R649-3-1 et seq., the Utah Division of Oil, Gas and Mining issues conditions of approval, and permit to drill the listed well. This permit is issued in accordance with the requirements of R649-3-11. The expected producing formation or pool is the NAVAJO Formation(s), completion into any other zones will require filing a Sundry Notice (Form 9). Completion and commingling of more than one pool will require approval in accordance with R649-3-22.

Duration:

This approval shall expire one year from the above date unless substantial and continuous operation is underway, or a request for extension is made prior to the expiration date

General:

Compliance with the requirements of Utah Admin. R. 649-1 et seq., the Oil and Gas Conservation General Rules, and the applicable terms and provisions of the approved Application for permit to drill.

Conditions of Approval:

State approval of this well does not supercede the required federal approval, which must be obtained prior to drilling.

In accordance with Utah Admin. R.649-3-11, Directional Drilling, the operator shall submit a complete angular deviation and directional survey report to the Division within 30 days following completion of the well.

This proposed well is located in an area for which drilling units (well spacing patterns) have not been established through an order of the Board of Oil, Gas and Mining (the "Board"). In order to avoid the possibility of waste or injury to correlative rights, the operator is requested, once the well has been drilled, completed, and has produced, to analyze geological and engineering data generated therefrom, as well as any similar data from surrounding areas if available. As soon as is practicable after completion of its analysis, and if the analysis suggests an area larger than the quarter-quarter section upon which the well is located is being drained, the operator is requested to seek an appropriate order from the Board establishing drilling and spacing units in conformance with such analysis by filing a Request for Agency Action with the Board.

The Application for Permit to Drill has been forwarded to the Resource Development Coordinating

API Well No: 43039500030000

Committee for review of this action. The operator will be required to comply with any applicable recommendations resulting from this review. (See attached)

Compliance with the Conditions of Approval/Application for Permit to Drill outlined in the Statement of Basis (copy attached).

Notification Requirements:

The operator is required to notify the Division of Oil, Gas and Mining of the following actions during drilling of this well:

• Within 24 hours following the spudding of the well – contact Carol Daniels at 801-538-5284 (please leave a voicemail message if not available)

OR

submit an electronic sundry notice (pre-registration required) via the Utah Oil & Gas website at https://oilgas.ogm.utah.gov

Reporting Requirements:

All reports, forms and submittals as required by the Utah Oil and Gas Conservation General Rules will be promptly filed with the Division of Oil, Gas and Mining, including but not limited to:

- Entity Action Form (Form 6) due within 5 days of spudding the well
- Monthly Status Report (Form 9) due by 5th day of the following calendar month
- Requests to Change Plans (Form 9) due prior to implementation
- Written Notice of Emergency Changes (Form 9) due within 5 days
- Notice of Operations Suspension or Resumption (Form 9) due prior to implementation
- Report of Water Encountered (Form 7) due within 30 days after completion
- Well Completion Report (Form 8) due within 30 days after completion or plugging

Approved By:

Acting Associate Director, Oil & Gas

FORM APPROVED Form 3160-3 OMB No. 1004-0137 (August 2007) Expires July 31, 2010 UNITED STATES Lease Serial No. DEPARTMENT OF THE INTERIOR UTU-82536 BUREAU OF LAND MANAGEMENT If Indian, Allotee or Tribe Name APPLICATION FOR PERMIT TO DRILL OR REENTER 7. If Unit or CA Agreement, Name and No. **✓** DRILL REENTER la. Type of work: N/A 8. Lease Name and Well No. ✓ Oil Well Gas Well ✓ Single Zone Multiple Zone Rough Canyon Federal 30-1 lb. Type of Well: 9. API Well No. Name of Operator Wolverine Operating Company of Utah, LLC 43.039-50003 3b. Phone No. (include area code) 10. Field and Pool, or Exploratory 3a. Address 1140 N Centennial Park Drive Richfield, Utah 84701 Exploratory 11. Sec., T. R. M. or Blk. and Survey or Area Location of Well (Report location clearly and in accordance with any State requirements.*) Sec. 30, T17S, R1E, SLB&M At surface 288' FNL, 452' FWL Sec 32-T17S-R1E (being in NW4/NW4) At proposed prod. zone 1830' FSL, 810' FEL Sec 30-T17S-R1E (being in NE4/SE4) 12. County or Parish 13. State 14. Distance in miles and direction from nearest town or post office* Sanpete UT 5 miles North-Northeast of Fayette, Utah 16. No. of acres in lease 763.60 Distance from proposed* 810 feet 17. Spacing Unit dedicated to this well location to nearest 40 acres property or lease line, ft. (Also to nearest drig. unit line, if any) 20. BLM/BIA Bond No. on file 19. Proposed Depth 18. Distance from proposed location* to nearest well, drilling, completed, **BLM WYB000616** 12,400' TVD applied for, on this lease, ft. 22. Approximate date work will start* 23. Estimated duration 21. Elevations (Show whether DF, KDB, RT, GL, etc.) 90 days 6171' GL 07/15/2010 24. Attachments The following, completed in accordance with the requirements of Onshore Oil and Gas Order No.1, must be attached to this form: Bond to cover the operations unless covered by an existing bond on file (see 1. Well plat certified by a registered surveyor. Item 20 above). 2. A Drilling Plan. 3. A Surface Use Plan (if the location is on National Forest System Lands, the Operator certification Such other site specific information and/or plans as may be required by the SUPO must be filed with the appropriate Forest Service Office).

<i>i</i>	10.25121	
25. Signature Van Siene	Name (Printed Typed) Paul Spiering	Date 04/14/2010
Title District Land Manager		
Approved by (Signature)	Name (Printed Typed) Wayne A. Wetzel	Date 20 July 2010
Title Assoc Field Manager	Rich Field Field Offi	ce
Application approval does not warrant or certify that the applicant h conduct operations thereon.	olds legal or equitable title to those rights in the subject lease which	would entitle the applicant to

Conditions of approval, if any, are attached. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United

(Continued on page 2)

RECEIVED JUL 26 2010

DIV. OF OIL, GAS & MINING

APR 14 2010

Conditions of Approval Attached

States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Richfield BLM Field Office

Conditions of Approval (COAs)

Based on this environmental assessment, the subject ROW grant UTU-83172, mineral materials purchase contract, and the APD will be issued subject to regulations under 43 CFR 2800, 43 CFR 3600, 43 CFR 3100 and oil and gas onshore orders. The following mitigating stipulations that are either required by policy, law, or regulation or are needed to insure mitigation of associated surface disturbance activities. Part A applies to the ROW grant and the mineral materials purchase contract and Parts A and B apply to the APD.

A. Surface Use Conditions of Approval

- 1. The Holder shall secure all relevant Federal, state and local permits prior to beginning construction activities.
- 2. Issuance of ROW grant UTU-83172 to Wolverine Operating Company of Utah, LLC does not affect any rights to public highways that may have attached to the described access road segments identified as Sanpete County asserted roads, pursuant to RS-2477 (43 U.S.C. 932 repealed by the Federal Land Policy and Management Act of October 21, 1976).
- 3. Road construction, operation and maintenance will be in compliance with the terms and conditions of the subject grant, the American Association of State Highway and Transportation (AASHTO) safety standards, and will meet criteria for the Manual of Uniform Traffic Control Devices (MUTCD) manual for signs (regulatory, warning/caution, speed, delineators, and other roadway appurtenances, etc.).
- **4.** The Holder shall <u>clearly mark the exterior boundary of the ROW areas **prior to beginning** <u>construction</u> activities. The right-of-way width is variable (includes cut and fill and truck turn-out areas) as depicted sheets PP- 01 through PP-14 and Sheet 1B of the construction diagrams submitted with the ROW application (See Jones and DeMille Engineering, Inc. Drawings dated 03/29/2010, topographic map dated 03/30/2010, and revised Summary of Construction Sheet 1B dated 07/09/2010).</u>
- **5.** The Holder shall conduct all activities associated with the construction, operation, maintenance, and termination of the described access road within the authorized limits of the described ROW area, unless otherwise approved in writing by the Authorized Officer.
- **6.** No turn-a-round areas are authorized outside the ROW areas. Use of existing roads will be required during all phases of construction, operation, maintenance and termination activities. For segments located away from existing roads/trails, travel will be restricted to within the granted ROW areas, unless prior approved in writing by the Authorized Officer.
- 7. The proposed grant shall be issued subject to valid prior existing rights such as existing county-maintained roads and includes other authorized rights-of-way that may be located adjacent to or which may be affected by the construction, operation, maintenance and termination of this described right-of-way.
- **8.** Any existing facilities which may be damaged during operation, maintenance, or termination of this ROW shall be repaired or restored to the same condition as existed prior to the damage. Any costs for such damage or repair shall be the total responsibility of the Holder.
- **9.** Gravel material to be used for the subject road surface shall be obtained from the authorized mineral materials site in the project area.

- 10. The Holder shall implement erosion control and re-vegetation measures to insure that the lands disturbed by construction and maintenance activities will be restored to a stable, productive, and aesthetically acceptable condition.
- 11. Surface disturbances that are created on public land as a result of construction, maintenance, operation, and termination activities, outside of the travel width of the subject access road, shall be reshaped and re-contoured, to approximate natural contours and conditions, to the extent practicable; evenly redistributing stockpiled topsoil over the re-contoured areas, the cut and fill slopes, and all other disturbed areas and seeded. The seed mixture specified below will be utilized. There will be no primary or secondary noxious weeds in the seed mixture. The seed shall be certified weed-free seed. The authorized Officer is to be notified a minimum of 15 days prior to seeding of the project.

SEEDING RATE/ACRE **NAME** 1.0 lb Pure Live Seed Sandberg Bluegrass Luna Pubescent Wheatgrass 1.5 lb Pure Live Seed Bozoisky Russian Wildrye 1.5 lbs Pure Live Seed 1.5 lbs Pure Live Seed Magnar Great Basin Wildrye 1.5 lbs Pure Live Seed Covar Sheep Fescue Gooseberry Leaf Globemallow 0.5 lb Pure Live Seed Yellow Sweetclover 0.5 lb Pure Live Seed 1.5 lbs Pure Live Seed Delar Small Burnet 0.5 lb Pure Live Seed Richfield Firecracker Penstemon (P. eatonii) 0.5 lb Pure Live Seed Palmer Penstemon (P. palmeri) 2.0 lbs Pure Live Seed Appar Lewis Flax Common Sunflower 2.0 lbs Pure Live Seed 0.5 lb Pure Live Seed Wyoming Big Sagebrush Forage Kochia 1.0 lb Pure Live Seed 16.0 lbs Pure Live Seed Total

During Road construction topsoil (6 inches or maximum available) will be stockpiled in a berm along the edge of the road for use in road reclamation. All of the seed should be mixed together and either broadcast seeded or drill seeded. If the area is broadcast seeded then this should be done by using a four-wheeler equipped with a seeder. Seeding rate should be 16 pounds per acre. After broadcast seeding, then the area should be dragged with a small harrow (used with four wheeler), which will cover the seed.

If the area is drill seeded then a small tractor equipped with a farm drill should be used. Seeding rate should be 8 pounds per acre.

All of the seeding should be done in mid to late Fall (October/November) to prevent premature sprouting and subsequent winter killing of the forb species, due to late summer/early Fall precipitation combined with warm soil temperatures.

The Holder shall have three growing seasons following issuance of the grant to establish an acceptable stand of one perennial plant per square foot. Failing this, the authorized Officer may accept whatever level of reclamation is achieved if a good faith attempt at reclamation has been demonstrated by the Holder.

12. The Holder shall be responsible for weed control within the limits of the described ROW areas. The Holder shall also be responsible for consultation and coordination with the Authorized Officer for acceptable weed control methods (within limits imposed in the grant stipulations). Equipment used to

construct the subject access road shall be washed to remove invasive weed seeds prior to entering the project area.

- 13. Heavy equipment, used to construct and rehabilitate the access road, shall be cleaned and/or sprayed (power washed) to remove any noxious or invasive weeds and seeds, prior to being moved to the project site. Any other equipment and vehicles, that have been used at other locations, where noxious weeds or seeds could have attached to the equipment, must also be sprayed and/or cleaned.
- 14. To reduce the emission of fugitive dust, routine watering and/or application of magnesium chloride shall be applied to the access road, as needed.
- **15.** Drilling and construction activities are likely to occur during late summer or fall. Impacts to nesting bird species, therefore, are not anticipated. Big game species, however, will be protected by activity restriction between December 15th and May 15th.
- 16. The Holder shall be responsible for informing all persons associated with this project that they shall be subject to prosecution for knowingly disturbing historic or archaeological sites or for collecting artifacts. Any cultural and/or paleontological resource (historic or prehistoric site or object) discovered by the Holder, or any person working on their behalf, on federal land shall be immediately reported to the Authorized Officer. The Holder shall suspend all operations in the immediate area of such discovery until written authorization to proceed is issued by the authorized Officer. An evaluation of the discovery shall be made by the Authorized Officer to determine appropriate actions to prevent the loss of significant cultural or scientific values. The Holder shall be responsible for the cost of the evaluation and any decision as to proper mitigation measures will be made by the Authorized Officer after consulting with the Holder.
- 17. The ROW and mineral material site areas shall be kept free of trash, litter, discarded materials, and debris that are on site or generated as a result of the Holder's activities. The areas shall be maintained a sanitary condition during all construction, operation, maintenance and termination activities. Waste materials shall be removed and disposed of promptly at an appropriate waste disposal site. "Waste" means all discarded matter including, but not limited to, human waste, trash, garbage, refuse, pipe, oil, oil drums, grease, petroleum products, ashes, concrete, construction materials, and equipment. Debris/waste shall not be buried or burned without Holder obtaining prior written permission from the Authorized Officer.
- 18. The Holder shall locate, handle, and store gas, diesel fuel, oil, lubricants, and other petroleum products in such a manner as to prevent them from entering into and contaminating soils on the public land. Should petroleum spills occur within the described area as a result of construction, maintenance, and termination activities, the Holder shall be responsible for clean-up of any spills in accordance with Federal and State regulation and associated costs.
- 19. Fire suppression equipment must be available to suppress any wildfires caused by construction or related activities. In the event of a wildfire, the BLM Richfield Field Office (RFO) and the Richfield Interagency Fire Center (RIFC) shall be notified. The RFO phone number is (435) 896-1515 and the RIFC Dispatch phone number is (435) 896-8404. Suppression of any wildfires started as a result of construction, operation, maintenance and termination activities shall be the liability of the Holder.
- 20. If at any time hereafter, the Holder wishes to reconstruct, remodel, or relocate any portion of the ROW areas or change, modify, or add improvements or facilities thereon, the **prior** written approval of the Authorized Officer must be obtained.

- 21. Once construction has been completed of the above described long-term access road ROW and associated components, the temporary interim staging areas and turn outs will be re-contoured and the associated surface disturbances reclaimed, as prescribed by the BLM.
- 22. When the authorized use is no longer needed, and prior to abandonment of the facilities, the Holder or authorized representative shall meet with the Authorized Officer to arrange a joint inspection of the ROW. The inspection shall be held to agree on an acceptable abandonment and rehabilitation plan, which may include but not limited to removal of structures, recontouring and reseeding the areas. The Authorized Officer must approve the plan in writing **prior** to the Holder commencing any abandonment and/or rehabilitation activities.
- 23. The Contract for the Sale of Mineral Materials on public land will be subject to all pre-existing rights on the land covered by the contract, the Purchaser's mining and reclamation plans, the sale terms and stipulations, and the applicable federal and state regulations.
- 24. The existing access road to the gravel pit will be used; limited maintenance to its existing width and existing road bed material, and a slight modification as to the direction of entrance onto the pit access road to allow large truck access will be allowed.
- 25. The Purchaser, under the Contract for the Sale of Mineral Materials, will contact BLM at least 48 hours prior to the start of gravel removal operations from the mineral material site. Contact Kathleen Anders at (435)-896-1545.
- 26. During the life of the project, and until the mineral material site is released from liability for reclamation, the Purchaser will inspect the site at least annually for noxious weeds. If invasive noxious weeds are found, the Purchaser will treat the weeds to eliminate further reproduction, and treatment will continue until the weeds have been eradicated. If noxious weeds are found, the BLM will be notified by the Purchaser of their presence.
- 27. If the access road to the mineral material site becomes rutted, widened or otherwise deteriorates through use related to the mineral material extraction, or if the access road does not have a post-mining use, the road will be reclaimed. Reclamation will include re-contouring the tracks, pulling in any berm, ripping the surface, and seeding.
- 28. The Authorized Officer will be contacted at least 48 hours prior to commencing any reclamation work at the mineral material site. Final reclamation, including re-vegetation of the site, will be deemed complete and satisfactory when approved by the Authorized Officer.
- 29. The Purchaser, under the Contract for the Sale of Mineral Materials, will submit an annual production report to the BLM Richfield Field Office on or before January 31 of each year for production during the previous year. The first annual report will be due on or before January 31, 2011, for production during 2010, and subsequent reports will be due by that date of each year.
- 30. The Authorized Officer or his delegated representative will be allowed, at any time, to examine the records of the Purchaser, under the Contract for the Sale of Mineral Materials, to determine the quantity of mineral material removed and to inspect the material site for compliance with federal regulations and provisions of the contract.
- 31. The terms and conditions of the Contract for the Sale of Mineral Materials will apply to the Purchaser and any employees, independent contractors and/or subcontractors of the Purchaser. The Purchaser will be required to diligently supervise any employee, independent contractor, and/or subcontractor who

operate at the subject material site. Any violation of the terms and conditions of the Contract for the Sale of Mineral Materials by the Purchaser, employees, or contractor will subject the Purchaser to penalties.

- 32. All permanent structures, including pumping units, constructed or installed will be painted a flat, non-reflective color, as described on page 40 of the Gold Book (Surface Operating Standards and Guidelines for Oil and Gas Exploration and Development, 4th Edition 2006). Prior to painting permanent structures, the operator will submit a Sundry Notice for approval of a color proposed by the applicant. Permanent structures are defined as being on location for six months or longer. Facilities that must conform to a color standard required Occupational Safety and Health Act (OSHA) may not conform to the Gold Book standards.
- **33.** Applicant committed measures outlined in the Surface Use Plan of Operations submitted with the Application for Permit to Drill are considered part of the Conditions of Approval.
- 34. A certified blaster shall be on site and perform the operations on an as-need basis. All applicable regulations including those of the Bureau of Alcohol, Tobacco and Fireams shall be followed for the use of explosive materials. No explosives shall be stored on site.
- 35. All safety measures shall be compliant with OSHA requirements.

Access Road ROW Monitoring Requirements:

Monitoring will be conducted in accordance with 43 CFR 2805.10(3), which states "Each grant that BLM issues for 20 or more years will contain a provision requiring periodic review at the end of the twentieth year and subsequently at 10-year intervals. BLM may change the terms and conditions of the grant as a result of these reviews in accordance with 43 CFR 2805.15(e) of this subpart". The operation and maintenance of the ROW area will be inspected and monitored to assure compliance with the grant terms and conditions for the protection of the resources, the environment and the public health, safety and welfare. If needed, the Applicant will take corrective action as required by the Authorized Officer.

B. Well Downhole Condition of Approval

I. Please Note:

All lease and/or unit operations will be conducted in such a manner that full compliance is made with applicable laws, regulations (43 CFR parts 3100 and 3160), lease terms, Onshore Oil and Gas Orders, Notice to Lessee's, and this approved plan of operation.

A copy of the approved application and these conditions shall be maintained on location during all construction and drilling operations. Deviation from the approved plan without prior approval is not allowed.

The operator is fully responsible for the actions of his subcontractors.

Operators have the responsibility to assure that activities authorized by this permit are conducted in a manner that complies with other applicable Federal, State, and local laws and regulations.

Approval of this application does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which will entitle the applicant to conduct operations thereon.

This Application for Permit to Drill (APD) shall be valid for two years from the date of approval, provided the lease does not expire. If activities have not commenced by the end of the two-year period, the APD shall be returned to the operator without prejudice. Should the operator still desire to drill the well, a new APD must be submitted to this office. Upon written request by the operator, a one-time **two year** extension to this time period may be granted by the Authorized Officer (AO).

Failure to comply with the provisions of this permit (including applicable regulations, stipulations, and/or approval conditions) will be considered a violation subject to the enforcement provisions of 43 CFR Subpart 3163.

If fill materials are needed to maintain roads or well sites, proper permits must be obtained from the appropriate surface owner. On BLM administered lands, the use of materials shall conform with 43 CFR §3610.2-3.

II. Required Notifications:

The operator and contractor shall contact the BLM Richfield Field Office at least 48 hours prior to commencement of access and site construction or reclamation activities. (Contact: Stan Andersen - (435) 896-1532).

The operator shall contact the BLM Price Field Office at least 24 hours prior to the following operations (Contact: Marvin Hendricks - (435) 636-3661, FAX (435) 636-3657):

- spudding (including dry hole digger or rig hole rigs);
- running and cementing all casing strings;
- pressure testing of BOPE or any casing string.
- pressure integrity test (mud weight equivalency test) of each casing shoe.

In the case of newly drilled dry holes, and in any emergency situation, after hours notification and authorization may be obtained by contacting the following individuals, in the order listed:

Marvin Hendricks (435) 650-9136 (Cell) Petroleum Engineer (435) 637-1850 (Home) BLM Price Field Office (435) 636-3661 (Office) marvin hendricks@blm.gov

Al McKee (801) 828-7498 (Cell)
Petroleum Engineer (801) 572-6911 (Home)

BLM Utah State Office

Walton Willis (435) 650-9140 (Cell) Petroleum Eng. Technician (435) 636-3662 (Office)

BLM Price Field Office walton_willis@blm.gov

Fire Activities: BLM Richfield Field Office Cornell Christensen 435 896-1500 and Richfield Interagency Fire Center (RIFC) 435 896-8404.

III. Conditions of Approval: Note - New or revised COAs are in bold print.

- **A. Drilling Plan -** The drilling plan of the Application for Permit to Drill will be supplemented as follows:
 - 1. Onshore Order No. 2, *Drilling Operations*, requires that all formations containing usable quality water (less than 10,000 ppm) be protected via cement. If encountered while drilling, usable quality water will require protection by bring the cement at least ± 100 ' above the usable quality water zone.
 - 2. During drilling operations, drilling reports (and mud reports) shall be emailed daily to the Price Field Office petroleum engineer and petroleum engineering technician. Within 30 days of finishing drilling and completion operations, a chronological daily operations history shall be submitted to this office.
 - 3. The authorized officer shall be notified when operations are 500 feet above or 3 days before (whichever is earlier) drilling the first formation (Twin Creek) that may contain H₂S.
 - 4. If there is a possibility that H₂S gas may be present, the drilling rig shall be equipped with H₂S detection and monitoring equipment that activates visible and audible alarms when concentrations of 10 and 15 ppm, respectively, are exceeded.
 - 5. A copy of the Drilling Operations Plan (DOP) shall be available during operations at the wellsite beginning 500 feet above or 3 days before (whichever is earlier) drilling the first formation (Twin Creek) that may contain H₂S.
 - 6. A copy of the Public Protection Plan (PPP) shall be available onsite at all times during drilling and completion operations.
 - 7. The H₂S DOP and PPP shall be reviewed by the operator on an annual basis and a copy of any necessary revisions shall be submitted to the authorized officer upon request. The DOP and/or PPP will also be reviewed during any operator changes. The BLM will be notified when this review has been completed.
 - 8. If unanticipated H₂S in excess of 100 ppm in the gas stream is encountered, the operator shall immediately ensure control of the well, suspend drilling operations (unless detrimental to well control), and obtain materials and safety equipment to bring the operations into compliance with the applicable provisions of Onshore Order No. 6, *Hydrogen Sulfide Operations*. In addition, the operator shall notify the authorized officer of the event and the mitigating steps that have or are being taken, as soon as possible, but no later than the next business day. If said notifications are subsequent to actual resumption of drilling operations, the operator shall notify the authorized officer of the date that drilling was actually resumed.

Should H₂S in excess of 100 ppm in the gas stream be encountered, the following requirements (9 -17) from Onshore Order No. 6 shall apply:

- 9. Equipment to indicate wind direction shall be installed at prominent locations and be visible at all times during drilling operations (OO#6.III.C.3.d.i).
- 10. Operational danger or caution sign(s) shall be displayed along all controlled access to the site. The sign shall be painted a high visibility red, black and white or yellow with black lettering. The sign shall be placed a minimum of 200 feet but no more than 500 feet from the location and at a location which allows vehicles to turn around (OO#6.III.C.3.d.ii, iii, iv & v).
- 11. As an alternative road is not practical to build, a clearly marked footpath flagged to a safe area is acceptable (OO#6.III.C.2.a).
- 12. Metallurgical properties of all tubular goods and well control equipment shall conform to NACE STD #MR-0175-90 or equivalent (OO#6.III.C.4.c).
- 13. A rotating head and mud gas separator shall be utilized while drilling all formations of concern (OO#6.III.C.4.a.ix).
- 14. A mud degasser shall be in place and operable during the drilling of all formations of concern (OO#6.III.C.4.b.ii).
- 15. A remote controlled-choke shall be utilized while drilling all formations of concern. (OO#6.III.C.4.a.viii)
- A flare system shall be designed and installed to safely gather and burn H2S bearing gas, and be located not less than 150 feet from the wellbore. The system shall be equipped with a suitable and safe ignition source. In situations involving non-combustible gas, a supplemental fuel source shall be used to maintain ignition. (OO#6.III.C.4.a.ii, iii, iv & v).
- 17. If production is established, a description of the H₂S detection system utilized at the production facilities will be provided to determine the concentration of any H₂S released (OO#6.III.B.2.h).
- 18. All required notifications, including any requests for approval or hydrogen sulfide issues, shall be made to: Marvin Hendricks at (435) 636-3661 (office); or (435) 650-9136 (cell). Please leave as detailed as message as necessary.
- 19. One digital copy of all logs (in PDF or TIFF format), and one hard copy of core descriptions, core analyses, drill stem tests, well-test data, geologic summaries, sample descriptions, and all other surveys or data obtained and compiled during the drilling and/or completion operations shall be submitted to the BLM, Price Field Office, 125 South 600 West, Price, Utah, 84501.
- 20. Operations authorized by this permit shall not be suspended for more than 30 days without prior approval of the Authorized Officer (AO). All conditions of approval shall be applicable during any operations conducted with a replacement/completion rig.

- 21. Gas produced from this well may not be vented or flared beyond an initial authorized test period of 30 days or 50 MMCF following its completion, whichever comes first, without the prior written approval of the authorized officer. Should gas be vented or flared without approval beyond the authorized test period, the operator may be directed to shut-in the well until the gas can be captured or approval to continue venting or flaring as uneconomic is granted and the operator shall be required to compensate the lessor for the portion of the gas vented or flared without approval which is determined to have been avoidably lost. In order to continue venting or flaring beyond the 30 day period, the operator shall be required to demonstrate that either the volume or physical properties of the gas make it uneconomical to recover and must receive authorization to continue venting or flaring from the authorized officer.
- 22. Section 102 (b) (3) of the Federal Oil and Gas Royalty Management Act of 1982, as implemented by the applicable provisions of the operating regulations at Title 43 CFR 3162.4-1 (c), requires that "not later than the 5th business day after any well begins production on which royalty is due anywhere on a lease site or allocated to a lease site, or resumes production in the case of a well which has been off production for more than 90 days, the operator shall notify the authorized officer by letter or sundry notice, Form 3160-5, or orally to be followed by a letter or sundry notice, of the date on which such production has begun or resumed."

The date on which production is begun or resumed will be construed for oil wells as the date on which liquid hydrocarbons are first sold or shipped from a temporary storage facility, such as a test tank, and for which a run ticket is required to be generated or, the date on which liquid hydrocarbons are first produced into a permanent storage facility, whichever occurs first; and, for gas wells as the date on which associated liquid hydrocarbons are first sold or shipped from a temporary storage facility, such as a test tank, and for which a run ticket is required to be generated or, the date on which gas is first measured through permanent metering facilities, whichever occurs first.

Should Wolverine fail to comply with the above requirement in the manner and time allowed, you shall be liable for a civil penalty of up to \$10,000 per violation for each day such violation continues, not to exceed a maximum of 20 days. See Section 109 (c) (3) of the Federal Oil and Gas Royalty Management Act of 1982 and the implementing regulations at Title 43 CFR 3162.4-1 (c) and 3163.2 (e) (2).

SURFACE USE PLAN OF OPERATIONS

For inclusion with Application for Permit to Drill

Name of Operator:

Wolverine Operating Company of Utah, LLC

Address:

1140 N. Centennial Park Drive

Richfield, Utah 84701

Rough Canyon Federal 30-1

Surface Well Location:

288' FNL & 452' FWL, (being in NW4/NW4)

Section 32, T17S, R1E, SLB&M

Sanpete County, Utah

Bottom Hole Location:

1830' FSL & 810' FEL, (being in NE4/SE4)

Section 30, T17S, R1E, SLB&M

Sanpete County, Utah

Access Road Location:

Existing two-track road leads from Highway SR 28 Easterly across the S2SE Section 1-T18S-R1W and across the W2W2 Section 6-T18S-R1E to the mouth of Rough Canyon in the SWSW Section 31-T17S-R1E. A new road is proposed to be built Northeasterly through Rough Canyon to the East line of Section 31. A Title V right-of-way application is being submitted to the Richfield BLM office covering both above existing road and new road. The portion of the lease road continuing into Section 32 will be constructed under terms of an Easement from State of Utah School and Institutional Trust Lands Administration (SITLA) and the well pad will be constructed under terms of a Special Use Lease from same.

Fee surface use is not required for construction and drilling of the referenced well and access road. State surface use is required for construction of the well pad and that portion of the access road that is situated in Section 32-T17S-R1E. Federal surface use for access is being requested with the associated Title V Right-of-Way application through the BLM – Richfield Field Office.

The dirt contractor will be provided with an approved copy of the surface use plan of operations and conditions of approval before initiating construction.

Existing Roads:

The vicinity map in the APD drawing packet shows the proposed well location east of Highway SR28 in the Sanpitch Mountain range. The closest town is Fayette, Utah (well location being 5 miles North-northeast of

<u>Driving directions</u>: From Gunnison, Utah, travel north on SR 28, under Utah Department of Transportation (UDOT) maintenance approximately 8.5 miles to a driveway on the East side connecting the highway to a two-track road. Proceed through the gate Easterly, thence Northerly a distance of about 1.42 miles on said two-track to its terminus near the mouth of Rough Canyon. Continue Northeasterly up the narrow canyon on a to-be-constructed new road a distance of about 1.38 miles to the Section 31 east line and SITLA boundary. Continue into Section 32 on SITLA land a distance of 700+ feet to the Rough Canyon Federal 30-1 well pad.

Access Roads to be Constructed and Reconstructed:

The surface condition of the existing two-track road is not adequate to bear rig-related traffic and will require improvement. The width of the traveled way will be increased from about 8 feet+/- to 12 feet, and 8 foot wide vehicle turnouts will be constructed at strategic points to allow trucks to pass. See drawing sheets TS-01 (Type 2 Typical Section) and TS-02 in the Right-of-Way application for detail on existing road improvements. Details on

areas of construction are shown on sheets PP-01 through PP-04 of the Right-of-Way application.

From the mouth of Rough Canyon to the BLM-SITLA land boundary, a new road will need to be constructed, following the meander of the bottom of the wash, a distance of 7,295.32 linear feet (1.38 miles). Due to the tight turns and confinement of the canyon walls the traveled way of this road will need to be a minimum of 14 feet; with extra width of up to 40.2 feet on curves. The roadbed will be fortified with untreated base course and granular borrow taken from the existing community gravel pit referenced below under *Construction Materials*. See drawing sheets TS-01 (Type 1 Typical Section) and TS-02 for detail on new road construction. Details on areas of construction are shown on sheets PP-04 through PP-14 of the Right-of-Way application. Best management practices will be used in all stages of design and construction.

The continuation of the new road into Section 32 (SITLA land) to the well pad will be constructed under authority of an easement from SITLA. Details of construction for that portion of the lease road are included in the APD packet submitted herewith. The well pad will be constructed under authority of a Special Use Lease from SITLA (Application #1680) and details of pad layout and construction design are also included in the APD packet.

Total length of the improved portion of the road across BLM land is 1.42 miles. Total length of new constructed access road is 1.52 miles (being 1.38 miles across BLM land and .14 mile across SITLA land).

Road construction, operation and maintenance will be in compliance with the terms and conditions of the BLM and SITLA Conditions of Approval, the American Association of State Highway and Transportation (AASHTO) safety standards, and will meet criteria for the Manual of Uniform Traffic Control Devices (MUTCD) manual for signs.

Energy dissipating structures and silt fences will be utilized to minimize erosion that may result from the road construction.

The Operator intends to install a cattle guard in addition to the gate near where the existing two-track road enters the highway. The cattle guard will be installed in the existing fence opening and the gate will be reinstalled to the side.

All existing roads and the new road will be maintained and kept in good repair during all phases of operation. Vehicle operators will obey posted speed restrictions and observe safe speeds commensurate with road and weather conditions.

Equipment to be used in construction will consist of conventional heavy equipment, including bulldozers, scrapers, excavators, backhoes, compactors and water trucks. In the event rock blasting is necessary in excavation a certified blaster will be called in to perform the operation on an as-needed basis. All applicable regulations, including those of the Bureau of Alcohol, Tobacco and Firearms, will be followed for the use of explosive materials. No explosives will be stored on site. Boulders that are exposed by excavation, that cannot be broken up and used as aggregate, will be buried in the right-of-way, unless otherwise requested by the Authorized Officer.

Location of Existing Wells within a one-mile radius:

There are no wells (oil, gas, water, injection or disposal, producing or being drilled) within a one-mile radius of the proposed location.

Location of Existing and/or Proposed Facilities if Well is Productive:

(a) On well pad—A temporary testing facility may be constructed on this location in the event drilling is successful, consisting of treater/separator, tanks and related components. The facility would be surrounded by a dike of sufficient capacity to contain the storage capacity of the largest tank. All loading lines and valves would be located inside the berm surrounding the tank battery.

(b) Off well pad – It is not possible to know whether an off-well pad production facility would be necessary in the event of a discovery. In the event such a facility is needed a site closer to Highway SR 28 would potentially be used for collection, treating and load-out. The Operator will submit this information for approval at such time as production requirements are known.

Location and Type of Water Supply (Rivers, Creeks, Lakes, Ponds and Wells):

The Operator intends to lease water rights from a private water right owner: water right number 63-3169. This will be done by temporary change order through the Utah Division of Water Rights office in Richfield, Utah. Water will be drafted from the Sevier River at a load-out point tentatively located in the NE4 of Section 2-18S-1W, subject to

change, depending on the level of the reservoir at the time of need. Should additional water sources be pursued they will be properly permitted through the State of Utah – Division of Water Rights. The BLM will be notified of any changes in water supply.

Construction Materials:

Natural earth materials used for fill on the well pad will be taken from cuts made in construction of the pad. Imported granular borrow from an approved source will be applied to the surface of the well pad and access road where deemed necessary. The roadbed will be fortified with granular borrow taken from an existing community gravel pit that is located nearby. An application for mineral materials sale for that purpose is being submitted concurrently with this APD. If additional materials are needed they will be taken from an approved source.

Methods for Handling Waste Disposal:

The reserve pit will be used for the disposal of waste mud and drill cuttings. All borehole fluids and salts will be contained in the reserve pit. It will be located in cut material and will be lined with 12 mil minimum thickness plastic nylon reinforced liner material. The liner will overlay a felt liner pad only if sharp rock edges result from excavation. The pit liner will overlap the top of the pit walls and be covered with dirt and/or rocks to hold it in place. No trash, scrap pipe, etc. that could puncture the liner will be disposed of in the pit. Pit walls will be sloped no greater than 2:1. A minimum 2-foot freeboard will be maintained in the pit at all times during the drilling and completion operations. After evaporation of fluids, back-fill of sub-soil and compaction to prevent settling will occur within 90 days of cessation of pit use. If necessary, any remaining fluids will be pumped out of the pit and transported off site.

No chemicals subject to reporting under SARA Title III (hazardous materials) in an amount greater than 10,000 pounds will be used, produced, stored, transported, or disposed of in association with the drilling, testing, or completion of the well. Furthermore, no extremely hazardous substances, as defined in 40 CFR 355, in threshold planning quantities, will be used, produced, stored, transported, or disposed of in association with the drilling, testing, or completion of the well.

Wastewater will not be discharged on the surface at this site and the drilling of the well will not require a wastewater management plan.

All rubbish and debris will be kept in containers on the well site, and will be hauled to an approved disposal site upon completion of drilling operations and as needed during such operations. There will be no chemical disposal of any type.

Self-contained, portable toilets will be used for human waste, and the waste will be disposed at an approved human waste disposal facility. Sanitation will comply with local and state regulations.

Ancillary Facilities:

No ancillary facilities are anticipated at this time.

Well Site Layout:

Pad Location and Layout Drawings in the APD drawing packet show the proposed well site layout including location of the reserve pit and access road onto the pad, turnaround areas, parking areas, living facilities, soil material stockpiles, and the orientation of the rig with respect to the pad and other facilities. Cross section sheets in said packet show cuts and fills required for construction, and their relationship to topography. As detailed above under Methods for Handling Waste Disposal, the reserve pit will be lined and appropriate measures as described above will be taken to prevent leakage. The pit will be fenced on three sides during drilling operations and then the fourth side will be immediately fenced when the rig is moved off location.

The pad and road designs will be consistent with SITLA, UDOGM and BLM requirements.

A pre-construction meeting with responsible company representative and contractors will be conducted at the project site prior to commencement of surface-disturbing activities. The pad and road will be construction-staked (centerline and exterior boundaries) prior to this meeting.

All surface disturbing activities will be supervised by a qualified, responsible company representative who is aware of the terms and conditions of approval from the BLM under the Title V Right-of-Way, and APD, and terms and

conditions of approval from SITLA under the Easement and Special Use Lease.

All cut and fill slopes will be such that stability can be maintained for the life of the activity.

The stockpiled topsoil (first 6 inches or maximum available) will be isolated in a berm by the well pad. Topsoil will be stockpiled for reclamation in such a way as to prevent soil loss and contamination.

Water spraying may be implemented if necessary to minimize dust.

Plans for Reclamation of the Surface:

Interim Reclamation: In the event production is achieved the Operator will perform interim reclamation of the site. Interim reclamation will consist of reclamation of the reserve pit and reclamation of that portion of the well pad not needed for ongoing operations. After evaporation of fluids, the pit will be back-filled with sub-soil and/or rock and compacted to prevent settling. The pit area will be surfaced with granular borrow to render it a usable part of the well pad. All portions of the pad no longer necessary for well workover, testing or treating will be contoured to match the surrounding terrain to the best extent practicable. Stockpiled topsoil will be evenly distributed thereon, scarified and seeded as per Conditions of Approval.

<u>Final Reclamation</u>: In the event the well is a dry hole, or at such time that all production ceases and the well has been plugged and abandoned, the Operator will perform final reclamation of the site. Final reclamation will consist of reclamation of the reserve pit, the well pad and the access road as it crosses SITLA and BLM land. In the event the right-of-way across BLM land is assignable to SITLA, and such assignment is approved, reclamation of the BLM right-of-way may be partial, according to terms and conditions of said right-of-way. The Operator will comply with all Conditions of Approval for reclamation of the right-of-way.

Any accumulation of hydrocarbons in the reserve pit will be removed and recovered for sale unless it is determined by the authorized officer to be waste oil. All waste oil will be disposed of properly at approved facilities. The portion of the reserve pit liner that is exposed above the cuttings will be cut and removed from the site and disposed in an authorized landfill. After evaporation of fluids, the pit will be back-filled with subsoil and/or rock from the reserve pit stockpile and compacted to prevent settling.

Unless otherwise directed, road base material used in the construction of the access road and pad will be removed from the site and disposed in a proper manner. If the reserve pit has adequate capacity, then some or all of the road base material may be buried in the reserve pit, provided that the granular is not contaminated by oil or other waste materials. The access road will be contoured using an excavator or similar equipment, rather than simply ripping the surface.

Subsoil from the portions of the well pad that are fill will be pulled up onto the pad in order to reestablish the original slope to the best extent possible. The portions that are cut will be filled to match the original slope of the land to the best extent possible. Topsoil from the stockpile will then be evenly distributed over the entire impacted area. The entire impacted area will be scarified and seeded in late fall, using the seed mix and methods described in BLM and SITLA conditions of approval. Final reclamation will take place within 180 days after plugging date of the last well on site, depending on weather, season and other extenuating circumstances.

During the life of the project and until the site is released from liability for reclamation, the project will be inspected at least annually for noxious weeds. If invasive noxious weeds are found, the weeds will be treated to eliminate further reproduction, and treatment shall continue until the weeds have been eradicated. If noxious weeds are found, BLM and SITLA will be notified of their occurrence.

See Additional Detail on Plans for Reclamation of the Surface on Addendum to Surface Use Plan of Operations, attached hereto.

Surface Ownership:

The surface of the proposed well site and the Section 32 portion (.14 mile) of the access road is State owned and is administered by the State of Utah School and Institutional Trust Lands Administration (SITLA). The access road across Section 31-T17S-R1E, Section 6-T18S-R1E and Section 1-T18S-R1W is federally owned and is administered by the Bureau of Land Management, United States Department of Interior.

Other Information:

The topsoil (6 inches, or maximum amount present) will be stripped and removed from the well pad and stockpiled for future reclamation of the site. This topsoil shall be stockpiled separately from any other excavated materials. It will be reserved for reclamation and not utilized for any other purpose. If it is to be stockpiled for more than one year it will be seeded in the fall with a seed mix approved by the authorized officer.

Heavy equipment used to construct and rehabilitate the well pad and access road will be cleaned and/or sprayed to remove any noxious or invasive weeds and seeds, prior to entering to the project site. Any other equipment and vehicles that have been used in other locations where noxious weeds or seeds could have attached to the equipment will also be sprayed and/or cleaned.

Due to the narrow canyon, adequate truck turnouts are not possible on the new-built portion of the road. While smaller vehicles would be able to pass on the traveled surface, larger trucks would not. Flagmen with radio communication will be stationed at the upper and lower ends of Rough Canyon at all times when rig traffic is present, to prevent opposing traffic from meeting in this confined area.

In the event of a flash flood, traffic on the new road in Rough Canyon would be shut down until the flow of water ceased and the road surface could be returned to a passable condition.

All equipment and vehicles will be confined to the access road and well pad.

Western Land Services will conduct a Class III archeological survey and will submit same under separate cover to the appropriate agencies.

Western Land Services will conduct a T&E survey and prepare an EA for the proposed well site. The T&E report and EA will be submitted under separate cover to the appropriate agencies.

No stream alteration or drainage crossings are involved that require additional State or Federal approval.

All permanent structures, including pumping units, constructed or installed will be painted a flat, non-reflective color as described on page 40 of the Gold Book (Surface Operating Standards and Guidelines for Oil and Gas Exploration and Development, 4th Edition 2006). Permanent structures are defined as being on location for six months or longer. Facilities required to comply with Occupational Safety and Health Act (OSHA) shall be excluded.

Fire suppression equipment will be available to suppress any wildfires caused by construction or related activities. In the event of a wildfire the Sanpete County Fire Warden will be notified, (435) 835-2117.

Operator Certification

I hereby certify that I, or someone under my direct supervision, have inspected the drill site and access route proposed herein; that I am familiar with the conditions which currently exist; that I, or someone under my direct supervision, have full knowledge of state and Federal laws applicable to this operation; that the statements made in this APD package are, to the best of my knowledge, true and correct; and that the work associated with the operations proposed herein will be performed in conformity with this APD package and the terms and conditions under which it is approved. I also certify that I, or the company I represent, am responsible for the operations conducted under this application. These statements are subject to the provisions of 18 U.S.C. 1001 for the filing of false statements.

Executed this 14th day of April, 2010.

Signature:

Paul Spiering

Position Title:

District Land Martager

Address:

Wolverine Operating Company of Utah, LLC

1140 N. Centennial Park Drive

Richfield, Utah 84701

Telephone:

435-896-1943

Field representative (if not above signatory)

Charlie Irons, Senior Landman

Address:

1140 N Centennial Park Drive

Richfield, Utah 84701

Telephone:

435-896-1943

Agents not directly employed by the operator must submit a letter from the operator authorizing that agent to act or file this application on their behalf.

Wolverine Operating Company of Utah, LLC Rough Canyon Federal 30-1 Addendum to Surface Use Plan of Operations

Additional Detail on: Plans for Reclamation of the Surface

I. Reclamation Objectives:

The objective of <u>interim reclamation</u> is to restore vegetative cover and a portion of the landform sufficient to maintain healthy, biologically active topsoil; control erosion; and minimize habitat, visual, and forage loss during the life of the well or facilities, to the best extent practicable.

The long-term objective of <u>final reclamation</u> is to return the land to a condition approximating that which existed prior to disturbance, to the best extent practicable. This includes restoration of the landform and natural vegetative community, hydrologic systems, visual resources, and wildlife habitats. To ensure that the long-term objective will be reached through human and natural processes, actions will be taken to ensure standards are met for site stability, visual quality, hydrological functioning, and vegetative productivity.

II. Reclamation Performance Standards

The following reclamation performance standards will be met:

<u>Interim Reclamation</u> – Includes disturbed areas that may be redisturbed during operations and will be redisturbed at final reclamation to achieve restoration of the original landform and a natural vegetative community.

Will be judged successful when the BLM authorized officer determines that...

• Disturbed areas not needed for active, long-term production operations or vehicle travel have been recontoured, protected from erosion, and revegetated with a self-sustaining, native (or as otherwise approved) plant community sufficient to minimize visual impacts, provide forage, stabilize soils, and impede the invasion of noxious, invasive, and non-native weeds.

<u>Final Reclamation</u> – Includes disturbed areas where the original landform and a natural vegetative community have been restored.

Will be judged successful when the BLM authorized officer determines that...

- The original landform has been restored to the best extent practicable for all disturbed areas including well pads, production facilities, roads, pipelines, and utility corridors.
- General: A self-sustaining, native (or otherwise approved) plant community is established on the site, with a density sufficient to control erosion and invasion by non-native plants and to reestablish wildlife habitat or forage production. At a minimum, the established plant community will consist of species included in the seed mix and/or desirable species occurring in the surrounding natural vegetation.
- Specific: No single species will account for more than [30]% total vegetative composition unless it is evident at higher levels in the adjacent landscape. Permanent vegetative cover will be determined successful when the basal cover of desirable perennial species is at least [80]% of the basal cover on adjacent or nearby undisturbed areas where vegetation is in a healthy condition; or [80]% of the potential basal cover as defined in the National Resource Conservation Service Ecological Site(s) for the area. Plants must be resilient as evidenced by well-developed root systems and flowers. [Shrubs, will be well established and in a "young" age class at a minimum (therefore, not comprised mainly of seedlings that may not survive until the following year).]
- In agricultural areas, irrigation systems and soil conditions are reestablished in such a way as to ensure successful cultivation and harvesting of crops.

• Erosion features are equal to or less than surrounding area and erosion control is sufficient so that water naturally infiltrates into the soil and gullying, headcutting, slumping, and deep or excessive rills (greater than 3 inches) are not observed.

The site is free of State- or county-listed noxious weeds, oil field debris and equipment, and contaminated soil. Invasive and non-native weeds are controlled.

III. Reclamation Actions

During initial well pad, production facility, road, pipeline, and utility corridor construction and prior to completion of the final well on the well pad, pre-interim reclamation stormwater management actions will be taken to ensure disturbed areas are quickly stabilized to control surface water flow and to protect both the disturbed and adjacent areas from erosion and siltation. This may involve construction and maintenance of temporary silt ponds, silt fences, berms, ditches, and mulching.

When the last well on the pad has been completed, some portions of the well location will undergo interim reclamation and some portions of the well pad will usually undergo final reclamation. Most well locations will have limited areas of bare ground, such as a small area around production facilities or the surface of a rocked road. Other areas will have interim reclamation where workover rigs and fracturing tanks may need a level area to set up in the future. Some areas will undergo final reclamation where portions of the well pad will no longer be needed for production operations and can be recontoured to restore the original landform.

The following minimum reclamation actions will be taken to ensure that the reclamation objectives and standards are met. It may be necessary to take additional reclamation actions beyond the minimum in order to achieve the Reclamation Standards.

Reclamation - General

Procedure:

The BLM will be notified 24 hours prior to commencement of any reclamation operations.

Housekeeping:

- Immediately upon well completion, the well location and surrounding areas(s) will be cleared of, and maintained free of, all debris, materials, trash, and equipment not required for production.
- No hazardous substances, trash, or litter will be buried or placed in pits. Upon well completion, any hydrocarbons in the pit will be remediated or removed.

Vegetation Clearing:

- Vegetation removal and the degree of surface disturbance will be minimized wherever possible.
- During vegetation clearing activities, trees and woody vegetation removed from the well pad and access road will be moved aside prior to any soil disturbing activities. Care will be taken to avoid mixing soil with the trees and woody vegetation. Trees left for wood gathering will be cut [twelve inches or less from the ground], delimbed, and the trunks, six (6) inches or more in diameter will be removed and placed either by the uphill side of the access road, or moved to the end of the road, or to a road junction for easy access for wood gatherers and to reduce vehicle traffic on the well pad. Trees with a trunk diameter less than six (6) inches and woody vegetation will be used to trap sediment, slow runoff, or scattered on reclaimed areas to stabilize slopes, control erosion, and improve visual resources.]

Topsoil Management:

- Operations will disturb the minimum amount of surface area necessary to conduct safe and efficient operations. When possible, equipment will be stored and operated on top of vegetated ground to minimize surface disturbance.
- Where possible, in areas to be heavily disturbed, the top [eight (8)] inches of soil material, will be stripped
 and stockpiled around the perimeter of the well location and along the perimeter of the access road to
 control run-on and run-off, and to make redistribution of topsoil more efficient during interim reclamation.

- Stockpiled topsoil may include vegetative material. Topsoil will be clearly segregated and stored separately from subsoils.
- Earthwork for interim and final reclamation will be completed within 6 months of well completion or plugging unless a delay is approved in writing by the BLM authorized officer.
- Salvaging and spreading topsoil will not be performed when the ground or topsoil is frozen or too wet to adequately support construction equipment. If such equipment creates ruts in excess of four (4) inches deep, the soil will be deemed too wet.
- No major depressions will be left that would trap water and cause ponding unless the purpose is to trap runoff and sediment.

Seeding:

- <u>Seedbed Preparation</u>. Initial seedbed preparation will consist of recontouring to the appropriate interim or final reclamation standard. All compacted areas to be seeded will be ripped to a minimum depth of 18 inches, where practicable, with a minimum furrow spacing of 2 feet, followed by recontouring the surface and then evenly spreading the stockpiled topsoil. Prior to seeding, the seedbed will be scarified and left with a rough surface.
- If broadcast seeding is to be used and is delayed, final seedbed preparation will consist of contour cultivating to a depth of 4 to 6 inches within 24 hours prior to seeding, dozer tracking, or other imprinting in order to loosen up the soil and create seed germination micro-sites.
- <u>Seed Application</u>. Seeding will be conducted no more than 24 hours following completion of final seedbed preparation. A certified weed-free seed mix designed by BLM to meet reclamation standards will be used.
- The application rate is based on 45 pure live seeds (PLS) per square foot, drill-seeded to a depth of 0.25 to 0.5 inch, which is the method that will be used where feasible. [However, shrub species will be seeded during the winter on the ground surface or preferably on top of snow.] In areas that will not be drill-seeded, the seed mix will be broadcast-seeded at twice the application rate described and covered no more than 0.25 inch deep with a harrow, drag bar, or roller or will be broadcast-seeded into imprints, such as fresh dozer cleat marks.
- No seeding will occur from May 15 to September 15. Fall seeding is preferred and will be conducted after September 15 and prior to ground freezing. Shrub species will be seeded separately and will be seeded during the winter. Spring seeding will be conducted after the frost leaves the ground and no later than May 15.

Erosion Control and Mulching:

- Mulch, silt fencing, waddles, hay bales, and other erosion control devices will be used on areas at risk of soil movement from wind and water erosion.
- Mulch will be used if necessary to control erosion, create vegetation micro-sites, and retain soil moisture and may include hay, small-grain straw, wood fiber, live mulch, cotton, jute, or synthetic netting. Mulch will be free from mold, fungi, and certified free of noxious or invasive weed seeds.
- If straw mulch is used, it will contain fibers long enough to facilitate crimping and provide the greatest cover.

Pit Closure:

- Reserve pits will be closed and backfilled within six months of release of the rig, weather permitting. Immediately upon well completion, any hydrocarbons or trash in the pit will be removed. Pits will be allowed to dry, be pumped dry, or solidified in-situ prior to backfilling.
- Following completion activities, pit liners will be removed down to the solids level and disposed of at an approved landfill, or treated to prevent their reemergence to the surface and interference with long-term successful revegetation. If it was necessary to line the pit with a synthetic liner, the pit will not be trenched (cut) or filled (squeezed) while containing fluids. When dry, the pit will be backfilled with a minimum of 5 feet of soil material. In relatively flat areas the pit area will be slightly mounded above the surrounding grade to allow for settling and to promote surface drainage away from the backfilled pit.

Management of Invasive, Noxious, and Non-Native Species:

- All reclamation equipment will be cleaned prior to use to reduce the potential for introduction of noxious weeds or other undesirable non-native species.
- An intensive weed monitoring and control program will be implemented prior to site preparation for planting and will continue until interim or final reclamation is approved by the authorized officer.
- Monitoring will be conducted at least annually during the growing season to determine the presence of any invasive, noxious, and non-native species. Invasive, noxious, and non-native species that have been identified during monitoring will be promptly treated and controlled. A Pesticide Use Proposal (PUP) will be submitted to the BLM for approval prior to the use of herbicides.

Interim Reclamation Procedures - Additional

Recontouring:

- Interim reclamation actions will be completed no later than 6 months from when the final well on the location has been completed, weather permitting. The portions of the cleared well site not needed for active operational and safety purposes will be recontoured to the original contour if feasible, or if not feasible, to an interim contour that blends with the surrounding topography as much as possible. Sufficient semi-level area will remain for setup of a workover rig and to park equipment. In some cases, rig anchors may need to be pulled and reset after recontouring to allow for maximum interim reclamation.
- If the well is a producer, the interim cut and fill slopes prior to re-seeding will not be steeper than a 3:1 ratio, unless the adjacent native topography is steeper. Note: Constructed slopes may be much steeper during drilling, but will be recontoured to the above ratios during interim reclamation.
- Roads and well production equipment, such as tanks, treaters, separators, vents, electrical boxes, and equipment associated with pipeline operation, will be placed on location so as to permit maximum interim reclamation of disturbed areas. If equipment is found to interfere with the proper interim reclamation of disturbed areas, the equipment will be moved so proper recontouring and revegetation can occur.

Application of Topsoil & Revegetation:

• Topsoil will be evenly respread and aggressively revegetated over the entire disturbed area not needed for all-weather operations including road cuts & fills and to within a few feet of the production facilities, unless an all-weather, surfaced, access route or small "teardrop" turnaround is needed on the well pad.

Visual Resources Mitigation:

- Trees, if present, and tall vegetation will be left along the edges of the pads whenever feasible to provide screening.
- To help mitigate the contrast of recontoured slopes, reclamation will include measures to feather cleared lines of vegetation and to save and redistribute cleared trees, debris, and rock over recontoured cut and fill slopes.
- To reduce the view of production facilities from visibility corridors and private residences, facilities will not be placed in visually exposed locations (such as ridgelines and hilltops) unless such locations are necessary for operations.
- Production facilities will be clustered and placed away from cut slopes and fill slopes to allow the maximum recontouring of the cut and fill slopes.
- All long-term above ground structures will be painted (from the BLM "Supplemental Environmental Colors" chart) to blend with the natural color of the late summer landscape background.

Final Reclamation Procedures - Additional

- Final reclamation actions will be completed within 6 months of well plugging, weather permitting.
- All disturbed areas, including roads, pipelines, pads, production facilities, and interim reclaimed areas will be recontoured to the contour existing prior to initial construction or a contour that blends indistinguishably with the surrounding landscape. Salvaged topsoil will be spread evenly over the entire disturbed site to ensure successful revegetation. To help mitigate the contrast of recontoured slopes, reclamation will include measures to feather cleared lines of vegetation and to save and redistribute cleared trees, woody debris, and large rocks over recontoured cut and fill slopes.

- Water breaks and terracing will only be installed when absolutely necessary to prevent erosion of fill material. Water breaks and terracing are not permanent features and will be removed and reseeded when the rest of the site is successfully revegetated and stabilized.
- If necessary to ensure timely revegetation, the pad will be fenced to BLM standards to exclude livestock grazing for the first two growing seasons or until seeded species become firmly established, whichever comes later. Fencing will meet standards found on page 18 of the Gold Book, 4th Edition, or will be fenced with operational electric fencing.
- Final abandonment of pipelines and flowlines will involve flushing and properly disposing of any fluids in the lines. All surface lines and any lines that are buried close to the surface that may become exposed in the foreseeable future due to water or wind erosion, soil movement, or anticipated subsequent use, must be removed. Deeply buried lines may remain in place unless otherwise directed by the authorized officer.

Reclamation Monitoring and Final Abandonment Approval

- Reclaimed areas will be monitored annually. Actions will be taken to ensure that reclamation standards are met as quickly as reasonably practical and are maintained during the life of the permit.
- If specifically requested by the authorized officer reclamation monitoring will be documented in an annual reclamation report submitted to the authorized officer by the operator. The report will document compliance with all aspects of the reclamation objectives and standards, identify whether the reclamation objectives and standards are likely to be achieved in the near future without additional actions, and identify actions that have been or will be taken to meet the objectives and standards. If specifically requested monitoring and reporting will continue annually until interim or final reclamation is approved. Any time 30% or more of a reclaimed area is redisturbed, monitoring will be reinitiated.
- The authorized officer will be informed when reclamation has been completed, appears to be successful, and the site is ready for final inspection.

STATE OF UTAH

DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

ENTITY ACTION FORM

Operator:

Wolverine Operating Company of Utah, LLC

Operator Account Number: N 1655

Address:

One Riverfront Plaza, 55 Campau NW

city Grand Rapids, MI

zip 49503 state MI

Phone Number: (616) 458-1150

Well 1

API Number	Well Name		QQ	Sec	Twp	Rng	County
4303950003	Rough Canyon Federal 30-1		NWNW	32	178	1E	Sanpete
Action Code	Current Entity Number	New Entity Number	Spud Date			tity Assignment Effective Date	
Α	99999	17764	8	3/29/201	0	9	7/7/10
'ammonte:	4.4					AANIF	TREUTIN

NAVA

BHL= See 30 NESE

CONFIDENTIAL

Well 2

API Number Action Code	Well Name		QQ	Sec	Twp	Rng	County
	Current Entity Number	New Entity Number	S	pud Dat	te		y Assignment fective Date
Comments:							<u> </u>

Well 3

API Number	Well I	Name	QQ	Sec	Twp	Rng	County
Action Code	Current Entity Number	New Entity Number	S	l pud Da	l te		ty Assignment fective Date
Comments:							er

ACTION CODES:

- A Establish new entity for new well (single well only)
- **B** Add new well to existing entity (group or unit well)
- C Re-assign well from one existing entity to another existing entity
- D Re-assign well from one existing entity to a new entity
- **E** Other (Explain in 'comments' section)

RECEIVED

Helene Bardolph Name (Please Print) Signature **Engineering Assistant** 8/31/2010

Date

AUG 3 1 2010

Title

	FORM 9			
	5.LEASE DESIGNATION AND SERIAL NUMBER: UTU-82536			
SUND	6. IF INDIAN, ALLOTTEE OR TRIBE NAME:			
Do not use this form for propo bottom-hole depth, reenter plu DRILL form for such proposals	7.UNIT or CA AGREEMENT NAME:			
1. TYPE OF WELL Oil Well				8. WELL NAME and NUMBER: Rough Canyon Federal 30-1
2. NAME OF OPERATOR: WOLVERINE OPERATING COM	PANY OF UTAH, LLC			9. API NUMBER: 43039500030000
3. ADDRESS OF OPERATOR: One Riverfront Plaza 55 Camp	PH au NW, Grand Rapids, MI, 49503	ONE N	UMBER: 616 458-1150 Ext	9. FIELD and POOL or WILDCAT: WILDCAT
4. LOCATION OF WELL FOOTAGES AT SURFACE: 0288 FNL 0452 FWL	TO DANCE MEDICINA			COUNTY: SANPETE
QTR/QTR, SECTION, TOWNSHI Qtr/Qtr: NWNW Section: 3:	2 Township: 17.0S Range: 01.0E Meridia	n: S		STATE: UTAH
CHE	CK APPROPRIATE BOXES TO INDICA	ATE N	ATURE OF NOTICE, REPORT,	OR OTHER DATA
TYPE OF SUBMISSION			TYPE OF ACTION	
	☐ ACIDIZE		ALTER CASING	CASING REPAIR
NOTICE OF INTENT Approximate date work will start:	CHANGE TO PREVIOUS PLANS	_	CHANGE TUBING	CHANGE WELL NAME
SUBSEQUENT REPORT	CHANGE WELL STATUS		COMMINGLE PRODUCING FORMATIONS	CONVERT WELL TYPE
Date of Work Completion:	☐ DEEPEN ☐ OPERATOR CHANGE	_	FRACTURE TREAT	☐ NEW CONSTRUCTION ☐ PLUG BACK
,	PRODUCTION START OR RESUME	_	RECLAMATION OF WELL SITE	RECOMPLETE DIFFERENT FORMATION
SPUD REPORT Date of Spud:	REPERFORATE CURRENT FORMATION		SIDETRACK TO REPAIR WELL	TEMPORARY ABANDON
8/28/2010	TUBING REPAIR		VENT OR FLARE	WATER DISPOSAL
DRILLING REPORT Report Date:	water shutoff		SI TA STATUS EXTENSION	APD EXTENSION
Report Date:	☐ WILDCAT WELL DETERMINATION	_	OTHER	OTHER:
12 DESCRIBE PROPOSED OR CO	MPLETED OPERATIONS. Clearly show all p			<u></u>
l .	at 5:00 PM on 8/28/2010 usin		- , , ,	ordines, etc.
·	LK 12.			Accepted by the
				Jtah Division of
				, Gas and Mining
			FOR	R RECORD ONLY
				•
NAME (PLEASE PRINT) Paul Spiering	PHONE NUMBE 435 896-1943	R	TITLE District Land Manager	
SIGNATURE N/A			DATE 9/10/2010	

STATE OF UTAH DEPARTMENT OF NATURAL RESOURCES					FORM 9
DIVISION OF OIL, GAS, AND MINING					SE DESIGNATION AND SERIAL NUMBER: 82536
SUNDRY NOTICES AND REPORTS ON WELLS					NDIAN, ALLOTTEE OR TRIBE NAME:
Do not use this form for proposals to drill new wells, significantly deepen existing wells below current bottom-hole depth, reenter plugged wells, or to drill horizontal laterals. Use APPLICATION FOR PERMIT TO DRILL form for such proposals.					F or CA AGREEMENT NAME:
1. TYPE OF WELL Oil Well					L NAME and NUMBER: GH CANYON FED 30-1
2. NAME OF OPERATOR: WOLVERINE OPERATING COM	IPANY OF UTAH, LLC				NUMBER: 9500030000
3. ADDRESS OF OPERATOR: One Riverfront Plaza 55 Camp	pau NW, Grand Rapids, MI, 49503	HONE N	UMBER: 616 458-1150 Ext	9. FIEI WILD	L D and POOL or WILDCAT: CAT
4. LOCATION OF WELL FOOTAGES AT SURFACE: 0288 FNL 0452 FWL				SANP	
QTR/QTR, SECTION, TOWNSH: Qtr/Qtr: NWNW Section: 3	IP, RANGE, MERIDIAN: 2 Township: 17.0S Range: 01.0E Meridi	an: S		STATE UTAH	
11. CHE	CK APPROPRIATE BOXES TO INDIC	CATE N	ATURE OF NOTICE, REPOR	RT, OR OT	HER DATA
TYPE OF SUBMISSION			TYPE OF ACTION		
	ACIDIZE		ALTER CASING		CASING REPAIR
NOTICE OF INTENT Approximate date work will start:	☐ CHANGE TO PREVIOUS PLANS☐ CHANGE WELL STATUS	_	CHANGE TUBING COMMINGLE PRODUCING FORMATION	L [CHANGE WELL NAME CONVERT WELL TYPE
SUBSEQUENT REPORT	DEEPEN		FRACTURE TREAT	vs ∟ □	NEW CONSTRUCTION
Date of Work Completion:	OPERATOR CHANGE		PLUG AND ABANDON		PLUG BACK
SPUD REPORT	PRODUCTION START OR RESUME	□ ı	RECLAMATION OF WELL SITE		RECOMPLETE DIFFERENT FORMATION
Date of Spud:	REPERFORATE CURRENT FORMATION	☐ :	SIDETRACK TO REPAIR WELL		TEMPORARY ABANDON
	☐ TUBING REPAIR	□ ,	VENT OR FLARE		WATER DISPOSAL
✓ DRILLING REPORT Report Date:	☐ WATER SHUTOFF	☐ <i>:</i>	SI TA STATUS EXTENSION		APD EXTENSION
10/14/2010	☐ WILDCAT WELL DETERMINATION		OTHER	оті	HER:
	OMPLETED OPERATIONS. Clearly show all Please see attached report for	•	•	s, volumes,	etc.
					oted by the
					Division of s and Mining
			FU	אאי	ECORP ₁₄ ONLY
NAME (PLEASE PRINT) Helene Bardolph	PHONE NUMBI 616 458-1150	ER	TITLE Engineering Administrative	Assistant	
SIGNATURE N/A			DATE 10/14/2010		

August/September 2010 Drilling Update

Wolverine Operating Company of Utah, LLC Rough Canyon Federal 30-1 API #43039500030000 NWNW, Section 32, T17S, R1E Sevier County, Utah

28 - 29 August 2010

Depth 0' GL, no casing set. MIRURT. MW – none, Vis. – none, FL – N/A. Surveys: none.

30 August 2010

Depth 1' GL, no casing set. MIRURT, spud at 1700 hrs, 8/29/10 w/ 38" bit. MW – 8.8, Vis. – 53, FL – not controlled. Surveys: none.

31 August 2010

Depth 15' GL, no casing set. Drill to 15' w/ 38" bit. MW - 8.8, Vis. -53, FL - not controlled. Surveys: none.

1 September 2010

Depth 44' GL, no casing set. Drill to 44' GL. MW – 8.8, Vis. – 53, FL – not controlled. Surveys: none.

2 September 2010

Depth 69' GL, no casing set. Drill to 69' GL. MW - 8.8, Vis. - 53, FL - not controlled. Surveys: $\frac{1}{2}$ degree @ 55'.

3 September 2010

Depth 75' GL, 32" x 3/8" wall @ 75' GL. Drill to 76', POOH, run 32" casing to 75' GL, run tremmie pipe, pump 25 sx Neat mixed at 15.6 ppg, WOC, run tremmie pipe, tag cmt at 68' GL, mix cement. MW – 8.8, Vis. – 53, FL – not controlled. Surveys: none.

4 September 2010

Depth 79' GL, 32" x 3/8" wall @ 75' GL. Pump 125 sx Neat mixed at 15.3 pg, WOC, run tremmie pipe, tag cmt at 51', mix & pump 50 sx Neat mixed at 15.3 ppg, filled to GL, did not fall back, WOC, PU 26" bit & BHA, RU rotary table, hook up flow lines, GIH, tag cmt @ 68' GL, drill cmt from 68' to 75', drill to 79', POOH to change top sub. MW – 8.8, Vis. – 60, FL – not controlled. Surveys: none.

5 September 2010

Depth 79' GL, 32" x $\frac{3}{8}$ " wall @ 75' GL. POOH, add DC's, GIH, drill to 133', POOH, PU DC's, drill to 170'. MW – 8.7, Vis. – 60, FL – not controlled. Surveys: none.

6 September 2010

Depth 298' GL, 32" x $\frac{3}{8}$ " wall @ 75' GL. Drill to 250' GL, C&C, survey, drill to 290', survey, switch to reverse circulation, drill to 298' GL. MW – 9.3, Vis. – 46, FL – 8. Surveys: 1 degree @ 110', 1 degree @ 220' & 1 degree @ 250'.

7 September 2010

Depth 390' GL, 32" x %" wall @ 75' GL. Drill to 330, survey, drill to 390, attempt survey, tool separated from wire line, POOH, remove survey tool, GIH. MW – 9.3, Vis. – 43, FL – 9. Surveys: 1 degree @ 10', 1.25 degrees @ 300'.

8 September 2010

Depth 494' GL, 32" x $\frac{3}{8}$ " wall @ 75' GL. GIH, survey, C&C, drill to 430, survey, drill to 470, C&C, survey, drill to 494'. MW – 9, Vis. – 42, FL – 9. Surveys: 0.25 degrees @ 100', 0.25 degrees @ 200', 0.75 degrees @ 390' & 0.25 degrees @ 440'.

9 September 2010

Depth 585' GL, 32" x 3/8" wall @ 75' GL. Drill to 510', survey, drill to 550', losing mud @ 100 bbl/hr, survey, drill to 585'. MW – 8.7, Vis. – 40, FL – 14. Surveys: 1 degree @ 480' & 1.5 degrees @ 520'.

10 September 2010

Depth 671' GL, 32" x $\frac{3}{8}$ " wall @ 75' GL. Drill to 590', losing 20 bbl/ hr mud, C&C, survey, drill to 630', C&C, survey, drill to 670', started losing returns at 648, lost all returns at 670', survey, drill to 671, still losing all returns, POOH. MW – 8.7, Vis. – 45, FL – 14. Surveys: 1 degree @ 560', 1 degree @ 600' & $1\frac{1}{2}$ degrees @640'.

11 September 2010

Depth 705' GL, 32" x 3/8" wall @ 75' GL. POOH, LD some DC's, GIH, pump LCM slugs, drill to 674', losing 50 bbl/hr mud, drill to 678', losing 50 bbl/hr, drill to 705' lost all returns, mix mud & LCM. MW – 8.7, Vis. – 51, FL – 14. Surveys: none.

12 September 2010

Depth 752' GL, 32" x $\frac{3}{8}$ " wall @ 75' GL. Mix & pump LCM slugs, drill to 714', losing 25 bbl/hr mud, C&C, drill to 734', losing 50 bbl/hr mud, C&C, survey, drill to 746', losing 75 bbl/hr mud, lost total returns at 746', mix LCM slugs, lost 400 bbl mud, drill to 750', losing 90 bbl/hr mud, lost all returns at 750', lost 300 bbl mud, drill to 751', losing 125 bbl/hr mud, lost all returns at 750', losing 125 bbl/hr, mis LCM slugs. MW - 8.7, Vis. - 51, FL - 14. Surveys: $2\frac{1}{4}$ degrees @ 700'.

13 September 2010

Depth 762' GL, 32" x 3/8" wall @ 75' GL. Mix & pump LCM slugs, drill to 754', losing 125 bbl/hr mud, survey, lost returns, TFNB, establish partial circulation, drill to 762', losing 75 bbl/hr . MW – 8.9, Vis. – 55, FL – 14. Surveys: 13/4 degrees @ 720'.

14 September 2010

Depth 803' GL, 32" x ¾" wall @ 75' GL. Drill to 775', losing 75 bbl/hr mud, survey, drill to 785', losing 125 bbl/hr mud, drill to 803', lost returns, mix & pump slugs, attempt to drill blind, discontinued due to high torque, mix & pump LCM slugs. MW – 8.6, Vis. – 40, FL – not controlled. Surveys: 1 degree @ 740'

15 September 2010

Depth 856' GL, 32" x $\frac{1}{2}$ " wall @ 75' GL. Mix & pump mud + LCM slugs, PU 20' off bottom, switch to conventional circulation, drill to 856 w/ no returns, losing 75 bbl/hr mud. MW – 8.8, Vis. – 70, FL – NC. Surveys: none.

16 September 2010

Depth 916' GL, 32" x $\frac{3}{8}$ " wall @ 75' GL. Drill to 916', losing 100 bbl/hr mud. MW – 8.8, Vis. – 70, FL – NC. Surveys: none.

17 September 2010

Depth 971' GL, 32" x 3/8" wall @ 75' GL. Drill to 935, C&C, survey, drill to 971'. MW – 8.6, Vis. – 68, FL – NC. Surveys: 13/4 degrees @ 880'.

18 September 2010

Depth 1047' GL, 32" x %" wall @ 75' GL. Drill blind to 1015, survey, drill blind to 1047'. MW - 8.9, Vis. - 68, FL - NC. Surveys: 1 degrees @ 950'.

19 September 2010

Depth 1140' GL, 32" x $\frac{3}{8}$ " wall @ 75' GL. Drill & survey, circulate conventional, losing 125 bbl/hr mud. MW – 8.6, Vis. – 93, FL – NC. Surveys: 2 degrees @ 1020' & 2°@ 1060'.

20 September 2010

Depth 1228' GL, 32" x $\frac{3}{8}$ " wall @ 75' GL. Drill & survey, circulate conventional, losing 125 bbl/hr mud. MW – 8.6, Vis. – 84, FL – NC. Surveys: $\frac{21}{2}$ ° @ 1100'& 2° @ 1140'.

21 September 2010

Depth 1235' GL, 32" x $\frac{3}{8}$ " wall @ 75' GL. Drill to 1235', C&C, found fluid level in hole, POOH to 975', switch to flooded reverse circulating method, wash back to 1215', POOH. MW – 8.6, Vis. – 62, FL – NC. Surveys: $\frac{13}{4}$ °@ 1180'.

22 September 2010

Depth 1280' GL, 32" x $\frac{3}{8}$ " wall @ 75' GL. PU new bit, GIH, drill. MW – 8.9, Vis. – 44, FL – NC. Surveys: none.

23 September 2010

Depth 1371' GL, 32" x 3/8" wall @ 75' GL. Drill & survey, circulate w/ flooded reverse method.. MW – 8.9, Vis. – 43, FL – NC. Surveys: 1½° @ 1220', 2½° @ 1260', 2°@ 1280' & 1¼° @ 1300'.

24 September 2010

Depth 1425' GL, 32" x %" wall @ 75' GL. Drill & survey to TD at 1425', C&C, POOH, LDDP& BHA, clean up tools, tongs & wrenches. MW – 9.1, Vis. – 45, FL – NC. Surveys: 2°@ 1360'.

25 September 2010

Depth 1425' GL, 32" x $\frac{3}{8}$ " wall @ 75' GL. Prep to run casing, cut off 32" csg, set landing plate, run 22" x $\frac{1}{2}$ " wall casing to 840'. MW – 8.8, Vis. – 45, FL – NC. Surveys: none.

26 September 2010

Depth 1425' GL, 32" x 3/8" wall @ 75' GL. Run casing to 900', wait on crane, RU 250 ton crane, run casing to 1421', RD crane. MW – 8.8, Vis. – 45, FL – NC. Surveys: none.

27 September 2010

Depth 1425' GL, 22" x ½" wall @ 1421' GL. Fluid level at 778', pump to clear 1¾ tremmie pipe, (1) mix & pump 44 sx (1.17 cf/sk) Cl. "G" cement + 4% CaCl2 mixed @ 15.4 ppg, POOH, WOC, tag cmt @ 1375', (2) mix & pump 44 sx (1.17 cf/sk) Cl. "G" cement + 4% CaCl2 mixed @ 15.4 ppg, POOH, WOC, tag cmt @ 1325', (3) mix & pump 44 sx (1.17 cf/sk) Cl. "G" cement + 4% CaCl2 mixed @ 15.4 ppg, POOH, WOC, tag cmt @ 1265', POOH w/ tremmie pipe to clear plugged pipe, GIH w/ tremmie pipe, tag cmt @ 1263',

MW - 8.8, Vis. - 45, FL - NC. Surveys: none.

28 September 2010

Depth 1425' GL, 22" x ½" wall @ 1421' GL.

(4) mix & pump 44 sx (1.17 cf/sk) Cl. "G" cement + 4% CaCl2 mixed @ 15.4 ppg, POOH, WOC, tag cmt @ 1175', (5) mix & pump 44 sx (1.17 cf/sk) Cl. "G" cement + 4% CaCl2 mixed @ 15.4 ppg, POOH, WOC, tag cmt @ 1095', (6) mix & pump 275 sx (1.17 cf/sk) Cl. "G" cement + 3% CaCl2 mixed @ 15.5 ppg, POOH, WOC, tag cmt @ 760', (7) mix & pump 325 sx (1.17 cf/sk) Cl. "G" cement + 2% CaCl2 mixed @ 15.3 ppg, POOH, WOC, tag cmt @ 480', (8) mix & pump 44 sx (1.17 cf/sk) Cl. "G" cement + 2% CaCl2 mixed @ 15.3 ppg, 2

MW - 8.8, Vis. -45, FL - NC. Surveys: none.

29 September 2010

Depth 1371' GL, 22" x ½" wall @ 1421' GL.

(8 continued) Tag cement at 472', (9) mix & pump 44 sx (1.17 cf/sk) Cl. "G" cement + 4% CaCl2 mixed @ 15.4 ppg, POOH, WOC, tag cmt @ 470', (10) mix & pump 325 sx (1.17 cf/sk) Cl. "G" cement + 3% CaCl2 mixed @ 15.4 ppg, POOH, WOC, tag cmt @ 330', (11) mix & pump 165 sx (1.17 cf/sk) Cl. "G" cement + 3% CaCl2 mixed @ 15.5 ppg, POOH, WOC, tag cmt @ 185', (12) mix & pump 325 sx (1.17 cf/sk) Cl. "G" cement + 3% CaCl2 mixed @ 15.3 ppg, POOH, WOC, tag cmt @ 35', (13) mix & pump 65 sx (1.17 cf/sk) Cl. "G" cement + 3% CaCl2 mixed @ 15.3 ppg, circulate to surface, cement standing at surface,

WOC, RDRT, MW – 8.8, Vis. – 45, FL – NC. Surveys: none.

30 September 2010

Depth 1425' GL, 22" x ½" wall @ 1421' GL. RDRT, PU air hammer, drill mouse hole for big rig, RDMO Boart Longyear LK-12 rig. MW – 8.8, Vis. – 45, FL – NC. Surveys: none.

Carol Daniels - Rough Canyon Federal 30-1 Update TINS ROLE S-32 43-039-50003 SAN LOTA ANAMANAMANAMANAMANA LOTA AN CANTONOMA PENGLOPECA LAMITE MENGLOPAS LOTA MA

From: "William Donovan"

To:

"'Allen, Geoff", "'Arthurs, Shane", "'Blair, Richard", "'Brock Pope ", "'Chamberlain, Don'", "'Childers, Eli'", "'Chris Schaugaard", "'Daniel Jenkins'", "'Daniels, Carol", "'De la Torre, Juan C'", "'Dennis'", "'Denton, Derek'", "'Dieste, Bobby'", "'Doucet, Dustin'", "'Dustin Dunning'", "'Foreman, Ron'", "'George Zamantakis'", "'Hall, Denise'", "'Hammell, Hank'", "'Harry Melnikoff'", "'Hendricks, Marvin'", "'Hutcinson, Clayton'", "'Jeff Ainge'", "'Jim Barry'", "'Jones, Mark'", "'Kulow, Kyle'", "'Kyle Cox'", "'LaDee Roundy'",

"Larimore, Mark", "Lewis, John", "Martin Petel", "Matt Harmon", "McCoy,

Charlene'", "'McCoy, Tim'", "'O'Connell, David'", "'Perry, Bud (Smith Bits)'", "'Pickup, Marc'", "Rees, John M'", "Revert, Scott'", "Robinson, Darin'", "Ryan Thomas'", "Shaun Burns'", "Shawn Moulton'", "Shelton, Shorty'", "Smuin, Troy", "Steffen, Dana'",

"'Tujillo, Chris'", "'Tyler Ross'", "'Willis, Walton'", "'Winkler, Matt'", "'Zimmerman, Bill'"

10/30/2010 2:03 PM Date:

Subject: Rough Canyon Federal 30-1 Update

10/30/2010 1:42 PM

Drilling at 2,807', ROP 4 FPH

Notice new e-mail address for rig

Bill Donovan Wolverine Operating Company of Utah, LLC Rough Canyon Federal 30-1 AFE 224 API 43-039-50003-00-00 Rig (970) 361-3276 boart@drillmail.net Cell (720) 351-7470 donovan@petroleum-eng.com

> RECEIVED NOV 0 1 2010

Carol Daniels - Rough Canyon Federal 30-1 Update T179 RolE 5-32 43-039-5 0003

"Wolverine Exploration Rig" From:

"Ainge, Jeff", "Allen, Geoff", "Arthurs, Shane", "Blair, Richard", "Brock Pope", To:

"Chamberlain, Don", "Childers, Eli", "Chris Schaugaard", "Daniel Jenkins", "Daniels, Carol", "De la Torre, Juan C", "Dennis", "Denton, Derek", "Dieste, Bobby", "Doucet, Dustin", "Dustin Dunning", "Foreman, Ron", "George Zamantakis", "Hall, Denise", "Hammell, Hank", "Harry Melnikoff", "Hendricks, Marvin", "Hutcinson, Clayton", "Jim Barry", "Jones, Mark", "Kulow, Kyle", "Kyle Cox", "LaDee Roundy", "Larimore, Mark",

"Lewis, John", "Martin Pete", "Matt Harmon", "McCoy, Charlene", "McCoy, Tim", "O'Connell, David", "Perry, Bud (Smith Bits)", "Pickup, Marc", "Rees, John M", "Revert, Scott", "Robinson, Darin", "Ryan Thomas", "Shaun Burns", "Shawn Moulton", "Shelton, Shorty", "Smuin, Troy", "Steffen, Dana", "Tujillo, Chris", "Tyler Ross", "Willis, Walton",

"Winkler, Matt", "Zimmerman, Bill"

Date:

10/29/2010 5:22 PM

Subject: Rough Canyon Federal 30-1 Update

10/29/2010 5:19 PM

Drilling at 2,734', ROP 4 FPH

Bill Donovan Drilling Supervisor Wolverine Gas and Oil Company of Utah, LLC Rough Canyon Federal 30-1. AFE 224 Rig (970) 361-3276 Cell (720) 351-7470 boart@drillmail.net

> RECEIVED NOV 0 1 2010

STATE OF UTAH DEPARTMENT OF NATURAL RESOURCES				FORM 9				
	DIVISION OF OIL, GAS, AND M	3	5.LEASE DESIGNATION AND SERIAL NUMBER UTU-82536					
SUNDI	6. IF INDIAN, ALLOTTEE OR TRIBE NAME:							
	sals to drill new wells, significantly deep ugged wells, or to drill horizontal laterals			7.UNIT or CA AGREEMENT NAME:				
1. TYPE OF WELL Oil Well				8. WELL NAME and NUMBER: ROUGH CANYON FED 30-1				
2. NAME OF OPERATOR: WOLVERINE OPERATING COM	IPANY OF UTAH, LLC			9. API NUMBER: 43039500030000				
3. ADDRESS OF OPERATOR: One Riverfront Plaza 55 Camp	Ploau NW, Grand Rapids, MI, 49503	HONE N	UMBER: 616 458-1150 Ext	9. FIELD and POOL or WILDCAT: WILDCAT				
4. LOCATION OF WELL FOOTAGES AT SURFACE: 0288 FNL 0452 FWL				COUNTY: SANPETE				
QTR/QTR, SECTION, TOWNSH: Qtr/Qtr: NWNW Section: 3	IP, RANGE, MERIDIAN: 2 Township: 17.0S Range: 01.0E Meridia	an: S		STATE: UTAH				
11. CHE	CK APPROPRIATE BOXES TO INDIC	ATE N	ATURE OF NOTICE, REPORT,	OR OTHER DATA				
TYPE OF SUBMISSION			TYPE OF ACTION					
	☐ ACIDIZE		ALTER CASING	CASING REPAIR				
NOTICE OF INTENT Approximate date work will start:	CHANGE TO PREVIOUS PLANS		CHANGE TUBING	CHANGE WELL NAME				
	CHANGE WELL STATUS		COMMINGLE PRODUCING FORMATIONS	CONVERT WELL TYPE				
SUBSEQUENT REPORT Date of Work Completion:	DEEPEN		FRACTURE TREAT	NEW CONSTRUCTION				
	OPERATOR CHANGE		PLUG AND ABANDON	PLUG BACK				
SPUD REPORT Date of Spud:	PRODUCTION START OR RESUME		RECLAMATION OF WELL SITE	RECOMPLETE DIFFERENT FORMATION				
Bute of Spau.	REPERFORATE CURRENT FORMATION	_	SIDETRACK TO REPAIR WELL	☐ TEMPORARY ABANDON				
✓ DRILLING REPORT	☐ TUBING REPAIR		VENT OR FLARE	☐ WATER DISPOSAL				
Report Date: 10/31/2010	WATER SHUTOFF	□ : _	SI TA STATUS EXTENSION	APD EXTENSION				
10/31/2010	☐ WILDCAT WELL DETERMINATION		OTHER	OTHER:				
12. DESCRIBE PROPOSED OR COMPLETED OPERATIONS. Clearly show all pertinent details including dates, depths, volumes, etc. Please see attached report for drilling details								
	ass see attached report for a			Accepted by the				
			l	Jtah Division of				
				, Gas and Mining				
			FOF	RECOMREDOONLY				
NAME (PLEASE PRINT) Helene Bardolph	PHONE NUMBE 616 458-1150	R	TITLE Engineering Administrative Ass	istant				
SIGNATURE N/A			DATE 11/18/2010					
			I.					

Subject: Wolverine Operating Company of Utah, LLC

Rough Canyon Federal 30-1

NW¹/₄ NW¹/₄ Sec 32-T17S-R1E surface location

NE¹/₄ SE¹/₄ Sec 30-T17S-R1E BHL

Sanpete County, Utah

1 October 2010

Depth 1425' GL, 22" x ½" wall @ 1421' GL. RDMO Boart Longyear rig LK-12, prepare pad for Boart Longyear rig LM-700. MW – nr, Vis. – nr, FL – nr. Surveys: none.

2 October 2010

Depth 1425' GL, 22" x $\frac{1}{2}$ " wall @ 1421' GL. Prepare pad, start mobilizing Boart Longyear rig LM-700. MW – nr, Vis. – nr, FL – NC. Surveys: none.

3 October 2010

Depth 1425' GL, 22" x ½" wall @ 1421' GL. Mobilizing Boart Longyear rig LM-700. MW – nr, Vis. – nr, FL – NC. Surveys: none.

4 October 2010

Depth 1425' GL, 22" x ½" wall @ 1421' GL. Mobilizing Boart Longyear rig LM-700. MW – nr, Vis. – nr, FL – NC. Surveys: none.

<u>5 October 2010 – 11 October 2010</u>

Depth 1425' GL, 22" x ½" wall @ 1421' GL. MIRURT Boart-Longyear rig LM-700. MW – nr, Vis. – nr, FL – nr. Surveys: none.

12 October 2010

Depth 1425' GL, 22" x ½" wall @ 1421' GL. Finalize rig up, PU BHA & drill pipe. MW – nr, Vis. – nr, FL – nr. Surveys: none.

13 October 2010

Depth 1453' GL, 22" x $\frac{1}{2}$ " wall @ 1421' GL. PU drill pipe, C&C, drill cement 1439-48, drill. MW – 8.8, Vis. – 45, FL – no control. Surveys: none.

14 October 2010

Depth 1586' GL, 22" x ½" wall @ 1421' GL. Drilling. MW - 8.9, Vis. - 42, FL - 6.8. Surveys: none. 15 October 2010

Depth 1720' GL, 22" x ½" wall @ 1421' GL. Drill & survey. MW – 9.0, Vis. – 48, FL – 6.6. Surveys: 3° @ 1525' & 3° @ 1581'.

16 October 2010

Depth 1720' GL, 22" x ½" wall @ 1421' GL. Drill & survey. MW – 8.9, Vis. – 51, FL – 6.8. Surveys: 4° @ 1660', 3¼° @ 1691' & 4° @ 1721'.

17 October 2010

Depth 1864' GL, 22" x ½" wall @ 1421' GL. Drill & survey. MW – 8.8, Vis. – 53, FL – 8.2. Surveys: 4° @ 1755' & 3½° @ 1791'.

18 October 2010

Depth 1938' GL, 22" x ½" wall @ 1421' GL. Drill & survey. MW - 8.7, Vis. - 47, FL - 8. Surveys: $3\frac{3}{4}$ ° @ 1821' & $3\frac{1}{4}$ ° @ 1850'.

19 October 2010

Depth 2020' GL, 22" x ½" wall @ 1421' GL. Drill & survey, run gyro survey, drill, trip for new bit. MW - 8.7, Vis. -55, FL -8.8. Surveys: 3% @ 1960'.

20 October 2010

Depth 2040' GL, 22" x $\frac{1}{2}$ " wall @ 1421' GL. TFNB, change roller reamers, drill. MW - 8.7, Vis. - 51, FL - 6.6. Surveys: none.

21 October 2010

Depth 2201' GL, 22" x ½" wall @ 1421' GL. Drill & survey. MW - 8.9, Vis. -53, FL - 8.8. Surveys: 334° @ 2046 & 334° @ 2116.

22 October 2010

Depth 2345' GL, 22" x ½" wall @ 1421' GL. Drill & survey. MW - 8.9, Vis. - 53, FL - 10. Surveys: 4° @ 2150, 4° @ 2216 & 4¾° @ 2280.

23 October 2010

Depth 2509' GL, 22" x $\frac{1}{2}$ " wall @ 1421' GL. Drill & survey. MW - 8.9, Vis. - 50, FL - 11. Surveys: $2\frac{1}{4}$ ° @ 2320' & $4\frac{3}{4}$ ° @ 2385'.

24 October 2010

Depth 2620' GL, 22" x ½" wall @ 1421' GL. Drill & survey. MW – 8.9, Vis. – 50, FL – 10.4. Surveys: 6° @ 2450' & 4½° @ 2519'.

25 October 2010

Depth 2629' GL, 22" x $\frac{1}{2}$ " wall @ 1421' GL. Drill to 2626, C&C, TFNB, drill. MW - 8.9, Vis. - 51, FL - 8.6. Surveys: none.

26 October 2010

Depth 2698' GL, 22" x ½" wall @ 1421' GL. Drill & survey. MW – 8.8, Vis. – 47, FL – 11. Surveys: 6° @ 2580.

27 October 2010

Depth 2700' GL, 22" x ½" wall @ 1421' GL. Drill & survey, TFNB. MW - 8.7, Vis. - 38, FL - 15.6. Surveys: $5\frac{3}{4}$ ° @ 2665.

28 October 2010

Depth 2700' GL, 22" x $\frac{1}{2}$ " wall @ 1421' GL. TIH w/ mill, ream bottom of hole, POOH, PU bit, GIH, ream 2691 to 2694. MW - 8.8, Vis. - 47, FL - 15.6. Surveys: none.

29 October 2010

Depth 2702' GL, 22" x ½" wall @ 1421' GL. Ream 2694-2700, TFNB, drill. MW – 8.6, Vis. – 58, FL – 16.4. Surveys: none.

30 October 2010

Depth 2780' GL, 22" x ½" wall @ 1421' GL. Drill. MW – 8.7, Vis. – 59, FL – 7. Surveys: none.

31 October 2010

Depth 2850' GL, 22" x ½" wall @ 1421' GL. Drill & survey. MW – 8.8, Vis. – 50, FL – 14.4. Surveys: 6° @ 2770'.

CONFIDENTIAL

1	UNITED STATE DEPARTMENT OF THE BUREAU OF LAND MAN	ON Exp 5. Lease Serial No	FORM APPROVED OM B No. 1004-0137 Expires: March 31, 2007 5. Lease Scrial No.						
	NOTICES AND RE			UTU-85253	-				
abandoned w	nis form for proposals (ell. Use Form 3160-3 (N/A	If Indian, Allottee or Tribe Name N/A						
SUBMIT IN TR	IPLICATE- Other inst	ructions on rev	/erse side.	7. If Unit or CA	/Agreement, Name and/or No.				
1. Type of Well Oil Well 🗆 📗	Gas Well Other			N/A					
		8. Well Name at Rough Can	ad No. yon Federal 30-1						
Name of Operator Wolverine O Address	perating Company of Utah, L	9. API Well N 4303950003	= -						
55 Campau NW, Grand Rapids, MI 49503 616-458-1150					10. Field and Pool, or Exploratory Area				
4. Location of Well (Footage, Sec.,				Explorator	,				
SHL: 288' FNL, 452' FWL, S	ec 32, T17S, R1E, NWNW			11. County or Pa	•				
12. CHECK A	PPROPRIATE BOX(ES) TO	INDICATE NAT	URE OF NOTICE,	REPORT, OR O	THER DATA				
TYPE OF SUBMISSION			TYPE OF ACTION	, , , , , , , , , , , , , , , , , , , ,					
✓ Notice of Intent	Acidize	Deepen	Production (S	Start/Resume)	Water Shut-Off				
	Alter Casing Casing Repair	Fracture Treat	Reclamation	<u></u>	Well Integrity				
Subsequent Report	Change Plans	New Construction Plug and Abando		 A bandan	Other				
Final Abandonment Notice	Convert to Injection	Plug Back	Water Dispos						
determined that the site is ready Wolverine Operating Com	npany of Utah, LLC proposes ace of reaching the target form	filed only after all requ several changes to t	the approved APD to	mation, have been con	npleted, and the operator has				
	nent 10-05-2010 for details.				- 11.19.200				
And the second s	Accepted by the Utah Division of	The second of th		m e Thin					
	Utah Nivision of	.	Enderal App	roval Of This Necessary	Initials:				
C	u, Gas and Minir	13	Action Is	Necessary	The second				
Dat C	25/10/10	#			30PY				
14. I hereby certify that the fore Name (Printed/Typed) Edward A Higue	,	Titlo	M						
		THE	Manager - Developn	nent					
Signature		Date		10/05/2010	· · · · · · · · · · · · · · · · · · ·				
	THIS SPACE FOR I	FEDERAL OR	STATE OFFICE	EUSE					
Approved by			Title	Date					
Conditions of approval, if any, are a certify that the applicant holds legal which would entitle the applicant to	or equitable title to those rights in conduct operations thereon.	n the subject lease	Office						
Title 18 U.S.C. Section 1001 and Title States any false, fictitious or fraudule	e43 U.S.C. Section 1212, make it a ent statements or representations	crime for any person as to any matter within	knowingly and willfull to its jurisdiction.	y to make to any dep	artment or agency of the United				
(Instructions on page 2)			REC	CEIVED					

OCT 1 2 2010

CONFIDENTIAL

Wolverine Operating Company of Utah, LLC Rough Canyon Federal 30-1 Sundry Attachment 10-05-2010


- 1. Change of conductor size: The original APD had proposed setting 20" conductor to 1200' MD and cementing to surface. This conductor was to be set with Boart rig, using reverse circulation method. After reviewing the drilling performance at the Painted Rock prospect, we proposed setting larger conductor casing to accommodate drilling the surface hole with the Boart rig. Therefore, we proposed drilling a 28" hole and setting 22", 0.50" wall thickness, 104 #/ft A53B ERW, PE pipe to 1421' (GL). (Note: this casing setting depth will be 1399' DF when referenced to the Patterson rig derrick floor.) The conductor was cemented to surface using 1656 sacks, Class G with 2-4% CaCl, placed in ten separate stages with tremie pipe. Cement weight ranged from 15.3 to 15.5 ppg, with a 1.17 yield.
- 2. Setting Surface Casing: The original APD proposed using Patterson rig 304, using conventional drilling methods to set 13-3/8" surface casing in a 17.5" hole at 4000' DF. Wolverine proposes drilling the surface casing with Boart rig LM 700, using the reverse circulation method, drilling a 19" hole to 4000' DF and setting the 13-3/8" casing. The only change in this section is drilling a 19" hole instead of a 17.5" hole, using Boart rig, and cementing with Boart rig, using tremie pipe method. Because of the 19" hole, the cement volumes will increase, and the cement type will be Class G with 2-4% CaCl. Anticipated cement volume: 4750 sacks, Class G, 15.6 ppg, 1.17 yield.
- Change of Drlg Fluid: The original APD proposed drilling the Arapien section with a salt mud system. We are now proposing drilling this section with OBM, because of the hole problems we've seen in recently drilled exploration wells, and for the potential similar issues could be encountered in this well.
- 4. Revised directional plan: Because the surface casing will be set with Boart rig, directional drilling will not start until surface casing is set and cemented. The attached directional plan reflects kicking off at 4200'. BHL has not changed. The revised directional plan will result in a slightly longer wellbore trajectory. Therefore, the new proposed TD will be 13,100' (approximately 300' feet deeper). The proposed casing depth for the 9-5/8" and 5.5 liner would also move down 300' to approximately 10,400' and 13,100', respectively.




Wolverine Gas & Oil Company Rough Canyon Federal 30-1 Sanpete County, Utah









SITE DETAILS: Sanpete County, Utah

Site Centre Latitude: 39° 17' 40.276 N Longitude: 111° 50' 16,454 W

Positional Uncertainity: 0.0

Convergence: -0.22 Local North: Grid

Azimuths to Grid North True North: 0.22° Magnetic North: 0.229 Magnetic Field

Strength: 0.0snT Dip Angle: 0.00° Date: 2010/04/08 Model: USER DEFINED

					Surface	Location			1111	
			orthing 0273.10		Easting 4368.00		atittude 40.276 N	111° 5	Longitud 60' 16.454	
Se	c ME	Inc	Azi	TVD	+N/-S	+E/-W	Dieg	TFace	VSect	Target
					0.0	0.0	0.00	0.00	0.0	-700
1	4200.		0.00	4200.0	0.0	0.0	0.00	0.00	0.0	
2	4200.	0.00	0.00	4200.8	0.0	0.0	0.00	0.00	0.0	
3	5667.	29.34	329.21	5604.6	315.7	-188.1	2.00	329.21	367.5	
4	9199.0	29.34	329.21	8683.3	1802.3	-1073.9	0.00	329.21	2098.0	
5	10666.0	0.00	0.00	10087.0	2118.0	-1262.0	2.00	180.00	2465.5	Vertical Point
6	10680.0		0.00	10101.0	2118.0	-1262.0	0.00			
8	13079.0		0.00	12500.0	2118.0	-1262.0	0.00	0.00	2465.5 2465.5	Navajo PBHL.

	STATE OF UTAH DEPARTMENT OF NATURAL RESOU		FORM 9					
	DIVISION OF OIL, GAS, AND M	3	5.LEASE DESIGNATION AND SERIAL NUMBER UTU-82536					
SUND	RY NOTICES AND REPORT	S ON	I WELLS	6. IF INDIAN, ALLOTTEE OR TRIBE NAME:				
	sals to drill new wells, significantly deep ugged wells, or to drill horizontal laterals			7.UNIT or CA AGREEMENT NAME:				
1. TYPE OF WELL Oil Well				8. WELL NAME and NUMBER: ROUGH CANYON FED 30-1				
2. NAME OF OPERATOR: WOLVERINE OPERATING COM	PANY OF UTAH, LLC			9. API NUMBER: 43039500030000				
3. ADDRESS OF OPERATOR: One Riverfront Plaza 55 Camp	Ploau NW, Grand Rapids, MI, 49503	HONE N	UMBER: 616 458-1150 Ext	9. FIELD and POOL or WILDCAT: WILDCAT				
4. LOCATION OF WELL FOOTAGES AT SURFACE: 0288 FNL 0452 FWL	TO DANCE MEDITION			COUNTY: SANPETE				
QTR/QTR, SECTION, TOWNSHI Qtr/Qtr: NWNW Section: 3.	2 Township: 17.0S Range: 01.0E Meridia	an: S		STATE: UTAH				
11. CHE	CK APPROPRIATE BOXES TO INDIC	CATE N	ATURE OF NOTICE, REPORT,	OR OTHER DATA				
TYPE OF SUBMISSION			TYPE OF ACTION					
	☐ ACIDIZE		ALTER CASING	CASING REPAIR				
NOTICE OF INTENT Approximate date work will start:	☐ CHANGE TO PREVIOUS PLANS		CHANGE TUBING	☐ CHANGE WELL NAME				
	CHANGE WELL STATUS		COMMINGLE PRODUCING FORMATIONS	CONVERT WELL TYPE				
SUBSEQUENT REPORT Date of Work Completion:	DEEPEN		FRACTURE TREAT	☐ NEW CONSTRUCTION				
	OPERATOR CHANGE		PLUG AND ABANDON	☐ PLUG BACK				
SPUD REPORT Date of Spud:	PRODUCTION START OR RESUME		RECLAMATION OF WELL SITE	☐ RECOMPLETE DIFFERENT FORMATION				
	☐ TUBING REPAIR		SIDETRACK TO REPAIR WELL VENT OR FLARE	☐ TEMPORARY ABANDON ☐ WATER DISPOSAL				
✓ DRILLING REPORT	WATER SHUTOFF	_	VENT OR FLARE SI TA STATUS EXTENSION	APD EXTENSION				
Report Date: 12/1/2010	WILDCAT WELL DETERMINATION	_	OTHER	OTHER:				
12 PEGGPTPE PROPOSED OF SO			-	<u> </u>				
12. DESCRIBE PROPOSED OR COMPLETED OPERATIONS. Clearly show all pertinent details including dates, depths, volumes, etc. Please see attached drilling summary for details.								
		,		Accepted by the				
			ι	Jtah Division of				
				, Gas and Mining				
			FOF	RECORDONLY				
NAME (PLEASE PRINT) Helene Bardolph	PHONE NUMBE	ER	TITLE	istant				
SIGNATURE	616 458-1150		Engineering Administrative Assistant DATE					
N/A			12/1/2010					

August/September 2010 Drilling Update

Wolverine Operating Company of Utah, LLC Rough Canyon Federal 30-1 API #43039500030000 NWNW, Section 32, T17S, R1E Sevier County, Utah

1 November 2010

Depth 2861' GL, 22" x $\frac{1}{2}$ " wall @ 1421' GL. Drill to 2861, TFNB. MW - 8.8, Vis. - 50, FL - 10.4. Surveys: none.

2 November 2010

Depth 2898' GL, 22" x $\frac{1}{2}$ " wall @ 1421' GL. GIH, wash & ream to bottom, drill. MW - 8.8, Vis. - 56, FL - 13.6. Surveys: none.

3 November 2010

Depth 2912' GL, 22" x $\frac{1}{2}$ " wall @ 1421' GL. Drill & survey, POOH looking for leaks in drill string. MW -8.8, Vis. -56, FL -13.6. Surveys: 6° @ 2862.

4 November 2010

Depth 2912' GL, 22" x ½" wall @ 1421' GL. POOH, change bit, GIH, attempt to circulate on bottom, plugged string, POOH. MW – 8.8, Vis. – 56, FL – 13.6. Surveys: none.

5 November 2010

Depth 2959' GL, 22" x $\frac{1}{2}$ " wall @ 1421' GL. POOH, GIH building stands, drilling. MW – 8.7, Vis. – 55, FL – 11.2. Surveys: none.

6 November 2010

Depth 3049' GL, 22" x $\frac{1}{2}$ " wall @ 1421' GL. Drill & survey. MW - 8.9, Vis. - 55, FL - 8.4. Surveys: 6° @ 2920'.

7 November 2010

Depth 3102 GL, 22" x ½" wall @ 1421' GL. Drill & survey, POOH. MW – 8.9, Vis. – 57, FL – 12. Surveys: 5¼° @ 3000'.

8 November 2010

Depth 3123 GL, 22" x $\frac{1}{2}$ " wall @ 1421' GL. POOH for new bit, GIH, drill & survey. MW – 8.9, Vis. – 55, FL – 8.2. Surveys: 6° @ 3070'.

9 November 2010

Depth 3220' DF, 22" x $\frac{1}{2}$ " wall @ 1421' GL. Drill & survey. MW - 9, Vis. - 58, FL - 10. Surveys: 5° @ 3145'.

10 November 2010

Depth 3318' DF, 22" x $\frac{1}{2}$ " wall @ 1421' GL. Drill & survey. MW -9, Vis. -58, FL -10.5. Surveys: none.

11 November 2010

Depth 3329' DF, 22" x ½" wall @ 1421' GL. Drill & survey, POOH, change bit, GIH. MW – 9, Vis. – 58, FL – 10.5. Surveys: 5¾° @ 3245'.

12 November 2010

Depth 3351' DF, 22" x ½" wall @ 1421' GL. GIH, drill. MW – 9, Vis. – 60, FL – 9. Surveys: none.

13 November 2010

Depth 3353' DF, 22" x $\frac{1}{2}$ " wall @ 1421' GL. Drill, TFNB, drill. MW - 8.9, Vis. - 57, FL - 9. Surveys: none.

14 November 2010

Depth 3385' DF, 22" x $\frac{1}{2}$ " wall @ 1421' GL. Drill & survey. MW - 8.9, Vis. - 58, FL - 9. Surveys: $5\frac{3}{4}$ ° @ 3317'.

15 November 2010

Depth 3449' DF, 22" x ½" wall @ 1421' GL. Drill. MW -9, Vis. - 56, FL - 8. Surveys: 6° @ 3070'.

16 November 2010

Depth 3457' DF, 22" x ½" wall @ 1421' GL. Drill & survey, TFNB. MW – 9, Vis. – 57, FL – 8. Surveys: 7° @ 3384'.

17 November 2010

Depth 3472' DF, 22" x $\frac{1}{2}$ " wall @ 1421' GL. GIH, drill. MW - 9.1, Vis. - 56, FL - 9.2. Surveys: none.

18 November 2010

Depth 3512' DF, 22" x ½" wall @ 1421' GL. Drill & survey, POOH. MW – 9, Vis. – 55, FL – 8. Surveys: 6¼° @ 3450'.

19 November 2010

Depth 3545' DF, 22" x ½" wall @ 1421' GL. TFNB, drill. MW – 9.1, Vis. – 48, FL – 9.2. Surveys: none.

20 November 2010

Depth 3617' DF, 22" x $\frac{1}{2}$ " wall @ 1421' GL. Drill & survey. MW – 8.9, Vis. – 56, FL – 9.5. Surveys: 6 $\frac{1}{2}$ ° @ 3511'.

21 November 2010

Depth 3690' DF, 22" x ½" wall @ 1421' GL. Drill & survey. MW – 8.9, Vis. – 55, FL – 9.6. Surveys: 6½° @ 3571'.

22 November 2010

Depth 3710' DF, 22" x ½" wall @ 1421' GL. Drill, POOH. MW -8.9, Vis. -56, FL -10.2. Surveys: $6\frac{1}{4}$ ° @ 3647'.

23 November 2010

Depth 3711' DF, 22" x $\frac{1}{2}$ " wall @ 1421' GL. GIH, C&C, wash to bottom, C&C, POOH. MW – 8.9, Vis. – 56, FL – 10.2. Surveys: none.

24 November 2010

Depth 3733' DF, 22" x $\frac{1}{2}$ " wall @ 1421' GL. POOH, PU BHA, GIH, circ & wash to bottom, drill. MW -8.8, Vis. -58, FL -10.8. Surveys: none.

25 November 2010

Depth 3807' DF, 22" x $\frac{1}{2}$ " wall @ 1421' GL. Drill & survey, stuck pipe, work free, POOH 100', wash to bottom. MW - 8.8, Vis. - 58, FL - 10.8. Surveys: none.

26 November 2010

Depth 3829' DF, 22" x $\frac{1}{2}$ " wall @ 1421' GL. Wash to bottom, drill & survey, stuck pipe, work free, POOH. MW - 8.8, Vis. - 60, FL - 12.8. Surveys: 6° @ 3720'.

27 November 2010

Depth 3829' DF, 22" x $\frac{1}{2}$ " wall @ 1421' GL. GIH, mix & pump mud. MW -9.8, Vis. -65, FL - not measured. Surveys: none.

28 November 2010

Depth 3829' DF, 22" x $\frac{1}{2}$ " wall @ 1421' GL. Build mud weight, GIH, wash to 3698', pull up to 3644', C&C. MW - 9.5, Vis. - 64, FL - 12. Surveys: none.

29 November 2010

Depth 3829' DF, 22" x ½" wall @ 1421' GL. C&C, build mud weight, wash to 3814. MW –10, Vis. – 75, FL – 12. Surveys: none.

30 November 2010

Depth 3829' DF, 22" x ½" walls @1421' GL. Wash to 3826', Bit stuck, unplugged, circulate and condition mud. MW 10.10, Vis. 67, FL – Not reported. Surveys: none

Carol Daniels - Rough Canyon Federal 30-1 Update TIPS ROLE 5-32 43-039-50003

From:

"Bill Donovan"

To:

"Allen, Geoff", "'Arthurs, Shane'", "'Blair, Richard'", "'Brock Pope ", "'Chamberlain, Don'", "'Childers, Eli'", "'Chris Schaugaard'", "'Daniel Jenkins'", "'Daniels, Carol'", "'Denton, Derek'", "'Dieste, Bobby'", "'Foreman, Ron'", "'George Zamantakis "', "'Hall, Denise'", "'Harry Melnikoff", "'Hendricks, Marvin'", "'Hutcinson, Clayton'", "'Jeff Ainge'", "'Jim Barry'", "'Jimmy Germon'", "'Jones, Mark'", "Kenneth Schultz Jr", "'Kent Donner'", "'Kulow, Kyle'", "'Kyle Cox'", "'Lewis, John'", "'McCoy, Charlene'", "'McCoy, Tim'", "'Nilles, Chris'", "'O'Connell, David'", "'Perry, Bud (Smith Bits)'", "'Pickup, Marc'", "'Dieste, Marc'', "'Dies

"'Revert, Scott'", "'Robinson, Darin'", "'Ryan Thomas'", "'Shawn Moulton'", "'Shelton,

Shorty'", , "'Steffen, Dana'", "'Tujillo, Chris'", "'Tyler Ross'", "'Winkler, Matt'",

"'Zimmerman, Bill'"

Date:

12/24/2010 6:57 PM

Subject: Rough Canyon Federal 30-1 Update

12/24/2010 6:54 PM

Drilling 12 1/4" hole at 4,098'

Next casing point has not been determined

Bill Donovan
Wolverine Operating Company of Utah, LLC
Rough Canyon Federal 30-1
AFE 224 API 43-039-50003-00-00
Rig (970) 361-3276
boart@drillmail.net
Cell (720) 351-7470
donovan@petroleum-eng.com

RECEIVED DEC 2 7 2010

CONFIDENTIAL

Carol Daniels - Rough Canyon Federal 30-1 Update TINS ROLE 5-32 43-039-50003

From: "Bill Donovan"

"'Allen, Geoff", "'Arthurs, Shane'", "'Blair, Richard'", "'Brock Pope ", "'Chamberlain, To:

Don'", "'Childers, Eli'", "'Chris Schaugaard'", "'Daniel Jenkins'", "'Daniels, Carol'", "Denton, Derek", "Dieste, Bobby", "Foreman, Ron", "George Zamantakis", "Hall, Denise", "'Harry Melnikoff", "'Hendricks, Marvin'", "Howard, Art", "'Hutcinson,

Clayton'", "'Jeff Ainge'", "'Jim Barry'", "'Jimmy Germon'", "'Jones, Mark'", "Kenneth Schultz Jr", "'Kent Donner'", "'Kulow, Kyle'", "'Kyle Cox'", "Levi Smuin", "Levi Smuin",

"Lewis, John'", "'McCoy, Charlene'", "'McCoy, Tim'", "'Nilles, Chris'", "'O'Connell, David", "'Perry, Bud (Smith Bits)", "'Pickup, Marc'", "'Revert, Scott'", "'Robinson, Darin'", "'Ryan Thomas'", "'Shawn Moulton'", "'Shelton, Shorty'", , "'Steffen, Dana'",

"'Tujillo, Chris'", "'Tyler Ross'", "'Winkler, Matt'", "'Zimmerman, Bill'"

Date: 12/25/2010 4:19 PM

Subject: Rough Canyon Federal 30-1 Update

12/25/2010 4:15 PM

Drilling at 4,147'

Casing point has not been determined

Bill Donovan Wolverine Operating Company of Utah, LLC Rough Canyon Federal 30-1 AFE 224 API 43-039-50003-00-00 Rig (970) 361-3276 boart@drillmail.net Cell (720) 351-7470 donovan@petroleum-eng.com

> RECEIVED DEC 2 7 2010

Carol Daniels - Rough Canyon Federal 30-1 Update T175 ROIE 5-32 43-039-50003

From:

"Bill Donovan"

To:

"'Allen, Geoff", "'Arthurs, Shane", "'Blair, Richard", "Bolding, Russell", "'Brock Pope ", "'Chamberlain, Don", "'Childers, Eli", "'Chris Schaugaard", "'Daniel Jenkins", "'Daniels, Carol", "'Denton, Derek", "'Dieste, Bobby", "'Foreman, Ron", "'George Zamantakis ", "'Hall, Denise", "'Harry Melnikoff", "'Hendricks, Marvin'", "Howard, Art", "'Hutcinson, Clayton'", "'Jeff Ainge", "'Jim Barry", "'Jimmy Germon'", "'Jones, Mark'", "Kenneth Schultz Jr", "'Kent Donner'", "'Kulow, Kyle'", "'Kyle Cox'", "Levi Smuin", "Levi Smuin", "'Levi Smuin", "'Lev

"'Lewis, John'", "'McCoy, Charlene'", "'McCoy, Tim'", "'Nilles, Chris'", "'O'Connell, David'", "'Perry, Bud (Smith Bits)'", "'Pickup, Marc'", "'Revert, Scott'", "'Robinson, Darin'", "'Ryan Thomas'", "'Shawn Moulton'", "'Shelton, Shorty'", "'Steffen, Dana'",

"'Tujillo, Chris'", "'Tyler Ross'", "'Winkler, Matt'", "'Zimmerman, Bill'"

Date:

12/26/2010 8:46 PM

Subject: Rough Canyon Federal 30-1 Update

12/26/2010 8:38 PM

Drilling at 4,183'

Casing point has not been determined.

Bill Donovan
Wolverine Operating Company of Utah, LLC
Rough Canyon Federal 30-1
AFE 224 API 43-039-50003-00-00
Rig (970) 361-3276
boart@drillmail.net
Cell (720) 351-7470
donovan@petroleum-eng.com

RECEIVED
DEC 2 7 2010

Carol Daniels - Rough Canyon Federal 30-1 Update 7/15 ROLE 5-32 43-039-5003

From:

"Bill Donovan"

To:

""Allen, Geoff", ""Arthurs, Shane", ""Blair, Richard", "Bolding, Russell", ""Brock Pope", ""Chamberlain, Don", ""Childers, Eli", ""Chris Schaugaard", ""Daniel Jenkins", ""Daniels, Carol", ""Denton, Derek", ""Dieste, Bobby", ""Foreman, Ron", ""George Zamantakis "", ""Hall, Denise", "Harlan Wilkins", ""Harry Melnikoff", ""Hendricks, Marvin", "Howard, Art", ""Hutcinson, Clayton", ""Jeff Ainge", ""Jim Barry", ""Jimmy Germon", ""Jones, Mark", "Kenneth Schultz Jr", ""Kent Donner", ""Kulow, Kyle", ""Kyle Cox", "Levi Smuin", "Levi Smuin", "Lewis, John", ""McCoy, Charlene'", ""McCoy, Tim'", ""Nilles, Chris'", ""O'Connell, David'", ""Perry, Bud (Smith Bits)", ""Pickup, Marc'", ""Revert, Scott'", ""Robinson, Darin", ""Ryan Thomas'", ""Shawn Moulton", ""Shelton, Shorty", ""Steffen, Dana", ""Tujillo, Chris'", ""Tyler Ross'", ""Winkler, Matt'", ""Zimmerman, Bill"

Date:

12/27/2010 6:14 PM

Subject: Rough Canyon Federal 30-1 Update

12/27/2010 6:09 PM

Drilling at 4,267'

The casing point has not been determined.

Bill Donovan
Wolverine Operating Company of Utah, LLC
Rough Canyon Federal 30-1
AFE 224 API 43-039-50003-00-00
Rig (970) 361-3276
boart@drillmail.net
Cell (720) 351-7470
donovan@petroleum-eng.com

RECEIVED
DEC 2 8 2010

Carol Daniels - Rough Canyon Federal 30-1 Update T175 ROLE S-32 43-039-50003

From:

"Bill Donovan"

To:

"'Allen, Geoff", "'Arthurs, Shane'", "'Blair, Richard'", "Bolding, Russell", "'Brock Pope'", "'Chamberlain, Don'", "'Childers, Eli", "'Chris Schaugaard'", "'Daniel Jenkins'", "'Daniels, Carol'", "'Denton, Derek'", "'Dieste, Bobby'", "'Foreman, Ron'", "'George Zamantakis "", "'Hall, Denise'", "Harlan Wilkins", "'Harry Melnikoff", "'Hendricks, Marvin'", "Howard, Art", "'Hutcinson, Clayton'", "'Jeff Ainge'", "'Jim Barry'", "'Jimmy Germon'", "'Jones, Mark'", "Kenneth Schultz Jr", "'Kent Donner'", "'Kulow, Kyle'", "'Kyle Cox'", "Levi Smuin", "Levi Smuin", "'Lewis, John'", "'McCoy, Charlene'", "'McCoy, Tim'", "'Nilles, Chris'", "'O'Connell, David'", "'Perry, Bud (Smith Bits)", "'Pickup, Marc'", "'Revert, Scott'", "'Robinson, Darin'", "'Ryan Thomas'", "'Shawn Moulton'", "'Shelton, Shorty'", "Steffen, Dana", "'Tujillo, Chris", "Tyler Ross", "Willis, Walton", "Willis, Walton" Home", "'Winkler, Matt'", "'Zimmerman, Bill'"

Date:

12/28/2010 7:33 PM

Subject: Rough Canyon Federal 30-1 Update

12/28/2010 7:30 PM

Tripping for a new bit,

The casing point has not been determined.

Bill Donovan Wolverine Operating Company of Utah, LLC Rough Canvon Federal 30-1 AFE 224 API 43-039-50003-00-00 Rig (970) 361-3276 boart@drillmail.net Cell (720) 351-7470 donovan@petroleum-eng.com

> RECEIVED JAN 03 2011

Carol Daniels - Rough Canyon Federal 30-1 Update _ 175 ROIE S-32 43-039-50003

From:

"Bill Donovan"

To:

"'Allen, Geoff", "'Arthurs, Shane'", "'Blair, Richard'", "Bolding, Russell", "'Brock Pope "', "Chamberlain, Don", "Childers, Eli", "Chris Schaugaard", "Daniel Jenkins", "Daniels, Carol'", "'Denton, Derek'", "'Dieste, Bobby'", "'Foreman, Ron'", "'George Zamantakis "", "'Hall, Denise'", "Harlan Wilkins", "'Harry Melnikoff", "'Hendricks, Marvin'", "Howard, Art", "'Hutcinson, Clayton'", "'Jeff Ainge'", "'Jim Barry'", "'Jimmy Germon'", "'Jones, Mark'", "Kenneth Schultz Jr", "'Kent Donner'", "'Kulow, Kyle'", "'Kyle Cox'", "Levi Smuin", "Levi Smuin", "Lewis, John", ""McCoy, Charlene", ""McCoy, Tim", ""Nilles, Chris'", ""O'Connell, David", ""Perry, Bud (Smith Bits)", ""Pickup, Marc'", ""Revert, Scott'", "'Robinson, Darin'", "'Ryan Thomas'", "'Shawn Moulton'", "'Shelton, Shorty'", "'Steffen, Dana'", "'Tujillo, Chris'", "'Tyler Ross'", "Willis, Walton", "Willis, Walton Home", "'Winkler, Matt'", "'Zimmerman, Bill'"

Date:

12/29/2010 7:23 PM

Subject: Rough Canyon Federal 30-1 Update

12/29/2010 7:11 PM

Drilling at 4,350'

Casing point has not been determined.

Over one foot of snow has fallen. If you plan to come to the rig bring chains

Bill Donovan Wolverine Operating Company of Utah, LLC Rough Canyon Federal 30-1 AFE 224 API 43-039-50003-00-00 Rig (970) 361-3276 boart@drillmail.net Cell (720) 351-7470 donovan@petroleum-eng.com

> RECEIVED JAN 0 3 2011

Carol Daniels - Rough Canyon Federal 30-1 Update T125 ROLE 5-32, 43-039-50003

From:

"Bill Donovan"

To:

"'Allen, Geoff", "'Arthurs, Shane'", "'Blair, Richard'", "Bolding, Russell", "'Brock Pope '", "'Chamberlain, Don'", "'Childers, Eli", "'Chris Schaugaard'", "'Daniel Jenkins'", "'Daniels, Carol'", "'Denton, Derek'", "'Dieste, Bobby'", "'Foreman, Ron'", "'George Zamantakis '", "'Hall, Denise'", "Harlan Wilkins", "'Harry Melnikoff", "'Hendricks, Marvin'", "Howard, Art", "'Hutcinson, Clayton'", "'Jeff Ainge'", "'Jim Barry'", "'Jimmy Germon'", "'Jones, Mark'", "Kenneth Schultz Jr", "'Kent Donner'", "'Kulow, Kyle'", "'Kyle Cox'", "Levi Smuin", "Levi Smuin", "Lewis, John'", "'McCoy, Charlene'", "'McCoy, Tim'", "'Nilles, Chris'", "'O'Connell, David'", "'Perry, Bud (Smith Bits)'", "'Pickup, Marc'", "'Revert, Scott'", "'Robinson, Darin'", "'Ryan Thomas'", "'Shawn Moulton'", "'Shelton, Shorty'", "'Steffen, Dana'", "'Tujillo, Chris'", "'Tyler Ross'", "Willis, Walton", "Willis, Walton

Home", "'Winkler, Matt'", "'Zimmerman, Bill'"

Date:

12/30/2010 4:15 PM

Subject: Rough Canyon Federal 30-1 Update

12/30/2010 4:02 PM

Drilling at 4,439'

The casing point had not been determined.

If you plan to come to the rig, you must have chains and expect to use them.

Bill Donovan
Wolverine Operating Company of Utah, LLC
Rough Canyon Federal 30-1
AFE 224 API 43-039-50003-00-00
Rig (970) 361-3276
boart@drillmail.net
Cell (720) 351-7470
donovan@petroleum-eng.com

JAN 0 3 2011

Carol Daniels - Rough Canyon Federal 30-1 Update T175 RolE 5-32 43-039.50003

From: "Bill Donovan"

To: "'Allen, Geoff", "'Arthurs, Shane'", "'Blair, Richard'", "Bolding, Russell", "'Brock Pope '", "'Chamberlain, Don'", "'Childers, Eli'", "'Chris Schaugaard'", "'Daniel Jenkins'", "'Daniels,

"Chamberlain, Don'", "'Childers, Eli", "'Chris Schaugaard'", "'Daniel Jenkins'", "'Daniels Carol'", "'Denton, Derek'", "'Dieste, Bobby'", "'Foreman, Ron'", "'George Zamantakis '", "'Hall, Denise'", "Harlan Wilkins", "'Harry Melnikoff", "'Hendricks, Marvin'", "Howard, Art", "'Hutcinson, Clayton'", "'Jeff Ainge'", "'Jim Barry'", "'Jimmy Germon'", "'Jones, Mark'", "Kenneth Schultz Jr", "'Kent Donner'", "'Kulow, Kyle'", "'Kyle Cox'", "Levi Smuin", "Levi Smuin", "Lewis, John'", "'McCoy, Charlene'", "'McCoy, Tim'", "'Nilles, Chris'", "'O'Connell, David'", "'Perry, Bud (Smith Bits)'", "'Pickup, Marc'", "'Revert, Scott'", "'Robinson, Darin'", "'Ryan Thomas'", "'Shawn Moulton'", "'Shelton, Shorty'", ""Steffen, Dana'", "'Tujillo, Chris'", "'Tyler Ross'", "Willis, Walton", "Willis, Walton

Home", "'Winkler, Matt'", "'Zimmerman, Bill'"

Date: 1/1/2011 6:12 AM

Subject: Rough Canyon Federal 30-1 Update

12/31/2010 10:14 PM

Drilling at 4,540'

Casing point has not been determined.

Bill Donovan
Wolverine Operating Company of Utah, LLC
Rough Canyon Federal 30-1
AFE 224 API 43-039-50003-00-00
Rig (970) 361-3276
boart@drillmail.net
Cell (720) 351-7470
donovan@petroleum-eng.com

RECEIVED
JAN 0 3 2011

Carol Daniels - Rough Canyon Federal 30-1 Update T125 RolE 5-32 43-039-50003

From:

"Bill Donovan"

To:

"'Allen, Geoff", "'Arthurs, Shane'", "'Blair, Richard", "Bolding, Russell", "'Brock Pope ", "'Chamberlain, Don'", "'Childers, Eli", "'Chris Schaugaard", "'Daniel Jenkins'", "'Daniels, Carol'", "'Denton, Derek'", "'Dieste, Bobby", "'Foreman, Ron'", "'George Zamantakis "', "'Hall, Denise'", "Harlan Wilkins", "'Harry Melnikoff", "'Hendricks, Marvin'", "Howard, Art", "'Hutcinson, Clayton'", "'Jeff Ainge'", "'Jim Barry'", "'Jimmy Germon'", "'Jones, Mark'", "Kenneth Schultz Jr", "'Kent Donner'", "'Kulow, Kyle'", "'Kyle Cox'", "Levi Smuin", "Levi Smuin", "Levi Smuin", "Levi Smuin", "'WcCoy, Charlene'", "'McCoy, Tim'", "'Nilles, Chris'", "'O'Connell, David'", "'Perry, Bud (Smith Bits)'", "'Pickup, Marc'", "'Revert, Scott'", "Robinson, Darin'", "'Ryan Thomas'", "'Shawn Moulton'", "'Shelton, Shorty'", ""Steffen, Dana'", "'Tujillo, Chris'", "'Tyler Ross'", "Willis, Walton", "Willis, Walton

Home", "'Winkler, Matt'", "'Zimmerman, Bill'"

Date:

1/1/2011 8:21 PM

Subject: Rough Canyon Federal 30-1 Update

1/1/2011 8:17 PM

Drilling at 4,597', PR 5.3 fph

Casing point has not been determined

Bill Donovan
Wolverine Operating Company of Utah, LLC
Rough Canyon Federal 30-1
AFE 224 API 43-039-50003-00-00
Rig (970) 361-3276
boart@drillmail.net
Cell (720) 351-7470
donovan@petroleum-eng.com

RECEIVED
JAN 0 3 2011

DIV. OF OIL GAS & PROMOTE

Carol Daniels - Rough Canyon Federal 30-1 Update

T125 ROLE 5-32

From:

"Bill Donovan"

To:

"'Allen, Geoff", "'Arthurs, Shane'", "'Blair, Richard'", "Bolding, Russell", "'Brock Pope'", "'Chamberlain, Don'", "'Childers, Eli", "'Chris Schaugaard'", "'Daniel Jenkins'", "'Daniels, Carol'", "'Denton, Derek'", "'Dieste, Bobby'", "'Foreman, Ron'", "'George Zamantakis '", "'Hall, Denise'", "Harlan Wilkins", "'Harry Melnikoff", "'Hendricks, Marvin'", "Howard, Art", "'Hutcinson, Clayton'", "'Jeff Ainge'", "'Jim Barry'", "'Jimmy Germon'", "'Jones, Mark'", "Kenneth Schultz Jr", "'Kent Donner'", "'Kulow, Kyle'", "'Kyle Cox'", "Levi Smuin", "Levi Smuin", "'Lewis, John'", "'McCoy, Charlene'", "'McCoy, Tim'", "'Nilles, Chris'", "'O'Connell, David'", "'Perry, Bud (Smith Bits)", "'Pickup, Marc'", "'Revert, Scott'", "'Robinson, Darin'", "'Ryan Thomas'", "'Shawn Moulton'", "'Shelton, Shorty'", "Steffen, Dana", "'Tujillo, Chris'", "'Tyler Ross'", "Willis, Walton", "Willis, Walton Home", "'Winkler, Matt'", "'Zimmerman, Bill'"

Date:

1/3/2011 5:15 AM

Subject: Rough Canyon Federal 30-1 Update

1/3/2011 5:08 AM

Washing and reaming to bottom after trip for new bit. Hole depth 4,627'

Bill Donovan Wolverine Operating Company of Utah, LLC Rough Canyon Federal 30-1 AFE 224 API 43-039-50003-00-00 Rig (970) 361-3276 boart@drillmail.net Cell (720) 351-7470 donovan@petroleum-eng.com

> RECEIVED JAN 03 2011

CONFIDENTIAL

Carol Daniels - Rough Canyon Federal 30-1 Update 7 175 R OLE 5-32 43-037-50003

From: "I

"Bill Donovan"

To:

"Allen, Geoff", "'Arthurs, Shane'", "'Blair, Richard'", "Bolding, Russell", "'Brock Pope "', "'Chamberlain, Don'", "'Childers, Eli'", "'Chris Schaugaard'", "'Daniel Jenkins'", "'Daniels, Carol'", "'Denton, Derek'", "'Dieste, Bobby", "'Foreman, Ron'", "'George Zamantakis '", "'Hall, Denise'", "Harlan Wilkins", "'Harry Melnikoff", "'Hendricks, Marvin'", "Howard, Art", "'Hutcinson, Clayton'", "'Jeff Ainge'", "'Jim Barry'", "'Jimmy Germon'", "'Jones, Mark'", "Kenneth Schultz Jr", "'Kent Donner'", "'Kulow, Kyle'", "'Kyle Cox'", "Levi Smuin", "Levi Smuin", "Lewis, John'", "'McCoy, Charlene'", "'McCoy, Tim'", "'Nilles, Chris'", "'O'Connell, David'", "'Perry, Bud (Smith Bits)'", "'Pickup, Marc'", "'Revert, Scott'", "'Robinson, Darin'", "'Ryan Thomas'", "'Shawn Moulton'", "'Shelton, Shorty'", ""Steffen, Dana'", "'Tujillo, Chris'", "'Tyler Ross'", "Willis, Walton", "Willis, Walton

Home", "'Winkler, Matt'", "'Zimmerman, Bill'"

Date:

1/4/2011 5:42 AM

Subject: Rough Canyon Federal 30-1 Update

1/4/2011 5:27 AM

Drilling at 4,705'

Casing point has not been determined.

Bill Donovan
Wolverine Operating Company of Utah, LLC
Rough Canyon Federal 30-1
AFE 224 API 43-039-50003-00-00
Rig (970) 361-3276
boart@drillmail.net
Cell (720) 351-7470
donovan@petroleum-eng.com

RECEIVED
JAN 0 4 2011

Carol Daniels - Rough Canyon Federal 30-1 Update T175 RolE 5-32 43-039-50003

From:

"Bill Donovan"

To:

"'Allen, Geoff", "'Arthurs, Shane'", "'Blair, Richard'", "Bolding, Russell", "'Brock Pope "', "'Chamberlain, Don'", "'Childers, Eli'", "'Chris Schaugaard'", "'Daniel Jenkins'", "'Daniels, Carol'", "'Denton, Derek'", "'Dieste, Bobby", "'Foreman, Ron'", "'George Zamantakis "', "'Hall, Denise'", "Harlan Wilkins", "'Harry Melnikoff", "'Hendricks, Marvin'", "Howard, Art", "'Hutcinson, Clayton'", "'Jeff Ainge'", "'Jim Barry'", "'Jimmy Germon'", "'Jones, Mark'", "Kenneth Schultz Jr", "'Kent Donner'", "'Kulow, Kyle'", "'Kyle Cox'", "Levi Smuin", "Levi Smuin", "Lewis, John'", "'McCoy, Charlene'", "'McCoy, Tim'", "'Nilles, Chris'", "'O'Connell, David'", "'Perry, Bud (Smith Bits)'", "'Pickup, Marc'", "'Revert, Scott'", "'Robinson, Darin'", "'Ryan Thomas'", "'Shawn Moulton'", "'Shelton, Shorty'", ""Steffen, Dana'", "'Tujillo, Chris'", "'Tyler Ross'", "Willis, Walton", "Willis, Walton

Home", "'Winkler, Matt'", "'Zimmerman, Bill'"

Date:

1/5/2011 5:34 AM

Subject: Rough Canyon Federal 30-1 Update

1/5/2011 5:11 AM

Drilling at 4,782', PR 4.2 fph

Casing point has not been determined

Bill Donovan
Wolverine Operating Company of Utah, LLC
Rough Canyon Federal 30-1
AFE 224 API 43-039-50003-00-00
Rig (970) 361-3276
boart@drillmail.net
Cell (720) 351-7470
donovan@petroleum-eng.com

RECEIVED
JAN 0 5 2011

Form 3160-5 (September 2001)

UNITED STATES DEPARTMENT OF THE INTERIOR

RECEIV

JAN 1 0 2011

FORM APPROVED OMB No. 1004-0135 Expires January 31, 2004

DUKEAU (M. CHIAD MAMAGRIMEN	TA CONTRACTOR
		DIV OF UIL GAS 6. **
SUNDRY NOTICE	S AND REPORTS O	N WELL OF OIL, GAS &
	1 / 1 111	

5. Lease Serial No. UTU-82536

abandoned we	N/A								
SUBMIT IN TR	IPLICATE - Other instr	ructions on I	everse sid	e	7. If Unit or	CA/Agreemer	nt, Name and/or No.	_	
1. Type of Well	3								
Oil Well Gas Well		8. Well Name and No. Rough Canyon Federal 30-1							
 Name of Operator Wolverine Operating Com 	noany of Utah, LLC				9. API Well No.				
3a. Address	.pu,	3b. Phone N	o. (include area	code)	43039500				
55 Campau NW, Grand R	apids, MI 49503	616-		,	10. Field and Pool, or Exploratory Area				
4. Location of Well (Footage, Sec.		on)			Exploratory				
288' FNL, 452' FWL, Sec 32, T17S, R1E (NW4/NW4)				11. County or Parish, Sta					
			•		Sanpete				
12. CHECK AP	PROPRIATE BOX(ES) T	O INDICATE	NATURE (OF NOTICE, R	EPORT, OR	OTHER D.	ATA		
TYPE OF SUBMISSION			TYPE C	OF ACTION					
	☐ Acidize	Deepen		Production (Start	/Resume)	☐ Water Sh	ut-Off		
☐ Notice of Intent	☐ Alter Casing	☐ Fracture T	reat \Box	Reclamation		☐ Well Inte	grity		
☑ Subsequent Report	Casing Repair	☐ New Cons	truction - 🗆	Recomplete		Other _		_	
Subsequent Report	✓ Change Plans	Plug and A	Abandon 🗆	Temporarily Ab	andon				
☐ Final Abandonment Notice	Convert to Injection	Plug Back		Water Disposal					
following completion of the invitesting has been completed. Findetermined that the site is ready Wolverine Operating Communications with 1451 sacks of 14.4 pto complete the cementing chloride. 2. Surface Casing: 9-5/8" to surface, and on to which to surface using approximation placed at 3500' so cementing chloride.	nal Abandonment Notices shall for final inspection.) apany of Utah LLC, Rouse pany of Utah, LLC is dreen made to the approve of: Originally 13-3/8" casts string was set as a copp. 1.05 cf/sk ,Schlumb g to surface in seven lift for the wellhead spool with the wellhead spool with the wellhead spool with the string to surface in section of Science in seven lift for the wellhead spool with the wellhead spool with the wellhead spool with the well head spool with the wellhead spool with	gh Canyon F illing the Rou d APD. sing was to b conductor strin erger TXI Ble s using a total proposed as s ill be welded hlumberger T	ederal 30-1 gh Canyon e set in the g at 3770' i end for a TC al of 3513 cf surface casi for placeme	Federal 30-1 Arapien as sun the North Ho OC of approxin f (~2977 sacks	and becaus urface casing orn/Indianolo nately 2710' s) of 15.3 to the set into the	g. However a and cem '. A tremie 15.6 ppg	conditions er, because of the to surface pipe was used + 1% calcium and cemented will be cemented will be cemented to the comented to the comented t	ee i	
14. I hereby certify that the foregoin	ng is true and correct		1			Date:	1.25.20	Ī1	
Name (Printed/Typed)			Title Mana	ger of Develop	oment		VS	•	
Edward A. Higuera	//		1 tue	9		Initials:		iji -	
Signature			Date 01/04	/2011					
D :::	THIS SPACE	FOR FEDERA	AL OR STAT	E OFFICE USE					
Approved by	VII		Title	ret_Eng.		aie '	20/2011		
Conditions of appreval, if any, are certify that the applicant holds legs which would entitle the applicant to	al or equitable title to those rig	tice does not wan ghts in the subjec	rant or t lease Office	Dogun	Federa	al Approval	Of This ssan		

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Action Is Necessan



WOLVERINE GAS AND OIL COMPANY

OF UTAH, LLC

Energy Exploration in Partnership with the Environment

January 4, 2011

Mr. Stan Andersen Fluid Minerals Group, BLM Richfield Field Office 150 East 900 North Richfield, UT 84701 JAN 1 0 2011
DIV. OF OIL, GAS & MINING

Re: Rough Canyon Federal 30-1

Dear Mr. Anderson,

Enclosed are one original and two copies of the following sundry: Rough Canyon Federal 30-1, Change of Plans

Please let me know if you have any questions or concerns regarding the above mentioned document.

Please consider this our official request to keep the enclosed document confidential.

Sincerely,

Helene Bardolph

Engineering Administrative Assistant

Enclosures

cc: Mr. John Rogers, UDOGM

CONFIDENTIAL

Carol Daniels - Rough Canyon Federal 30-1 Update T175 ROLE 5-30 43-637.50003

From:

"Bill Donovan"

To:

""Allen, Geoff", "'Arthurs, Shane'", "'Blair, Richard'", "Bolding, Russell", "'Brock Pope "', "'Chamberlain, Don'", "'Childers, Eli", "'Chris Schaugaard'", "'Daniel Jenkins'", "'Daniels, Carol'", "'Denton, Derek'", "'Dieste, Bobby", "'Foreman, Ron'", "'George Zamantakis '", "'Hall, Denise'", "Harlan Wilkins", "'Harry Melnikoff", "'Hendricks, Marvin'", "Howard, Art", "'Hutcinson, Clayton'", "'Jeff Ainge'", "'Jim Barry'", "'Jimmy Germon'", "'Jones, Mark'", "Kenneth Schultz Jr", "'Kent Donner'", "'Kulow, Kyle'", "'Kyle Cox'", "Levi Smuin", "Levi Smuin", "Lewis, John'", "'McCoy, Charlene'", "'McCoy, Tim'", "'Nilles, Chris'", "'O'Connell, David'", "'Perry, Bud (Smith Bits)'", "'Pickup, Marc'", "'Revert, Scott'", "'Robinson, Darin'", "'Ryan Thomas'", "'Shawn Moulton'", "'Shelton, Shorty'", ""Steffen, Dana'", "'Tujillo, Chris'", "'Tyler Ross'", "Willis, Walton", "Willis, Walton

Home", "'Winkler, Matt'", "'Zimmerman, Bill'"

Date:

1/11/2011 10:11 PM

Subject:

Rough Canyon Federal 30-1 Update

CC:

"Jack Magill"

1/11/2011 10:10 PM

Trip for new bit

Bill Donovan
Wolverine Operating Company of Utah, LLC
Rough Canyon Federal 30-1
AFE 224 API 43-039-50003-00-00
Rig (970) 361-3276
boart@drillmail.net
Cell (720) 351-7470
donovan@petroleum-eng.com

RECEIVED
JAN 1 2 2011

CONFIDENTIAL

Carol Daniels - Rough Canyon Federal 30-1 Update TIPS ROLE 5-32 43-039-50003

From:

"Jack Magill"

To:

""Allen, Geoff", ""Arthurs, Shane", ""Blair, Richard", ""Bolding, Russell", ""Brock Pope "", ""Chamberlain, Don", ""Childers, Eli", ""Chris Schaugaard", ""Daniel Jenkins", ""Daniels, Carol", ""Denton, Derek", ""Dieste, Bobby", ""Foreman, Ron", ""George Zamantakis "", ""Hall, Denise", ""Harlan Wilkins", ""Harry Melnikoff", ""Hendricks, Marvin'", ""Howard, Art", ""Hutcinson, Clayton'", ""Jeff Ainge", ""Jim Barry", ""Jimmy Germon'", ""Jones, Mark", ""Kenneth Schultz Jr", ""Kent Donner", ""Kulow, Kyle", ""Kyle Cox", ""Levi Smuin", ""Levi Smuin", ""Lewis, John", ""McCoy, Charlene", ""McCoy, Tim", ""Nilles, Chris", ""O'Connell, David", ""Perry, Bud (Smith Bits)", ""Pickup, Marc", ""Revert, Scott'", ""Robinson, Darin", ""Ryan Thomas", ""Shawn Moulton'", ""Shelton, Shorty", , ""Steffen, Dana'", ""Tujillo, Chris", ""Tyler Ross", ""Willis, Walton'", ""Willis, Walton Home'", ""Winkler, Matt", ""Zimmerman, Bill",

Date:

1/13/2011 4:50 AM

Subject: Rough Canyon Federal 30-1 Update

1/13/11 4:44 AM

Drilling at 5240'

Jack Magill
Wolverine Operating Company of Utah, LLC
Rough Canyon Federal 30-1
AFE 224 API 43-039-50003-00-00
Rig (970) 361-3276
boart@drillmail.net

JAN 1 3 2011

Carol Daniels - Rough Canyon Federal 30-1 Update TIZS ROIE 5-32 4303950003

From:

"Jack Magill"

To:

Jenkins", "Daniels, Carol", "Denton, Derek", "Dieste, Bobby", "Foreman, Kon", "George Zamantakis", "Hall, Denise", "Harlan Wilkins", "Harry Melnikoff", "Hendricks, Marvin", "Howard, Art", "Hutcinson, Clayton", "Jeff Ainge", "Jim Barry", "Jimmy Germon", "Jones, Mark", "Kenneth Schultz Jr", "Kent Donner", "Kulow, Kyle", "Kyle Cox", "Levi Smuin", "Levi Smuin", "Lewis, John", "McCoy, Charlene", "McCoy, Tim", "Nilles, Chris", "O'Connell, David", "Perry, Bud (Smith Bits)", "Pickup, Marc", "Revert, Scott", "Robinson, Darin", "Ryan Thomas", "Shawn Moulton", "Shelton Shorty", "Steffen Dana", "Tuiillo Chris", "Tyler Ross"

Moulton'", "'Shelton, Shorty'", "'Steffen, Dana'", "'Tujillo, Chris'", "'Tyler Ross'", "'Willis, Walton'", "'Willis, Walton Home'", "'Winkler, Matt'", "'Zimmerman, Bill'",

Date:

1/13/2011 9:04 PM

Subject: Rough Canyon Federal 30-1 Update

Drilling at 5293'.

Jack Magill Wolverine Operating Company of Utah, LLC Rough Canyon Federal 30-1 Rig (970) 361-3276

RECEIVED
JAN 1 9 2011



Carol Daniels - Rough Canyon Federal 30-1 Update TIAS ROLE 5-32 43-039-5000 3

From:

"Jack Magill"

To:

"'Allen, Geoff", "'Arthurs, Shane", "'Blair, Richard", "'Bolding, Russell", "'Brock Pope ", "'Chamberlain, Don'", "'Childers, Eli", "'Chris Schaugaard", "'Daniel Jenkins'", "'Daniels, Carol", "'Denton, Derek'", "'Dieste, Bobby'", "'Foreman, Ron'", "'George Zamantakis '", "'Hall, Denise", "'Harlan Wilkins'", "'Harry Melnikoff", "'Hendricks, Marvin'", "'Howard, Art'", "'Hutcinson, Clayton'", "'Jeff Ainge'", "'Jim Barry'", "'Jimmy Germon'", "'Jones, Mark'", "'Kenneth Schultz Jr'", "'Kent Donner'", "'Kulow, Kyle'", "'Kyle Cox'", "'Levi Smuin'", "'Levi Smuin'", "'Lewis, John'", "'McCoy, Charlene'", "'McCoy, Tim'", "'Nilles, Chris'", "'O'Connell, David'", "'Perry, Bud (Smith Bits)'", "'Pickup, Marc'", "'Revert, Scott'", "'Robinson, Darin'", "'Ryan Thomas'", "'Shawn Moulton'", "'Shelton, Shorty'", "'Steffen, Dana'", "'Tujillo, Chris'", "'Tyler Ross'",

"Willis, Walton", "Willis, Walton Home", "Winkler, Matt", "Zimmerman, Bill",

Date:


1/14/2011 4:40 PM

Subject: Rough Canyon Federal 30-1 Update

Drilling ahead at 5362'

Jack Magill Wolverine Rough Canyon Federal 30-1 970.361.3276

JAN 1 9 2011



Carol Daniels - Wolverine Rough Canyon Federal 30-1 Update 7/15 RolE 5-31 43-03950003

From:

"Jack Magill"

To:

"'Allen, Geoff", "'Arthurs, Shane'", "'Blair, Richard'", "'Bolding, Russell'", "'Brock Pope

"", ""Chamberlain, Don'", ""Childers, Eli"", ""Chris Schaugaard"", ""Daniel Jenkins"", ""Daniels, Carol"", ""Denton, Derek"", ""Dieste, Bobby"", ""Foreman, Ron'", ""George Zamantakis", ""Hall, Denise", ""Harlan Wilkins", ""Harry Melnikoff", ""Hendricks, Marvin", ""Howard, Art", ""Hutcinson, Clayton", ""Jeff Ainge", ""Jim Barry", ""Jimmy Germon'", ""Jones, Mark", ""Kenneth Schultz Jr"", ""Kent Donner", ""Kulow, Kyle", ""Kyle Cox", ""Levi Smuin", ""Levi Smuin", ""Lewis, John'", ""McCoy, Charlene", ""McCoy, Tim'", ""Nilles, Chris'", ""O'Connell, David", ""Perry, Bud (Smith Bits)", ""Pickup, Marc'", ""Revert, Scott'", ""Robinson, Darin'", ""Ryan Thomas'", ""Shawn Moulton'", ""Shelton, Shorty'", ""Steffen, Dana'", ""Tujillo, Chris'", ""Tyler Ross'", ""Willis, Walton'", ""Willis, Walton Home", ""Winkler, Matt", ""Zimmerman, Bill""

Date:

1/17/2011 4:48 PM

Subject: Wolverine Rough Canyon Federal 30-1 Update

Drilled to 5550', TOH, bit at 420'.

1/17/2011 4:45 PM

Jack Magill
Wolverine Operating Company of Utah, LLC
Rough Canyon Federal 30-1
AFE 224 API 43-039-50003-00-00
Rig (970) 361-3276
boart@drillmail.net

No virus found in this message. Checked by AVG - www.avg.com

Version: 10.0.1191 / Virus Database: 1435/3374 - Release Date: 01/11/11

RECEIVED

JAN 1 9 2011

Carol Daniels - Wolverine Rough Canyon Federal 30-1 Update 7/15 RolE S- 32 43 0395 0003

From:

"Jack Magill"

To:

"'Allen, Geoff", "'Arthurs, Shane'", "'Blair, Richard'", "'Bolding, Russell'", "'Brock Pope

"", ""Chamberlain, Don"", ""Childers, Eli"", ""Chris Schaugaard"", ""Daniel Jenkins"", ""Daniels, Carol"", ""Denton, Derek"", ""Dieste, Bobby"", ""Foreman, Ron"", ""George Zamantakis "", ""Hall, Denise"", ""Harlan Wilkins"", ""Harry Melnikoff"", ""Hendricks, Marvin"", ""Howard, Art"", ""Hutcinson, Clayton"", ""Jeff Ainge"", ""Jim Barry"", ""Jimmy Germon"", ""Jones, Mark"", ""Kenneth Schultz Jr"", ""Kent Donner"", ""Kulow, Kyle"", ""Kyle Cox", ""Levi Smuin"", ""Levi Smuin"", ""Lewis, John"", ""McCoy, Charlene"", ""McCoy, Tim"", ""Nilles, Chris'", ""O'Connell, David", ""Perry, Bud (Smith Bits)"", ""Pickup, Marc", ""Revert, Scott", ""Robinson, Darin", ""Ryan Thomas", ""Shawn Moulton", ""Shelton, Shorty", , ""Steffen, Dana", ""Tujillo, Chris", ""Tyler Ross", ""Willis, Walton", ""Willis, Walton Home", ""Winkler, Matt", ""Zimmerman, Bill""

Date:

1/19/2011 7:10 AM

Subject: Wolverine Rough Canyon Federal 30-1 Update

1/19/2011 7:06 AM

Drilling at 5618'

Jack Magill
Wolverine Operating Company of Utah, LLC
Rough Canyon Federal 30-1
Rig (970) 361-3276
boart@drillmail.net

JAN 1 9 2011

Carol Daniels - Rough Canyon Federal 30-1 Update TIPS ROLE 5-32 43-039-50003

From:

"Jack Magill"

To:

"'Allen, Geoff", "'Arthurs, Shane'", "'Bolding, Russell'", "'Chamberlain, Don'", "'Childers,

Eli", "'Chris Schaugaard'", "'Daniel Jenkins'", "'Daniels, Carol'", "'Dieste, Bobby'" "Foreman, Ron", "Hall, Denise", "Harlan Wilkins", "Harry Melnikoff", "Hendricks, Marvin'", "'Howard, Art'", "'Hutcinson, Clayton'", "'Jim Barry'", "'Jimmy Germon'" "Jones, Mark", "Kenneth Schultz Jr", "Kent Donner", "Kyle Cox", "Levi Smuin" "Levi Smuin", "Lewis, John", "McCoy, Charlene", "McCoy, Tim", "Nilles, Chris", "Revert, Scott", "Robinson, Darin", "Ryan Thomas", "Shawn Moulton", "Shelton, Shorty'", "'Steffen, Dana'", "'Tujillo, Chris'", "'Tyler Ross'", "'Willis, Walton'", "'Willis,

Walton Home", "Winkler, Matt'", "Zimmerman, Bill",

Date:

1/21/2011 1:14 PM

Subject: Rough Canyon Federal 30-1 Update

1/21/2011 1:05 PM MST

Drilling at 5789'.

Jack Magill Wolverine Operating Company of Utah, LLC Rough Canyon Federal 30-1 Rig (970) 361-3276

> RECEIVED JAN 2 4 2011

Carol Daniels - Rough Canyon Federal 30-1 Update T175 ROLF 5-32 43-639-50003

From:

"Jack Magill"

To:

"'Jack Magill", "'Allen, Geoff", "'Bolding, Russell", "'Chamberlain, Don'", "'Childers, Eli", "'Chris Schaugaard'", "'Daniel Jenkins'", "'Daniels, Carol'", "'Dieste, Bobby'", "Foreman, Ron", "Hall, Denise", "Harlan Wilkins", "Harry Melnikoff", "Hendricks, Marvin'", "'Howard, Art'", "'Hutcinson, Clayton'", "'Jim Barry'", "'Jimmy Germon'", "'Jones, Mark'", "'Kenneth Schultz Jr", "'Kent Donner'", "'Kyle Cox'", "'Levi Smuin'" "Levi Smuin", "Lewis, John", "McCoy, Charlene", "McCoy, Tim", "Nilles, Chris", "Revert, Scott", "Robinson, Darin", "Ryan Thomas", "Shawn Moulton", "Shelton, Shorty", "Steffen, Dana", "Tujillo, Chris", "Tyler Ross", "Willis, Walton", "Willis,

Walton Home", "Winkler, Matt", "Zimmerman, Bill"

Date:

1/22/2011 6:14 AM

Subject: Rough Canyon Federal 30-1 Update

1/22/2011 6:07 AM MST

Drill to 5846', survey, POOH for new bit.

Jack Magill Wolverine Operating Company of Utah, LLC Rough Canyon Federal 30-1 Rig (970) 361-3276

> RECEIVED JAN 2 4 2011

CONFIDENTIAL

Carol Daniels - Rough Canyon Federal 30-1 Update T175 RolE 5-31 43-039-50003

From:

"Jack Magill"

To:

"'Jack Magill'", "'Allen, Geoff", "'Bolding, Russell'", "'Chamberlain, Don'", "'Childers, Eli'", "'Chris Schaugaard'", "'Daniels, Carol'", "'Dieste, Bobby'", "'Hendricks, Marvin'", "'Howard, Art'", "'Jim Barry'", "'Jones, Mark'", "'Kenneth Schultz Jr'", "'Kent Donner'", "'Kyle Cox'", "'Levi Smuin'", "'Levi Smuin'", "'Lewis, John'", "'McCoy, Charlene'",

"McCoy, Tim'", "'Revert, Scott'", "'Robinson, Darin'", "'Tyler Ross'", "'Willis, Walton'",

"Willis, Walton Home"

Date:

1/23/2011 8:33 PM

Subject: Rough Canyon Federal 30-1 Update

1/23/2011 8:30 PM MST

Drilling at 5854'.

Jack Magill Wolverine Operating Company of Utah, LLC Rough Canyon Federal 30-1 Rig (970) 361-3276

RECEIVED
JAN 2 4 2011

Carol Daniels - Rough Canyon Federal 30-1 Update T115 ROLF 5-32 43-03950003

From:

"Jack Magill"

To:

"'Jack Magill'", "'Allen, Geoff", "'Bolding, Russell'", "'Chamberlain, Don'", "'Childers, Eli'", "'Chris Schaugaard'", "'Daniels, Carol'", "'Dieste, Bobby'", "'Hendricks, Marvin'", "'Howard, Art'", "'Jim Barry'", "'Jones, Mark'", "'Kenneth Schultz Jr'", "'Kent Donner'", "'Kyle Cox'", "'Levi Smuin'", "'Levi Smuin'", "'Lewis, John'", "'McCoy, Charlene'",

"'McCoy, Tim'", "'Revert, Scott'", "'Robinson, Darin'", , "'Willis, Walton'", "'Willis, Walton

Home'"

Date:

1/24/2011 4:24 PM

Subject: Rough Canyon Federal 30-1 Update

1/24/2011 4:22 PM MST

Drilling at 5909'.

Jack Magill Wolverine Operating Company of Utah, LLC Rough Canyon Federal 30-1 Rig (970) 361-3276



RECEIVED JAN 2 4 2011

Carol Daniels - Wolverine Rough Canyon Federal 30-1 Update T125 ROIE 5-32

43-039-5003

From:

"Jack Magill"

To:

"Jack Magill", "'Allen, Geoff", "'Bolding, Russell", "'Chamberlain, Don'", "'Childers, Eli'", "'Chris Schaugaard'", "'Daniels, Carol'", "'Dieste, Bobby'", "'Hendricks, Marvin'", "'Howard, Art'", "'Jim Barry'", "'Jones, Mark'", "'Kenneth Schultz Jr'", "'Kent Donner'", "'Kyle Cox'", "'Levi Smuin'", "'Levi Smuin'", "'Lewis, John'", "'McCoy, Charlene'",

"'McCoy, Tim'", "'Revert, Scott'", "'Robinson, Darin'", "'Willis, Walton'", "'Willis, Walton

Home'", "'Ken Clare'"

Date:

1/26/2011 3:44 PM

Subject: Wolverine Rough Canyon Federal 30-1 Update

1/26/2011 3:40 PM MST

Drilled to 5978, leaks in air string, POOH to turnaround point, GIH looking for air leaks.

Jack Magill Wolverine Operating Company of Utah, LLC Rough Canyon Federal 30-1 Rig (970) 361-3276

> **RECEIVED** JAN 2 6 2011

Carol Daniels - Wolverine Rough Canyon Federal 30-1 Update 7/25 ROIE 5-32 43-03950003

From:

"Jack Magill"

To:

"'Jack Magill'", "'Allen, Geoff", "'Bolding, Russell'", "'Chamberlain, Don'", "'Childers, Eli'", "'Chris Schaugaard'", "'Daniels, Carol'", "'Dieste, Bobby'", "'Hendricks, Marvin'", "'Howard, Art'", "'Jim Barry'", "'Jones, Mark'", "'Kenneth Schultz Jr'", "'Kent Donner'", "'Kyle Cox'", "'Levi Smuin'", "'Levi Smuin'", "'Lewis, John'", "'McCoy, Charlene'",

"'McCoy, Tim'", "'Revert, Scott'", "'Robinson, Darin'", "'Willis, Walton'", "'Willis, Walton

Home'"

Date:

1/25/2011 3:58 PM

Subject: Wolverine Rough Canyon Federal 30-1 Update

1/25/2011 3:54 PM MST

Drilling at 5948'.

Jack Magill Wolverine Operating Company of Utah, LLC Rough Canyon Federal 30-1 Rig (970) 361-3276

JAN 2 6 2011

Carol Daniels - Wolverine Rough Canyon Federal 30-1 Update

TIPS ROLE 5-32 43-039-50003

From:

"ken Clare"

To:

"'Jack Magill'", "'Allen, Geoff", "'Bolding, Russell'", "'Chamberlain, Don'", "'Childers, Eli'", "'Chris Schaugaard'", "'Daniels, Carol'", "'Dieste, Bobby'", "'Hendricks, Marvin'", "'Howard, Art'", "'Jim Barry'", "'Jones, Mark'", "'Kenneth Schultz Jr'", "'Kent Donner'", "'Kyle Cox'", "'Levi Smuin'", "'Levi Smuin'", "'Lewis, John'", "'McCoy, Charlene'",

"McCoy, Tim", "Revert, Scott", "Robinson, Darin", "Willis, Walton", "Willis, Walton"

Home'"

Date:

1/27/2011 3:31 PM

Subject: Wolverine Rough Canyon Federal 30-1 Update

1/27 /2011 3:30 PM MST

Drilling @ 6028'

Ken Clare Wolverine Operating Company of Utah, LLC Rough Canyon Federal 30-1 Rig (970) 361-3276

RECEIVED
JAN 2 7 2011

Carol Daniels - Wolverine Rough Canyon Federal 30-1 Update

T175 ROIW 5-32 43-039-50093

From:

"ken Clare"

To:

"Jack Magill", "'Allen, Geoff", "'Bolding, Russell", "'Chamberlain, Don'", "'Childers, Eli", "'Chris Schaugaard'", "'Daniels, Carol'", "'Dieste, Bobby'", "'Hendricks, Marvin'", "'Howard, Art'", "'Jim Barry'", "'Jones, Mark'", "'Kenneth Schultz Jr'", "'Kent Donner'", "'Kyle Cox'", "'Levi Smuin'", "'Levi Smuin'", "'Lewis, John'", "'McCoy, Charlene'", "'McCoy, Tim'", "'Revert, Scott'", "'Robinson, Darin'", "'Willis, Walton'", "'Willis, Walton'', "'Willis, Walton'', "'Willis, "'Willis, "'Willis, "'Willis,

Home'"

Date:

1/28/2011 3:50 PM

Subject: Wolverine Rough Canyon Federal 30-1 Update

CC:

Drilling @ 6067' Ken Clare Wolverine Operating Company of Utah, LLC Rough Canyon Federal 30-1 Rig (970) 361-3276

> RECEIVED JAN 28 2011

Carol Daniels - RE: Wolverine Rough Canyon Federal 30-1 Update

T115 ROLE 5-32 43-039-5 0003

From:

"ken Clare"

To:

"'Allen, Geoff", "'Bolding, Russell", "'Chamberlain, Don'", "'Childers, Eli'", "'Chris

Schaugaard", "Daniels, Carol", "Dieste, Bobby", "Hendricks, Marvin", "Howard, Art", "Jim Barry", "Jones, Mark", "Kenneth Schultz Jr", "Kent Donner", "Kyle Cox", "Levi Smuin", "Levi Smuin", "Lewis, John", "McCoy, Charlene", "McCoy, Tim", "Revert, Scott", "Robinson, Darin", "Willis, Walton", "Willis, Walton Home",

Date:

1/29/2011 5:06 PM

Subject: RE: Wolverine Rough Canyon Federal 30-1 Update

TOOH, N/U hydrill Ken Clare Wolverine Operating Company of Utah, LLC Rough Canyon Federal 30-1 Rig (970) 361-3276

> RECEIVED JAN 2 9 2011

Carol Daniels - Wolverine Rough Canyon Federal 30-1 Update

T125 ROLES-32 43-039-50003

From:

"ken Clare"

To:

"'Allen, Geoff", "'Bolding, Russell'", "'Chamberlain, Don'", "'Childers, Eli'", "'Chris

Schaugaard", "'Daniels, Carol", "'Dieste, Bobby", "'Hendricks, Marvin'", "'Howard, Art'", "'Jim Barry", "'Jones, Mark'", "'Kenneth Schultz Jr", "'Kent Donner'", "'Kyle Cox'", "'Levi Smuin'", "'Levi Smuin'", "'Lewis, John'", "'McCoy, Charlene'", "'McCoy, Tim'", "'Revert,

Scott'", "'Robinson, Darin'", "'Willis, Walton'", "'Willis, Walton Home'"

Date:

1/30/2011 4:12 PM

Subject: Wolverine Rough Canyon Federal 30-1 Update

Tripping in depth 3954', functioned Hydrill & trained crew on BOP function & drill

From: ken Clare [mailto:boart@drillmail.net] Sent: Saturday, January 29, 2011 5:03 PM

To: 'Allen, Geoff'; 'Bolding, Russell'; 'Chamberlain, Don'; 'Childers, Eli'; 'Chris Schaugaard'; 'Daniels, Carol'; 'Dieste, Bobby'; 'Hendricks, Marvin'; 'Howard, Art'; 'Jim Barry'; 'Jones, Mark'; 'Kenneth Schultz Jr'; 'Kent Donner'; 'Kyle Cox'; 'Levi Smuin'; 'Levi Smuin'; 'Lewis, John'; 'McCoy, Charlene'; 'McCoy, Tim'; 'Revert, Scott'; 'Robinson,

Darin'; Stan_Andersen@blm.gov; 'Willis, Walton'; 'Willis, Walton Home'; boart@drillmail.net

Subject: RE: Wolverine Rough Canyon Federal 30-1 Update

TOOH, N/U hydrill Ken Clare Wolverine Operating Company of Utah, LLC Rough Canyon Federal 30-1 Rig (970) 361-3276

> RECEIVED JAN 3 0 2011

Carol Daniels - Wolverine Rough Canyon Federal 30-1 Update

T175 ROIES-32 43-039-50003

From:

"ken Clare"

To:

"'ken Clare'", "'Allen, Geoff", "'Bolding, Russell'", "'Chamberlain, Don'", "'Childers, Eli'",

"'Chris Schaugaard'", "'Daniels, Carol'", "'Dieste, Bobby'", "'Hendricks, Marvin'", "'Howard, Art'", "'Jim Barry'", "'Jones, Mark'", "'Kenneth Schultz Jr'", "'Kent Donner'", "'Kyle Cox'", "'Levi Smuin'", "'Levi Smuin'", "'Lewis, John'", "'McCoy, Charlene'",

"'McCoy, Tim'", "'Revert, Scott'", "'Robinson, Darin'", , "'Willis, Walton'", "'Willis, Walton

Home'"

Date:

1/31/2011 3:36 PM

Subject: Wolverine Rough Canyon Federal 30-1 Update

Drilling @ 6138' Ken Clare Wolverine Operating Company of Utah, LLC Rough Canyon Federal 30-1 Rig (970) 361-3276

> RECEIVED JAN 3 1 2011

T 125 ROIE 5-32-43-039-50003

CONFIDENTIAL

From:

"ken Clare" <boart@drillmail.net>

To:

"ken Clare" <boart@drillmail.net>, "Allen, Geoff" <geoff.allen@fmcti...

Date:

2/1/2011 3:51 PM

Subject:

Wolverine Rough Canyon Federal 30-1 Update

Drilling @ 6204' Ken Clare

Wolverine Operating Company of Utah, LLC

Rough Canyon Federal 30-1

Rig (970) 361-3276

RECEIVED FEB 0 1 2011

Carol Daniels - Wolverine Rough Canyon Federal 30-1 Update

43-039-50003

From:

"ken Clare"

To:

"'ken Clare'", "'Allen, Geoff", "'Bolding, Russell'", "'Chamberlain, Don'", "'Childers, Eli'",

"Chris Schaugaard", "'Daniels, Carol", "'Dieste, Bobby", "'Hendricks, Marvin'", "'Howard, Art'", "'Jim Barry'", "'Jones, Mark'", "'Kenneth Schultz Jr'", "'Kent Donner'", "'Kyle Cox'", "'Levi Smuin'", "'Levi Smuin'", "'Lewis, John'", "'McCoy, Charlene'",

"'McCoy, Tim'", "'Revert, Scott'", "'Robinson, Darin'", "'Willis, Walton'", "'Willis, Walton

Home'"

Date:

2/2/2011 4:03 PM

Subject: Wolverine Rough Canyon Federal 30-1 Update

Drilling @ 6235 ' Ken Clare Wolverine Operating Company of Utah, LLC Rough Canyon Federal 30-1 Rig (970) 361-3276

> RECEIVED FEB 0 2 2011

TITS ROLE 5-32 43-039-50003

From:

"ken Clare" <boart@drillmail.net>

To:

"ken Clare" <boart@drillmail.net>, "Allen, Geoff" <geoff.allen@fmcti...

Date:

2/3/2011 4:06 PM

Subject:

Wolverine Rough Canyon Federal 30-1 Update

Drilling @ 6304'

Ken Clare

Wolverine Operating Company of Utah, LLC

Rough Canyon Federal 30-1

Rig (970) 361-3276

RECEIVED FEB 0 3 2011

TIRS ROLE 5-32 43-039-5 0003

CONFIDENTIAL

From:

"ken Clare" <boart@drillmail.net>

To:

"ken Clare" <boart@drillmail.net>, "Allen, Geoff" <geoff.allen@fmcti...

Date:

2/4/2011 4:04 PM

Subject:

Wolverine Rough Canyon Federal 30-1 Update

Drilling @ 6365'

100% Conglomoerate

Ken Clare

Wolverine Operating Company of Utah, LLC

Rough Canyon Federal 30-1

Rig (970) 361-3276

RECEIVED FEB 0 4 2011

T175 ROIE 5-32 43-039-5 0003

From:

"ken Clare" <boart@drillmail.net>

To:

CONFIDENTIAL "ken Clare" <boart@drillmail.net>, "Allen, Geoff" <geoff.allen@fmcti...

Date:

2/5/2011 3:29 PM

Subject:

Wolverine Rough Canyon Federal 30-1 Update

Drilled to 6395', TOOH for new bit, 100%Conglomerate

Ken Clare

Wolverine Operating Company of Utah, LLC

Rough Canyon Federal 30-1

Rig (970) 361-3276

RECEIVED FEB 0 5 2011

SUNDF Do not use this form for propositions bettom-hole depth, reenter plud RILL form for such proposals. 1. TYPE OF WELL Oil Well 2. NAME OF OPERATOR: WOLVERINE OPERATING COM 3. ADDRESS OF OPERATOR: One Riverfront Plaza 55 Camp 4. LOCATION OF WELL FOOTAGES AT SURFACE: 0288 FNL 0452 FWL QTR/QTR, SECTION, TOWNSHI	5.LEASE DESIGNATION AND SERIAL NUMBER: UTU-82536 6. IF INDIAN, ALLOTTEE OR TRIBE NAME: 7.UNIT OF CA AGREEMENT NAME: 8. WELL NAME and NUMBER: ROUGH CANYON FED 30-1 9. API NUMBER: 43039500030000 9. FIELD and POOL OF WILDCAT: WILDCAT COUNTY: SANPETE STATE:				
Qtr/Qtr: NWNW Section: 32 Township: 17.0S Range: 01.0E Meridian: S			UTAH		
CHECK APPROPRIATE BOXES TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA					
TYPE OF SUBMISSION	TYPE OF ACTION				
	CHANGE TO PREVIOUS PLANS CHANGE WELL STATUS DEEPEN OPERATOR CHANGE PRODUCTION START OR RESUME REPERFORATE CURRENT FORMATION TUBING REPAIR WATER SHUTOFF WILDCAT WELL DETERMINATION MPLETED OPERATIONS. Clearly show all pertine ached document for details of Degranuary 2011 drilling.	ecember 2010 through A L Oil	CASING REPAIR CHANGE WELL NAME CONVERT WELL TYPE NEW CONSTRUCTION PLUG BACK RECOMPLETE DIFFERENT FORMATION TEMPORARY ABANDON MATER DISPOSAL APD EXTENSION OTHER: COlumes, etc. CCCEPTED by the Utah Division of Gas and Mining RECORD ONLY		
NAME (PLEASE PRINT) Helene Bardolph	PHONE NUMBER 616 458-1150	TITLE Engineering Administrative Assi	istant		
SIGNATURE N/A	010 430-1130	DATE 2/22/2011	State		

Subject: Wolverine Operating Company of Utah, LLC

Rough Canyon Federal 30-1 NW¹/₄ NW¹/₄ Sec 32-T17S-R1E surface location NE¹/₄ SE¹/₄ Sec 30-T17S-R1E BHL Sanpete County, Utah.

December 2010 Drilling Update

30 November 2010

Depth 3829' DF, 22" x $\frac{1}{2}$ " wall @ 1421' GL. Wash fill from 3814 to 3826. MW - 10, Vis. - 75, FL - 12. Surveys: none.

1 December 2010

Depth 3829' DF, 22" x $\frac{1}{2}$ " wall @ 1421' GL. C&C, wash down and up, C&C. MW – 10.2, Vis. – 67, FL – 10.2. Surveys: none.

2 December 2010

Depth 3829' DF, 22" x $\frac{1}{2}$ " wall @ 1421' GL. C&C, rebuild mud volume, C&C. MW - 9.5, Vis. - 68, FL - 9.2. Surveys: none.

3 December 2010

Depth 3829' DF, 22" x ½" wall @ 1421' GL. C&C, wash & ream, C&C. MW – 9.2, Vis. – 65, FL – 9. Surveys: none.

4 December 2010

Depth 3829' DF, 22" x $\frac{1}{2}$ " wall @ 1421' GL. C&C, POOH. MW - 9.4, Vis. - 63, FL - 7. Surveys: none.

5 December 2010

Depth 3829' DF, 22" x $\frac{1}{2}$ " wall @ 1421' GL. LD BHA, RU to run casing, run 13-3/8 casing with 1.9" parasite string. MW – 9.3, Vis. – 62, FL – 6.5. Surveys: none.

6 December 2010

Depth 3829' DF, 22" x $\frac{1}{2}$ " wall @ 1421' GL. Run 13-3/8 casing, tag at 3770', land at 3769', cement w/ Schlumberger, diagnose casing issue. MW -9.1, Vis. -53, FL -14. Surveys: none.

7 December 2010

Depth 3829' DF, 22" x $\frac{1}{2}$ " wall @ 1421' GL. Diagnose casing issue, wait on wireline truck, ran CCL/temp survey, leak in joint from 752 to 798, ran CCL/CBL, TOC @ 2710', wait on gage ring, ring cut too large, drift w/ 12.1" gage ring, casing open to cementing plug, wait on Boart camera truck. MW -9, Vis. -54, FL -10. Surveys: none.

8 December 2010

Depth 3829' DF, $13\frac{3}{8}$ @ 3769' DF. Wait on tools, cut off casing above slips, RU false rotary table, GIH w/ drill string to 900', evacuate hole, POOH, GIH w/ camera, fluid level at 650', POOH w/ camera, GIH w/ drill string to 1100', evacuate hole, POOH w/ drill string, GIH w/ camera, examine casing from 752' to 798', ok, POOH w/ camera, retool to investigate for deeper leak. MW – 9, Vis. – 55, FL – 9.5. Surveys: none.

9 December 2010

Depth 3829' DF, $13\frac{3}{8}$ @ 3769' DF. Make up stands of $5\frac{1}{2}$ DP, wait on spinner survey tools, run spinner survey, leak located at air injection sub at 2483', pump water down parasite string, set up casing alignment assy. MW – 9, Vis. – 32, FL – 13.4. Surveys: none.

10 December 2010

Depth 3829' DF, $13\frac{3}{8}$ @ 3769' DF. Prep to run csg alignment assy, GIH w/ $12\frac{1}{4}$ " OD csg alignment assy, space out over air sub interval, hook up to hang both DP and casing from block/top drive assy, pull csg slips, found csg parted, slack off until taking weight, set slips on csg, POOH w/ csg alignment assy, RU tremmie pipe, GIH down annulus w/ tremmie pipe to 2360'. MW – 9, Vis. – 32, FL – 13.4. Surveys: none.

11 December 2010

Depth 3829' DF, $13\frac{3}{8}$ @ 3769' DF. GIH w/ tremmie pipe to 2770', RU cementer, mix & pump 270 cf of 15.6 ppg cement, pull tremmie pipe to 2250', WOC, tag cmt at 2365', mix & pump 388 cf of 15.6 ppg cmt, pull tremmie pipe to 1770', WOC, tag cmt at 2140', tremmie pipe plugged, pull up tremmie pipe and attempt to clear. MW – 8.9, Vis. – 67, FL – 10.8. Surveys: none. 12 December 2010

Depth 3829' DF, $13\frac{3}{8}$ @ 3769' DF. POOH w/ tremmie pipe, found 40' plugged w/ cmt, GIH w/ tremmie pipe, tag at 2105', mix and pump 333 cf of 15.3 ppg cmt, POOH w/ tremmie pipe to 1500', WOC, GIH w/ tremmie pipe, tag cmt at 1870', mix & pump 322 cf of 15.3 ppg cmt, POOH w/ tremmie pipe to 1270', WOC, GIH to 1670'. MW - 8.9, Vis. - 62, FL - 9.8. Surveys: none.2 13 December 2010

Depth 3829' DF, 13% @ 3769' DF. Tag cmt at 1700' w/ tremmie pipe, cement w/ 333 cf of 15.6 ppg cmt, POOH w/ tremmie pipe to 1100', WOC, GIH w/ tremmie pipe to tag @ 1370', cement w/ 1071 cf of 15.6 ppg cmt, POOH w/ tremmie pipe, WOC, GIH w/ tremmie pipe, tag cmt @ 150', cement w/ 187 cf of 15.3 ppg cmt, cement to surface WOC. MW –9.1, Vis. – 66, FL – 10.7. Surveys: none. 14 December 2010

Depth 3829' DF, $13\frac{3}{8}$ @ 3769' DF. WOC, cut off $13\frac{3}{8}$ csg, break down csg alignment assy, PU $12\frac{1}{4}$ bit and scraper, GIH, work through air inj sub, POOH, LD scraper, GIH w/ bit. MW – 9.2, Vis. – 41, FL – 12.7. Surveys: none.

15 December 2010

Depth 3829' DF, $13\frac{3}{8}$ @ 3769' DF. GIH, tag @ 3707', C&C, POOH, PU Howco squeeze pkr, GIH w/pkr, pkr set down at 830', POOH, left pkr in hole, check pkr performance, no seal, RU on parasite string. MW -9, Vis. -34, FL -16.2. Surveys: none.

16 December 2010

Depth 3829' DF, $13\frac{3}{8}$ @ 3769' DF. Check csg leak, POOH w/ DP, fill csg, pump 5 bw dn parasite string, cement down parasite string, pump 150 sx of 15.8 ppg class "G" cement, flush w/ 2 bw, WOC, make up and rack back stands of drill pipe. MW - 8.9, Vis. - 49, FL - 11.6. Surveys: none. 17 December 2010

Depth 3829' DF, $13\frac{3}{8}$ @ 3769' DF. MU stands of DP, check parasite string, plugged w/ cmt, GIH, circ at 801', drill up pkr to 831', pkr released and went down hole, wash to 895', POOH, PU stands of dp, GIH w/ bit, tag plug @ 2465', drill pkr & cmt to 2582', wash to 2665', fill csg, hole standing full, pooh. MW - 8.8, Vis. - 42, FL - 11.6. Surveys: none.

18 December 2010

Depth 3829' DF, $13\frac{3}{8}$ @ 3769' DF. POOH, PU stands of dp, tag at 3702', circulate, drill to 3737', hole standing full, drill cmt to 3767', empty mud tank, build mud, C&C, drill to 3771, starting to lose fluid, POOH, static fluid level at 886', stand back stands of dp, GIH. MW – 8.8, Vis. – 50, FL – 11.6. Surveys: none.

19 December 2010

Depth 3829' DF, $13\frac{3}{8}$ @ 3769' DF. C&C, to 3777', bit plugging, POOH, bit plugged, clean out bit, fluid level at 1201', GIH, ream to 3779', bit plugged, POOH. MW -8.8, Vis. -47, FL -11. Surveys: none.

20 December 2010

Depth 3829' DF, 13³/₈ @ 3769' DF. POOH, clean bit, MU BHA, GIH, ream to 3782', bit plugged, POOH. MW –8.8, Vis. – 58, FL – 8.6. Surveys: none.

21 December 2010

Depth 3829' DF, $13\frac{3}{8}$ @ 3769' DF. Unplug shock sub, LD shock sub & IBS, GIH, ream to 3818', . MW -8.8, Vis. -47, FL -8.8. Surveys: none.

22 December 2010

Depth 3886' DF, $13\frac{3}{8}$ @ 3769' DF. Ream to 3829', drill. MW - 8.7, Vis. - 77, FL - 9.2. Surveys: none.

23 December 2010

Depth 3981' DF, 13\% @ 3769' DF. Drill & survey. MW - 8.7, Vis. - 64, FL - 8.6. Surveys: 6° @ 3840'.

24 December 2010

Depth 4065' DF, 13\% @ 3769' DF. Drill & survey. MW - 8.9, Vis. - 60, FL - 8.8. Surveys: 6° @ 3940'.

25 December 2010

Depth 4119' DF, 13\% @ 3769' DF. Drill & survey. MW - 9, Vis. - 65, FL - 8.7. Surveys: 6° @ 4040'.

26 December 2010

Depth 4163' DF, 13\% @ 3769' DF. Drill, C&C, POOH. MW -9, Vis. - 73, FL - 9.5. Surveys: none. 27 December 2010

Depth 4213' DF, $13\frac{3}{8}$ @ 3769' DF. PU new bit, inspect BHA, GIH, drill. MW -9, Vis. -60, FL -9. Surveys: none.

28 December 2010

Depth 4304' DF, 13\% @ 3769' DF. Drill & survey. MW - 9, Vis. - 58, FL - 10. Surveys: 6° @ 4200'.

29 December 2010

Depth 4328' DF, 13\% @ 3769' DF. Drill, C&C, POOH, PU new bit, GIH. MW – 8.9, Vis. – 55, FL – 9.5. Surveys: none.

30 December 2010

Depth 4398' DF, 13\% @ 3769' DF. GIH, drill & survey. MW - 9, Vis. - 56, FL - 9.5. Surveys: 6° @ 4330'.

31 December 2010

Depth 4495' DF, 13\% @ 3769' DF. Drill. MW -9, Vis. -53, FL - 9.5. Surveys: none.

January 2011 – Drilling Summary

Wolverine Operating Company of Utah, LLC

Rough Canyon Federal 30-1

NW¹/₄ NW¹/₄ Sec 32-T17S-R1E surface location

Sanpete County, Utah

1 January 2011

Depth 4560' DF, 13\% @ 3769' DF. Drill & survey. MW - 9, Vis. - 56, FL - 9.5. Surveys: 5.5° @ 4431'.

2 January 2011

Depth 4617' DF, 13\% @ 3769' DF. Drill & survey. MW -9, Vis. - 54, FL - 9. Surveys: 6° @ 4532'.

3 January 2011

Depth 4627' DF, 13\% @ 3769' DF. Drill, POOH, PU new bit, GIH. MW -9, Vis. - 60, FL - 9.5. Surveys: none

4 January 2011

Depth 4707' DF, 13\% @ 3769' DF. Drill & survey. MW – 9, Vis. – 60, FL – 9.5. Surveys: 6° @ 4615'.

5 January 2011

Depth 4785' DF, 13\% @ 3769' DF. Drill & survey. MW -9, Vis. - 56, FL - 9.4. Surveys: 5.5° @ 4700'.

6 January 2011

Depth 4861' DF, 13\% @ 3769' DF. Drill & circulate. MW - 9, Vis. - 57, FL - 8.8. Surveys: none.

7 January 2011

Depth 4926' DF, 13\% @ 3769' DF. Drill & survey. MW -8.9, Vis. - 59, FL - 8.6. Surveys: 5.5° @ 4800'.

8 January 2011

Depth 5015' DF, 13\% @ 3769' DF. Drill & survey. MW – 9.1, Vis. – 56, FL – 9. Surveys: 5.75° @ 4906'.

9 January 2011

Depth 5093' DF, 13\% @ 3769' DF. Drill & survey, TFNB. MW – 9.2, Vis. – 55, FL – 8.8. Surveys: 6\circ @ 5040'.

10 January 2011

Depth 5118' DF, 13% @ 3769' DF. TFNB, drill. MW - 9.3, Vis. - 40, FL - 8.8. Surveys: none

11 January 2011

Depth 5192' DF, 13\% @ 3769' DF. Drill. MW – 9.2, Vis. – 53, FL – 8.4. Surveys: none.

12 January 2011

Depth 5207' DF, 133/8 @ 3769' DF. Drill, TFNB. MW -9.5, Vis. - 56, FL - 8. Surveys: none.

13 January 2011

Depth 5245' DF, $13\frac{3}{8}$ @ 3769' DF. TFNB, drill & survey. MW – 9.1, Vis. – 55, FL – 9. Surveys: 5° @ 5154'.

14 January 2011

Depth 5320' DF, 13\% @ 3769' DF. Drill & survey. MW -9.2, Vis. - 52, FL - 9.4. Surveys: 5.5° @ 5260'.

15 January 2011

Depth 5420' DF, 133/8 @ 3769' DF. Drill. MW – 9.3, Vis. – 58, FL – 9.4. Surveys: none. 16 January 2011

Depth 5517' DF, $13\frac{3}{8}$ @ 3769' DF. Drill & survey. MW – 9.3, Vis. – 61, FL – 8.4. Surveys: 6° @ 5367'.

17 January 2011

Depth 5550' DF, 13% @ 3769' DF. Drill, POOH for leaks in air string. MW – 9.3, Vis. – 70, FL – 9.2. Surveys: none

18 January 2011

Depth 5550' DF, $13\frac{3}{8}$ @ 3769' DF. POOH looking for leaks in air string, replace bit, roller reamer & blade reamer, GIH. MW – 8.9, Vis. – not reported, FL – 11.9. Surveys: none.

19 January 2011

Depth 5618' DF, 13% @ 3769' DF. GIH, circ. to bottom, drill, survey. MW –8.9, Vis. – 52, FL – 10.8. Surveys: none.

20 January 2011

Depth 5690' DF, 133/8 @ 3769' DF. Survey, drill, C&C, drill. MW – 8.9, Vis. – 52, FL – 10.8. Surveys: 6° @ 5560'.

21 January 2011

Depth 5761' DF, 13\% @ 3769' DF. C&C, drill C&C, drill. MW -9, Vis. - 50, FL - 11.2. Surveys: none.

22 January 2011

Depth 5846' DF, 13\% @ 3769' DF. Drill, survey, POOH. MW – 9, Vis. – 52, FL – 9.6. Surveys: 6° @ 5720'.

23 January 2011

Depth 5846' DF, $13\frac{3}{8}$ @ 3769' DF. POOH, install new bit, GIH. MW – 9, Vis. – 52, FL – 9.6. Surveys: none.

24 January 2011

Depth 5883' DF, 13% @ 3769' DF. GIH, C&C, drill. MW – 9, Vis. – 56, FL – 12.5. Surveys: none.

25 January 2011

Depth 5938' DF, $13\frac{3}{8}$ @ 3769' DF. Drill, rig repair, drill, POOH. MW -9, Vis. -56, FL -11.6. Surveys: none.

26 January 2011

Depth 5976' DF, 133/8 @ 3769' DF. GIH, C&C, POOH, C&C, GIH, drill & survey. MW – 9, Vis. – 63, FL – 10.5. Surveys: none.

27 January 2011

Depth 6000' DF, 13\% @ 3769' DF. Survey, drill. MW -9, Vis. -62, FL - 10.5. Surveys: 6° @ 5915'.

28 January 2011

Depth 6051' DF, 13\% @ 3769' DF. Drill, POOH. MW -9, Vis. -61, FL - 10.5. Surveys: none.

29 January 2011

Depth 6066' DF, $13\frac{3}{8}$ @ 3769' DF. Trip for leaks in air string, drill, trip for leaks in air string. MW – 9, Vis. – 61, FL – 10.5. Surveys: none.

30 January 2011

Depth 6066' DF, 13\% @ 3769' DF. POOH, NU Hydril & rotating hd, GIH. MW – 9, Vis. – 61, FL – 10.5. Surveys: none.

31 January 2011

Depth 6098' DF, 13% @ 3769' DF. GIH, drill. MW – 9.1, Vis. – 63, FL – 10.5. Surveys: none.

Carol Daniels - Rough Canyon Federal 30-1 Update TINGROLE 5-32. 43 039 5000 3

From:

"Wolverine Supervisor"

To:

"Ainge, Jeff", "Allen, Geoff", "Arthurs, Shane", "Blair, Richard", "Brock Pope", "Chamberlain, Don", "Childers, Eli", "Chris Schaugaard", "Daniel Jenkins", "Daniels, Carol", "De la Torre, Juan C", "Dennis", "Denton, Derek", "Dieste, Bobby", "Doucet, Dustin", "Dustin Dunning", "Foreman, Ron", "George Zamantakis", "Hall, Denise", "Hammell, Hank", "Harry Melnikoff", "Hendricks, Marvin", "Hutcinson, Clayton", "Jim Barry", "Jimmy Germon", "Jones, Mark", "KC Schultz", "Kent Donner", "Kulow, Kyle", "Kyle Cox", "LaDee Roundy", "Larimore, Mark", "Lewis, John", "Martin Pete", "Marvin Hendricks", "Matt Harmon", "McCoy, Charlene", "McCoy, Tim", "Nilles, Chris",

"O'Connell, David", "Perry, Bud (Smith Bits)", "Pickup, Marc", "Rees, John M", "Revert, Scott", "Robinson, Darin", "Ryan Thomas", "Shaun Burns", "Shawn Moulton", "Shelton, Shorty", , "Steffen, Dana", "Tujillo, Chris", "Tyler Ross", "Willis, Walton", "Willis,

Walton Home", "Winkler, Matt", "Zimmerman, Bill"

Date:

2/20/2011 9:34 AM

Subject: Rough Canyon Federal 30-1 Update

2/20/2011 9:30 AM

Rig repair, not drilling

Bill Donovan Drilling Supervisor Wolverine Gas and Oil Company of Utah, LLC Rough Canyon Federal 30-1, AFE 224 Ria (970) 361-3276 Cell (720) 351-7470 boart@drillmail.net

RECEIVED FEB 2 2 2011

CONFIDENTIAL

Carol Daniels - Rough Canyon Federal 30-1 Update

T175 ROIE 5-32 43-03950003

From:

"Wolverine Supervisor"

To:

"Ainge, Jeff", "Allen, Geoff", "Arthurs, Shane", "Blair, Richard", "Brock Pope", "Chamberlain, Don", "Childers, Eli", "Chris Schaugaard", "Daniel Jenkins", "Daniels, Carol", "De la Torre, Juan C", "Dennis", "Denton, Derek", "Dieste, Bobby", "Doucet, Dustin", "Dustin Dunning", "Foreman, Ron", "George Zamantakis", "Hall, Denise", "Hammell, Hank", "Harry Melnikoff", "Hendricks, Marvin", "Hutcinson, Clayton", "Jim Barry", "Jimmy Germon", "Jones, Mark", "KC Schultz", "Kent Donner", "Kulow, Kyle", "Kyle Cox", "LaDee Roundy", "Larimore, Mark", "Lewis, John", "Martin Pete", "Marvin Hendricks", "Matt Harmon", "McCoy, Charlene", "McCoy, Tim", "Nilles, Chris",

"O'Connell, David", "Perry, Bud (Smith Bits)", "Pickup, Marc", "Rees, John M", "Revert, Scott", "Robinson, Darin", "Ryan Thomas", "Senda Serrano", "Shaun Burns", "Shawn Moulton", "Shelton, Shorty", , "Steffen, Dana", "Tujillo, Chris", "Tyler Ross", "Willis,

Walton", "Willis, Walton Home", "Winkler, Matt", "Zimmerman, Bill"

Date:

2/22/2011 8:38 AM

Subject: Rough Canyon Federal 30-1 Update

2/22/2011 8:35 AM

Rig repair

Expect to be drilling later this week

Bill Donovan Drilling Supervisor Wolverine Gas and Oil Company of Utah, LLC Rough Canyon Federal 30-1. AFE 224 Rig (970) 361-3276 Cell (720) 351-7470 boart@drillmail.net

> RECEIVED FEB 2 2 2011

Carol Daniels - Rough Canyon Federal 30-1 update T 195 PolE 5-32, 430395 0003

From:

"Wolverine Supervisor"

To:

"Ainge, Jeff", "Allen, Geoff", "Arthurs, Shane", "Blair, Richard", "Brock Pope", "Chamberlain, Don", "Childers, Eli", "Chris Schaugaard", "Daniel Jenkins", "Daniels, Carol", "De la Torre, Juan C", "Dennis", "Denton, Derek", "Dieste, Bobby", "Doucet, Dustin", "Dustin Dunning", "Foreman, Ron", "George Zamantakis", "Hall, Denise", "Hammell, Hank", "Harry Melnikoff", "Hendricks, Marvin", "Hutcinson, Clayton", "Jim Barry", "Jimmy Germon", "Jones, Mark", "KC Schultz", "Kent Donner", "Kulow, Kyle", "Kyle Cox", "LaDee Roundy", "Larimore, Mark", "Lewis, John", "Martin Pete", "Marvin Hendricks", "Matt Harmon", "McCoy, Charlene", "McCoy, Tim", "Nilles, Chris",

"O'Connell, David", "Perry, Bud (Smith Bits)", "Pickup, Marc", "Rees, John M", "Revert, Scott", "Robinson, Darin", "Ryan Thomas", "Senda Serrano", "Shaun Burns", "Shawn Moulton", "Shelton, Shorty", , "Steffen, Dana", "Tujillo, Chris", "Tyler Ross", "Willis,

Walton", "Willis, Walton Home", "Winkler, Matt", "Zimmerman, Bill"

Date:

2/23/2011 10:50 AM

Subject:

Rough Canyon Federal 30-1 update

CC:

"'Hendricks, Marvin'", "Knight, Randy", , "'Willis, Walton'", "'Willis, Walton Home'"

2/23/2011 10:47 AM

Rig Repair

Bill Donovan **Drilling Supervisor** Wolverine Gas and Oil Company of Utah, LLC Rough Canyon Federal 30-1, AFE 224 Rig (970) 361-3276 Cell (720) 351-7470 boart@drillmail.net

> RECEIVED FEB 2 3 2011

T 175 ROIE 5-32 API-# 43 039 50003

From:

"Wolverine Supervisor" <boart@drillmail.net>

To:

"Ainge, Jeff" <jainge@varelintl.com>, "Allen, Geoff" <geoff.allen@fmcti....

Date:

2/24/2011 6:45 AM

Subject:

Rough Canyon Federal 30-1 update

CC:

"Knight, Randy" <randy_knight@blm.gov>

2/24/2011 6:42 AM

Rig repair

Bill Donovan

Drilling Supervisor

Wolverine Gas and Oil Company of Utah, LLC

Rough Canyon Federal 30-1, AFE 224

Rig (970) 361-3276

Cell (720) 351-7470

boart@drillmail.net

RECEIVED FEB 2 4 2011

CONFIDENTIAL

Carol Daniels - Rough Canyon Federal 30-1 Update T175 ROLE 5-32

From:

"Wolverine Supervisor"

To:

"Ainge, Jeff", "Allen, Geoff", "Arthurs, Shane", "Blair, Richard", "Brock Pope", "Chamberlain, Don", "Childers, Eli", "Chris Schaugaard", "Daniel Jenkins", "Daniels, Carol", "De la Torre, Juan C", "Dennis", "Denton, Derek", "Dieste, Bobby", "Doucet, Dustin", "Dustin Dunning", "Foreman, Ron", "George Zamantakis", "Hall, Denise", "Hammell, Hank", "Harry Melnikoff", "Hendricks, Marvin", "Hutcinson, Clayton", "Jim Barry", "Jimmy Germon", "Jones, Mark", "KC Schultz", "Kent Donner", "Kulow, Kyle", "Kyle Cox", "LaDee Roundy", "Larimore, Mark", "Lewis, John", "Martin Pete", "Marvin Hendricks", "Matt Harmon", "McCoy, Charlene", "McCoy, Tim", "Nilles, Chris",

"O'Connell, David", "Perry, Bud (Smith Bits)", "Pickup, Marc", "Rees, John M", "Revert, Scott", "Robinson, Darin", "Ryan Thomas", "Senda Serrano", "Shaun Burns", "Shawn Moulton", "Shelton, Shorty", , "Steffen, Dana", "Tujillo, Chris", "Tyler Ross", "Willis,

Walton", "Willis, Walton Home", "Winkler, Matt", "Zimmerman, Bill"

Date:

2/25/2011 7:25 AM

Subject: Rough Canyon Federal 30-1 Update

CC:

"Knight, Randy"

2/25/2011 7:21 AM

Rig repair

Bill Donovan Drilling Supervisor Wolverine Gas and Oil Company of Utah, LLC Rough Canyon Federal 30-1, AFE 224 Rig (970) 361-3276 Cell (720) 351-7470 boart@drillmail.net

> RECEIVED FEB 2 8 2011

Carol Daniels - Rough Canyon Federal 30-1 Update TIZS ROIE 5-32 4303950003

From:

"Wolverine Supervisor"

To:

"Ainge, Jeff", "Allen, Geoff", "Arthurs, Shane", "Blair, Richard", "Brock Pope", "Chamberlain, Don", "Childers, Eli", "Chris Schaugaard", "Daniel Jenkins", "Daniels, Carol", "De la Torre, Juan C", "Dennis", "Denton, Derek", "Dieste, Bobby", "Doucet, Dustin", "Dustin Dunning", "Foreman, Ron", "George Zamantakis", "Hall, Denise", "Hammell, Hank", "Harry Melnikoff", "Hendricks, Marvin", "Hutcinson, Clayton", "Jim Barry", "Jimmy Germon", "Jones, Mark", "KC Schultz", "Kent Donner", "Kulow, Kyle", "Kyle Cox", "LaDee Roundy", "Larimore, Mark", "Lewis, John", "Martin Pete", "Marvin Hendricks", "Matt Harmon", "McCoy, Charlene", "McCoy, Tim", "Nilles, Chris",

"O'Connell, David", "Perry, Bud (Smith Bits)", "Pickup, Marc", "Rees, John M", "Revert, Scott", "Robinson, Darin", "Ryan Thomas", "Senda Serrano", "Shaun Burns", "Shawn Moulton", "Shelton, Shorty", , "Steffen, Dana", "Tujillo, Chris", "Tyler Ross", "Willis,

Walton", "Willis, Walton Home", "Winkler, Matt", "Zimmerman, Bill"

Date:

2/26/2011 8:12 AM

Subject: Rough Canyon Federal 30-1 Update

CC:

"Knight, Randy"

2/26/2011 8:10 AM

Rig repair

Bill Donovan Drilling Supervisor Wolverine Gas and Oil Company of Utah, LLC Rough Canyon Federal 30-1, AFE 224 Rig (970) 361-3276 Cell (720) 351-7470 boart@drillmail.net

> RECEIVED FEB 2 8 2011

Carol Daniels - Rough Canyon Federal 30-1 Update TIPS ROLE 5-32 43.03950003

From:

"Wolverine Supervisor"

To:

"Ainge, Jeff", "Allen, Geoff", "Arthurs, Shane", "Blair, Richard", "Brock Pope", "Chamberlain, Don", "Childers, Eli", "Chris Schaugaard", "Daniel Jenkins", "Daniels, Carol", "De la Torre, Juan C", "Dennis", "Denton, Derek", "Dieste, Bobby", "Doucet, Dustin", "Dustin Dunning", "Foreman, Ron", "George Zamantakis", "Hall, Denise", "Hammell, Hank", "Harry Melnikoff", "Hendricks, Marvin", "Hutcinson, Clayton", "Jim Barry", "Jimmy Germon", "Jones, Mark", "KC Schultz", "Kent Donner", "Kulow, Kyle", "Kyle Cox", "LaDee Roundy", "Larimore, Mark", "Lewis, John", "Martin Pete", "Marvin Hendricks", "Matt Harmon", "McCoy, Charlene", "McCoy, Tim", "Nilles, Chris",

"O'Connell, David", "Perry, Bud (Smith Bits)", "Pickup, Marc", "Rees, John M", "Revert, Scott", "Robinson, Darin", "Ryan Thomas", "Senda Serrano", "Shaun Burns", "Shawn Moulton", "Shelton, Shorty", , "Steffen, Dana", "Tujillo, Chris", "Tyler Ross", "Willis,

Walton", "Willis, Walton Home", "Winkler, Matt", "Zimmerman, Bill"

Date:

2/27/2011 7:37 AM

Subject: Rough Canyon Federal 30-1 Update

CC:

"Knight, Randy"

2/27/2011 7:33 AM

Rig repair.

TOH to inspect drill string.

Bill Donovan Drilling Supervisor Wolverine Gas and Oil Company of Utah, LLC Rough Canyon Federal 30-1, AFE 224 Rig (970) 361-3276 Cell (720) 351-7470 boart@drillmail.net

> RECEIVED FEB 2 8 2011

DW OF CIL, OF S & MINING

Carol Daniels - Rough Canyon Federal 30-1 Update TIRS ROLE 5-32 43 03950003

From:

"Wolverine Supervisor"

To:

"Ainge, Jeff", "Allen, Geoff", "Arthurs, Shane", "Blair, Richard", "Brock Pope", "Chamberlain, Don", "Childers, Eli", "Chris Schaugaard", "Daniel Jenkins", "Daniels, Carol", "De la Torre, Juan C", "Dennis", "Denton, Derek", "Dieste, Bobby", "Doucet, Dustin", "Dustin Dunning", "Foreman, Ron", "George Zamantakis", "Hall, Denise", "Hammell, Hank", "Harry Melnikoff", "Hendricks, Marvin", "Hutcinson, Clayton", "Jim Barry", "Jimmy Germon", "Jones, Mark", "KC Schultz", "Kent Donner", "Kulow, Kyle", "Kyle Cox", "LaDee Roundy", "Larimore, Mark", "Lewis, John", "Martin Pete", "Marvin Hendricks", "Matt Harmon", "McCoy, Charlene", "McCoy, Tim", "Nilles, Chris",

"O'Connell, David", "Perry, Bud (Smith Bits)", "Pickup, Marc", "Rees, John M", "Revert, Scott", "Robinson, Darin", "Ryan Thomas", "Senda Serrano", "Shaun Burns", "Shawn Moulton", "Shelton, Shorty", , "Steffen, Dana", "Tujillo, Chris", "Tyler Ross", "Willis,

Walton", "Willis, Walton Home", "Winkler, Matt", "Zimmerman, Bill"

Date:

2/28/2011 9:59 AM

Subject: Rough Canyon Federal 30-1 Update

CC:

"Knight, Randy"

2/28/2011 9:55 AM

Rig repair

Bill Donovan Drilling Supervisor Wolverine Gas and Oil Company of Utah, LLC Rough Canyon Federal 30-1, AFE 224 Rig (970) 361-3276 Cell (720) 351-7470 boart@drillmail.net

> RECEIVED FEB 2 8 2011

CONFIDENTIAL

Carol Daniels - Rough Canyon Federal 30-1 Update

TIPS ROLE S-32 43-039-5 0003

From:

"Wolverine Supervisor"

To:

"Ainge, Jeff", "Allen, Geoff", "Arthurs, Shane", "Blair, Richard", "Brock Pope", "Chamberlain, Don", "Childers, Eli", "Chris Schaugaard", "Daniel Jenkins", "Daniels, Carol", "De la Torre, Juan C", "Dennis", "Denton, Derek", "Dieste, Bobby", "Doucet, Dustin", "Dustin Dunning", "Foreman, Ron", "George Zamantakis", "Hall, Denise", "Hammell, Hank", "Harry Melnikoff", "Hendricks, Marvin", "Hutcinson, Clayton", "Jim Barry", "Jimmy Germon", "Jones, Mark", "KC Schultz", "Kent Donner", "Kulow, Kyle", "Kyle Cox", "LaDee Roundy", "Larimore, Mark", "Lewis, John", "Martin Pete", "Marvin Hendricks", "Matt Harmon", "McCoy, Charlene", "McCoy, Tim", "Nilles, Chris",

"O'Connell, David", "Perry, Bud (Smith Bits)", "Pickup, Marc", "Rees, John M", "Revert, Scott", "Robinson, Darin", "Ryan Thomas", "Senda Serrano", "Shaun Burns", "Shawn Moulton", "Shelton, Shorty", , "Steffen, Dana", "Tujillo, Chris", "Tyler Ross", "Willis,

Walton", "Willis, Walton Home", "Winkler, Matt", "Zimmerman, Bill"

Date:

3/7/2011 6:58 AM

Subject: Rough Canyon Federal 30-1 Update

CC:

"Knight, Randy"

3/7/2011 6:54 AM

Demobbing Boart LK700 Rig. Will redress pad and then mobilize Patt 304 about early next week.

Tom Zupan Drilling Supervisor Wolverine Gas and Oil Company of Utah, LLC Rig (970) 361-3276 Cell (970) 314-8219

wolvexpl@drillmail.net

RECEIVED MAR 07 2011

STATE OF UTAH DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS, AND MINING SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill new wells, significantly deepen existing wells below current bottom-hole depth, reenter plugged wells, or to drill horizontal laterals. Use APPLICATION FOR PERMIT TO DRILL form for such proposals. 1. TYPE OF WELL Oil Well 2. NAME OF OPERATOR: WOLVERINE OPERATING COMPANY OF UTAH, LLC 3. ADDRESS OF OPERATOR: One Riverfront Plaza 55 Campau NW, Grand Rapids, MI, 49503 616 458-1150 Ext 4. LOCATION OF WELL FOOTAGES AT SURFACE: 0288 FNL 0452 FWL QTR/QTR, SECTION, TOWNSHIP, RANGE, MERIDIAN:			5.LEASE DESIGNATION AND SERIAL NUMBER: UTU-82536 6. IF INDIAN, ALLOTTEE OR TRIBE NAME: 7.UNIT OF CA AGREEMENT NAME: 8. WELL NAME and NUMBER: ROUGH CANYON FED 30-1 9. API NUMBER: 43039500030000 9. FIELD and POOL OF WILDCAT: WILDCAT COUNTY: SANPETE STATE:	
Qtr/Qtr: NWNW Section: 32 Township: 17.0S Range: 01.0E Meridian: S			UTAH	
CHECK APPROPRIATE BOXES TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA				
TYPE OF SUBMISSION	TYPE OF ACTION			
	CHANGE TO PREVIOUS PLANS CHANGE WELL STATUS DEEPEN OPERATOR CHANGE PRODUCTION START OR RESUME REPERFORATE CURRENT FORMATION TUBING REPAIR WATER SHUTOFF WILDCAT WELL DETERMINATION MPLETED OPERATIONS. Clearly show all pertines attached file for February 2011 of	drilling update. A L Oil	CASING REPAIR CHANGE WELL NAME CONVERT WELL TYPE NEW CONSTRUCTION PLUG BACK RECOMPLETE DIFFERENT FORMATION TEMPORARY ABANDON WATER DISPOSAL APD EXTENSION OTHER: COLUMNES, etc. CCCEPTED BY THE STANDARD ONLY	
NAME (PLEASE PRINT) Helene Bardolph	PHONE NUMBER 616 458-1150	TITLE Engineering Administrative Assi	stant	
SIGNATURE N/A	010 420-1120	DATE 3/11/2011		

Wolverine Operating Company of Utah, LLC

Rough Canyon Federal 30-1

NW¹/₄ NW¹/₄ Sec 32-T17S-R1E surface location

NE¹/₄ SE¹/₄ Sec 30-T17S-R1E Projected BHL

Sanpete County, Utah

1 February 2011

Depth 6174' DF, 13\% @ 3769' DF. Drill. MW -9.1, Vis. - 54, FL - 10.4. Surveys: none.

2 February 2011

Depth 6228' DF, 13\% @ 3769' DF. Drill & survey. MW – 9.1, Vis. – 57, FL – 10.2. Surveys: 6° @ 6150'.

3 February 2011

Depth 6271' DF, 13\% @ 3769' DF. Drill. MW -9.1, Vis. -52, FL - 10.2. Surveys: none.

4 February 2011

Depth 6338' DF, 13\% @ 3769' DF. Drill. MW -9.1, Vis. - 56, FL - 10.5. Surveys: none.

5 February 2011

Depth 6395' DF, 13\% @ 3769' DF. Drill, POOH. MW – 9.2, Vis. – 55, FL – 10.5. Surveys: none.

6 February 2011

Depth 6395' DF, $13\frac{3}{8}$ @ 3769' DF. POOH, slip drilling line, change bit & roller reamers, GIH. MW -9, Vis. -61, FL -10.5. Surveys: none.

7 February 2011

Depth 6442' DF, 13\% @ 3769' DF. GIH, drill. MW - 9.2, Vis. - 55, FL - 10.5. Surveys: none.

8 February 2011

Depth 6491' DF, 13\% @ 3769' DF. Drill. MW -9.3, Vis. - 56, FL - 8.4. Surveys: none.

9 February 2011

Depth 6502' DF, $13\frac{3}{8}$ @ 3769' DF. Drill, C&C, run survey, tool stuck, pull survey line off survey tool, POOH w/ bit, survey tool left in hole, change bit, GIH. MW – 9.2, Vis. – 54, FL – 8.6. Surveys: none.

10 February 2011

Depth 6502' DF, $13\frac{3}{8}$ @ 3769' DF. Inspect DC's looking for Totco tool, GIH, with bit depth at 2395' dropped block to floor, wait on orders. MW -9.2, Vis. -57, FL -8.5. Surveys: none.

11-16 February 2011

Depth 6502' DF, $13\frac{3}{8}$ @ 3769' DF. Investigate problems that resulted in dropped block. MW -9.2, Vis. -57, FL -8.5. Surveys: none.

17-22 February 2011

Depth 6502' DF, $13\frac{3}{8}$ @ 3769' DF. Investigate problems that resulted in dropped block. MW -9.2, Vis. -57, FL -8.5. Surveys: none.

23 February – 1 March 2011

Depth 6502' DF, 13\% @ 3769' DF. Investigate problems that resulted in dropped block, rig repair.

MW –9.2, Vis. – 57, FL – 8.5. Surveys: none.

CONFIDENTIAL

Carol Daniels - Rough Canyon Federal 30-1 Update

T115 ROLE 5-32 43-039-50003

From:

"Wolverine Supervisor"

To:

"Ainge, Jeff", "Allen, Geoff", "Arthurs, Shane", "Blair, Richard", "Brock Pope", "Chamberlain, Don", "Childers, Eli", "Chris Schaugaard", "Daniel Jenkins", "Daniels, Carol", "De la Torre, Juan C", "Dennis", "Denton, Derek", "Dieste, Bobby", "Doucet, Dustin", "Dustin Dunning", "Foreman, Ron", "George Zamantakis", "Hall, Denise" "Hammell, Hank", "Harry Melnikoff", "Hendricks, Marvin", "Hutcinson, Clayton", "Jim Barry", "Jimmy Germon", "Jones, Mark", "KC Schultz", "Kent Donner", "Kulow, Kyle", "Kyle Cox", "LaDee Roundy", "Larimore, Mark", "Lewis, John", "Martin Pete", "Marvin Hendricks", "Matt Harmon", "McCoy, Charlene", "McCoy, Tim", "Nilles, Chris",

"O'Connell, David", "Perry, Bud (Smith Bits)", "Pickup, Marc", "Rees, John M", "Revert, Scott", "Robinson, Darin", "Ryan Thomas", "Senda Serrano", "Shaun Burns", "Shawn Moulton", "Shelton, Shorty", , "Steffen, Dana", "Tujillo, Chris", "Tyler Ross", "Willis,

Walton", "Willis, Walton Home", "Winkler, Matt", "Zimmerman, Bill"

Date:

3/8/2011 9:39 AM

Subject: Rough Canyon Federal 30-1 Update

CC:

"Knight, Randy"

3/8/2011 9:36 AM

Continue demobbing Boart LK700. Anticipate begin mob of Pat 304 early next week.

Tom Zupan **Drilling Supervisor** Wolverine Gas and Oil Company of Utah, LLC Rig (970) 361-3276 Cell (970) 314-8219

wolvexpl@drillmail.net

Carol Daniels - Rough Canvon Federal 30-1 Update

+ 195 ROE 5-32 Control of the Contro

43-03950023

From:

"Wolverine Supervisor"

To:

"'Hendricks, Marvin'", "Knight, Randy", , "'Willis, Walton'", "'Willis, Walton Home'",

"Daniels, Carol", "Doucet, Dustin", "Jarvis, Dan", "Jones, Mark", "Ainge, Jeff", "Allen,

Geoff", "Arthurs, Shane", "Blair, Richard", "Brock Pope", "Chamberlain, Don", "Childers, Eli", "Chris Schaugaard", "Daniel Jenkins", "De la Torre, Juan C", "Dennis",

"Denton, Derek", "Dieste, Bobby", "Dustin Dunning", "Foreman, Ron", "George

Zamantakis ", "Hall, Denise", "Harry Melnikoff", "Hutcinson, Clayton", "Jim Barry", "Jimmy Germon", "Kent Donner", "Kulow, Kyle", "Kyle Cox", "LaDee Roundy", "Larimore, Mark", "Lewis, John", "Martin Pete", "McCoy, Charlene", "McCoy, Tim", "Nilles, Chris", "O'Connell, David", "Perry, Bud (Smith Bits)", "Pickup, Marc", "Rees, John M", "Revert, Scott", "Robinson, Darin", "Ryan Thomas", "Senda Serrano", "Shaun Burns", "Shawn Moulton", "Shelton, Shorty", "Steffen, Dana", "Tujillo, Chris", "Tyler

Ross", "Winkler, Matt", "Zimmerman, Bill"

Date:

3/11/2011 7:46 AM

Subject: Rough Canyon Federal 30-1 Update

3/11/2011 7:42 AM

Clearing and preparing location for Patterson UTI 304 rig move.

Bill Donovan Drilling Supervisor Wolverine Gas and Oil Company of Utah, LLC Rough Canyon Federal 30-1, AFE 224 Ria (970) 361-3276 Cell (720) 351-7470 boart@drillmail.net

> RECEIVED MAR 1 4 2011

Carol Daniels - Rough Canyon Federal 30-1 Update 7./19 ROTE 532

43-039-50003

From:

"Wolverine Supervisor"

To:

"'Hendricks, Marvin'", "Knight, Randy", , "'Willis, Walton'", "'Willis, Walton Home'", "Daniels, Carol'", "Doucet, Dustin", "Jarvis, Dan", "'Jones, Mark'"

Date:

3/12/2011 7:01 AM

Subject: Rough Canyon Federal 30-1 Update

3/12/2011 6:57 AM

Preparing pad for rig

Bill Donovan Drilling Supervisor Wolverine Gas and Oil Company of Utah, LLC Rough Canyon Federal 30-1, AFE 224 Rig (970) 361-3276 Cell (720) 351-7470 boart@drillmail.net

RECEIVED

MAR 1 4 2011

Carol Daniels - Rough Canyon Federal 30-1 update + 175 ROIE 5-32 43-039 5003

From:

"Wolverine Supervisor"

To:

"'Daniels, Carol'", "Doucet, Dustin", "Jarvis, Dan", "'Jones, Mark'", "'Hendricks, Marvin'", "Knight, Randy", "'Willis, Walton'", "'Willis, Walton Home'"

Date:

3/13/2011 6:27 AM

Subject: Rough Canyon Federal 30-1 update

3/13/2011 6:23 AM

Preparing location

Bill Donovan Drilling Supervisor Wolverine Gas and Oil Company of Utah, LLC Rough Canyon Federal 30-1, AFE 224 Rig (970) 361-3276 Cell (720) 351-7470 boart@drillmail.net

RECEIVED

MAR 1 4 2011

Carol Daniels - Rough Canyon Federal 30-1 Update

T175 ROLE 5-32

43-639-5-00-3

From:

"Wolverine Supervisor"

To:

"'Hendricks, Marvin'", "Knight, Randy", , "'Willis, Walton'", "'Willis, Walton Home'",

"Daniels, Carol", "Doucet, Dustin", "Jarvis, Dan", "'Jones, Mark'"

Date:

3/14/2011 6:26 AM

Subject: Rough Canyon Federal 30-1 Update

3/14/2011 6:22 AM

Start moving Patterson UTI 304 today

Bill Donovan
Drilling Supervisor
Wolverine Gas and Oil Company of Utah, LLC
Rough Canyon Federal 30-1, AFE 224
Rig (970) 361-3276
Cell (720) 351-7470
boart@drillmail.net

RECEIVED

MAR 1 4 2011

CONFIDENTIAL

Carol Daniels - Rough Canyon Federal 30-1 Update TITS ROLE 5-32 43-039-5003 ERG FIRETS CONTRIBED INTERFERENCES STREET FRANKFIERE BELIEFEN MENTER DE FELLENGEMENDE MET

From:

"Wolverine Supervisor"

To:

"'Hendricks, Marvin'", "Knight, Randy", , "'Willis, Walton'", "'Willis, Walton Home'", "Daniels, Carol'", "Doucet, Dustin", "Jarvis, Dan", "Jones, Mark'"

Date:

3/15/2011 7:49 PM

Subject: Rough Canyon Federal 30-1 Update

3/15/2011 7:47 PM

Moving rig

Bill Donovan Drilling Supervisor Wolverine Gas and Oil Company of Utah, LLC Rough Canyon Federal 30-1, AFE 224 Rig (970) 361-3276 Cell (720) 351-7470 boart@drillmail.net

> RECEIVED MAR 1 6 2011 DIV. OF OIL, GAS & MINING

Carol Daniels - Rough Canyon Federal 30-1 Update TIMS ROIE 5-32 43-039 50003

From:

"Wolverine Supervisor"

To:

"'Daniels, Carol'" , "Doucet, Dustin" , "Jarvis, Dan" , "'Jones, Mark'" , "'Hendricks, Marvin'" , "Knight, Randy" , , "'Willis, Walton'" , "'Willis, Walton Home'"

Date:

3/17/2011 6:38 AM

Subject: Rough Canyon Federal 30-1 Update

3/17/2011 6:36 AM

Moving rig

Bill Donovan Drilling Supervisor Wolverine Gas and Oil Company of Utah, LLC Rough Canyon Federal 30-1, AFE 224 Rig (970) 361-3276 Cell (720) 351-7470 boart@drillmail.net

> RECEIVED MAR 1 / 2011

Carol Daniels - Rough Canyon Federal 30-1 Update T178 Rolf 5-32 43-039-5003

From:

"Wolverine Supervisor"

To:

"'Daniels, Carol'", "Doucet, Dustin", "Jarvis, Dan", "'Jones, Mark'", "'Hendricks, Marvin'", "Knight, Randy", "'Willis, Walton'", "'Willis, Walton Home'"

Date:

3/18/2011 7:19 AM

Subject: Rough Canyon Federal 30-1 Update

3/18/2011 7:16 AM

Continue to rig up.

Bill Donovan Drilling Supervisor Wolverine Gas and Oil Company of Utah, LLC Rough Canyon Federal 30-1, AFE 224 Rig (970) 361-3276 Cell (720) 351-7470 boart@drillmail.net

> RECEIVED MAR 2 2 2011

Carol Daniels - Rough Canyon Federal 30-1 Update T178 Rolf 5-32 43-039-50003

From:

"Wolverine Supervisor"

To:

"'Daniels, Carol'", "Doucet, Dustin", "Jarvis, Dan", "'Jones, Mark'", "'Hendricks, Marvin'",

"Knight, Randy",, "'Willis, Walton'", "'Willis, Walton Home'"

Date:

3/19/2011 8:58 PM

Subject: Rough Canyon Federal 30-1 Update

3/19/2011 8:56 PM

Derrick raised and centered over hole

Bill Donovan Drilling Supervisor Wolverine Gas and Oil Company of Utah, LLC Rough Canyon Federal 30-1, AFE 224 Rig (970) 361-3276 Cell (720) 351-7470 boart@drillmail.net

> **RECEIVED** MAR 2 2 2011 DIV. OF OIL, GAS & MINING

Sundry Number: 14166 API Well Number: 43039500030000

	STATE OF UTAH		FORM 9			
	5.LEASE DESIGNATION AND SERIAL NUMBER:					
I	UTU-82536					
SUNDR	6. IF INDIAN, ALLOTTEE OR TRIBE NAME:					
Do not use this form for propos bottom-hole depth, reenter plu DRILL form for such proposals.						
1. TYPE OF WELL Oil Well	8. WELL NAME and NUMBER: ROUGH CANYON FED 30-1					
2. NAME OF OPERATOR: WOLVERINE OPERATING COMP	9. API NUMBER: 43039500030000					
3. ADDRESS OF OPERATOR: One Riverfront Plaza 55 Campa	9. FIELD and POOL or WILDCAT: WILDCAT					
4. LOCATION OF WELL FOOTAGES AT SURFACE: 0288 FNL 0452 FWL	COUNTY: SANPETE					
QTR/QTR, SECTION, TOWNSHI Qtr/Qtr: NWNW Section: 32	STATE: UTAH					
CHECK APPROPRIATE BOXES TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA						
TYPE OF SUBMISSION	TYPE OF ACTION					
	☐ ACIDIZE	☐ ALTER CASING	☐ CASING REPAIR			
NOTICE OF INTENT Approximate date work will start:	☐ CHANGE TO PREVIOUS PLANS	☐ CHANGE TUBING	☐ CHANGE WELL NAME			
_	☐ CHANGE WELL STATUS	☐ COMMINGLE PRODUCING	FORMATIONS CONVERT WELL TYPE			
SUBSEQUENT REPORT Date of Work Completion:	DEEPEN	☐ FRACTURE TREAT	☐ NEW CONSTRUCTION			
	OPERATOR CHANGE	☐ PLUG AND ABANDON	☐ PLUG BACK			
SPUD REPORT	PRODUCTION START OR RESUME	☐ RECLAMATION OF WELL S	TE RECOMPLETE DIFFERENT FORMATION			
Date of Spud:	REPERFORATE CURRENT FORMATION	☐ SIDETRACK TO REPAIR W	ELL TEMPORARY ABANDON			
	☐ TUBING REPAIR	☐ VENT OR FLARE	☐ WATER DISPOSAL			
✓ DRILLING REPORT Report Date:	☐ WATER SHUTOFF	☐ SI TA STATUS EXTENSION	☐ APD EXTENSION			
3/31/2011	☐ WILDCAT WELL DETERMINATION	OTHER	OTHER:			
12 DESCRIBE PROPOSED OR CO	MPLETED OPERATIONS. Clearly show all p	pertinent details including dat	res denths volumes etc			
	see attached document for		es, deptils, volumes, etc.			
			Accepted by the			
			Utah Division of			
			Oil, Gas and Mining			
			FOR RECORD ONLY			
NAME (PLEASE PRINT) Helene Bardolph	PHONE NUMBE 616 458-1150		TITLE Engineering Administrative Assistant			
SIGNATURE N/A		DATE 4/7/2011				

Sundry Number: 14166 API Well Number: 43039500030000

Subject: Wolverine Operating Company of Utah, LLC

Rough Canyon Federal 30-1

NW¹/₄ NW¹/₄ Sec 32-T17S-R1E surface location NE¹/₄ SE¹/₄ Sec 30-T17S-R1E Projected BHL

Sanpete County, Utah.

23 February – 1 March 2011

Depth 6502' DF, 13% @ 3769' DF. Investigate problems that resulted in dropped block, rig repair. MW -9.2, Vis. -57, FL -8.5. Surveys: none.

2 March 2011

Depth 6502' DF, $13\frac{3}{8}$ @ 3769' DF. Rig repair, GIH w/ overshot in attempt to catch survey tool, wash to bottom, POOH. MW -9.2, Vis. -44, FL -17. Surveys: none.

3 March 2011

Depth 6502' DF, 13\% @ 3769' DF. POOH, LD DP & DC's. MW -9.2, Vis. - 44, FL - 17. Surveys: none.

4 March 2011

Depth 6502' DF, 13\% @ 3769' DF. LDDP, RDRT. MW -9.2, Vis. -44, FL - 17. Surveys: none. 5 March - 9 March 2011

Depth 6502' DF, 13\% @ 3769' DF. RDRT. MW -9.2, Vis. -44, FL - 17. Surveys: none.

10 March – 14 March 2011

Depth 6502' DF, $13\frac{3}{8}$ @ 3769' DF. RDMORT, clean up location and prep for MIRU Patterson rig. MW -9.2, Vis. -44, FL -17. Surveys: none.

15 March – 21 March 2011

Depth 6502' DF, 13\% @ 3769' DF. MIRU Patterson rig 304. MW -9.2, Vis. - 44, FL - 17. Surveys: none.

22 – 24 March 2011

Depth 6502' DF, 13% @ 3769' DF. MIRU Patterson rig 304. MW -9.2, Vis. -44, FL -17. Surveys: none.

25 March 2011

Depth 6502' DF, $13\frac{3}{8}$ @ 3769' DF. Build stands of drill pipe, PU bit and junk basket. MW -9.2, Vis. -44, FL -17. Surveys: none.

26 March 2011

Depth 6502' DF, $13\frac{3}{8}$ @ 3769' DF. GIH to 2977', break circulation, GIH, spot 150 bbl LCM pill at csg shoe, GIH to 6470', rig repair. MW -8.6, Vis. -48, FL -8.7. Surveys: none.

27 March 2011

Depth 6502' DF, $13\frac{3}{8}$ @ 3769' DF. Rig repair, POOH to csg shoe, rig repair. MW -8.6, Vis. -49, FL -8.1. Surveys: none.

28 March 2011

1

Sundry Number: 14166 API Well Number: 43039500030000

Depth 6505' DF, 13\% @ 3769' DF. Rig repair, GIH to 6494', break circulation, drill on junk 6494' to 6505'. MW -8.6, Vis. -51, FL - 8.8. Surveys: none.

29 March 2011

Depth 6516' DF, 13\% @ 3769' DF. Drill on junk, POOH, PU new BHA, GIH, survey. MW - 8.6, Vis. − 51, FL − 9.8. Surveys: 5.01° @ 6481'.

30 March 2011

Depth 6605' DF, 13\% @ 3769' DF. Work on lost circulation, drill, POOH to casing shoe, build mud volume, GIH, MWD not responding, spot LCM pill. MW -8.6, Vis. -49, FL - 8.1. Surveys: none.

31 March 2011

Depth 6605' DF, 13\% @ 3769' DF. Wait on LCM pill to soak, pump LCM pill, wait on pill to soak, pump LCM pill, wait on pill to soak, POOH, change MWD, GIH w/ new bit. MW - 8.6, Vis. - 49, FL -8.1. Surveys: none.

Carol Daniels - Rough Canyon Federal 30-1 Update + 175 ROIE 5-32 4303950003

"Wolverine Supervisor" From: "'Daniels, Carol'", "Doucet, Dustin", "Jarvis, Dan", "'Jones, Mark'", "'Hendricks, Marvin'", "Knight, Randy", "'Willis, Walton'", "'Willis, Walton Home'" To: 4/6/2011 11:28 AM Date: **Subject:** Rough Canyon Federal 30-1 Update 4/6/2011 7:00 AM Drilling 12 1/2" with aerated mud at 7082', 3 fph. 4/5/2011 6:32 AM Drilling with aerated mud at 6999', 6 fph. 4/3/2011 1:15 PM RECEIVED Drilling with aerated mud at 6885', 4.5 fph. APR 0 6 2011 DIV. OF OIL, GAS & MINING 4/1/2011 4:29 PM Drilling with aerated mud at 6659', 6.3 fph.

3/31/2011 6:57 AM

Current depth is 6605'. Making trip to continue drilling 12.25" hole.

Tom Zupan Drilling Supervisor Wolverine Gas and Oil Company of Utah, LLC Rig (970) 361-3276 Cell (970) 314-8219

wolvexpl@drillmail.net

Carol Daniels - Rough Canyon Federal 30-1 Update T17S ROIES-32 43-039-50003 From: "Wolverine Supervisor" "'Daniels, Carol'", "Doucet, Dustin", "Jarvis, Dan", "'Jones, Mark'", "'Hendricks, Marvin'", "Knight, Randy", "Willis, Walton", "Willis, Walton Home'" To: 4/7/2011 6:39 AM Date: Subject: Rough Canyon Federal 30-1 Update 4/7/2011 6:35 AM PONEIDENITIAL Drilling with aerated mud at 7200', 5 fph. 4/6/2011 7:00 AM Drilling 12 ¼" with aerated mud at 7082', 3 fph. 4/5/2011 6:32 AM Drilling with aerated mud at 6999', 6 fph. **PLCEIVED** APR 0 / 2011 4/3/2011 1:15 PM DIV. OF OIL, GAS & MINING Drilling with aerated mud at 6885', 4.5 fph. 4/1/2011 4:29 PM Drilling with aerated mud at 6659', 6.3 fph. 3/31/2011 6:57 AM Current depth is 6605'. Making trip to continue drilling 12.25" hole. **Tom Zupan Drilling Supervisor**

wolvexpl@drillmail.net

Rig (970) 361-3276 Cell (970) 314-8219

Wolverine Gas and Oil Company of Utah, LLC

Carol Daniels - Rough Canyon Federal 30-1 Update T175 ROLE 5-32 43-039-50003

From: "Wolverine Supervisor" "'Daniels, Carol'", "Doucet, Dustin", "Jarvis, Dan", "'Jones, Mark'", "'Hendricks, Marvin'", "Knight, Randy", "'Willis, Walton'", "'Willis, Walton Home'" To: Date: 4/8/2011 7:01 AM Subject: Rough Canyon Federal 30-1 Update 4/8/2011 6:58 AM Trip in with new bit and stabs at 432'. TD is 7258'. 4/7/2011 6:35 AM Drilling with aerated mud at 7200', 5 fph. 4/6/2011 7:00 AM Drilling 12 1/2" with aerated mud at 7082', 3 fph. 4/5/2011 6:32 AM Drilling with aerated mud at 6999', 6 fph. RECEIVED 4/3/2011 1:15 PM APR 1 3 2011 DIV. OF OIL, GAS & MINING Drilling with aerated mud at 6885', 4.5 fph. 4/1/2011 4:29 PM Drilling with aerated mud at 6659', 6.3 fph. 3/31/2011 6:57 AM Current depth is 6605'. Making trip to continue drilling 12.25" hole.

Carol Daniels - Rough Canyon Federal 30-1 Update 7/98 ROIE 5-32 43-039-50003

From:

"Wolverine Supervisor"

To:

"'Daniels, Carol'", "Doucet, Dustin", "Jarvis, Dan", "'Jones, Mark'", "'Hendricks, Marvin'", "Knight, Randy", , "'Willis, Walton'", "'Willis, Walton Home'"

Date:

4/9/2011 7:03 AM

Subject: Rough Canyon Federal 30-1 Update

4/9/2011 7:00 AM

Drilling at 7,327', ROP 4-5 fph

Bill Donovan Drilling Supervisor Wolverine Gas and Oil Company of Utah, LLC Rough Canyon Federal 30-1, AFE 224 Rig (970) 361-3276 Cell (720) 351-7470 wolvexpl@drillmail.net

> RECEIVED APR 1 3 2011

Carol Daniels - Rough Canyon Federal 30-1 Update

From:

"Wolverine Supervisor"

To:

"Hendricks, Marvin", "Knight, Randy", "Willis, Walton", "Willis, Walton Home",

"Daniels, Carol", "Doucet, Dustin", "Jarvis, Dan", "Jones, Mark"

Date:

4/10/2011 6:21 AM

Subject: Rough Canyon Federal 30-1 Update

4/10/2011 6:19 AM

Drilling at 7,413', ROP 4 fph

Bill Donovan Drilling Supervisor Wolverine Gas and Oil Company of Utah, LLC Rough Canyon Federal 30-1, AFE 224 Rig (970) 361-3276 Cell (720) 351-7470 wolvexpl@drillmail.net

> RECEIVED APR 1 3 2011

Carol Daniels - Rough Canyon Federal 30-1 Update 7/15 POLF 5-20 43-039. 50003

From:

"Wolverine Supervisor"

To:

"'Hendricks, Marvin'", "Knight, Randy", , "'Willis, Walton'", "'Willis, Walton Home'", "Daniels, Carol'", "Doucet, Dustin", "Jarvis, Dan", "Jones, Mark'"

Date:

4/11/2011 6:59 AM

Subject: Rough Canyon Federal 30-1 Update

4/11/2011 6:55 AM

Drilling at 7,533', PR 5-8 fph

Casing point has not been determined

Bill Donovan Drilling Supervisor Wolverine Gas and Oil Company of Utah, LLC Rough Canyon Federal 30-1, AFE 224 Rig (970) 361-3276 Cell (720) 351-7470 wolvexpl@drillmail.net

> RECEIVED APR 1 3 2011

Carol Daniels - Rough Canyon Federal 30-1 Update TIDS ROLE 5-32 43-039-50003

From:

"Wolverine Supervisor"

To:

"'Hendricks, Marvin'" , "Knight, Randy" , , "'Willis, Walton'" , "'Willis, Walton Home'" , "'Daniels, Carol'" , "Doucet, Dustin" , "Jarvis, Dan" , "'Jones, Mark'"

Date:

4/12/2011 7:22 AM

Subject: Rough Canyon Federal 30-1 Update

4/12/2011 7:19 AM

Hole depth 7,596', TIH w/NB

Bill Donovan Drilling Supervisor Wolverine Gas and Oil Company of Utah, LLC Rough Canyon Federal 30-1, AFE 224 Rig (970) 361-3276 Cell (720) 351-7470 wolvexpl@drillmail.net

> RECEIVED APR 1 3 2011

Carol Daniels - Rough Canyon Federal 30-1 Update 7 /75 ROIE 5-32 43-039-50003

From:

"Wolverine Supervisor"

To:

"'Daniels, Carol'", "Doucet, Dustin", "Jarvis, Dan", "'Jones, Mark'", "'Hendricks, Marvin'", "Knight, Randy", "Willis, Walton'", "'Willis, Walton Home'"

Date:

4/14/2011 7:07 AM

Subject: Rough Canyon Federal 30-1 Update

4/14/2011 7:04 AM

Drilling at 7,670'

Casing point has not been determined

Bill Donovan Drilling Supervisor Wolverine Gas and Oil Company of Utah, LLC Rough Canyon Federal 30-1, AFE 224 Rig (970) 361-3276 Cell (720) 351-7470 wolvexpl@drillmail.net

> RECEIVED APR 1 4 2011

Carol Daniels - Rough Canyon Federal 30-1 Update TITS ROIE S-31 4303950003

From: "Wolverine Supervisor"

To: "Hendricks, Marvin'", "Knight, Randy", "Willis, Walton'", "Willis, Walton Home",

""Daniels, Carol", "Doucet, Dustin", "Jarvis, Dan", "'Jones, Mark'"

Date: 4/20/2011 7:22 AM

Subject: Rough Canyon Federal 30-1 Update

4/20/2011 7:17 AM

Drilling at 8,182', PR 6 fph

Geologist seeing some changes. Casing point has not been determined

Bill Donovan
Drilling Supervisor
Wolverine Gas and Oil Company of Utah, LLC
Rough Canyon Federal 30-1, AFE 224
Rig (970) 361-3276
Cell (720) 351-7470
wolvexpl@drillmail.net

RECEIVED
APR 2 0 2011

Carol Daniels - Rough Canyon Federal 30-1, Update 7/73 ROLE 5-32 43039-50003

From:

"Wolverine Supervisor"

To:

"'Hendricks, Marvin'", "Knight, Randy", , "'Willis, Walton'", "'Willis, Walton Home'", "Daniels, Carol'", "Doucet, Dustin", "Jarvis, Dan", "'Jones, Mark'"

Date:

4/15/2011 7:20 AM

Subject: Rough Canyon Federal 30-1, Update

4/15/2011 7:17 AM

Drilling at 7,772', ROP 7 FPH

Bill Donovan **Drilling Supervisor** Wolverine Gas and Oil Company of Utah, LLC Rough Canyon Federal 30-1, AFE 224 Rig (970) 361-3276 Cell (720) 351-7470 wolvexpl@drillmail.net

> RECEIVED APR 1 8 2011

Carol Daniels - Rough Canyon Federal 30-1 Update T175R01E5-32 4303950003

From:

"Wolverine Supervisor"

To:

"'Hendricks, Marvin'" , "Knight, Randy" , , "'Willis, Walton'" , "'Willis, Walton Home'" , "'Daniels, Carol'" , "Doucet, Dustin" , "Jarvis, Dan" , "'Jones, Mark'"

Date:

4/17/2011 8:09 AM

Subject: Rough Canyon Federal 30-1 Update

4/17/2011 8:05 AM

Depth 7,826', PR 1 FPH

Casing point has not been determined

Bill Donovan Drilling Supervisor Wolverine Gas and Oil Company of Utah, LLC Rough Canyon Federal 30-1, AFE 224 Rig (970) 361-3276 Cell (720) 351-7470 wolvexpl@drillmail.net

> RECEIVED APR 1 8 2011

Carol Daniels - Rough Canyon Federal 30-1 Update 1175 ROIE 5-32 43-039-5000

From:

"Wolverine Supervisor"

To:

"'Hendricks, Marvin'", "Knight, Randy", , "'Willis, Walton'", "'Willis, Walton Home'", "Daniels, Carol'", "Doucet, Dustin", "Jarvis, Dan", "Jones, Mark"

4/18/2011 7:21 AM Date:

Subject: Rough Canyon Federal 30-1 Update

4/18/2011 7:15 AM

Drilling at 7,851', PR 5 fph

Casing point has not been determined

Bill Donovan Drilling Supervisor Wolverine Gas and Oil Company of Utah, LLC Rough Canyon Federal 30-1, AFE 224 Rig (970) 361-3276 Cell (720) 351-7470 wolvexpl@drillmail.net

> RECEIVED APR 1 8 2011

Carol Daniels - Rough Canyon Federal 30-1 Update

From:

"Wolverine Supervisor"

To:

"Hendricks, Marvin'", "Knight, Randy", , "Willis, Walton'", "Willis, Walton Home",

"Daniels, Carol", "Doucet, Dustin", "Jarvis, Dan", "Jones, Mark"

Date:

4/22/2011 7:02 AM

Subject: Rough Canyon Federal 30-1 Update

4/22/2011 6:57 AM

Hole depth 8,424', TOH for bit

The Geologist has a correlation and an estimated depth for casing

Bill Donovan Drilling Supervisor Wolverine Gas and Oil Company of Utah, LLC Rough Canyon Federal 30-1, AFE 224 Rig (970) 361-3276 Cell (720) 351-7470 wolvexpl@drillmail.net

RECEIVED

APR 2 6 2011

Carol Daniels - Rough Canyon Federal 30-1 Update -POLF 5-32

From:

"Wolverine Supervisor"

To:

"'Hendricks, Marvin'", "Knight, Randy", , "'Willis, Walton'", "'Willis, Walton Home'", "Daniels, Carol'", "Doucet, Dustin", "Jarvis, Dan", "'Jones, Mark'"

Date:

4/24/2011 7:22 AM

Subject: Rough Canyon Federal 30-1 Update

4/24/2011 7:20 AM

Drilling at 8443'.

Tom Zupan Drilling Supervisor Wolverine Gas and Oil Company of Utah, LLC Rig (970) 361-3276 Cell (970) 314-8219

wolvexpl@drillmail.net

RECEIVED

APR 2 6 2011

Carol Daniels - Rough Canyon Federal 30-1 Update T175 ROIE 3-32 43-039-50003

From: "Wolverine Supervisor"

"'Hendricks, Marvin'", "Knight, Randy", , "'Willis, Walton'", "'Willis, Walton Home'", "Daniels, Carol'", "Doucet, Dustin", "Jarvis, Dan", "Jones, Mark" To:

4/25/2011 6:48 AM Date:

Subject: Rough Canyon Federal 30-1 Update

4/25/2011 6:47 AM

Drilling at 8545'.

Tom Zupan Drilling Supervisor Wolverine Gas and Oil Company of Utah, LLC Rig (970) 361-3276 Cell (970) 314-8219

wolvexpl@drillmail.net

RECEIVED

APR 2 6 2011

Carol Daniels - Rough Canyon Federal 30-1 Update -

From:

"Wolverine Supervisor"

To:

"'Hendricks, Marvin'", "Knight, Randy", , "'Willis, Walton'", "'Willis, Walton Home'",

"Daniels, Carol", "Doucet, Dustin", "Jarvis, Dan", "'Jones, Mark'"

Date:

4/26/2011 6:39 AM

Subject: Rough Canyon Federal 30-1 Update

4/26/2011 6:37 AM

Drilling at 8622'.

Tom Zupan Drilling Supervisor Wolverine Gas and Oil Company of Utah, LLC Rig (970) 361-3276 Cell (970) 314-8219

wolvexpl@drillmail.net

RECEIVED APR 2 6 2011

	STATE OF UTAH			FORM 9		
	E LEASE DESCRIPTION AND SERVAL NUMBER.					
	5.LEASE DESIGNATION AND SERIAL NUMBER: UTU-82536					
SUNDR	6. IF INDIAN, ALLOTTEE OR TRIBE NAME:					
Do not use this form for propos bottom-hole depth, reenter plu DRILL form for such proposals.	7.UNIT or CA AGREEMENT NAME:					
1. TYPE OF WELL Oil Well	8. WELL NAME and NUMBER: ROUGH CANYON FED 30-1					
2. NAME OF OPERATOR: WOLVERINE OPERATING COMPANY OF UTAH, LLC				9. API NUMBER: 43039500030000		
3. ADDRESS OF OPERATOR: One Riverfront Plaza 55 Campau NW, Grand Rapids, MI, 49503 PHONE NUMBER: 616 458-1150 Ext				9. FIELD and POOL or WILDCAT: WILDCAT		
4. LOCATION OF WELL FOOTAGES AT SURFACE: 0288 FNL 0452 FWL				COUNTY: SANPETE		
QTR/QTR, SECTION, TOWNSHIP, RANGE, MERIDIAN: Qtr/Qtr: NWNW Section: 32 Township: 17.0S Range: 01.0E Meridian: S			STATE: UTAH			
CHECK APPROPRIATE BOXES TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA						
TYPE OF SUBMISSION	TYPE OF ACTION					
	ACIDIZE	☐ ALTER C	ASING	CASING REPAIR		
NOTICE OF INTENT Approximate date work will start:	☐ CHANGE TO PREVIOUS PLANS	☐ CHANGE	TUBING	☐ CHANGE WELL NAME		
Approximate date work will start.	☐ CHANGE WELL STATUS	Соммін	GLE PRODUCING FORMATIONS	☐ CONVERT WELL TYPE		
SUBSEQUENT REPORT Date of Work Completion:	☐ DEEPEN	FRACTU	RE TREAT	☐ NEW CONSTRUCTION		
	OPERATOR CHANGE	☐ PLUG AN	ID ABANDON	☐ PLUG BACK		
SPUD REPORT	☐ PRODUCTION START OR RESUME	RECLAM	ATION OF WELL SITE	☐ RECOMPLETE DIFFERENT FORMATION		
Date of Spud:	☐ REPERFORATE CURRENT FORMATION	SIDETRA	ACK TO REPAIR WELL	☐ TEMPORARY ABANDON		
✓ DRILLING REPORT Report Date:	☐ TUBING REPAIR	U VENT OF	t FLARE	☐ WATER DISPOSAL		
	☐ WATER SHUTOFF	☐ SI TA ST	ATUS EXTENSION	☐ APD EXTENSION		
4/30/2011	☐ WILDCAT WELL DETERMINATION	OTHER		OTHER:		
	MPLETED OPERATIONS. Clearly show all p			olumes, etc.		
Please see attached file for drilling details.						
			Δ	ccepted by the		
				Itah Division of		
				, Gas and Mining		
			FOR	RECORD ONLY		
				THE COMP ONE		
NAME (PLEASE PRINT) Helene Bardolph PHONE NUMBER 616 458-1150			TITLE Engineering Administrative Assistant			
SIGNATURE			DATE 5/11/2011			
N/A		5/11	/2011			

Wolverine Operating Company of Utah, LLC Rough Canyon Federal 30-1 NW¼ NW¼ Sec 32-T17S-R1E surface location NE¼ SE¼ Sec 30-T17S-R1E Projected BHL Sanpete County, Utah.

April 2011 Drilling Summary

1 April 2011

Depth 6615' DF, 13. @ 3769' DF. Build mud volume, weight up to 8.8 ppg, add 15 ppb LCM, GIH, wash and ream to bottom, drill, pump service. MW -8.8, Vis. - 55, FL - 7. Surveys: none.

2 April 2011

Depth 6731' DF, 13. @ 3769' DF. Pump service, drill & survey. MW - 8.9, Vis. - 55, FL - 9.8. Surveys: 5.01° @ 6640'.

3 April 2011

Depth 6858' DF, 13. @ 3769' DF. Drill & survey. MW - 8.8, Vis. - 54, FL - 14. Surveys: 4.92°@ 6738'.

4 April 2011

Depth 6953' DF, 13. @ 3769' DF. Drill & survey, C&C, POOH. MW - 8.8, Vis. - 44, FL - 13. Surveys: 4.9° @ 6830'.

5 April 2011

Depth 6995' DF, 13. @ 3769' DF. POOH, change bit and stabilizers, GIH, ream to btm, drill to 6995. MW - 8.8, Vis. - 41, FL - 12.6. Surveys: 5.1° @ 6915' & 5.19°@ 6924'.

6 April 2011

Depth 7080' DF, 13. @ 3769' DF. Drill & survey. MW - 8.9, Vis. - 48, FL - 9.2. Surveys: 5.01° @ 7016'.

7 April 2011

Depth 7197' DF, 13. @ 3769' DF. Drill & survey. MW -8.95, Vis. - 48, FL - 9. Surveys: 4.92° @ 7117'.

8 April 2011

Depth 7258' DF, 13. @ 3769' DF. Drill & survey, TFNB. MW - 8.8, Vis. - 51, FL - 6. Surveys: 4.92° @ 7246'.

9 April 2011

Depth 7323' DF, 13. @ 3769' DF. GIH, ream to bottom, drill. MW -8.8, Vis. -50, FL -7.8. Surveys: none.

10 April 2011

Depth 7412' DF, 13. @ 3769' DF. Drill & survey. MW - 8.8, Vis. - 63, FL

- 7.6. Surveys: 5.1° @ 7313′.

11 April 2011

Depth 7531' DF, 13. @ 3769' DF. Drill & survey. MW - 8.8, Vis. - 75, FL - 7.4. Surveys: 5.32°@ 7408'.

12 April 2011

Depth 7596' DF, 13. @ 3769' DF. Drill & survey, POOH. MW - 8.8, Vis. - 67, FL - 7.2. Surveys: 5.8° @ 7568'.

13 April 2011

Depth 7596' DF, 13. @ 3769' DF. PU bit, IBS & reamer, GIH, ream to bottom. MW -8.7, Vis. - 56, FL - 7.5. Surveys: none.

14 April 2011

Depth 7665' DF, 13. @ 3769' DF. Ream to bottom, drill & survey. MW - 8.9, Vis. - 53, FL - 7. Surveys: 5.8° @ 7596'.

15 April 2011

Depth 7766' DF, 13. @ 3769' DF. Drill & survey. MW -8.8, Vis. - 67, FL - 6. Surveys: 5.8° @ 7691'.

16 April 2011

Depth 7794' DF, 13. @ 3769' DF. Drill & survey, POOH, PU new bit, pump service. MW - 8.8, Vis. - 58, FL - 6.8. Surveys: 5.8° @ 7741'.

17 April 2011

Depth 7825' DF, 13. @ 3769' DF. Pump service, GIH, drill & survey. MW - 8.8, Vis. - 60, FL - 7. Surveys: 5.89°@ 7786'.

18 April 2011

Depth 7844' DF, 13. @ 3769' DF. Drill & survey, TFNB, drill. MW - 8.8, Vis. - 52, FL - 6.5. Surveys: 5.89°@ 7775'.

19 April 2011

Depth 8011' DF, 13. @ 3769' DF. Drill & survey. MW - 8.8, Vis. - 52, FL - 6.8. Surveys: 6° @ 7880'.

20 April 2011

Depth 8174' DF, 13. @ 3769' DF. Drill & survey. MW -8.9, Vis. - 60, FL - 6.5. Surveys: 6.4° @ 8071'.

21 April 2011

Depth 8331' DF, 13. @ 3769' DF. Drill & survey. MW - 8.8, Vis. - 64, FL - 7. Surveys: 7.1° @ 8165' & 7.9° @ 8260'.

22 April 2011

Depth 8424' DF, 13. @ 3769' DF. Drill & survey, C&C, POOH. MW -8.8, Vis. - 50, FL - 6. Surveys: 8.8° @ 8351'.

23 April 2011

Depth 8438' DF, 13. @ 3769' DF. POOH, change BHA, GIH, drill. MW - 8.8,

Vis. - 62, FL - 6.4. Surveys: none.

24 April 2011

Depth 8439' DF, 13. @ 3769' DF. Drill, C&C, POOH, change BHA, GIH, W&R to bottom. MW - 8.8, Vis. - 50, FL - 7. Surveys: none.

25 April 2011

Depth 8542' DF, 13. @ 3769' DF. Drill & survey. MW - 8.8, Vis. - 58, FL - 6.8. Surveys: 9°@ 8396' & 9° @ 8481'.

26 April 2011

Depth 8619' DF, 13. @ 3769' DF. Drill & survey. MW - 8.8, Vis. - 55, FL - 7. Surveys: 9.4° @ 8541'.

27 April 2011

Depth 8619' DF, 13. @ 3769' DF. Drill & survey, TFNB, GIH. MW -8.8, Vis. - 52, FL - 7.1. Surveys: 9.4° @ 8541'.

28 April 2011

Depth 8772' DF, 13. @ 3769' DF. Drill & survey. MW - 8.8, Vis. - 60, FL - 6.7. Surveys: 9.49° @ 8641' & 9.71° @ 8721'.

29 April 2011

Depth 8863' DF, 13. @ 3769' DF. Drill & survey. MW -8.8, Vis. - 57, FL - 7. Surveys: 9.89° @ 8812'.

30 April 2011

Depth 8966' DF, 13. @ 3769' DF. Drill & survey. MW - 8.8, Vis. - 54, FL - 7.9. Surveys: 10.11° @ 8907'.

Carol Daniels - Rough Canyon Federal 30-1 Update

43-039-50003

From:

"Wolverine Supervisor"

To:

"'Hendricks, Marvin'", "Knight, Randy", , "'Willis, Walton'", "'Willis, Walton Home'", "Daniels, Carol'", "Doucet, Dustin", "Jarvis, Dan", "Jones, Mark'"

Date:

4/27/2011 7:06 AM

Subject: Rough Canyon Federal 30-1 Update

4/27/2011 7:04 AM

Made bit trip and drilling at 8656'.

Tom Zupan **Drilling Supervisor** Wolverine Gas and Oil Company of Utah, LLC Rig (970) 361-3276 Cell (970) 314-8219

wolvexpl@drillmail.net

RECEIVED APR 2 7 2011

Carol Daniels - Rough Canyon Federal 30-1 Update T113 ROLE 5-32 43-039-50003

From:

"Wolverine Supervisor"

To:

"'Hendricks, Marvin'", "Knight, Randy", , "'Willis, Walton'", "'Willis, Walton Home'", "Daniels, Carol", "Doucet, Dustin", "Jarvis, Dan", "'Jones, Mark'"

Date:

4/28/2011 6:45 AM

Subject: Rough Canyon Federal 30-1 Update

4/28/2011 6:43 AM

Drilling at 8776'.

Tom Zupan **Drilling Supervisor** Wolverine Gas and Oil Company of Utah, LLC Rig (970) 361-3276 Cell (970) 314-8219

wolvexpl@drillmail.net

RECEIVED APR 2 8 2011

Carol Daniels - Rough Canyon Federal 30-1 Update TIDS ROLE 5-32, 43-039-50003

From:

"Wolverine Supervisor"

To:

"'Hendricks, Marvin'", "Knight, Randy", , "'Willis, Walton'", "'Willis, Walton Home'", "Daniels, Carol'", "Doucet, Dustin", "Jarvis, Dan", "Jones, Mark"

Date:

4/29/2011 6:54 AM

Subject: Rough Canyon Federal 30-1 Update

4/29/2011 6:50 AM

Drilling at 8866'.

Tom Zupan **Drilling Supervisor** Wolverine Gas and Oil Company of Utah, LLC Rig (970) 361-3276 Cell (970) 314-8219

wolvexpl@drillmail.net

RECEIVED MAY 02 2011

Carol Daniels - Rough Canyon Federal 30-1 Update TIPS ROLE 5-32 43-039-5003

From:

"Wolverine Exploration Rig"

To:

"'Hendricks, Marvin'", "Knight, Randy", , "'Willis, Walton'", "'Willis, Walton Home'",

"Daniels, Carol", "Doucet, Dustin", "Jarvis, Dan", "'Jones, Mark'"

Date:

4/30/2011 7:08 AM

Subject: Rough Canyon Federal 30-1 Update

4/30/2011 7:02 AM

Drilling at 8969'.

Note: Soon operations for the Boart Longyear Rig will begin on the Denmark Wash Fed 15-2 well. The supervisor for that rig will be using the boart@drillmail.net email address. Please begin to use that address for Boart/Denmark Wash issues.

The supervisor for the Patterson 304 on the Rough Canyon Fed 30-1 operation will be using only the wolvexpl@drillmail.net email address. Please use only this address for the Patterson/Rough Canyon issues.

Thank you, Tom

Tom Zupan Drilling Supervisor Wolverine Gas and Oil Company of Utah, LLC Rig (970) 361-3276 Cell (970) 314-8219

wolvexpl@drillmail.net

RECEIVED MAY 0 2 2011

DIY OF OIL GAS & MININE

Carol Daniels - Rough Canyon Federal 30-1 Update TIPS ROIE 5-32 43-039-50003

From:

"Wolverine Exploration Rig"

To:

"'Hendricks, Marvin'", "Knight, Randy", "Willis, Walton'", "Willis, Walton Home'",

"'Daniels, Carol'", "Doucet, Dustin", "Jarvis, Dan", "'Jones, Mark'"

Date:

5/1/2011 4:11 PM

Subject: Rough Canyon Federal 30-1 Update

5/1/2011 7:13 AM

Drlg @ 9063'.

Note: Soon operations for the Boart Longyear Rig will begin on the Denmark Wash Fed 15-2 well. The supervisor for that rig will be using the boart@drillmail.net email address. Please begin to use that address for Boart/Denmark Wash issues.

The supervisor for the Patterson 304 on the Rough Canyon Fed 30-1 operation will be using only the wolvexpl@drillmail.net email address. Please use only this address for the Patterson/Rough Canyon issues.

Thank you, Tom

Tom Zupan Drilling Supervisor Wolverine Gas and Oil Company of Utah, LLC Rig (970) 361-3276 Cell (970) 314-8219

wolvexpl@drillmail.net

RECEIVED MAY 02 2011

Carol Daniels - Rough Canyon Federal 30-1 Update TIPS ROLE 5-32 43-039-50003

From:

"Wolverine Exploration Rig"

To:

"'Hendricks, Marvin'", "Knight, Randy", "Willis, Walton'", "Willis, Walton Home'",

"Daniels, Carol", "Doucet, Dustin", "Jarvis, Dan", "'Jones, Mark'"

Date:

5/2/2011 6:27 AM

Subject: Rough Canyon Federal 30-1 Update

5/2/2011 6:24 AM

Tripping at 826'

Note: Soon operations for the Boart Longyear Rig will begin on the Denmark Wash Fed 15-2 well. The supervisor for that rig will be using the <u>boart@drillmail.net</u> email address. Please begin to use that address for Boart/Denmark Wash issues.

The supervisor for the Patterson 304 on the Rough Canyon Fed 30-1 operation will be using only the wolvexpl@drillmail.net email address. Please use only this address for the Patterson/Rough Canyon issues.

Thank you, Tom

Tom Zupan Drilling Supervisor Wolverine Gas and Oil Company of Utah, LLC Rig (970) 361-3276 Cell (970) 314-8219

wolvexpl@drillmail.net

RECEIVED MAY 02 2011

Page 1 of 1

Carol Daniels - Rough Canyon Federal 30-1 Update TI15 ROLE S-32 43 03950003

From:

"Wolverine Exploration Rig"

To:

"Hendricks, Marvin", "Knight, Randy", "Willis, Walton", "Willis, Walton Home",

"Daniels, Carol", "Doucet, Dustin", "Jarvis, Dan", "'Jones, Mark'"

Date:

5/3/2011 7:08 AM

Subject: Rough Canyon Federal 30-1 Update

5/3/2011 7:04 AM

Drilling at 9196'

Note: Soon operations for the Boart Longyear Rig will begin on the Denmark Wash Fed 15-2 well. The supervisor for that rig will be using the boart@drillmail.net email address. Please begin to use that address for Boart/Denmark Wash issues. 970-812-0022 phone

The supervisor for the Patterson 304 on the Rough Canyon Fed 30-1 operation will be using only the wolvexpl@drillmail.net email address. Please use only this address for the Patterson/Rough Canyon issues. 970-361-3276 phone.

Thank you, Tom

Tom Zupan Drilling Supervisor Wolverine Gas and Oil Company of Utah, LLC Rig (970) 361-3276 Cell (970) 314-8219

wolvexpl@drillmail.net

RECEIVED MAY 0 3 2011

Carol Daniels - Rough Canyon Federal 30-1 Update 7 17.5 ROVE S-32 43-039-50003

From:

"Wolverine Exploration Rig"

To:

"Hendricks, Marvin", "Knight, Randy", "Willis, Walton", "Willis, Walton Home",

"'Daniels, Carol'", "Doucet, Dustin", "Jarvis, Dan", "'Jones, Mark'"

Date:

5/4/2011 7:13 AM

Subject: Rough Canyon Federal 30-1 Update

5/4/2011 7:11 AM

Drilling at 9291'.

Note: Soon operations for the Boart Longyear Rig will begin on the Denmark Wash Fed 15-2 well. The supervisor for that rig will be using the boart@drillmail.net email address. Please begin to use that address for Boart/Denmark Wash issues. 970-812-0022 phone

The supervisor for the Patterson 304 on the Rough Canyon Fed 30-1 operation will be using only the wolvexpl@drillmail.net email address. Please use only this address for the Patterson/Rough Canyon issues. 970-361-3276 phone.

Thank you, Tom

Tom Zupan **Drilling Supervisor** Wolverine Gas and Oil Company of Utah, LLC Rig (970) 361-3276 Cell (970) 314-8219

wolvexpl@drillmail.net

RECEIVED MAY 0 4 2011

Carol Daniels - Rough Canyon Federal 30-1 Update 7/25 ROIES-32 43.039-50003

From:

"Wolverine Exploration Rig"

To:

"'Hendricks, Marvin'", "Knight, Randy", , "'Willis, Walton'", "'Willis, Walton Home'",

"Daniels, Carol", "Doucet, Dustin", "Jarvis, Dan", "Jones, Mark"

Date:

5/5/2011 7:08 AM

Subject: Rough Canyon Federal 30-1 Update

5/5/2011 7:04 AM

Drilling at 9353'

Note: Soon operations for the Boart Longyear Rig will begin on the Denmark Wash Fed 15-2 well. The supervisor for that rig will be using the boart@drillmail.net email address. Please begin to use that address for Boart/Denmark Wash issues. 970-812-0022 phone

The supervisor for the Patterson 304 on the Rough Canyon Fed 30-1 operation will be using only the wolvexpl@drillmail.net email address. Please use only this address for the Patterson/Rough Canyon issues. 970-361-3276 phone.

Thank you, Tom

Tom Zupan Drilling Supervisor Wolverine Gas and Oil Company of Utah, LLC Rig (970) 361-3276 Cell (970) 314-8219

wolvexpl@drillmail.net

RECEIVED MAY 0 5 2011

Carol Daniels - Rough Canyon Federal 30-1 Update + 175 ROLE 5-32 43-039-50003

From:

"Wolverine Exploration Rig"

To:

"Hendricks, Marvin", "Knight, Randy", , "Willis, Walton", "Willis, Walton Home",

"'Daniels, Carol", "Doucet, Dustin", "Jarvis, Dan", "'Jones, Mark'"

Date:

5/6/2011 7:03 AM

Subject: Rough Canyon Federal 30-1 Update

5/6/2011 7:00 AM

Drilling at 9407'

Note: Soon operations for the Boart Longyear Rig will begin on the Denmark Wash Fed 15-2 well. The supervisor for that rig will be using the boart@drillmail.net email address. Please begin to use that address for Boart/Denmark Wash issues. 970-812-0022 phone

The supervisor for the Patterson 304 on the Rough Canyon Fed 30-1 operation will be using only the wolvexpl@drillmail.net email address. Please use only this address for the Patterson/Rough Canyon issues. 970-361-3276 phone.

Thank you, Tom

Tom Zupan Drilling Supervisor Wolverine Gas and Oil Company of Utah, LLC Rig (970) 361-3276 Cell (970) 314-8219

wolvexpl@drillmail.net

RECEIVED
MAY 0 9 2011

Carol Daniels - Rough Canyon Federal 30-1 Update T195 ROIES-32 43-039-50003

From:

"Wolverine Exploration Rig"

To:

"'Hendricks, Marvin'", "Knight, Randy", "Willis, Walton'", "Willis, Walton Home'",

""Daniels, Carol", "Doucet, Dustin", "Jarvis, Dan", ""Jones, Mark"

Date:

5/7/2011 7:04 AM

Subject: Rough Canyon Federal 30-1 Update

5/7/2011 6:58 AM

Drilling at 9482'

Note: Operations for the Boart Longyear Rig have begun on the Denmark Wash Fed 15-2 well. The supervisor for that rig will be using the boart@drillmail.net email address. Please begin to use that address for Boart/Denmark Wash issues. 970-812-0022 phone

The supervisor for the Patterson 304 on the Rough Canyon Fed 30-1 operation will be using only the wolvexpl@drillmail.net email address. Please use only this address for the Patterson/Rough Canyon issues. 970-361-3276 phone.

Thank you, Tom

Tom Zupan Drilling Supervisor Wolverine Gas and Oil Company of Utah, LLC Rig (970) 361-3276 Cell (970) 314-8219

wolvexpl@drillmail.net

RECEIVED MAY 0 9 2011

Carol Daniels - Rough Canyon Federal 30-1 Update T125 ROLF 5-32 43-039-50003

From:

"Wolverine Exploration Rig"

To:

"Hendricks, Marvin'", "Knight, Randy", "Willis, Walton'", "Willis, Walton Home",

"Daniels, Carol", "Doucet, Dustin", "Jarvis, Dan", "'Jones, Mark'"

Date:

5/7/2011 6:38 PM

Subject: Rough Canyon Federal 30-1 Update

RECEIVED

MAY 0.9 2011

55/7/2011 6:29 PM

DIV. OF OIL, GAS & MINING

Drilled to 9482'. POOH, left 3 cones in the hole. Waiting on Magnet to fish cones. 9 5/8" casing point has been declared at 9482'. See schedule below.

				ESTIMATED SCHEDULE
DATE	DAY	START	HR	DESCRIPTION
		TIME		
7-May	Saturday	17:00	5.50	Wait on fishing tools
7-May		22:30	2.00	Work BHA
8-May	Sunday	0:30	5.00	TIH
		5:30	2.00	Circ and work magnet
		7:30	6.00	РООН
		13:30	9.00	Wireline log
		22:30	2.00	Work BHA
9-May	Monday	0:30	5.00	TIH
		5:30	2.00	Circ and condition for logs/casing
		7:30	3.00	POOH to shoe
		10:30	2.00	Run gyro survey inside 5" dp
		12:30	3.00	Continue to POOH
		15:30	3.00	RU Franks Casing Crews
		18:30	18.00	Run 9 5/8" casing
10-May	Tuesday	12:30	2.00	Circulate & RU Dowell
		14:30	5.00	Cement Stage 1
		19:30	2.00	Open DV and Circulate
		21:30	3.00	Cement Stage 2
11-May	Wednesday	0:30		

Note: Operations for the Boart Longyear Rig have begun on the Denmark Wash Fed 15-2 well. The supervisor for that rig will be using the boart@drillmail.net email address. Please begin to use that address for Boart/Denmark Wash issues. 970-812-0022 phone

The supervisor for the Patterson 304 on the Rough Canyon Fed 30-1 operation will be using only the wolvexpl@drillmail.net email address. Please use only this address for the Patterson/Rough Canyon issues. 970-361-3276 phone.

Thank you, Tom

Tom Zupan **Drilling Supervisor** Wolverine Gas and Oil Company of Utah, LLC Rig (970) 361-3276 Cell (970) 314-8219

wolvexpl@drillmail.net

Carol Daniels - Rough Canyon Federal 30-1 Update T175R RolE 5-32 43-039-50003

From:

"Wolverine Exploration Rig"

To:

"'Hendricks, Marvin'", "Knight, Randy", "Willis, Walton'", "Willis, Walton Home",

"Daniels, Carol", "Doucet, Dustin", "Jarvis, Dan", "'Jones, Mark'"

Date:

5/8/2011 7:03 AM

Subject: Rough Canyon Federal 30-1 Update

RECEIVED

5/8/2011 7:00 AM

MAY 09 2011

Trip in with magnet at 9300'.

DIV. OF OIL, GAS & MINING

				ESTIMATED SCHEDULE
		,		·
DATE	DAY	START	HR	DESCRIPTION
		TIME	''''	
7-May	Saturday	17:00	7.00	Wait on fishing tools
8-May	Sunday	0:00	2.00	Work BHA
		2:00	5.00	TIH
		7:00	2.00	Circ and work magnet
		9:00	6.00	РООН
		15:00	9.00	Wireline log
9-May	Monday	0:00	2.00	Work BHA
		2:00	5.00	TIH
		7:00	2.00	Circ and condition for logs/casing
		9:00	3.00	POOH to shoe
		12:00	2.00	Run gyro survey inside 5" dp
		14:00	3.00	Continue to POOH
		17:00	3.00	RU Franks Casing Crews
		20:00	18.00	Run 9 5/8" casing
10-May	Tuesday	14:00	2.00	Circulate & RU Dowell
		16:00	5.00	Cement Stage 1
		21:00	2.00	Open DV and Circulate
		23:00	3.00	Cement Stage 2
11-May	Wednesday	2:00	-	

Note: Operations for the Boart Longyear Rig have begun on the Denmark Wash Fed 15-2 well. The supervisor for that rig will be using the boart@drillmail.net email address. Please begin to use that address for Boart/Denmark Wash issues. 970-812-0022 phone

The supervisor for the Patterson 304 on the Rough Canyon Fed 30-1 operation will be using only the wolvexpl@drillmail.net email address. Please use only this address for the Patterson/Rough Canyon issues. 970-361-3276 phone.

Thank you, Tom

Tom Zupan Drilling Supervisor Wolverine Gas and Oil Company of Utah, LLC Rig (970) 361-3276 Cell (970) 314-8219

wolvexpl@drillmail.net

Carol Daniels - Rough Canyon Federal 30-1 Update T175 Rol E 5-32 43-039-50003

From:

"Wolverine Exploration Rig"

To:

"'Hendricks, Marvin'", "Knight, Randy", "Willis, Walton'", "Willis, Walton Home'",

"Daniels, Carol", "Doucet, Dustin", "Jarvis, Dan", "'Jones, Mark'"

Date:

5/9/2011 7:47 AM

Subject: Rough Canyon Federal 30-1 Update

5/9/2011 7:34 AM

TIH with mill at 8,496', TD 9,482'

This is the clean out run prior to running casing.

Wolverine Gas and Oil plans to run casing. This is the 24 hour notification. Marvin Hendricks and Mark Jones will also be notified by phone.

Bill Donovan
Drilling Supervisor
Wolverine Gas and Oil Company of Utah, LLC
Rough Canyon Federal 30-1, AFE 224
Rig (970) 361-3276
Cell (720) 351-7470
wolvexpl@drillmail.net

RECEIVED
MAY 0 9 2011

Carol Daniels - Rough Canyon Federal 30-1 update

T175 ROLE 5-32 4303950003

From:

"Wolverine Exploration Rig"

To:

"'Hendricks, Marvin'", "Knight, Randy", , "'Willis, Walton'", "'Willis, Walton Home'",

"Daniels, Carol", "Doucet, Dustin", "Jarvis, Dan", "'Jones, Mark'"

Date:

5/10/2011 9:50 AM

Subject: Rough Canyon Federal 30-1 update

5/10/2011 9:47 AM

Making up BHA for a clean out run prior to running casing.

Bill Donovan **Drilling Supervisor** Wolverine Gas and Oil Company of Utah, LLC Rough Canyon Federal 30-1, AFE 224 Rig (970) 361-3276 Cell (720) 351-7470 wolvexpl@drillmail.net

> RECEIVED MAY 1 0 2011

Carol Daniels - Rough Canyon Federal 30-1 Update TIPS ROIE 5-32 43-039-50003

From:

"Wolverine Exploration Rig"

To:

"'Hendricks, Marvin'", "Knight, Randy", , "'Willis, Walton'", "'Willis, Walton Home'", "Daniels, Carol", "Doucet, Dustin", "Jarvis, Dan", "Jones, Mark"

Date:

5/12/2011 6:47 AM

Subject: Rough Canyon Federal 30-1 Update

5/12/2011 6:44 AM

Running casing at 8,415'

Bill Donovan Drilling Supervisor Wolverine Gas and Oil Company of Utah, LLC Rough Canyon Federal 30-1, AFE 224 Rig (970) 361-3276 Cell (720) 351-7470 wolvexpl@drillmail.net

> RECEIVED MAY 1 6 2011

Carol Daniels - Rough Canyon Federal 30-1 Update TITS ROIE 5-35 43-039-50003

From:

"Wolverine Exploration Rig"

To:

"'Hendricks, Marvin'", "Knight, Randy", , "'Willis, Walton'", "'Willis, Walton Home'", "Daniels, Carol'", "Doucet, Dustin", "Jarvis, Dan", "Jones, Mark"

Date:

5/13/2011 9:27 AM

Subject: Rough Canyon Federal 30-1 Update

5/13/2011 9:24 AM

WOC

Bill Donovan **Drilling Supervisor** Wolverine Gas and Oil Company of Utah, LLC Rough Canyon Federal 30-1, AFE 224 Rig (970) 361-3276 Cell (720) 351-7470 wolvexpl@drillmail.net

> RECEIVED MAY 1 6 2011

Carol Daniels - Rough Canyon Federal 30-1 Update TIPS ROIES-32 43-039-5003

From:

"Wolverine Exploration Rig"

To:

"'Hendricks, Marvin'", "Knight, Randy", , "'Willis, Walton'", "'Willis, Walton Home'",

"Daniels, Carol", "Doucet, Dustin", "Jarvis, Dan", "'Jones, Mark'"

Date:

5/14/2011 9:04 AM

Subject: Rough Canyon Federal 30-1 Update

5/14/2011 9:02 AM

Finished testing BOP stack, start-strapping BHA.

Bill Donovan
Drilling Supervisor
Wolverine Gas and Oil Company of Utah, LLC
Rough Canyon Federal 30-1, AFE 224
Rig (970) 361-3276
Cell (720) 351-7470
wolvexpl@drillmail.net

RECEIVED
MAY 1 6 2011

Carol Daniels - Rough Canyon Federal 30-1 Update TIDS ROIE 5-3243-039-50003

From:

"Wolverine Exploration Rig"

To:

"'Hendricks, Marvin'", "Knight, Randy", , "'Willis, Walton'", "'Willis, Walton Home'", "Daniels, Carol'", "Doucet, Dustin", "Jarvis, Dan", "'Jones, Mark'"

5/15/2011 4:07 PM Date:

Subject: Rough Canyon Federal 30-1 Update

5/15/2011 4:03 PM

Ran tested BOP and ran LOT. Result will be sent under separate e-mail.

Bill Donovan **Drilling Supervisor** Wolverine Gas and Oil Company of Utah, LLC Rough Canyon Federal 30-1, AFE 224 Rig (970) 361-3276 Cell (720) 351-7470 wolvexpl@drillmail.net

Carol Daniels - Rough Canyon Federal 30-1 Update TIPS ROLE 5-32 43-037-5 0003

From:

"Wolverine Exploration Rig"

To:

"'Hendricks, Marvin'", "Knight, Randy", , "'Willis, Walton'", "'Willis, Walton Home'",

"'Daniels, Carol'", "Doucet, Dustin", "Jarvis, Dan", "'Jones, Mark'"

Date:

5/16/2011 6:33 AM

Subject: Rough Canyon Federal 30-1 Update

5/16/2011 6:31 AM

Running seismic survey on well (VSP)

Bill Donovan Drilling Supervisor Wolverine Gas and Oil Company of Utah, LLC Rough Canyon Federal 30-1, AFE 224 Rig (970) 361-3276 Cell (720) 351-7470 wolvexpl@drillmail.net

> RECEIVED MAY 1 6 2011

Carol Daniels - Rough Canyon Federal 30-1 Update TIPS ROIE 5-32 43-039-50003

From:

"Wolverine Exploration Rig"

To:

"'Hendricks, Marvin'", "Knight, Randy", , "'Willis, Walton'", "'Willis, Walton Home'", "Daniels, Carol", "Doucet, Dustin", "Jarvis, Dan", "Jones, Mark"

Date:

5/12/2011 6:47 AM

Subject: Rough Canyon Federal 30-1 Update

5/12/2011 6:44 AM

Running casing at 8,415'

Bill Donovan Drilling Supervisor Wolverine Gas and Oil Company of Utah, LLC Rough Canyon Federal 30-1, AFE 224 Rig (970) 361-3276 Cell (720) 351-7470 wolvexpl@drillmail.net

> RECEIVED MAY 1 6 2011

Carol Daniels - Rough Canyon Federal 30-1 Update TITS ROIE 5-35 43-039-50003

From:

"Wolverine Exploration Rig"

To:

"'Hendricks, Marvin'", "Knight, Randy", , "'Willis, Walton'", "'Willis, Walton Home'", "Daniels, Carol'", "Doucet, Dustin", "Jarvis, Dan", "Jones, Mark"

Date:

5/13/2011 9:27 AM

Subject: Rough Canyon Federal 30-1 Update

5/13/2011 9:24 AM

WOC

Bill Donovan **Drilling Supervisor** Wolverine Gas and Oil Company of Utah, LLC Rough Canyon Federal 30-1, AFE 224 Rig (970) 361-3276 Cell (720) 351-7470 wolvexpl@drillmail.net

> RECEIVED MAY 1 6 2011

Carol Daniels - Rough Canyon Federal 30-1 Update TIPS ROIES-32 43-039-5003

From:

"Wolverine Exploration Rig"

To:

"'Hendricks, Marvin'", "Knight, Randy", , "'Willis, Walton'", "'Willis, Walton Home'",

"Daniels, Carol", "Doucet, Dustin", "Jarvis, Dan", "'Jones, Mark'"

Date:

5/14/2011 9:04 AM

Subject: Rough Canyon Federal 30-1 Update

5/14/2011 9:02 AM

Finished testing BOP stack, start-strapping BHA.

Bill Donovan
Drilling Supervisor
Wolverine Gas and Oil Company of Utah, LLC
Rough Canyon Federal 30-1, AFE 224
Rig (970) 361-3276
Cell (720) 351-7470
wolvexpl@drillmail.net

RECEIVED
MAY 1 6 2011

Carol Daniels - Rough Canyon Federal 30-1 Update TIDS ROIE 5-3243-039-50003

From:

"Wolverine Exploration Rig"

To:

"'Hendricks, Marvin'", "Knight, Randy", , "'Willis, Walton'", "'Willis, Walton Home'", "Daniels, Carol'", "Doucet, Dustin", "Jarvis, Dan", "'Jones, Mark'"

5/15/2011 4:07 PM Date:

Subject: Rough Canyon Federal 30-1 Update

5/15/2011 4:03 PM

Ran tested BOP and ran LOT. Result will be sent under separate e-mail.

Bill Donovan **Drilling Supervisor** Wolverine Gas and Oil Company of Utah, LLC Rough Canyon Federal 30-1, AFE 224 Rig (970) 361-3276 Cell (720) 351-7470 wolvexpl@drillmail.net

Carol Daniels - Rough Canyon Federal 30-1 Update TIPS ROLE 5-32 43-037-5 0003

From:

"Wolverine Exploration Rig"

To:

"'Hendricks, Marvin'", "Knight, Randy", , "'Willis, Walton'", "'Willis, Walton Home'",

"'Daniels, Carol'", "Doucet, Dustin", "Jarvis, Dan", "'Jones, Mark'"

Date:

5/16/2011 6:33 AM

Subject: Rough Canyon Federal 30-1 Update

5/16/2011 6:31 AM

Running seismic survey on well (VSP)

Bill Donovan Drilling Supervisor Wolverine Gas and Oil Company of Utah, LLC Rough Canyon Federal 30-1, AFE 224 Rig (970) 361-3276 Cell (720) 351-7470 wolvexpl@drillmail.net

> RECEIVED MAY 1 6 2011

Carol Daniels - Rough Canyon Federal 30-1 Update TIPS ROIE 5-32 43-039-50003

From:

"Wolverine Exploration Rig"

To:

"'Hendricks, Marvin'", "Knight, Randy", , "'Willis, Walton'", "'Willis, Walton Home'", "Daniels, Carol", "Doucet, Dustin", "Jarvis, Dan", "Jones, Mark"

Date:

5/12/2011 6:47 AM

Subject: Rough Canyon Federal 30-1 Update

5/12/2011 6:44 AM

Running casing at 8,415'

Bill Donovan Drilling Supervisor Wolverine Gas and Oil Company of Utah, LLC Rough Canyon Federal 30-1, AFE 224 Rig (970) 361-3276 Cell (720) 351-7470 wolvexpl@drillmail.net

> RECEIVED MAY 1 6 2011

Carol Daniels - Rough Canyon Federal 30-1 Update TITS ROIE 5-35 43-039-50003

From:

"Wolverine Exploration Rig"

To:

"'Hendricks, Marvin'", "Knight, Randy", , "'Willis, Walton'", "'Willis, Walton Home'", "Daniels, Carol'", "Doucet, Dustin", "Jarvis, Dan", "Jones, Mark"

Date:

5/13/2011 9:27 AM

Subject: Rough Canyon Federal 30-1 Update

5/13/2011 9:24 AM

WOC

Bill Donovan **Drilling Supervisor** Wolverine Gas and Oil Company of Utah, LLC Rough Canyon Federal 30-1, AFE 224 Rig (970) 361-3276 Cell (720) 351-7470 wolvexpl@drillmail.net

> RECEIVED MAY 1 6 2011

Carol Daniels - Rough Canyon Federal 30-1 Update TIPS ROIES-32 43-039-5003

From:

"Wolverine Exploration Rig"

To:

"'Hendricks, Marvin'", "Knight, Randy", , "'Willis, Walton'", "'Willis, Walton Home'",

"Daniels, Carol", "Doucet, Dustin", "Jarvis, Dan", "'Jones, Mark'"

Date:

5/14/2011 9:04 AM

Subject: Rough Canyon Federal 30-1 Update

5/14/2011 9:02 AM

Finished testing BOP stack, start-strapping BHA.

Bill Donovan
Drilling Supervisor
Wolverine Gas and Oil Company of Utah, LLC
Rough Canyon Federal 30-1, AFE 224
Rig (970) 361-3276
Cell (720) 351-7470
wolvexpl@drillmail.net

RECEIVED
MAY 1 6 2011

Carol Daniels - Rough Canyon Federal 30-1 Update TIDS ROIE 5-3243-039-50003

From:

"Wolverine Exploration Rig"

To:

"'Hendricks, Marvin'", "Knight, Randy", , "'Willis, Walton'", "'Willis, Walton Home'", "Daniels, Carol'", "Doucet, Dustin", "Jarvis, Dan", "'Jones, Mark'"

5/15/2011 4:07 PM Date:

Subject: Rough Canyon Federal 30-1 Update

5/15/2011 4:03 PM

Ran tested BOP and ran LOT. Result will be sent under separate e-mail.

Bill Donovan **Drilling Supervisor** Wolverine Gas and Oil Company of Utah, LLC Rough Canyon Federal 30-1, AFE 224 Rig (970) 361-3276 Cell (720) 351-7470 wolvexpl@drillmail.net

Carol Daniels - Rough Canyon Federal 30-1 Update TIPS ROLE 5-32 43-037-5 0003

From:

"Wolverine Exploration Rig"

To:

"'Hendricks, Marvin'", "Knight, Randy", , "'Willis, Walton'", "'Willis, Walton Home'",

"'Daniels, Carol'", "Doucet, Dustin", "Jarvis, Dan", "'Jones, Mark'"

Date:

5/16/2011 6:33 AM

Subject: Rough Canyon Federal 30-1 Update

5/16/2011 6:31 AM

Running seismic survey on well (VSP)

Bill Donovan Drilling Supervisor Wolverine Gas and Oil Company of Utah, LLC Rough Canyon Federal 30-1, AFE 224 Rig (970) 361-3276 Cell (720) 351-7470 wolvexpl@drillmail.net

> RECEIVED MAY 1 6 2011

Carol Daniels - Rough Canyon Federal 30-1 Update TIPS ROIE 5-32 43-039-50003

From:

"Wolverine Exploration Rig"

To:

"'Hendricks, Marvin'", "Knight, Randy", , "'Willis, Walton'", "'Willis, Walton Home'", "Daniels, Carol", "Doucet, Dustin", "Jarvis, Dan", "Jones, Mark"

Date:

5/12/2011 6:47 AM

Subject: Rough Canyon Federal 30-1 Update

5/12/2011 6:44 AM

Running casing at 8,415'

Bill Donovan Drilling Supervisor Wolverine Gas and Oil Company of Utah, LLC Rough Canyon Federal 30-1, AFE 224 Rig (970) 361-3276 Cell (720) 351-7470 wolvexpl@drillmail.net

> RECEIVED MAY 1 6 2011

Carol Daniels - Rough Canyon Federal 30-1 Update TITS ROIE 5-35 43-039-50003

From:

"Wolverine Exploration Rig"

To:

"'Hendricks, Marvin'", "Knight, Randy", , "'Willis, Walton'", "'Willis, Walton Home'", "Daniels, Carol'", "Doucet, Dustin", "Jarvis, Dan", "Jones, Mark"

Date:

5/13/2011 9:27 AM

Subject: Rough Canyon Federal 30-1 Update

5/13/2011 9:24 AM

WOC

Bill Donovan **Drilling Supervisor** Wolverine Gas and Oil Company of Utah, LLC Rough Canyon Federal 30-1, AFE 224 Rig (970) 361-3276 Cell (720) 351-7470 wolvexpl@drillmail.net

> RECEIVED MAY 1 6 2011

Carol Daniels - Rough Canyon Federal 30-1 Update TIPS ROIES-32 43-039-5003

From:

"Wolverine Exploration Rig"

To:

"'Hendricks, Marvin'", "Knight, Randy", , "'Willis, Walton'", "'Willis, Walton Home'",

"Daniels, Carol", "Doucet, Dustin", "Jarvis, Dan", "'Jones, Mark'"

Date:

5/14/2011 9:04 AM

Subject: Rough Canyon Federal 30-1 Update

5/14/2011 9:02 AM

Finished testing BOP stack, start-strapping BHA.

Bill Donovan
Drilling Supervisor
Wolverine Gas and Oil Company of Utah, LLC
Rough Canyon Federal 30-1, AFE 224
Rig (970) 361-3276
Cell (720) 351-7470
wolvexpl@drillmail.net

RECEIVED
MAY 1 6 2011

Carol Daniels - Rough Canyon Federal 30-1 Update TIDS ROIE 5-3243-039-50003

From:

"Wolverine Exploration Rig"

To:

"'Hendricks, Marvin'", "Knight, Randy", , "'Willis, Walton'", "'Willis, Walton Home'", "Daniels, Carol'", "Doucet, Dustin", "Jarvis, Dan", "'Jones, Mark'"

5/15/2011 4:07 PM Date:

Subject: Rough Canyon Federal 30-1 Update

5/15/2011 4:03 PM

Ran tested BOP and ran LOT. Result will be sent under separate e-mail.

Bill Donovan **Drilling Supervisor** Wolverine Gas and Oil Company of Utah, LLC Rough Canyon Federal 30-1, AFE 224 Rig (970) 361-3276 Cell (720) 351-7470 wolvexpl@drillmail.net

Carol Daniels - Rough Canyon Federal 30-1 Update TIPS ROLE 5-32 43-037-5 0003

From:

"Wolverine Exploration Rig"

To:

"'Hendricks, Marvin'", "Knight, Randy", , "'Willis, Walton'", "'Willis, Walton Home'",

"'Daniels, Carol'", "Doucet, Dustin", "Jarvis, Dan", "'Jones, Mark'"

Date:

5/16/2011 6:33 AM

Subject: Rough Canyon Federal 30-1 Update

5/16/2011 6:31 AM

Running seismic survey on well (VSP)

Bill Donovan Drilling Supervisor Wolverine Gas and Oil Company of Utah, LLC Rough Canyon Federal 30-1, AFE 224 Rig (970) 361-3276 Cell (720) 351-7470 wolvexpl@drillmail.net

> RECEIVED MAY 1 6 2011

Carol Daniels - Rough Canyon Federal 30-1 Update TIZS ROIE 5-31 43.039-50003

From:

"Wolverine Exploration Rig"

To:

"'Daniels, Carol'", "Doucet, Dustin", "Jarvis, Dan", "'Jones, Mark'", "'Hendricks, Marvin'", "Knight, Randy", "Willis, Walton'", "'Willis, Walton Home'"

Date:

5/18/2011 9:05 AM

Subject: Rough Canyon Federal 30-1 Update

5/18/2011 9:02 AM

Circulate and condition OBM mud as shoe, new MW 10 ppg

Bill Donovan Drilling Supervisor Wolverine Gas and Oil Company of Utah, LLC Rough Canyon Federal 30-1, AFE 224 Rig (970) 361-3276 Cell (720) 351-7470 wolvexpl@drillmail.net

> RECEIVED MAY 1 8 2011

Carol Daniels - Rough Canyon Federal 30-1 Update T17S ROLE 5-32 43-039-50003

From: "Wolverine Exploration Rig"

"'Hendricks, Marvin'", "Knight, Randy", , "'Willis, Walton'", "'Willis, Walton Home'", "Daniels, Carol", "Doucet, Dustin", "Jarvis, Dan", "Jones, Mark" To:

Date: 5/23/2011 9:23 PM

Subject: Rough Canyon Federal 30-1 Update

5/23/2011 9:21 PM

Drilling at 9,623', PR 3 fph

Bill Donovan Drilling Supervisor Wolverine Gas and Oil Company of Utah, LLC Rough Canyon Federal 30-1, AFE 224 Rig (970) 361-3276 Cell (720) 351-7470 wolvexpl@drillmail.net

> RECEIVED MAY 2 4 2011

Carol Daniels - Rough Canyon Federal 30-1 Update TIPS ROIE 5-32 43-039-50003

From:

"Wolverine Exploration Rig"

To:

"'Hendricks, Marvin'", "Knight, Randy", , "'Willis, Walton'", "'Willis, Walton Home'", "Daniels, Carol", "Doucet, Dustin", "Jarvis, Dan", "Jones, Mark"

Date:

5/12/2011 6:47 AM

Subject: Rough Canyon Federal 30-1 Update

5/12/2011 6:44 AM

Running casing at 8,415'

Bill Donovan Drilling Supervisor Wolverine Gas and Oil Company of Utah, LLC Rough Canyon Federal 30-1, AFE 224 Rig (970) 361-3276 Cell (720) 351-7470 wolvexpl@drillmail.net

> RECEIVED MAY 1 6 2011

Carol Daniels - Rough Canyon Federal 30-1 Update TITS ROIE 5-35 43-039-50003

From:

"Wolverine Exploration Rig"

To:

"'Hendricks, Marvin'", "Knight, Randy", , "'Willis, Walton'", "'Willis, Walton Home'", "Daniels, Carol'", "Doucet, Dustin", "Jarvis, Dan", "Jones, Mark"

Date:

5/13/2011 9:27 AM

Subject: Rough Canyon Federal 30-1 Update

5/13/2011 9:24 AM

WOC

Bill Donovan **Drilling Supervisor** Wolverine Gas and Oil Company of Utah, LLC Rough Canyon Federal 30-1, AFE 224 Rig (970) 361-3276 Cell (720) 351-7470 wolvexpl@drillmail.net

> RECEIVED MAY 1 6 2011

Carol Daniels - Rough Canyon Federal 30-1 Update TIPS ROIES-32 43-039-5003

From:

"Wolverine Exploration Rig"

To:

"'Hendricks, Marvin'", "Knight, Randy", , "'Willis, Walton'", "'Willis, Walton Home'",

"Daniels, Carol", "Doucet, Dustin", "Jarvis, Dan", "'Jones, Mark'"

Date:

5/14/2011 9:04 AM

Subject: Rough Canyon Federal 30-1 Update

5/14/2011 9:02 AM

Finished testing BOP stack, start-strapping BHA.

Bill Donovan
Drilling Supervisor
Wolverine Gas and Oil Company of Utah, LLC
Rough Canyon Federal 30-1, AFE 224
Rig (970) 361-3276
Cell (720) 351-7470
wolvexpl@drillmail.net

RECEIVED
MAY 1 6 2011

Carol Daniels - Rough Canyon Federal 30-1 Update TIDS ROIE 5-3243-039-50003

From:

"Wolverine Exploration Rig"

To:

"'Hendricks, Marvin'", "Knight, Randy", , "'Willis, Walton'", "'Willis, Walton Home'", "Daniels, Carol'", "Doucet, Dustin", "Jarvis, Dan", "'Jones, Mark'"

5/15/2011 4:07 PM Date:

Subject: Rough Canyon Federal 30-1 Update

5/15/2011 4:03 PM

Ran tested BOP and ran LOT. Result will be sent under separate e-mail.

Bill Donovan **Drilling Supervisor** Wolverine Gas and Oil Company of Utah, LLC Rough Canyon Federal 30-1, AFE 224 Rig (970) 361-3276 Cell (720) 351-7470 wolvexpl@drillmail.net

Carol Daniels - Rough Canyon Federal 30-1 Update TIPS ROLE 5-32 43-037-5 0003

From:

"Wolverine Exploration Rig"

To:

"'Hendricks, Marvin'", "Knight, Randy", , "'Willis, Walton'", "'Willis, Walton Home'",

"'Daniels, Carol'", "Doucet, Dustin", "Jarvis, Dan", "'Jones, Mark'"

Date:

5/16/2011 6:33 AM

Subject: Rough Canyon Federal 30-1 Update

5/16/2011 6:31 AM

Running seismic survey on well (VSP)

Bill Donovan Drilling Supervisor Wolverine Gas and Oil Company of Utah, LLC Rough Canyon Federal 30-1, AFE 224 Rig (970) 361-3276 Cell (720) 351-7470 wolvexpl@drillmail.net

> RECEIVED MAY 1 6 2011

Carol Daniels - Rough Canyon Federal 30-1 Update TIZS ROIE 5-31 43.039-50003

From:

"Wolverine Exploration Rig"

To:

"'Daniels, Carol'", "Doucet, Dustin", "Jarvis, Dan", "'Jones, Mark'", "'Hendricks, Marvin'", "Knight, Randy", "Willis, Walton'", "'Willis, Walton Home'"

Date:

5/18/2011 9:05 AM

Subject: Rough Canyon Federal 30-1 Update

5/18/2011 9:02 AM

Circulate and condition OBM mud as shoe, new MW 10 ppg

Bill Donovan Drilling Supervisor Wolverine Gas and Oil Company of Utah, LLC Rough Canyon Federal 30-1, AFE 224 Rig (970) 361-3276 Cell (720) 351-7470 wolvexpl@drillmail.net

> RECEIVED MAY 1 8 2011

Carol Daniels - Rough Canyon Federal 30-1 Update T17S ROLE 5-32 43-039-50003

From: "Wolverine Exploration Rig"

"'Hendricks, Marvin'", "Knight, Randy", , "'Willis, Walton'", "'Willis, Walton Home'", "Daniels, Carol", "Doucet, Dustin", "Jarvis, Dan", "Jones, Mark" To:

Date: 5/23/2011 9:23 PM

Subject: Rough Canyon Federal 30-1 Update

5/23/2011 9:21 PM

Drilling at 9,623', PR 3 fph

Bill Donovan Drilling Supervisor Wolverine Gas and Oil Company of Utah, LLC Rough Canyon Federal 30-1, AFE 224 Rig (970) 361-3276 Cell (720) 351-7470 wolvexpl@drillmail.net

> RECEIVED MAY 2 4 2011

Carol Daniels - Rough Canyon Federal 30-1 Update TIPS ROIE 5-32 43-039-50003

From:

"Wolverine Exploration Rig"

To:

"'Hendricks, Marvin'", "Knight, Randy", , "'Willis, Walton'", "'Willis, Walton Home'", "Daniels, Carol", "Doucet, Dustin", "Jarvis, Dan", "Jones, Mark"

Date:

5/12/2011 6:47 AM

Subject: Rough Canyon Federal 30-1 Update

5/12/2011 6:44 AM

Running casing at 8,415'

Bill Donovan Drilling Supervisor Wolverine Gas and Oil Company of Utah, LLC Rough Canyon Federal 30-1, AFE 224 Rig (970) 361-3276 Cell (720) 351-7470 wolvexpl@drillmail.net

> RECEIVED MAY 1 6 2011

Carol Daniels - Rough Canyon Federal 30-1 Update TITS ROIE 5-35 43-039-50003

From:

"Wolverine Exploration Rig"

To:

"'Hendricks, Marvin'", "Knight, Randy", , "'Willis, Walton'", "'Willis, Walton Home'", "Daniels, Carol", "Doucet, Dustin", "Jarvis, Dan", "Jones, Mark"

Date:

5/13/2011 9:27 AM

Subject: Rough Canyon Federal 30-1 Update

5/13/2011 9:24 AM

WOC

Bill Donovan **Drilling Supervisor** Wolverine Gas and Oil Company of Utah, LLC Rough Canyon Federal 30-1, AFE 224 Rig (970) 361-3276 Cell (720) 351-7470 wolvexpl@drillmail.net

> RECEIVED MAY 1 6 2011

Carol Daniels - Rough Canyon Federal 30-1 Update TIPS ROIES-32 43-039-5003

From:

"Wolverine Exploration Rig"

To:

"'Hendricks, Marvin'", "Knight, Randy", , "'Willis, Walton'", "'Willis, Walton Home'",

"Daniels, Carol", "Doucet, Dustin", "Jarvis, Dan", "'Jones, Mark'"

Date:

5/14/2011 9:04 AM

Subject: Rough Canyon Federal 30-1 Update

5/14/2011 9:02 AM

Finished testing BOP stack, start-strapping BHA.

Bill Donovan
Drilling Supervisor
Wolverine Gas and Oil Company of Utah, LLC
Rough Canyon Federal 30-1, AFE 224
Rig (970) 361-3276
Cell (720) 351-7470
wolvexpl@drillmail.net

RECEIVED
MAY 1 6 2011

Carol Daniels - Rough Canyon Federal 30-1 Update TIDS ROIE 5-3243-039-50003

From:

"Wolverine Exploration Rig"

To:

"'Hendricks, Marvin'", "Knight, Randy", , "'Willis, Walton'", "'Willis, Walton Home'", "Daniels, Carol'", "Doucet, Dustin", "Jarvis, Dan", "'Jones, Mark'"

5/15/2011 4:07 PM Date:

Subject: Rough Canyon Federal 30-1 Update

5/15/2011 4:03 PM

Ran tested BOP and ran LOT. Result will be sent under separate e-mail.

Bill Donovan **Drilling Supervisor** Wolverine Gas and Oil Company of Utah, LLC Rough Canyon Federal 30-1, AFE 224 Rig (970) 361-3276 Cell (720) 351-7470 wolvexpl@drillmail.net

Carol Daniels - Rough Canyon Federal 30-1 Update TIPS ROLE 5-32 43-037-5 0003

From:

"Wolverine Exploration Rig"

To:

"'Hendricks, Marvin'", "Knight, Randy", , "'Willis, Walton'", "'Willis, Walton Home'",

"'Daniels, Carol'", "Doucet, Dustin", "Jarvis, Dan", "'Jones, Mark'"

Date:

5/16/2011 6:33 AM

Subject: Rough Canyon Federal 30-1 Update

5/16/2011 6:31 AM

Running seismic survey on well (VSP)

Bill Donovan Drilling Supervisor Wolverine Gas and Oil Company of Utah, LLC Rough Canyon Federal 30-1, AFE 224 Rig (970) 361-3276 Cell (720) 351-7470 wolvexpl@drillmail.net

> RECEIVED MAY 1 6 2011

Carol Daniels - Rough Canyon Federal 30-1 Update TIZS ROIE 5-31 43.039-50003

From:

"Wolverine Exploration Rig"

To:

"'Daniels, Carol'", "Doucet, Dustin", "Jarvis, Dan", "'Jones, Mark'", "'Hendricks, Marvin'", "Knight, Randy", "Willis, Walton'", "'Willis, Walton Home'"

Date:

5/18/2011 9:05 AM

Subject: Rough Canyon Federal 30-1 Update

5/18/2011 9:02 AM

Circulate and condition OBM mud as shoe, new MW 10 ppg

Bill Donovan Drilling Supervisor Wolverine Gas and Oil Company of Utah, LLC Rough Canyon Federal 30-1, AFE 224 Rig (970) 361-3276 Cell (720) 351-7470 wolvexpl@drillmail.net

> RECEIVED MAY 1 8 2011

Carol Daniels - Rough Canyon Federal 30-1 Update T17S ROLE 5-32 43-039-50003

From: "Wolverine Exploration Rig"

"'Hendricks, Marvin'", "Knight, Randy", , "'Willis, Walton'", "'Willis, Walton Home'", "Daniels, Carol", "Doucet, Dustin", "Jarvis, Dan", "Jones, Mark" To:

Date: 5/23/2011 9:23 PM

Subject: Rough Canyon Federal 30-1 Update

5/23/2011 9:21 PM

Drilling at 9,623', PR 3 fph

Bill Donovan Drilling Supervisor Wolverine Gas and Oil Company of Utah, LLC Rough Canyon Federal 30-1, AFE 224 Rig (970) 361-3276 Cell (720) 351-7470 wolvexpl@drillmail.net

> RECEIVED MAY 2 4 2011

Carol Daniels - Rough Canyon Federal 30-1 Update TIPS ROIE 5-32 43-039-50003

From:

"Wolverine Exploration Rig"

To:

"'Hendricks, Marvin'", "Knight, Randy", , "'Willis, Walton'", "'Willis, Walton Home'", "Daniels, Carol", "Doucet, Dustin", "Jarvis, Dan", "Jones, Mark"

Date:

5/12/2011 6:47 AM

Subject: Rough Canyon Federal 30-1 Update

5/12/2011 6:44 AM

Running casing at 8,415'

Bill Donovan Drilling Supervisor Wolverine Gas and Oil Company of Utah, LLC Rough Canyon Federal 30-1, AFE 224 Rig (970) 361-3276 Cell (720) 351-7470 wolvexpl@drillmail.net

> RECEIVED MAY 1 6 2011

Carol Daniels - Rough Canyon Federal 30-1 Update TITS ROIE 5-35 43-039-50003

From:

"Wolverine Exploration Rig"

To:

"'Hendricks, Marvin'", "Knight, Randy", , "'Willis, Walton'", "'Willis, Walton Home'", "Daniels, Carol", "Doucet, Dustin", "Jarvis, Dan", "Jones, Mark"

Date:

5/13/2011 9:27 AM

Subject: Rough Canyon Federal 30-1 Update

5/13/2011 9:24 AM

WOC

Bill Donovan **Drilling Supervisor** Wolverine Gas and Oil Company of Utah, LLC Rough Canyon Federal 30-1, AFE 224 Rig (970) 361-3276 Cell (720) 351-7470 wolvexpl@drillmail.net

> RECEIVED MAY 1 6 2011

Carol Daniels - Rough Canyon Federal 30-1 Update TIPS ROIES-32 43-039-5003

From:

"Wolverine Exploration Rig"

To:

"'Hendricks, Marvin'", "Knight, Randy", , "'Willis, Walton'", "'Willis, Walton Home'",

"Daniels, Carol", "Doucet, Dustin", "Jarvis, Dan", "'Jones, Mark'"

Date:

5/14/2011 9:04 AM

Subject: Rough Canyon Federal 30-1 Update

5/14/2011 9:02 AM

Finished testing BOP stack, start-strapping BHA.

Bill Donovan
Drilling Supervisor
Wolverine Gas and Oil Company of Utah, LLC
Rough Canyon Federal 30-1, AFE 224
Rig (970) 361-3276
Cell (720) 351-7470
wolvexpl@drillmail.net

RECEIVED
MAY 1 6 2011

Carol Daniels - Rough Canyon Federal 30-1 Update TIDS ROIE 5-3243-039-50003

From:

"Wolverine Exploration Rig"

To:

"'Hendricks, Marvin'", "Knight, Randy", , "'Willis, Walton'", "'Willis, Walton Home'", "Daniels, Carol'", "Doucet, Dustin", "Jarvis, Dan", "'Jones, Mark'"

5/15/2011 4:07 PM Date:

Subject: Rough Canyon Federal 30-1 Update

5/15/2011 4:03 PM

Ran tested BOP and ran LOT. Result will be sent under separate e-mail.

Bill Donovan **Drilling Supervisor** Wolverine Gas and Oil Company of Utah, LLC Rough Canyon Federal 30-1, AFE 224 Rig (970) 361-3276 Cell (720) 351-7470 wolvexpl@drillmail.net

Carol Daniels - Rough Canyon Federal 30-1 Update TIPS ROLE 5-32 43-037-5 0003

From:

"Wolverine Exploration Rig"

To:

"'Hendricks, Marvin'", "Knight, Randy", , "'Willis, Walton'", "'Willis, Walton Home'",

"'Daniels, Carol'", "Doucet, Dustin", "Jarvis, Dan", "'Jones, Mark'"

Date:

5/16/2011 6:33 AM

Subject: Rough Canyon Federal 30-1 Update

5/16/2011 6:31 AM

Running seismic survey on well (VSP)

Bill Donovan Drilling Supervisor Wolverine Gas and Oil Company of Utah, LLC Rough Canyon Federal 30-1, AFE 224 Rig (970) 361-3276 Cell (720) 351-7470 wolvexpl@drillmail.net

> RECEIVED MAY 1 6 2011

Carol Daniels - Rough Canyon Federal 30-1 Update TIZS ROIE 5-31 43.039-50003

From:

"Wolverine Exploration Rig"

To:

"'Daniels, Carol'", "Doucet, Dustin", "Jarvis, Dan", "'Jones, Mark'", "'Hendricks, Marvin'", "Knight, Randy", "Willis, Walton'", "'Willis, Walton Home'"

Date:

5/18/2011 9:05 AM

Subject: Rough Canyon Federal 30-1 Update

5/18/2011 9:02 AM

Circulate and condition OBM mud as shoe, new MW 10 ppg

Bill Donovan Drilling Supervisor Wolverine Gas and Oil Company of Utah, LLC Rough Canyon Federal 30-1, AFE 224 Rig (970) 361-3276 Cell (720) 351-7470 wolvexpl@drillmail.net

> RECEIVED MAY 1 8 2011

Carol Daniels - Rough Canyon Federal 30-1 Update T17S ROLE 5-32 43-039-50003

From: "Wolverine Exploration Rig"

"'Hendricks, Marvin'", "Knight, Randy", , "'Willis, Walton'", "'Willis, Walton Home'", "Daniels, Carol", "Doucet, Dustin", "Jarvis, Dan", "Jones, Mark" To:

Date: 5/23/2011 9:23 PM

Subject: Rough Canyon Federal 30-1 Update

5/23/2011 9:21 PM

Drilling at 9,623', PR 3 fph

Bill Donovan Drilling Supervisor Wolverine Gas and Oil Company of Utah, LLC Rough Canyon Federal 30-1, AFE 224 Rig (970) 361-3276 Cell (720) 351-7470 wolvexpl@drillmail.net

> RECEIVED MAY 2 4 2011

Page 1 of 1

Carol Daniels - Rough Canyon Federal 30-1 Update T175 ROLE 5-32 43 039 50023

From:

"Wolverine Exploration Rig"

To:

"'Hendricks, Marvin'", "Knight, Randy", , "'Willis, Walton'", "'Willis, Walton Home'",

"'Daniels, Carol'", "Doucet, Dustin", "Jarvis, Dan", "'Jones, Mark'"

Date:

5/26/2011 5:12 PM

Subject: Rough Canyon Federal 30-1 Update

5/26/2011 5:09 PM

Hole depth 9,654'

Placed cement plug in open hole to stop lost circulation.

Bill Donovan Drilling Supervisor Wolverine Gas and Oil Company of Utah, LLC Rough Canyon Federal 30-1, AFE 224 Rig (970) 361-3276 Cell (720) 351-7470 wolvexpl@drillmail.net

> RECEIVED MAY 3 1 2011

Carol Daniels - Rough Canyon Federal 30-1 Update TINS ROLE 5-32 4303950003

From:

"Wolverine Exploration Rig"

To:

"'Hendricks, Marvin'", "Knight, Randy", , "'Willis, Walton'", "'Willis, Walton Home'",

"Daniels, Carol", "Doucet, Dustin", "Jarvis, Dan", "Jones, Mark"

Date:

5/29/2011 6:57 AM

Subject: Rough Canyon Federal 30-1 Update

5/29/2011 6:55 AM

Trip in hole with AutoTrak at 9530'. TD is 9660'.

Tom Zupan Drilling Supervisor Wolverine Gas and Oil Company of Utah, LLC Rig (970) 361-3276 Cell (970) 314-8219

wolvexpl@drillmail.net

RECEIVED MAY 3 1 2011

Carol Daniels - Rough Canyon Federal 30-1 Update TTRS ROIE 5-32 43 0395 0003

From:

"Wolverine Exploration Rig"

To:

"'Hendricks, Marvin'", "Knight, Randy", , "'Willis, Walton'", "'Willis, Walton Home'", "Daniels, Carol", "Doucet, Dustin", "Jarvis, Dan", "'Jones, Mark'"

Date:

5/30/2011 7:34 AM

Subject: Rough Canyon Federal 30-1 Update

5/30/2011 7:31 AM

Drilling at 9780'.

Tom Zupan Drilling Supervisor Wolverine Gas and Oil Company of Utah, LLC Rig (970) 361-3276 Cell (970) 314-8219

wolvexpl@drillmail.net

RECEIVED MAY 3 1 2011

Carol Daniels - Rough Canyon Federal 30-1 Update TIPS ROIE S-32 43-039-50003

From:

"Wolverine Exploration Rig"

To:

"'Hendricks, Marvin'", "Knight, Randy", "Willis, Walton'", "Willis, Walton Home'", "Daniels, Carol", "Doucet, Dustin", "Jarvis, Dan", "Jones, Mark"

Date:

5/31/2011 7:01 AM

Subject: Rough Canyon Federal 30-1 Update

5/31/2011 6:58 AM

Drilling at 9911'

Tom Zupan Drilling Supervisor Wolverine Gas and Oil Company of Utah, LLC Rig (970) 361-3276 Cell (970) 314-8219

wolvexpl@drillmail.net

RECEIVED MAY 3 1 2011

Carol Daniels - Rough Canyon Federal 30-1 Update 7/75 ROLES-32 43-039-50003

"Wolverine Exploration Rig" From:

"'Hendricks, Marvin'", "Knight, Randy", , "'Willis, Walton'", "'Willis, Walton Home'", "Daniels, Carol", "Doucet, Dustin", "Jarvis, Dan", "'Jones, Mark'" To:

6/1/2011 6:53 AM Date:

Subject: Rough Canyon Federal 30-1 Update

6/1/2011 6:50 AM

Drilling at 10,042'

Tom Zupan Drilling Supervisor Wolverine Gas and Oil Company of Utah, LLC Rig (970) 361-3276 Cell (970) 314-8219

wolvexpl@drillmail.net

RECEIVED JUN 0 1 2011

Carol Daniels - Rough Canyon Federal 30-1 Update T175 Rolf S- 32 43-039-50003

From:

"Wolverine Exploration Rig"

To:

"'Hendricks, Marvin'", "Knight, Randy", , "'Willis, Walton'", "'Willis, Walton Home'",

"'Daniels, Carol'", "Doucet, Dustin", "Jarvis, Dan", "'Jones, Mark'"

Date:

6/2/2011 8:36 AM

Subject: Rough Canyon Federal 30-1 Update

6/2/2011 8:34 AM

Drilling at 10160'

Tom Zupan Drilling Supervisor Wolverine Gas and Oil Company of Utah, LLC Rig (970) 361-3276 Cell (970) 314-8219

wolvexpl@drillmail.net

RECEIVED
JUN 0 2 2011

	STATE OF UTAH		FORM 9	
DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS, AND MINING			5.LEASE DESIGNATION AND SERIAL NUMBER: UTU-82536	
SUNDRY NOTICES AND REPORTS ON WELLS			6. IF INDIAN, ALLOTTEE OR TRIBE NAME:	
Do not use this form for proposals to drill new wells, significantly deepen existing wells below current bottom-hole depth, reenter plugged wells, or to drill horizontal laterals. Use APPLICATION FOR PERMIT TO DRILL form for such proposals.			7.UNIT or CA AGREEMENT NAME:	
1. TYPE OF WELL Oil Well			8. WELL NAME and NUMBER: ROUGH CANYON FED 30-1	
2. NAME OF OPERATOR: WOLVERINE OPERATING COMPANY OF UTAH, LLC			9. API NUMBER: 43039500030000	
3. ADDRESS OF OPERATOR: One Riverfront Plaza 55 Campau NW, Grand Rapids, MI, 49503 PHONE NUMBER: 616 458-1150 Ext			9. FIELD and POOL or WILDCAT: WILDCAT	
4. LOCATION OF WELL FOOTAGES AT SURFACE: 0288 FNL 0452 FWL QTR/QTR, SECTION, TOWNSHIP, RANGE, MERIDIAN: Qtr/Qtr: NWNW Section: 32 Township: 17.0S Range: 01.0E Meridian: S			COUNTY: SANPETE	
			STATE: UTAH	
CHECK APPROPRIATE BOXES TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA				
TYPE OF SUBMISSION	TYPE OF ACTION			
		011 drilling details.	CASING REPAIR CHANGE WELL NAME CONVERT WELL TYPE NEW CONSTRUCTION PLUG BACK RECOMPLETE DIFFERENT FORMATION TEMPORARY ABANDON WATER DISPOSAL APD EXTENSION OTHER: Volumes, etc. ACCEPTED by the Utah Division of il, Gas and Mining R RECORD ONLY	
NAME (PLEASE PRINT) PHONE NUMBER Helene Bardolph 616 458-1150			Engineering Administrative Assistant	
SIGNATURE N/A		DATE 6/7/2011		

Subject: Wolverine Operating Company of Utah, LLC Rough Canyon Federal 30-1
NW¼ NW¼ Sec 32-T17S-R1E surface location
NE¼ SE¼ Sec 30-T17S-R1E Projected BHL
Sanpete County, Utah

1 May 2011

Depth 9056' DF, 13. @ 3769' DF. Drill & survey. MW - 8.8, Vis. - 43, FL - 7.8. Surveys: 10.5° @ 9002'.

2 May 2011

Depth 9143' DF, 13. @ 3769' DF. Drill & survey, TFNB. MW – 8.8, Vis. – 61, FL – 8.9. Surveys: 10.9°@ 9096'.

3 May 2011

Depth 9192' DF, 13. @ 3769' DF. TFNB, ream to bottom, drill. MW – 8.8, Vis. – 45, FL – 9.1. Surveys: none.

4 May 2011

Depth 9287' DF, 13. @ 3769' DF. Drill & survey. MW -8.8, Vis. - 51, FL - 7.5. Surveys: 10.7° @ 9205'.

5 May 2011

Depth 9351' DF, 13. @ 3769' DF. Drill & survey. MW – 8.9, Vis. – 49, FL – 5.1. Surveys: 10.9° @ 9286'.

6 May 2011

Depth 9398' DF, 13. @ 3769' DF. Drill to 9366', 15 stand short trip, drill. MW –8.8, Vis. – 51, FL – 8. Surveys: none.

7 May 2011

Depth 9480' DF, 13. @ 3769' DF. Drill & survey. MW – 8.8, Vis. – 54, FL – 7.5. Surveys: 10.8° @ 9378'.

8 May 2011

Depth 9482' DF, 13. @ 3769' DF. Drill, POOH for logs & casing. MW – 8.8, Vis. – 52, FL – 7.5. Surveys: none.

9 May 2011

Depth 9482' DF, 13. @ 3769' DF. Left cones in hole, magnet run, log w/ Halliburton, GIH w/ concave mill and junk baskets. MW – 8.75, Vis. – 58, FL – 6.6. Surveys: none.

10 May 2011

Depth 9482' DF, 13. @ 3769' DF. Ream tight spots, mill on junk, POOH, work tight spots, POOH, rig repair. MW – 8.8, Vis. – 47, FL – 7.5. Surveys: none.

11 May 2011

Depth 9483' DF, 13. @ 3769' DF. GIH for C&C, C&C, POOH, LD jars & x-o's, RU casers, run 9-5/8" casing. MW - 8.8, Vis. -64, FL -7.5. Surveys: none.

12 May 2011

Depth 9483' DF, 13. @ 3769' DF. Damaged shoe jt during make up, wait on replacement cementing shoe, run 9-5/8 casing. MW – 8.8, Vis. – 47, FL – 8. Surveys: none.

13 May 2011

Depth 9483' DF, 9. @ 9470' DF. Run 9. casing to 9469.52' DF, C&C, cement w/ Schlumberger. MW - 8.75, Vis. -43, FL - 7.5. Surveys: none.

14 May 2011

Depth 9483' DF, 9. @ 9470' DF. WOC, cut off pipe, weld on bradenhead, NU BOP's. MW –8.75, Vis. – 44, FL – 8. Surveys: none.

15 May 2011

Depth 9494' DF, 9. @ 9470' DF. Test BOP's, lay out & strap BHA, GIH to 3489', drill stage collar, GIH, drill cmt collar, shoe its and shoe, drill to 9494' DF. MW – 8.7, Vis. – 44, FL – 8. Surveys: none.

16 May 2011

Depth 9494' DF, 9. @ 9470' DF. C&C, conduct leak-off test to 14.2 ppg EMW, pump pill, POOH, RU Baker truck, run Gyrodata gyro survey 4200' to 2000', RU Baker seismic, run VSP log. MW – 8.8, Vis. – 52, FL – 7.5. Surveys: none.

17 May 2011

Depth 9494' DF, 9. @ 9470' DF. Run VSP open hole log, RU Zeco solids control eqip, RU Katch Kan equip, PU BHA, move OBM to active system, GIH. MW – 11.6, Vis. – 78, FL – 9.8. Surveys: none.

18 May 2011

Depth 9494' DF, 9. @ 9470' DF. Displace WBM w/ OBM, run leak-off test to 13 ppg, lost returns, lost 120 bbl OBM, POOH, stand back directional tools, GIH w/ packer, set at 3657', test annulus to 750 psi/30 min, OK, test drill pipe, losing mud, GIH w/ pkr. MW – 11.2, Vis. – 46, FL – 8.2. Surveys: none.

19 May 2011

Depth 9494' DF, 9. @ 9470' DF. Set pkr at 9362' DF, test csg to 700 psi/30min, OK, C&C, reduce MW from 11.6 to 10.6 ppg, POOH, LD pkr, GIH w/ directional tools. MW - 10, Vis. -49, FL -6.4. Surveys: none.

20 May 2011

Depth 9498' DF, 9. @ 9470' DF. Test MWD, GIH, drill, losing 10 bbl mud/hr, lower MW to 10.2 ppg, work on mud losses, POOH, LD BHA, PU tooth bit & junk basket. MW –10, Vis. – 36, FL – 6.8. Surveys: none.

21 May 2011

Depth 9498' DF, 9. @ 9470' DF. GIH, build LCM pill, spot on bottom, monitor well, C&C, . MW – 9.2, Vis. – 48, FL – nil. Surveys: none.

22 May 2011

Depth 9505' DF, 9. @ 9470' DF. C&C, drill, spot pill, POOH, PU directional BHA, GIH. MW – 9, Vis. – 47, FL – nil. Surveys: none.

23 May 2011

Depth 9576' MD, 9% @ 9470' DF. Drill & survey. MW - 9, Vis. - 46, FL - nil. Surveys: 11.1° @ 9487'.

24 May 2011

Depth 9650' MD, 9% @ 9470' DF. Drill & survey. MW – 9, Vis. – 47, FL – nil. Surveys: 11.3° @ 9520' & 11.1° @ 9574'.

25 May 2011

Depth 9654' MD, 9% @ 9470' DF. Drill, mud losses unsustainable, POOH, RU Schlumberger loggers, run cement imaging log over length of 9-5/8 casing. MW – 9, Vis. – 51, FL – nil. Surveys: none.

26 May 2011

Depth 9654' MD, 9% @ 9470' DF. GIH w/ Halliburton pkr, set pkr at 3422', test back side to 700 psi/30 min, held ok, losing mud below pkr, move pkr to 5029', test annulus to 700 psi/30 min, held ok, losing mud below pkr, POOH w/ pkr, GIH open ended. MW -9.1, Vis. -52, FL - nil. Surveys: none.

27 May 2011

Depth 9654' MD, 9% @ 9470' DF. GIH open ended to 9632', spot cement pill, pump 15 bbl spacer, 35.3 bbl cement, 5.7 bbl spacer, displace w/ 126 bbl OBM, POOH 30 stands, fill hole w/ OBM, shut in well and pressure up to 350 psi, pressure bled off to 324 psi, WOC. MW – 9, Vis. – 51, FL – nil. Surveys: none.

28 May 2011

Depth 9654' MD, 9% @ 9470' DF. Hold pressure, pressure dropped to 312 psi, bleed off pressure, POOH, GIH w/ mill tooth bit slick, W&R, circulate at 420 gpm, losing mud at 33 bph, C&C @ 210 gpm, losing mud at 0 bph, spot 60 bbl Strata Vanguard LCM pill, wait on LCM pill to soak, GIH to 9600'. MW – 9.1, Vis. – 48, FL – nil. Surveys: none.

29 May 2011

Depth 9660' DF, 9% @ 9470' DF. Drill, still losing mud, reduce MW to 8.5 ppg, drill, POOH, PU directional tools, GIH. MW – 8.5, Vis. – 46, FL – nil. Surveys: none.

30 May 2011

Depth 9771' DF, 9% @ 9470' DF. GIH, W&R, drill & survey. MW – 8.5, Vis. – 46, FL – nil. Surveys: 11.1° @ 9603', 10.9° @ 9634', 11.3° @ 9666' & 11.1° @ 9698'.

31 May 2011

Depth 9901' MD, 9¾ @ 9470' DF. Drill & survey. MW – 8.5, Vis. – 44, FL – nil. Surveys: 11.2° @ 9730', 11.3° @ 9762', 11.2° @ 9793' & 11.2° @ 9825'.

Carol Daniels - Rough Canyon Federal 30-1 Update 7/75 ROLE 5-32 43-039-5003

From:

"Wolverine Exploration Rig"

To:

"'Hendricks, Marvin'", "Knight, Randy", , "'Willis, Walton'", "'Willis, Walton Home'", "Daniels, Carol", "Doucet, Dustin", "Jarvis, Dan", "'Jones, Mark'"

Date:

6/3/2011 6:36 AM

Subject: Rough Canyon Federal 30-1 Update

6/3/2011 6:32 AM

Drilled to 10,229'. Tripped out. Changing out directional tools and bit.

Tom Zupan Drilling Supervisor Wolverine Gas and Oil Company of Utah, LLC Rig (970) 361-3276 Cell (970) 314-8219

wolvexpl@drillmail.net

RECEIVED JUN 06 2011

Carol Daniels - Rough Canyon Federal 30-1 Update Tins Role 5-32 43.639-50003

From:

"Wolverine Exploration Rig"

To:

"'Hendricks, Marvin'", "Knight, Randy", , "'Willis, Walton'", "'Willis, Walton Home'", "Daniels, Carol'", "Doucet, Dustin", "Jarvis, Dan", "'Jones, Mark'"

Date:

6/4/2011 7:05 AM

Subject: Rough Canyon Federal 30-1 Update

6/4/2011 7:02 AM

Drilling at 10293'

Tom Zupan Drilling Supervisor Wolverine Gas and Oil Company of Utah, LLC Rig (970) 361-3276 Cell (970) 314-8219

wolvexpl@drillmail.net

RECEIVED JUN 0 6 2011

Carol Daniels - Rough Canyon Federal 30-1 Update 7175 Rolf 5-32 43-03950003

From:

"Wolverine Exploration Rig"

To:

"'Hendricks, Marvin'", "Knight, Randy", , "'Willis, Walton'", "'Willis, Walton Home'",

"Daniels, Carol", "Doucet, Dustin", "Jarvis, Dan", "Jones, Mark"

Date:

6/6/2011 6:28 AM

Subject: Rough Canyon Federal 30-1 Update

6/6/2011 6:22 AM

TD 10542'. Letting open hole LCM pill soak with bit at 9440'.

Tom Zupan Drilling Supervisor Wolverine Gas and Oil Company of Utah, LLC Rig (970) 361-3276 Cell (970) 314-8219

wolvexpl@drillmail.net

RECEIVED JUN 06 2011

OF OIL, GAS & MINING

Carol Daniels - Rough Canyon Federal 30-1 Update TITS ROLE 5-32 43-039-50003

From:

"Wolverine Exploration Rig"

To:

"'Hendricks, Marvin'", "Knight, Randy", "Willis, Walton'", "Willis, Walton Home",

"'Daniels, Carol'", "Doucet, Dustin", "Jarvis, Dan", "'Jones, Mark'"

Date:

6/7/2011 6:43 AM

Subject: Rough Canyon Federal 30-1 Update

6/7/2011 6:37 AM

Drilling at 10590'.

Tom Zupan Drilling Supervisor Wolverine Gas and Oil Company of Utah, LLC Rig (970) 361-3276 Cell (970) 314-8219

wolvexpl@drillmail.net

RECEIVED JUN 07 2011

Carol Daniels - Rough Canyon Federal 30-1 Update T/7S ROIE 5-32 43 039 5 0033

From:

"Wolverine Exploration Rig"

To:

"'Hendricks, Marvin'", "Knight, Randy", , "'Willis, Walton'", "'Willis, Walton Home'", "Daniels, Carol", "Doucet, Dustin", "Jarvis, Dan", "'Jones, Mark'"

Date:

6/8/2011 6:37 AM

Subject: Rough Canyon Federal 30-1 Update

6/8/2011 6:33 AM

Trip out for BHA at 1010'

Tom Zupan Drilling Supervisor Wolverine Gas and Oil Company of Utah, LLC Rig (970) 361-3276 Cell (970) 314-8219

wolvexpl@drillmail.net

RECEIVED JUN 08 2011

HAVE OF OIL, GAS & MINING

Carol Daniels - Rough Canyon Federal 30-1 Update

From:

"Wolverine Exploration Rig"

To:

"'Hendricks, Marvin'", "Knight, Randy", , "'Willis, Walton'", "'Willis, Walton Home'", "Daniels, Carol", "Doucet, Dustin", "Jarvis, Dan", "'Jones, Mark'"

Date:

6/9/2011 6:51 AM

Subject: Rough Canyon Federal 30-1 Update

6/9/2011 6:47 AM

Drilling at 10720'.

Tom Zupan Drilling Supervisor Wolverine Gas and Oil Company of Utah, LLC Rig (970) 361-3276 Cell (970) 314-8219

wolvexpl@drillmail.net

RECEIVED JUN 09 2011

Carol Daniels - Rough Canyon Federal 30-1 Update TIDS ROLE S-31 43-039-50003

From:

"Wolverine Exploration Rig"

To:

"Hendricks, Marvin'", "Knight, Randy", "Willis, Walton'", "Willis, Walton Home",

"Daniels, Carol", "Doucet, Dustin", "Jarvis, Dan", "Jones, Mark"

Date:

6/10/2011 6:45 AM

Subject: Rough Canyon Federal 30-1 Update

6/10/2011 6:42 AM

Slide drilling @ 10859'.

Tom Zupan Drilling Supervisor Wolverine Gas and Oil Company of Utah, LLC Rig (970) 361-3276 Cell (970) 314-8219

wolvexpl@drillmail.net

RECEIVED JUN 1 3 2011

Carol Daniels - Rough Canyon Federal 30-1 Update 7/75 ROIE 5-32 43-039-50003

From: "Wolverine Exploration Rig"

To: "'Hendricks, Marvin'", "Knight, Randy", , "'Willis, Walton'", "'Willis, Walton Home'",

"Daniels, Carol", "Doucet, Dustin", "Jarvis, Dan", "'Jones, Mark'"

Date: 6/11/2011 10:47 AM

Subject: Rough Canyon Federal 30-1 Update

6/11/2011 10:30 AM

TOH for new bit at 10,972'. Total Safety called to rig up monitoring equipment during trip. IPS called for 30-day BOP stack test while out of hole. BOP stack last tested 5/14.

Possibly cut fault and drilled sandstone. No Twin Creek seen in samples. Geologists reviewing correlation.

Bill Donovan
Drilling Supervisor
Wolverine Gas and Oil Company of Utah, LLC
Rough Canyon Federal 30-1, AFE 224
Rig (970) 361-3276
Cell (720) 351-7470
wolvexpl@drillmail.net

RECEIVED
JUN 1 3 2011

Carol Daniels - Rough Canyon Federal 30-1 Update T 175 ROLES 32 43-039-50003

From:

"Wolverine Exploration Rig"

To:

"'Hendricks, Marvin'", "Knight, Randy", , "'Willis, Walton'", "'Willis, Walton Home'", "Daniels, Carol", "Doucet, Dustin", "Jarvis, Dan", "'Jones, Mark'"

Date:

6/12/2011 11:34 AM

Subject: Rough Canyon Federal 30-1 Update

6/12/2011 11:27 AM

Slide drilling at 10,976', PR 4 fph

Bill Donovan Drilling Supervisor Wolverine Gas and Oil Company of Utah, LLC Rough Canyon Federal 30-1, AFE 224 Rig (970) 361-3276 Cell (720) 351-7470 wolvexpl@drillmail.net

> RECEIVED JUN 1 3 2011

Carol Daniels - Rough Canyon Federal 30-1 Update TINS ROLE S-32 43-039,50003

From:

"Wolverine Exploration Rig"

To:

"Hendricks, Marvin'", "Knight, Randy", "Willis, Walton'", "Willis, Walton Home'",

"Daniels, Carol", "Doucet, Dustin", "Jarvis, Dan", "Jones, Mark"

Date:

6/13/2011 7:30 AM

Subject: Rough Canyon Federal 30-1 Update

6/13/2011 7:27 AM

Short trip at 11,085', PR 8 fph, drilling SS

Plan to log at 11,400'

Bill Donovan
Drilling Supervisor
Wolverine Gas and Oil Company of Utah, LLC
Rough Canyon Federal 30-1, AFE 224
Rig (970) 361-3276
Cell (720) 351-7470
wolvexpl@drillmail.net

RECEIVED
JUN 1 3 2011

Carol Daniels - Rough Canyon Federal 30-1 Notification of open hole logging

T 175 ROLE 5-32 43-039-50003

From:

"Wolverine Exploration Rig"

To:

"Daniels, Carol", "Doucet, Dustin", "Jarvis, Dan", "Jones, Mark", "Angela Wadman",

"'Hendricks, Marvin'", "Knight, Randy", , "Sue Wiler"

Date:

6/14/2011 4:01 PM

Subject: Rough Canyon Federal 30-1 Notification of open hole logging

6/14/2011 3:43 PM

Circulating bottoms up at 11,204', seep 20 bph

Plan to short trip to shoe, wait and check hole, trip to bottom, break circulation, TOH to open hole log

Bill Donovan Drilling Supervisor Wolverine Gas and Oil Company of Utah, LLC Rough Canyon Federal 30-1, AFE 224 You must be clean shaven and have a valid H2S card Rig (970) 361-3276 Cell (720) 351-7470 wolvexpl@drillmail.net

> **RECEIVED** JUN 1 4 2011

TIMS ROLE 5-32 43-039-50003 Carol Daniels - Rough Canyon Federal 30-1 Update

From:

"Wolverine Exploration Rig"

To:

"Angela Wadman" , "'Hendricks, Marvin'" , "Knight, Randy" , , "Sue Wiler" , "'Daniels, Carol'" , "Doucet, Dustin" , "Jarvis, Dan" , "Jones, Mark'"

Date:

6/14/2011 9:24 AM

Subject: Rough Canyon Federal 30-1 Update

6/14/2011 9:21 AM

Hole depth 11,175'

Spotted LCM pill

Bill Donovan Drilling Supervisor Wolverine Gas and Oil Company of Utah, LLC Rough Canyon Federal 30-1, AFE 224 You must be clean shaven and have a valid H2S card Rig (970) 361-3276 Cell (720) 351-7470 wolvexpl@drillmail.net

Carol Daniels - Rough Canyon Federal 30-1 Update TIS ROIE S-32 43 03950003

From: "Wolverine Exploration Rig"

To: "Angela Wadman", "'Hendricks, Marvin'", "Knight, Randy",, "Sue Wiler", "'Daniels,

Carol", "Doucet, Dustin", "Jarvis, Dan", "Jones, Mark"

Date: 6/15/2011 11:32 AM

Subject: Rough Canyon Federal 30-1 Update

6/15/2011 11:28 AM

Rigging up Halliburton loggers. TD 11,204'

A casing point decision on this well will be made later today.

Bill Donovan
Drilling Supervisor
Wolverine Gas and Oil Company of Utah, LLC
Rough Canyon Federal 30-1, AFE 224
You must be clean shaven and have a valid H2S card
Rig (970) 361-3276
Cell (720) 351-7470
wolvexpl@drillmail.net

RECEIVED
JUN 1 5 2011

Carol Daniels - Rough Canyon Federal 30-1 update 7/75 ROLF 5-32 43 037 50003

From:

"Wolverine Exploration Rig"

To:

"'Well Info'", "Angela Wadman", "'Hendricks, Marvin'", "Knight, Randy", , "Sue Wiler",

"Daniels, Carol", "Doucet, Dustin", "Jarvis, Dan", "Jones, Mark"

Date:

6/16/2011 8:17 AM

Subject: Rough Canyon Federal 30-1 update

6/16/2011 8:13 AM

Waiting on Orders.

A decision is expected this morning

Bill Donovan
Drilling Supervisor
Wolverine Gas and Oil Company of Utah, LLC
Rough Canyon Federal 30-1, AFE 224
You must be clean shaven and have a valid H2S card
Rig (970) 361-3276
Cell (720) 351-7470
wolvexpl@drillmail.net

RECEIVED
JUN 1 6 2011

Form 3160-4

(April 200	14)		· .		RTM	TED STATENT OF THE LAND M	IE IN						(OMBNO.	
	WEL	T CO	- 1			RECOMPL			T AN	D LOC	3	-	5. Lease	Serial No.	rch 31, 2007
lo Tymo s	£Wall		Well	Ton V	van f	71pm [7]	Yele out							-82536	or Tribe Name
la. Type of Well ☐ Oil Well ☐ Gas Well ✓ Dry ☐ Other b. Type of Completion: ☐ New Well ☐ Work Over ☐ Deepen ☐ Plug Back ☐ Diff. Resvr.							, L	N.A.		· · · · · · · · · · · · · · · · · · ·					
Other Plug and Abandon									7. Unit of N.A.	r CA Agree	ment Name and No.				
2. Name	of Operato	t Wol	verine O	peratir	ng Com	pany of Utal	ı, LLC						8. Lease	Name and	Weil No. 1 Federal 30-1
3. Addres	SS 55 Car	mpau N	W, Gran	ıd Rap	ids, Mi	49503	· · · ·	3a. Pho			area cod	le)	9. AFIW	ell No.	
4. Locati	on of Well	(Report	location c	learly a	nd in ac	cordance with	Federa		6-458-: ts)*	1150				95000300 and Pool, or	Exploratory
At sur	C.					17s, R1E, N		. •						oratory	
At top	prod. inter		•	-	.C 32, 1	. 175, KIE, IV	MIMAN						 Sec., T Survey 	., R., M., o or Area	n Block and 32,17S,1E
	-	-			∽ 21 T	17S, R1E,						-		y or Parish	13. State
At tota		L45 PIV		Date T.I				16. Date C	omplete	d fall	9111		Sanper 17. Elevat		UT RKB, RT, GL)*
	/2010			06/14	/2011			✓D&		Rea	dy to Pro		DF 61		
18. Total l	•	D 112			19. P	lug Back T.D.:				20. [epth Bri	dge Plug S	et: MD TVI		
21 Type I		VD 109		I Loge I	Qun (Sı	ıbmit copy of	TVD			22. V	Vas well	2072d2 L	/No		mit analysis)
	Dipmeter					iomit copy of	cacity			V	Vas DST	run?	No	Yes (Sub	mit report)
	-					set in well)					Pirectiona	d Survey?	No	✓ Yes (S	Submit copy)
Hole Size	Size/Gra		t. (#/ft.)	Top		Bottom (MI		e Cementer	No. c	f Sks. &	Ł Sh	urry Vol. (BBL)	Cement	Top*	Amount Pulled
38"	32" .3		onductr	0		75'		Depth	200 s		41		surfac	e	
26	22".50	C	onductr	0		1421'			1788	clss C	37	3	surfac	e	
19"	13 3/8	68	8	0		3769'				poz/t		5	surfac	e	
40.05"	+	110				0.470	 			clss G			<u> </u>		
12.25"	9 5/8 I	_80 5.	3.5			9470	357	75'		32-belo 32-belo			surfac	e	
24. Tubing	Record														
Size	Depth	Set (MI	D) Packe	r Depth	(MD)	Size	Dep	th Set (MD)	Packer	Depth (MD)	Size	Depth	Set (MD)	Packer Depth (MD)
25. Produc	ing Interva	ıls	<u> </u>	· · · · · · · · · · · · · · · · · · ·	1	· · · · · · · · · · · · · · · · · · ·	26.	Perforation	Record	[.	سلب				
	Formation	1		Top	,	Bottom		Perforated	interval		Size	No.	Holes		Perf. Status
A) B)		· · · · · · · · · · · · · · · · · · ·					-		<u> </u>						ran da antida da antida
C) D)															
D) 27. Acid, I	Zanatara Ta			1				·							RECEIVE
	Depth Interv		Cement	squeeze,	eic.		· · · · · · · · · · · · · · · · · · ·	A	mount a	nd Type	of Mater	rial		 	
							<u> </u>								NOV 2 9 2011
														וח	
20 Buodu	ation Into	mol A											/	D1	V. OF OIL, GAS & MIN
28. Produ Date First Produced	ction - Inte Test Date	Hours Tested	Test Produc		il BL	Gas MCF	Water BBL	Oil Grav Corr, Al	ity PI	Ga Gr	s avity	Production	1 Method		
Choke Size	Tbg, Press. Flwg. SI	Csg. Press,	24 Hr. Rate	OB	ii BL	Gas MCF	Water BBL	Gas/Oil Ratio		Well	Status	.1			
28a. Produ		erval B													
Date First Produced	Test Date	Hours Tested	Test Product	ion B	il BL	Gas MCF	Water BBL	Oil Grav Corr. Al	rity PI	Gas Grav	ity	Production	n Method		
Choke Size	Tbg, Press. Flwg, SI	Csg. Press.	24 Hr. Rate	OB	ii BL		Water BBL	Gas/Oil Ratio		Well	Status			Newson () (TENTIAL
*(See inst	tructions a	nd snace	s for addi	tional d	ata on i	page 2)							ية المعالمة	Ell Brown !	

28b. Produ	uction - Inte	rval C									
Date First Produced	Test Date	Hours Tested	Test Production	Oil BBL	Gas MCF	Water BBL	Oil Gravity Corr. API		Gas Gravity	Production Method	
Choke Size	Tbg. Press. Flwg. SI	Csg. Press.	24 Hr. Rate	Oil BBL	Gas MCF	Water BBL	Gas/Oil Ratio		Well Status		
28c. Prod	uction - Int	erval D	<u> </u>								
Date First Produced	Test Date	Hours Tested	Test Production	Oil BBL	Gas MCF	Water BBL	Oil Gravity Corr. API		Gas Gravity	Production Method	
Choke Size	Tbg. Press. Flwg. SI	Csg. Press.	24 Hr. Rate	Oil BBL	Gas MCF	Water BBL	Gas/Oil Ratio		Well Status		
29. Disp	osition of C	Sas (Sold, u	sed for fuel,	vented, etc	.)	<u> </u>					
30. Sum	mary of Por	ous Zones	(Include Aqu	iifers):			****		31. Formati	on (Log) Markers	
tests,	v all import including of ecoveries.	tant zones (depth interv	of porosity a val tested, cu	and content shion used,	s thereof: (time tool op	Cored interval en, flowing a	ls and all drill- nd shut-in pres	-stem ssures			
Form	nation	Тор	Bottom		Descri	ptions, Conte	nts, etc.			Name	Top Meas. Depth
1) It	em #23.	9 5/8" cen	plugging pronent details	ocedure):			+ 625 sx txi	lite; sta	Colton Flagstafi North H Indianol Cedar M Arapien Twin Cr Navajo	orn a Iountain eek	Surface 56 290 3200 6981 9790 10470 10873
										· .	
20 7 **											
✓ Ele	ctrical/Mec	hanical Lo	een attached gs (1 full set ng and cemen	req'd.)	✓ Geo	ne appropriate plogic Report re Analysis		eport	☑ Direction	al Survey	
34. I herel	y certify th	at the foreg	going and att	ached infor	mation is co	mplete and co	orrect as detern	nined fr	om all availal	ple records (see attached instru	ctions)*
Name (please prin	Edwar	d A. Higue	ra			Title M	lanage	r - Developr	nent	
Signat	ure		<u> </u>				_ Date	/17/20	11		
Title 18 U States any	S.C Section false, fictit	on 1001 and tious or fra	i Title 43 U udulent stat	S.C Section	on 1212, ma representat	ke it a crime ions as to an	for any person y matter withi	knowiz in its ju	ngly and wills risdiction.	fully to make to any departme	nt or agency of the United

Form 3160-4, page 2)

Operator:

Wolverine Operating Company of Utah, LLC

Well:

Rough Canyon Federal 30-1

Surface Location:

Section 32, T17S, R1E

API Number:

43039500030000

Lease:

UTU-82536

County/State:

Sanpete, UT

Re:

Plugging/Cement Plug Record

Plugging requirements were obtained from Marvin Hendrick, BLM, and the following abandonment plugs were set in the well:

Plug1: Set cement retainer at 9385' MD (displaced OBM out of hole with 9 ppg fresh water mud) and pumped plug #1 under retainer with 10 bbls water spacer, 17 bbls/84 sacks, 15.8 ppg, yield 1.16 cu. Ft/sack Class "G" cement, 10 bbls water spacer, then 124 bbls 9 ppg water based mud. Displaced 15 bbls below retainer and left 2 bbls cement on top of retainer. Pressure tested casing to 750 psi.

Plug 2: Set plug 2 at 6500'-6350 with 10 bbls water spacer, 10.6 bbls/52 sacks, 15.8 ppg, yield 1.16 cu. Ft/sack Class "G" cement (equivalent to 150 foot plug), and 3 bbls water spacer followed by 9 ppg FW mud.

Plug 3: Set 140-ft plug from 3845'-3705' with 10 bbls water spacer, 9.9 bbs/48 sacks, 15.8 ppg, yield 1.16 cu. Ft/sack Class "G" cement, 3 bbls water spacer followed by FW mud.

Set plug 4 at 1485' with 10 bbls water spacer, 7.8 bbls/38 sacks, 15.8 ppg, yield 1.16 cu. Ft/sack Class "G" cement, 3 bbls water followed by FW mud.

Set Plug 5 at surface with 3.2 bbls/16 sacks, 15.8 ppg, yield 1.16 cu.ft/sack Class G cement.

An above-ground post marker has been installed on the well location.



Form 3160-5 (April 2004)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

FORM APPROVED
OM B No. 1004-0137
Expires: March 31, 2007

5.	Lease S	erial No.
	TIVETE I	050506

not use	this	form	for proposals	to drill	or to	re-enter an	
ndoned	well.	Use	Form 3160 - 3	(APD) fo	r such	proposals.	

Do not use this form abandoned well. Use	N/A					
SUBMIT IN TRIPLICATE- Other instructions on reverse side.					CA/Agreement, Name and/or No.	
1. Type of Well Oil Well Gas W	N/A 8. Well Name and No.					
2. Name of Operator Wolverine Operating	Company of Utah,	LLC		Rough Canyon Federal 30-1 9. API Well No. 43039500030000		
3a. Address		3b. Phone No. (include	area code)			
55 Campau NW, Grand Rapids, MI 49503 616-458-1150					d Pool, or Exploratory Area	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) SHL: 288' FNL, 452' FWL, Sec 32, T17S, R1E, NWNW BHL: 149'FNL, 390' FEL, Sec 31, T17S, R1E, NENE					or Parish, State	
12. CHECK APPROPR	JATE BOX(ES) T	O INDICATE NATUR	E OF NOTICE, R	EPORT, OR	OTHER DATA	
TYPE OF SUBMISSION		TYP	E OF ACTION			
Notice of Intent Subsequent Report Final Abandonment Notice	cidize Iter Casing asing Repair change Plans	Deepen Fracture Treat New Construction Plug and Abandon	Production (Stan Reclamation Recomplete Temporarily Al	bandon	Water Shut-Off Well Integrity Other Daily drilling reports	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

See attached chronological listing of all daily drilling reports.

RECEIVED NOV 2 9 2011

DIV. OF OIL, GAS & MINING

14. I hereby certify that the foregoing is true and correct Name (Printed/Typed) Edward A. Higuera	Title	Manager - Development						
Signature	Date	11/18/2011						
THIS SPACE FOR FEDERAL OR STATE OFFICE USE								
Approved by		Title	Date					
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.								
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any p States any false, fictitious or fraudulent statements or representations as to any matter	erson within	knowingly and willfully to make to a its jurisdiction.	any department or agency of the United					

(Instructions on page 2)





Subject: Wolverine Operating Company of Utah, LLC

Rough Canyon Federal 30-1

NW¼ NW¼ Sec 32-T17S-R1E surface location

NE1/4 SE1/4 Sec 30-T17S-R1E BHL

Sanpete County, Utah.

28 - 29 August 2010

Depth 0' GL, no casing set. MIRURT. MW – none, Vis. – none, FL –N/A. Surveys: none.

30 August 2010

Depth 1' GL, no casing set. MIRURT, spud at 1700 hrs, 8/29/10 w/ 38" bit. MW – 8.8, Vis. – 53, FL – not controlled. Surveys: none.

31 August 2010

Depth 15' GL, no casing set. Drill to 15' w/ 38" bit. MW – 8.8, Vis. – 53, FL – not controlled. Surveys: none.

1 September 2010

Depth 44' GL, no casing set. Drill to 44' GL. MW – 8.8, Vis. – 53, FL – not controlled. Surveys: none.

2 September 2010

Depth 69' GL, no casing set. Drill to 69' GL. MW - 8.8, Vis. - 53, FL - not controlled. Surveys: $\frac{1}{2}$ degree @ 55'.

3 September 2010

Depth 75' GL, 32" x ." wall @ 75' GL. Drill to 76', POOH, run 32" casing to 75' GL, run tremmie pipe, pump 25 sx Neat mixed at 15.6 ppg, WOC, run tremmie pipe, tag cmt at 68' GL, mix cement. MW – 8.8, Vis. – 53, FL – not controlled. Surveys: none.

4 September 2010

Depth 79' GL, 32" x ." wall @ 75' GL. Pump 125 sx Neat mixed at 15.3 pg, WOC, run tremmie pipe, tag cmt at 51', mix & pump 50 sx Neat mixed at 15.3 ppg, filled to GL, did not fall back, WOC, PU 26" bit & BHA, RU rotary table, hook up flow lines, GIH, tag cmt @ 68' GL, drill cmt from 68' to 75', drill to 79', POOH to change top sub. MW – 8.8, Vis. – 60, FL – not controlled. Surveys: none.

5 September 2010

Depth 79' GL, 32" x ." wall @ 75' GL. POOH, add DC's, GIH, drill to 133', POOH, PU DC's, drill to 170'. MW – 8.7, Vis. – 60, FL – not controlled. Surveys: none.

6 September 2010

Depth 298' GL, 32" x ." wall @ 75' GL. Drill to 250' GL, C&C, survey, drill to 290', survey, switch to reverse circulation, drill to 298' GL. MW – 9.3, Vis. – 46, FL – 8. Surveys: 1 degree @ 110', 1 degree @ 220' & 1 degree @ 250'.

7 September 2010

Depth 390' GL, 32" x ." wall @ 75' GL. Drill to 330, survey, drill to 390, attempt survey, tool separated from wire line, POOH, remove survey tool, GIH. MW-9.3, Vis.-43, FL-9. Surveys: 1 degree @ 10', 1.25 degrees @ 300'.

8 September 2010

Depth 494' GL, 32" x ." wall @ 75' GL. GIH, survey, C&C, drill to 430, survey, drill to 470, C&C,

survey, drill to 494'. MW - 9, Vis. -42, FL - 9. Surveys: 0.25 degrees @ 100', 0.25 degrees @ 200', 0.75 degrees @ 390' & 0.25 degrees @ 440'.

9 September 2010

Depth 585' GL, 32" x ." wall @ 75' GL. Drill to 510', survey, drill to 550', losing mud @ 100 bbl/hr, survey, drill to 585'. MW - 8.7, Vis. - 40, FL - 14. Surveys: 1 degree @ 480' & 1.5 degrees @ 520'.

10 September 2010

Depth 671' GL, 32" x ." wall @ 75' GL. Drill to 590', losing 20 bbl/hr mud, C&C, survey, drill to 630', C&C, survey, drill to 670', started losing returns at 648, lost all returns at 670', survey, drill to 671, still losing all returns, POOH. MW - 8.7, Vis. - 45, FL - 14. Surveys: 1 degree @ 560', 1 degree @ 600' & $1\frac{1}{2}$ degrees @640'.

11 September 2010

Depth 705' GL, 32" x ." wall @ 75' GL. POOH, LD some DC's, GIH, pump LCM slugs, drill to 674', losing 50 bbl/hr mud, drill to 678', losing 50 bbl/hr, drill to 705' lost all returns, mix mud & LCM. MW – 8.7, Vis. – 51, FL – 14. Surveys: none.

12 September 2010

Depth 752' GL, 32" x ." wall @ 75' GL. Mix & pump LCM slugs, drill to 714', losing 25 bbl/hr mud, C&C, drill to 734', losing 50 bbl/hr mud, C&C, survey, drill to 746', losing 75 bbl/hr mud, lost total returns at 746', mix LCM slugs, lost 400 bbl mud, drill to 750', losing 90 bbl/hr mud, lost all returns at 750', lost 300 bbl mud, drill to 751', losing 125 bbl/hr mud, lost all returns at 750', lost 350 bbl mud, drill to 752', losing 125 bbl/hr, mis LCM slugs. MW – 8.7, Vis. – 51, FL – 14. Surveys: 2½ degrees @ 700'.

13 September 2010

Depth 762' GL, 32" x ." wall @ 75' GL. Mix & pump LCM slugs, drill to 754', losing 125 bbl/hr mud, survey, lost returns, TFNB, establish partial circulation, drill to 762', losing 75 bbl/hr . MW - 8.9, Vis. -55, FL - 14. Surveys: 1¾ degrees @ 720'.

14 September 2010

Depth 803' GL, 32" x ." wall @ 75' GL. Drill to 775', losing 75bbl/hr mud, survey, drill to 785', losing 125 bbl/hr mud, drill to 803', lost returns, mix & pump slugs, attempt to drill blind, discontinued due to high torque, mix & pump LCM slugs. MW – 8.6, Vis. – 40, FL – not controlled. Surveys: 1 degree @ 740'.

15 September 2010

Depth 856' GL, 32" x ." wall @ 75' GL. Mix & pump mud + LCM slugs, PU 20' off bottom, switch to conventional circulation, drill to 856 w/ no returns, losing 75 bbl/hr mud. MW - 8.8, Vis. - 70, FL - NC. Surveys: none.

16 September 2010

Depth 916' GL, 32" x ." wall @ 75' GL. Drill to 916', losing 100 bbl/hr mud. MW - 8.8, Vis. - 70, FL - NC. Surveys: none.

17 September 2010

Depth 971' GL, 32" x ." wall @ 75' GL. Drill to 935, C&C, survey, drill to 971'. MW – 8.6, Vis. – 68, FL – NC. Surveys: 134 degrees @ 880'.

18 September 2010

Depth 1047' GL, 32" x ." wall @ 75' GL. Drill blind to 1015, survey, drill blind to 1047'. MW – 8.9, Vis. – 68, FL – NC. Surveys: 1 degrees @ 950'.

19 September 2010

Depth 1140' GL, 32" x ." wall @ 75' GL. Drill & survey, circulate conventional, losing 125 bbl/hr mud. MW - 8.6, Vis. -93, FL -NC. Surveys: 2 degrees @ 1020' & 2° @ 1060'.

20 September 2010

Depth 1228' GL, 32" x ." wall @ 75' GL. Drill & survey, circulate conventional, losing 125 bbl/hr mud. MW - 8.6, Vis. -84, FL -NC. Surveys: $2\frac{1}{2}$ ° @ 1100' & 2° @ 1140'.

21 September 2010

Depth 1235' GL, 32" x ." wall @ 75' GL. Drill to 1235', C&C, found fluid level in hole, POOH to 975', switch to flooded reverse circulating method, wash back to 1215', POOH. MW – 8.6, Vis. – 62, FL – NC. Surveys: 134° @ 1180'.

22 September 2010

Depth 1280' GL, 32" x ." wall @ 75' GL. PU new bit, GIH, drill. MW – 8.9, Vis. – 44, FL – NC. Surveys: none.

23 September 2010

Depth 1371' GL, 32" x ." wall @ 75' GL. Drill & survey, circulate w/flooded reverse method.. MW – 8.9, Vis. – 43, FL – NC. Surveys: 1½° @ 1220', 2½° @ 1260', 2° @ 1280' & 1¼° @ 1300'.

24 September 2010

Depth 1425' GL, 32" x ." wall @ 75' GL. Drill & survey to TD at 1425', C&C, POOH, LDDP & BHA, clean up tools, tongs & wrenches. MW - 9.1, Vis. -45, FL -NC. Surveys: 2° @ 1360'.

25 September 2010

Depth 1425' GL, 32" x ." wall @ 75' GL. Prep to run casing, cut off 32" csg, set landing plate, run 22" x $\frac{1}{2}$ " wall casing to 840'. MW - 8.8, Vis. - 45, FL - NC. Surveys: none.

26 September 2010

Depth 1425' GL, 32" x ." wall @ 75' GL. Run casing to 900', wait on crane, RU 250 ton crane, run casing to 1421', RD crane. MW - 8.8, Vis. -45, FL - NC. Surveys: none.

27 September 2010

Depth 1425' GL, 22" x ½" wall @ 1421' GL. Fluid level at 778', pump to clear 1. tremmie pipe, (1) mix & pump 44 sx (1.17 cf/sk) Cl. "G" cement + 4% CaCl2 mixed @ 15.4 ppg, POOH, WOC, tag cmt @ 1375', (2) mix & pump 44 sx (1.17 cf/sk) Cl. "G" cement + 4% CaCl2 mixed @ 15.4 ppg, POOH, WOC, tag cmt @ 1325', (3) mix & pump 44 sx (1.17 cf/sk) Cl. "G" cement + 4% CaCl2 mixed @ 15.4 ppg, POOH, WOC, tag cmt @ 1265', POOH w/ tremmie pipe to clear plugged pipe, GIH w/ tremmie pipe, tag cmt @ 1263', MW – 8.8, Vis. – 45, FL – NC. Surveys: none.

28 September 2010

Depth 1425' GL, 22" x ½" wall @ 1421' GL. (4) mix & pump 44 sx (1.17 cf/sk) Cl. "G" cement + 4% CaCl2 mixed @ 15.4 ppg, POOH, WOC, tag cmt @ 1175', (5) mix & pump 44 sx (1.17 cf/sk) Cl. "G" cement + 4% CaCl2 mixed @ 15.4 ppg, POOH, WOC, tag cmt @ 1095', (6) mix & pump 275 sx (1.17 cf/sk) Cl. "G" cement + 3% CaCl2 mixed @ 15.5 ppg, POOH, WOC, tag cmt @ 760', (7) mix & pump 325 sx (1.17 cf/sk) Cl. "G" cement + 2% CaCl2 mixed @ 15.3 ppg, POOH, WOC, tag cmt @ 480', (8)

mix & pump 44 sx (1.17 cf/sk) Cl. "G" cement + 2% CaCl2 mixed @ 15.3 ppg, MW – 8.8, Vis. – 45, FL – NC. Surveys: none.

29 September 2010

Depth 1371' GL, 22" x ½" wall @ 1421' GL. (8 continued) Tag cement at 472', (9) mix & pump 44 sx (1.17 cf/sk) Cl. "G" cement + 4% CaCl2 mixed @ 15.4 ppg, POOH, WOC, tag cmt @ 470', (10) mix & pump 325 sx (1.17 cf/sk) Cl. "G" cement + 3% CaCl2 mixed @ 15.4 ppg, POOH, WOC, tag cmt @ 330', (11) mix & pump 165 sx (1.17 cf/sk) Cl. "G" cement + 3% CaCl2 mixed @ 15.5 ppg, POOH, WOC, tag cmt @ 185', (12) mix & pump 325 sx (1.17 cf/sk) Cl. "G" cement + 3% CaCl2 mixed @ 15.3 ppg, POOH, WOC, tag cmt @ 35', (13) mix & pump 65 sx (1.17 cf/sk) Cl. "G" cement + 3% CaCl2 mixed @ 15.3 ppg, circulate to surface, cement standing at surface, WOC, RDRT, MW – 8.8, Vis. – 45, FL – NC. Surveys: none.

30 September 2010

Depth 1425' GL, 22" x $\frac{1}{2}$ " wall @ 1421' GL. RDRT, PU air hammer, drill mouse hole for big rig, RDMO Boart Longyear LK-12 rig. MW – 8.8, Vis. – 45, FL – NC. Surveys: none.

1 October 2010

Depth 1425' GL, 22" x ½" wall @ 1421' GL. RDMO Boart Longyear rig LK-12, prepare pad for Boart Longyear rig LM-700. MW – nr, Vis. – nr, FL – nr. Surveys: none.

2 October 2010

Depth 1425' GL, 22" x ½" wall @ 1421' GL. Prepare pad, start mobilizing Boart Longyear rig LM-700. MW – nr, Vis. – nr, FL – NC. Surveys: none.

3 October 2010

Depth 1425' GL, 22" x ½" wall @ 1421' GL. Mobilizing Boart Longyear rig LM-700. MW – nr, Vis. – nr, FL – NC. Surveys: none.

4 October 2010

Depth 1425' GL, 22" x ½" wall @ 1421' GL. Mobilizing Boart Longyear rig LM-700. MW – nr, Vis. – nr, FL – NC. Surveys: none.

5 October 2010 – 11 October 2010

Depth 1425' GL, 22" x ½" wall @ 1421' GL. MIRURT Boart-Longyear rig LM-700. MW – nr, Vis. – nr, FL – nr. Surveys: none.

12 October 2010

Depth 1425' GL, 22" x ½" wall @ 1421' GL. Finalize rig up, PU BHA & drill pipe. MW – nr, Vis. – nr, FL – nr. Surveys: none.

13 October 2010

Depth 1453' GL, 22" x ½" wall @ 1421' GL. PU drill pipe, C&C, drill cement 1439-48, drill. MW – 8.8, Vis. – 45, FL – no control. Surveys: none.

14 October 2010

Depth 1586' GL, 22" x ½" wall @ 1421' GL. Drilling. MW – 8.9, Vis. – 42, FL – 6.8. Surveys: none.

15 October 2010

Depth 1720' GL, 22" x ½" wall @ 1421' GL. Drill & survey. MW – 9.0, Vis. – 48, FL – 6.6. Surveys: 3° @ 1525' & 3° @ 1581'.

16 October 2010

Depth 1720' GL, 22" x ½" wall @ 1421' GL. Drill & survey. MW - 8.9, Vis. - 51, FL - 6.8. Surveys: 4° @ 1660', $3\frac{1}{4}^{\circ}$ @ 1691' & 4° @ 1721'.

17 October 2010

Depth 1864' GL, 22" x ½" wall @ 1421' GL. Drill & survey. MW – 8.8, Vis. – 53, FL – 8.2. Surveys: 4° @ 1755' & 3½° @ 1791'.

18 October 2010

Depth 1938' GL, 22" x ½" wall @ 1421' GL. Drill & survey. MW – 8.7, Vis. – 47, FL – 8. Surveys: 3¾° @ 1821' & 3¼° @ 1850'.

19 October 2010

Depth 2020' GL, 22" x $\frac{1}{2}$ " wall @ 1421' GL. Drill & survey, run gyro survey, drill, trip for new bit. MW – 8.7, Vis. – 55, FL – 8.8. Surveys: $3\frac{3}{4}$ ° @ 1960'.

20 October 2010

Depth 2040' GL, 22" x $\frac{1}{2}$ " wall @ 1421' GL. TFNB, change roller reamers, drill. MW – 8.7, Vis. – 51, FL – 6.6. Surveys: none.

21 October 2010

Depth 2201' GL, 22" x ½" wall @ 1421' GL. Drill & survey. MW – 8.9, Vis. – 53, FL – 8.8. Surveys: 3¾° @ 2046 & 3¾° @ 2116.

22 October 2010

Depth 2345' GL, 22" x $\frac{1}{2}$ " wall @ 1421' GL. Drill & survey. MW - 8.9, Vis. - 53, FL - 10. Surveys: 4° @ 2150, 4° @ 2216 & $\frac{4}{4}$ ° @ 2280.

23 October 2010

Depth 2509' GL, 22" x ½" wall @ 1421' GL. Drill & survey. MW – 8.9, Vis. – 50, FL – 11. Surveys: 2½° @ 2320' & 4¾° @ 2385'.

24 October 2010

Depth 2620' GL, 22" x ½" wall @ 1421' GL. Drill & survey. MW – 8.9, Vis. – 50, FL – 10.4. Surveys: 6° @ 2450' & 4½° @ 2519'.

25 October 2010

Depth 2629' GL, 22" x $\frac{1}{2}$ " wall @ 1421' GL. Drill to 2626, C&C, TFNB, drill. MW - 8.9, Vis. - 51, FL - 8.6. Surveys: none.

26 October 2010

Depth 2698' GL, 22" x ½" wall @ 1421' GL. Drill & survey. MW – 8.8, Vis. – 47, FL – 11. Surveys: 6° @ 2580.

27 October 2010

Depth 2700' GL, 22" x ½" wall @ 1421' GL. Drill & survey, TFNB. MW - 8.7, Vis. - 38, FL - 15.6. Surveys: 534° @ 2665.

28 October 2010

Depth 2700' GL, 22" x $\frac{1}{2}$ " wall @ 1421' GL. TIH w/ mill, ream bottom of hole, POOH, PU bit, GIH, ream 2691 to 2694. MW -8.8, Vis. -47, FL -15.6. Surveys: none.

29 October 2010
Depth 2702' GL, 22" x ½" wall @ 1421' GL. Ream 2694-2700, TFNB, drill. MW – 8.6, Vis. – 58, FL – 16.4. Surveys: none.

30 October 2010

Depth 2780' GL, 22" x ½" wall @ 1421' GL. Drill. MW – 8.7, Vis. – 59, FL – 7. Surveys: none.

31 October 2010

Depth 2850' GL, 22" x ½" wall @ 1421' GL. Drill & survey. MW – 8.8, Vis. – 50, FL – 14.4. Surveys: 6° @ 2770'.

1 November 2010

Depth 2861' GL, 22" x $\frac{1}{2}$ " wall @ 1421' GL. Drill to 2861, TFNB. MW – 8.8, Vis. – 50, FL – 10.4. Surveys: none.

2 November 2010

Depth 2898' GL, 22" x $\frac{1}{2}$ " wall @ 1421' GL. GIH, wash & ream to bottom, drill. MW – 8.8, Vis. – 56, FL – 13.6. Surveys: none.

3 November 2010

Depth 2912' GL, 22" x $\frac{1}{2}$ " wall @ 1421' GL. Drill & survey, POOH looking for leaks in drill string. MW – 8.8, Vis. – 56, FL – 13.6. Surveys: 6° @ 2862.

4 November 2010

Depth 2912' GL, 22" x ½" wall @ 1421' GL. POOH, change bit, GIH, attempt to circulate on bottom, plugged string, POOH. MW – 8.8, Vis. – 56, FL – 13.6. Surveys: none.

5 November 2010

Depth 2959' GL, 22" x $\frac{1}{2}$ " wall @ 1421' GL. POOH, GIH building stands, drilling. MW – 8.7, Vis. – 55, FL – 11.2. Surveys: none.

6 November 2010

Depth 3049' GL, 22" x ½" wall @ 1421' GL. Drill & survey. MW – 8.9, Vis. – 55, FL – 8.4. Surveys: 6° @ 2920'.

7 November 2010

Depth 3102 GL, 22" x $\frac{1}{2}$ " wall @ 1421' GL. Drill & survey, POOH. MW - 8.9, Vis. - 57, FL - 12. Surveys: $\frac{5}{4}$ ° @ 3000'.

8 November 2010

Depth 3123 GL, 22" x $\frac{1}{2}$ " wall @ 1421' GL. POOH for new bit, GIH, drill & survey. MW – 8.9, Vis. – 55, FL – 8.2. Surveys: 6° @ 3070'.

9 November 2010

Depth 3220' DF, 22" x ½" wall @ 1421' GL. Drill & survey. MW – 9, Vis. – 58, FL – 10. Surveys: 5° @ 3145'.

10 November 2010

Depth 3318' DF, 22" x ½" wall @ 1421' GL. Drill & survey. MW – 9, Vis. – 58, FL – 10.5. Surveys: none.

11 November 2010

Depth 3329' DF, 22" x $\frac{1}{2}$ " wall @ 1421' GL. Drill & survey, POOH, change bit, GIH. MW – 9, Vis. – 58, FL – 10.5. Surveys: 5 $\frac{3}{4}$ ° @ 3245'.

12 November 2010

Depth 3351' DF, 22" x ½" wall @ 1421' GL. GIH, drill. MW – 9, Vis. – 60, FL – 9. Surveys: none.

13 November 2010

Depth 3353' DF, 22" x $\frac{1}{2}$ " wall @ 1421' GL. Drill, TFNB, drill. MW - 8.9, Vis. - 57, FL - 9. Surveys: none.

14 November 2010

Depth 3385' DF, 22" x ½" wall @ 1421' GL. Drill & survey. MW – 8.9, Vis. – 58, FL – 9. Surveys: 5¾° @ 3317'.

15 November 2010

Depth 3449' DF, 22" x ½" wall @ 1421' GL. Drill. MW -9, Vis. - 56, FL - 8. Surveys: 6° @ 3070'.

16 November 2010

Depth 3457' DF, 22" x ½" wall @ 1421' GL. Drill & survey, TFNB. MW – 9, Vis. – 57, FL – 8.

Surveys: 7° @ 3384'.

17 November 2010

Depth 3472' DF, 22" x ½" wall @ 1421' GL. GIH, drill. MW – 9.1, Vis. – 56, FL – 9.2. Surveys: none.

18 November 2010

Depth 3512' DF, 22" x ½" wall @ 1421' GL. Drill & survey, POOH. MW – 9, Vis. – 55, FL – 8. Surveys: 6¼° @ 3450'.

19 November 2010

Depth 3545' DF, 22" x $\frac{1}{2}$ " wall @ 1421' GL. TFNB, drill. MW - 9.1, Vis. - 48, FL - 9.2. Surveys: none.

20 November 2010

Depth 3617' DF, 22" x ½" wall @ 1421' GL. Drill & survey. MW – 8.9, Vis. – 56, FL – 9.5. Surveys: 6½° @ 3511'.

21 November 2010

Depth 3690' DF, 22" x ½" wall @ 1421' GL. Drill & survey. MW - 8.9, Vis. - 55, FL - 9.6. Surveys: $6\frac{1}{2}$ ° @ 3571'.

22 November 2010

Depth 3710' DF, 22" x ½" wall @ 1421' GL. Drill, POOH. MW –8.9, Vis. – 56, FL – 10.2. Surveys: 6¼° @ 3647'.

23 November 2010

Depth 3711' DF, 22" x $\frac{1}{2}$ " wall @ 1421' GL. GIH, C&C, wash to bottom, C&C, POOH. MW – 8.9, Vis. – 56, FL – 10.2. Surveys: none.

24 November 2010

Depth 3733' DF, 22" x $\frac{1}{2}$ " wall @ 1421' GL. POOH, PU BHA, GIH, circ & wash to bottom, drill. MW - 8.8, Vis. - 58, FL - 10.8. Surveys: none.

25 November 2010

Depth 3807' DF, 22" x $\frac{1}{2}$ " wall @ 1421' GL. Drill & survey, stuck pipe, work free, POOH 100', wash to bottom. MW - 8.8, Vis. - 58, FL - 10.8. Surveys: none.

26 November 2010

Depth 3829' DF, 22" x $\frac{1}{2}$ " wall @ 1421' GL. Wash to bottom, drill & survey, stuck pipe, work free, POOH. MW -8.8, Vis. -60, FL -12.8. Surveys: 6° @ 3720'.

27 November 2010

Depth 3829' DF, 22" x $\frac{1}{2}$ " wall @ 1421' GL. GIH, mix & pump mud. MW - 9.8, Vis. - 65, FL - not measured. Surveys: none.

28 November 2010

Depth 3829' DF, 22" x $\frac{1}{2}$ " wall @ 1421' GL. Build mud weight, GIH, wash to 3698', pull up to 3644', C&C. MW -9.5, Vis. -64, FL -12. Surveys: none.

29 November 2010

Depth 3829' DF, 22" x $\frac{1}{2}$ " wall @ 1421' GL. C&C, build mud weight, wash to 3814. MW -10, Vis. -75, FL -12. Surveys: none.

30 November 2010

Depth 3829' DF, 22" x ½" walls @1421' GL. Wash to 3826', Bit stuck, unplugged, circulate and condition mud. MW 10.10, Vis. 67, FL – Not reported. Surveys: none

1 December 2010

Depth 3829' DF, 22" x $\frac{1}{2}$ " wall @ 1421' GL. C&C, wash down and up, C&C. MW - 10.2, Vis. - 67, FL - 10.2. Surveys: none.

2 December 2010

Depth 3829' DF, 22" x $\frac{1}{2}$ " wall @ 1421' GL. C&C, rebuild mud volume, C&C. MW -9.5, Vis. -68, FL -9.2. Surveys: none.

3 December 2010

Depth 3829' DF, 22" x ½" wall @ 1421' GL. C&C, wash & ream, C&C. MW – 9.2, Vis. – 65, FL – 9. Surveys: none.

4 December 2010

Depth 3829' DF, 22" x ½" wall @ 1421' GL. C&C, POOH. MW – 9.4, Vis. – 63, FL – 7. Surveys: none.

5 December 2010

Depth 3829' DF, 22" x $\frac{1}{2}$ " wall @ 1421' GL. LD BHA, RU to run casing, run 13-3/8 casing with 1.9" parasite string. MW – 9.3, Vis. – 62, FL – 6.5. Surveys: none.

6 December 2010

Depth 3829' DF, 22" x $\frac{1}{2}$ " wall @ 1421' GL. Run 13-3/8 casing, tag at 3770', land at 3769', cement w/ Schlumberger, diagnose casing issue. MW -9.1, Vis. -53, FL -14. Surveys: none.

7 December 2010

Depth 3829' DF, 22" x $\frac{1}{2}$ " wall @ 1421' GL. Diagnose casing issue, wait on wireline truck, ran CCL/temp survey, leak in joint from 752 to 798, ran CCL/CBL, TOC @ 2710', wait on gage ring, ring cut too large, drift w/ 12.1" gage ring, casing open to cementing plug, wait on Boart camera truck. MW -9, Vis. -54, FL -10. Surveys: none.

8 December 2010

Depth 3829' DF, $13\frac{3}{8}$ @ 3769' DF. Wait on tools, cut off casing above slips, RU false rotary table, GIH w/ drill string to 900', evacuate hole, POOH, GIH w/ camera, fluid level at 650', POOH w/ camera, GIH w/ drill string to 1100', evacuate hole, POOH w/ drill string, GIH w/ camera, examine casing from 752' to 798', ok, POOH w/ camera, retool to investigate for deeper leak. MW – 9, Vis. – 55, FL – 9.5. Surveys: none.

9 December 2010

Depth 3829' DF, $13\frac{3}{8}$ @ 3769' DF. Make up stands of $5\frac{1}{2}$ DP, wait on spinner survey tools, run spinner survey, leak located at air injection sub at 2483', pump water down parasite string, set up casing alignment assy. MW -9, Vis. -32, FL -13.4. Surveys: none.

10 December 2010

Depth 3829' DF, 13% @ 3769' DF. Prep to run csg alignment assy, GIH w/ 12%" OD csg alignment assy, space out over air sub interval, hook up to hang both DP and casing from block/top drive assy, pull csg slips, found csg parted, slack off until taking weight, set slips on csg, POOH w/ csg alignment assy, RU tremmie pipe, GIH down annulus w/ tremmie pipe to 2360'. MW – 9, Vis. – 32, FL – 13.4. Surveys: none.

11 December 2010

Depth 3829' DF, $13\frac{3}{8}$ @ 3769' DF. GIH w/ tremmie pipe to 2770', RU cementer, mix & pump 270 cf of 15.6 ppg cement, pull tremmie pipe to 2250', WOC, tag cmt at 2365', mix & pump 388 cf of 15.6 ppg cmt, pull tremmie pipe to 1770', WOC, tag cmt at 2140', tremmie pipe plugged, pull up tremmie pipe and attempt to clear. MW - 8.9, Vis. -67, FL -10.8. Surveys: none.

12 December 2010

Depth 3829' DF, 13¾ @ 3769' DF. POOH w/ tremmie pipe, found 40' plugged w/ cmt, GIH w/ tremmie pipe, tag at 2105', mix and pump 333 cf of 15.3 ppg cmt, POOH w/ tremmie pipe to 1500', WOC, GIH w/ tremmie pipe, tag cmt at 1870', mix & pump 322 cf of 15.3 ppg cmt, POOH w/ tremmie pipe to 1270', WOC, GIH to 1670'. MW – 8.9, Vis. – 62, FL – 9.8. Surveys: none.

13 December 2010

Depth 3829' DF, 13% @ 3769' DF. Tag cmt at 1700' w/ tremmie pipe, cement w/ 333 cf of 15.6 ppg cmt, POOH w/ tremmie pipe to 1100', WOC, GIH w/ tremmie pipe to tag @ 1370', cement w/ 1071 cf of 15.6 ppg cmt, POOH w/ tremmie pipe, WOC, GIH w/ tremmie pipe, tag cmt @ 150', cement w/ 187 cf of 15.3 ppg cmt, cement to surface WOC. MW –9.1, Vis. – 66, FL – 10.7. Surveys: none.

14 December 2010

Depth 3829' DF, 13\% @ 3769' DF. WOC, cut off 13\% csg, break down csg alignment assy, PU 12\% bit and scraper, GIH, work through air inj sub, POOH, LD scraper, GIH w/ bit. MW - 9.2, Vis. - 41,

15 December 2010

Depth 3829' DF, 13\% @ 3769' DF. GIH, tag @ 3707', C&C, POOH, PU Howco squeeze pkr, GIH w/pkr, pkr set down at 830', POOH, left pkr in hole, check pkr performance, no seal, RU on parasite string. MW – 9, Vis. – 34, FL – 16.2. Surveys: none.

16 December 2010

Depth 3829' DF, $13\frac{3}{8}$ @ 3769' DF. Check csg leak, POOH w/ DP, fill csg, pump 5 bw dn parasite string, cement down parasite string, pump 150 sx of 15.8 ppg class "G" cement, flush w/ 2 bw, WOC, make up and rack back stands of drill pipe. MW - 8.9, Vis. - 49, FL - 11.6. Surveys: none.

17 December 2010

Depth 3829' DF, $13\frac{3}{8}$ @ 3769' DF. MU stands of DP, check parasite string, plugged w/ cmt, GIH, circ at 801', drill up pkr to 831', pkr released and went down hole, wash to 895', POOH, PU stands of dp, GIH w/ bit, tag plug @ 2465', drill pkr & cmt to 2582', wash to 2665', fill csg, hole standing full, pooh. MW -8.8, Vis. -42, FL -11.6. Surveys: none.

18 December 2010

Depth 3829' DF, 13% @ 3769' DF. POOH, PU stands of dp, tag at 3702', circulate, drill to 3737', hole standing full, drill cmt to 3767', empty mud tank, build mud, C&C, drill to 3771, starting to lose fluid, POOH, static fluid level at 886', stand back stands of dp, GIH. MW - 8.8, Vis. - 50, FL - 11.6. Surveys: none.

19 December 2010

Depth 3829' DF, 13% @ 3769' DF. C&C, to 3777', bit plugging, POOH, bit plugged, clean out bit, fluid level at 1201', GIH, ream to 3779', bit plugged, POOH. MW -8.8, Vis. -47, FL -11. Surveys: none.

20 December 2010

Depth 3829' DF, 13\% @ 3769' DF. POOH, clean bit, MU BHA, GIH, ream to 3782', bit plugged, POOH. MW -8.8, Vis. -58, FL - 8.6. Surveys: none.

21 December 2010

Depth 3829' DF, 13% @ 3769' DF. Unplug shock sub, LD shock sub & IBS, GIH, ream to 3818', . MW – 8.8, Vis. – 47, FL – 8.8. Surveys: none.

22 December 2010

Depth 3886' DF, $13\frac{3}{6}$ @ 3769' DF. Ream to 3829', drill. MW -8.7, Vis. -77, FL -9.2. Surveys: none.

23 December 2010

Depth 3981' DF, 13\% @ 3769' DF. Drill & survey. MW - 8.7, Vis. - 64, FL - 8.6. Surveys: 6° @ 3840'.

24 December 2010

Depth 4065' DF, 13\% @ 3769' DF. Drill & survey. MW - 8.9, Vis. -60, FL - 8.8. Surveys: 6° @ 3940'.

25 December 2010

Depth 4119' DF, 13\% @ 3769' DF. Drill & survey. MW - 9, Vis. - 65, FL - 8.7. Surveys: 6° @ 4040'.

26 December 2010

Depth 4163' DF, 13\% @ 3769' DF. Drill, C&C, POOH. MW -9, Vis. -73, FL - 9.5. Surveys: none.

27 December 2010

Depth 4213' DF, 13% @ 3769' DF. PU new bit, inspect BHA, GIH, drill. MW -9, Vis. -60, FL -9. Surveys: none.

28 December 2010

Depth 4304' DF, 133/2 @ 3769' DF. Drill & survey. MW – 9, Vis. – 58, FL – 10. Surveys: 6° @ 4200'.

29 December 2010

Depth 4328' DF, 13\% @ 3769' DF. Drill, C&C, POOH, PU new bit, GIH. MW – 8.9, Vis. – 55, FL – 9.5. Surveys: none.

30 December 2010

Depth 4398' DF, 13\% @ 3769' DF. GIH, drill & survey. MW - 9, Vis. - 56, FL - 9.5. Surveys: 6° @ 4330'.

31 December 2010

Depth 4495' DF, 13% @ 3769' DF. Drill. MW -9, Vis. -53, FL -9.5. Surveys: none.

1 January 2011

Depth 4560' DF, 13\% @ 3769' DF. Drill & survey. MW - 9, Vis. - 56, FL - 9.5. Surveys: 5.5° @ 4431'.

2 January 2011

Depth 4617' DF, 13\% @ 3769' DF. Drill & survey. MW -9, Vis. -54, FL -9. Surveys: 6\circ @ 4532'.

3 January 2011

Depth 4627' DF, 13% @ 3769' DF. Drill, POOH, PU new bit, GIH. MW -9, Vis. -60, FL -9.5. Surveys: none

4 January 2011

Depth 4707' DF, 13\% @ 3769' DF. Drill & survey. MW - 9, Vis. - 60, FL - 9.5. Surveys: 6° @ 4615'.

5 January 2011

Depth 4785' DF, 13\% @ 3769' DF. Drill & survey. MW -9, Vis. - 56, FL - 9.4. Surveys: 5.5° @ 4700'.

6 January 2011

Depth 4861' DF, 13\% @ 3769' DF. Drill & circulate. MW - 9, Vis. - 57, FL - 8.8. Surveys: none.

7 January 2011

Depth 4926' DF, 13\% @ 3769' DF. Drill & survey. MW -8.9, Vis. -59, FL - 8.6. Surveys: 5.5° @ 4800'.

8 January 2011

Depth 5015' DF, 13% @ 3769' DF. Drill & survey. MW – 9.1, Vis. – 56, FL – 9. Surveys: 5.75° @ 4906'.

9 January 2011

Depth 5093' DF, 13% @ 3769' DF. Drill & survey, TFNB. MW -9.2, Vis. -55, FL -8.8. Surveys: 6° @ 5040'.

10 January 2011

Depth 5118' DF, 13\% @ 3769' DF. TFNB, drill. MW - 9.3, Vis. - 40, FL - 8.8. Surveys: none

11 January 2011

Depth 5192' DF, 13\% @ 3769' DF. Drill. MW - 9.2, Vis. - 53, FL - 8.4. Surveys: none.

12 January 2011

Depth 5207' DF, 13\% @ 3769' DF. Drill, TFNB. MW -9.5, Vis. -56, FL - 8. Surveys: none.

13 January 2011

Depth 5245' DF, 13\% @ 3769' DF. TFNB, drill & survey. MW - 9.1, Vis. - 55, FL - 9. Surveys: 5° @ 5154'.

14 January 2011

Depth 5320' DF, 13\% @ 3769' DF. Drill & survey. MW -9.2, Vis. -52, FL - 9.4. Surveys: 5.5° @ 5260'.

15 January 2011

Depth 5420' DF, 13\% (a) 3769' DF. Drill. MW - 9.3, Vis. - 58, FL - 9.4. Surveys: none.

16 January 2011

Depth 5517' DF, 13\% @ 3769' DF. Drill & survey. MW - 9.3, Vis. - 61, FL - 8.4. Surveys: 6° @ 5367'.

17 January 2011

Depth 5550' DF, 13% @ 3769' DF. Drill, POOH for leaks in air string. MW -9.3, Vis. -70, FL -9.2. Surveys: none

18 January 2011

Depth 5550' DF, 13\% @ 3769' DF. POOH looking for leaks in air string, replace bit, roller reamer & blade reamer, GIH. MW - 8.9, Vis. - not reported, FL - 11.9. Surveys: none.

19 January 2011

Depth 5618' DF, 13\% @ 3769' DF. GIH, circ. to bottom, drill, survey. MW -8.9, Vis. - 52, FL - 10.8. Surveys: none.

20 January 2011

Depth 5690' DF, 133 @ 3769' DF. Survey, drill, C&C, drill. MW – 8.9, Vis. – 52, FL – 10.8. Surveys: 6° @ 5560'.

21 January 2011

Depth 5761' DF, 13\% @ 3769' DF. C&C, drill C&C, drill. MW -9, Vis. -50, FL - 11.2. Surveys: none.

22 January 2011

Depth 5846' DF, 133 @ 3769' DF. Drill, survey, POOH. MW – 9, Vis. – 52, FL – 9.6. Surveys: 6° @ 5720'.

23 January 2011

Depth 5846' DF, $13\frac{3}{8}$ @ 3769' DF. POOH, install new bit, GIH. MW -9, Vis. -52, FL -9.6. Surveys: none.

24 January 2011

Depth 5883' DF, 13\% @ 3769' DF. GIH, C&C, drill. MW - 9, Vis. - 56, FL - 12.5. Surveys: none.

25 January 2011

Depth 5938' DF, 13% @ 3769' DF. Drill, rig repair, drill, POOH. MW -9, Vis. - 56, FL - 11.6. Surveys: none.

26 January 2011

Depth 5976' DF, 133 @ 3769' DF. GIH, C&C, POOH, C&C, GIH, drill & survey. MW – 9, Vis. – 63, FL – 10.5. Surveys: none.

27 January 2011

Depth 6000' DF, 13\% @ 3769' DF. Survey, drill. MW -9, Vis. -62, FL - 10.5. Surveys: 6° @ 5915'.

28 January 2011

Depth 6051' DF, 13% @ 3769' DF. Drill, POOH. MW -9, Vis. -61, FL - 10.5. Surveys: none.

29 January 2011

Depth 6066' DF, 13% @ 3769' DF. Trip for leaks in air string, drill, trip for leaks in air string. MW – 9, Vis. – 61, FL – 10.5. Surveys: none.

30 January 2011

Depth 6066' DF, 13\% @ 3769' DF. POOH, NU Hydril & rotating hd, GIH. MW - 9, Vis. - 61, FL - 10.5. Surveys: none.

31 January 2011

Depth 6098' DF, 13\% @ 3769' DF. GIH, drill. MW - 9.1, Vis. - 63, FL - 10.5. Surveys: none.

1 February 2011

Depth 6174' DF, 13\% @ 3769' DF. Drill. MW -9.1, Vis. -54, FL -10.4. Surveys: none.

2 February 2011

Depth 6228' DF, 13\% @ 3769' DF. Drill & survey. MW - 9.1, Vis. - 57, FL - 10.2. Surveys: 6° @ 6150'.

3 February 2011

Depth 6271' DF, 13\% @ 3769' DF. Drill. MW -9.1, Vis. - 52, FL - 10.2. Surveys: none.

4 February 2011

Depth 6338' DF, 13\% @ 3769' DF. Drill. MW -9.1, Vis. -56, FL - 10.5. Surveys: none.

5 February 2011

Depth 6395' DF, 13\% @ 3769' DF. Drill, POOH. MW - 9.2, Vis. - 55, FL - 10.5. Surveys: none.

6 February 2011

Depth 6395' DF, 13% @ 3769' DF. POOH, slip drilling line, change bit & roller reamers, GIH. MW -9, Vis. -61, FL -10.5. Surveys: none.

7 February 2011

Depth 6442' DF, 13\% @ 3769' DF. GIH, drill. MW - 9.2, Vis. - 55, FL - 10.5. Surveys: none.

8 February 2011

Depth 6491' DF, 13% @ 3769' DF. Drill. MW -9.3, Vis. - 56, FL - 8.4. Surveys: none.

9 February 2011

Depth 6502' DF, 13% @ 3769' DF. Drill, C&C, run survey, tool stuck, pull survey line off survey tool, POOH w/ bit, survey tool left in hole, change bit, GIH. MW - 9.2, Vis. - 54, FL - 8.6. Surveys: none.

10 February 2011

Depth 6502' DF, 13% @ 3769' DF. Inspect DC's looking for Totco tool, GIH, with bit depth at 2395' dropped block to floor, wait on orders. MW -9.2, Vis. -57, FL -8.5. Surveys: none.

11-16 February 2011

Depth 6502' DF, 13% @ 3769' DF. Investigate problems that resulted in dropped block. MW -9.2, Vis. -57, FL -8.5. Surveys: none.

17-22 February 2011

Depth 6502' DF, 13% @ 3769' DF. Investigate problems that resulted in dropped block. MW -9.2, Vis. -57, FL -8.5. Surveys: none.

23 February - 1 March 2011

Depth 6502' DF, $13\frac{3}{8}$ @ 3769' DF. Investigate problems that resulted in dropped block, rig repair. MW -9.2, Vis. -57, FL -8.5. Surveys: none.

2 March 2011

Depth 6502' DF, 13\% @ 3769' DF. Rig repair, GIH w/ overshot in attempt to catch survey tool, wash to bottom, POOH. MW -9.2, Vis. -44, FL - 17. Surveys: none.

3 March 2011

Depth 6502' DF, 13\% @ 3769' DF. POOH, LD DP & DC's. MW -9.2, Vis. -44, FL - 17. Surveys: none.

4 March 2011

Depth 6502' DF, 13\% @ 3769' DF. LDDP, RDRT. MW -9.2, Vis. -44, FL - 17. Surveys: none.

5 March - 9 March 2011

Depth 6502' DF, 13\% @ 3769' DF. RDRT. MW -9.2, Vis. -44, FL - 17. Surveys: none.

10 March – 14 March 2011

Depth 6502' DF, $13\frac{3}{8}$ @ 3769' DF. RDMORT, clean up location and prep for MIRU Patterson rig. MW -9.2, Vis. -44, FL -17. Surveys: none.

15 March – 21 March 2011

Depth 6502' DF, 13\% @ 3769' DF. MIRU Patterson rig 304. MW -9.2, Vis. -44, FL - 17. Surveys: none.

22 - 24 March 2011

Depth 6502' DF, 13% @ 3769' DF. MIRU Patterson rig 304. MW -9.2, Vis. -44, FL - 17. Surveys: none.

25 March 2011

Depth 6502' DF, 13% @ 3769' DF. Build stands of drill pipe, PU bit and junk basket. MW -9.2, Vis. -44, FL -17. Surveys: none.

26 March 2011

Depth 6502' DF, 13\% @ 3769' DF. GIH to 2977', break circulation, GIH, spot 150 bbl LCM pill at csg shoe, GIH to 6470', rig repair. MW -8.6, Vis. -48, FL - 8.7. Surveys: none.

27 March 2011

Depth 6502' DF, 13% @ 3769' DF. Rig repair, POOH to csg shoe, rig repair. MW -8.6, Vis. -49, FL -8.1. Surveys: none.

28 March 2011

Depth 6505' DF, $13\frac{3}{6}$ @ 3769' DF. Rig repair, GIH to 6494', break circulation, drill on junk 6494' to 6505'. MW -8.6, Vis. -51, FL -8.8. Surveys: none.

29 March 2011

Depth 6516' DF, 13\% @ 3769' DF. Drill on junk, POOH, PU new BHA, GIH, survey. MW – 8.6, Vis. – 51, FL – 9.8. Surveys: 5.01° @ 6481'.

30 March 2011

Depth 6605' DF, 13\% @ 3769' DF. Work on lost circulation, drill, POOH to casing shoe, build mud volume, GIH, MWD not responding, spot LCM pill. MW -8.6, Vis. -49, FL - 8.1. Surveys: none.

31 March 2011

Depth 6605' DF, 13\% @ 3769' DF. Wait on LCM pill to soak, pump LCM pill, wait on pill to soak, pump LCM pill, wait on pill to soak, POOH, change MWD, GIH w/ new bit. MW – 8.6, Vis. – 49, FL – 8.1. Surveys: none.

1 April 2011

Depth 6615' DF, 13. @ 3769' DF. Build mud volume, weight up to 8.8 ppg, add 15 ppb LCM, GIH, wash and ream to bottom, drill, pump service. MW –8.8, Vis. –55, FL – 7. Surveys: none.

2 April 2011

Depth 6731' DF, 13. @ 3769' DF. Pump service, drill & survey. MW – 8.9, Vis. – 55, FL – 9.8. Surveys: 5.01° @ 6640'.

3 April 2011

Depth 6858' DF, 13. @ 3769' DF. Drill & survey. MW – 8.8, Vis. – 54, FL – 14. Surveys: 4.92°@ 6738'.

4 April 2011

Depth 6953' DF, 13. @ 3769' DF. Drill & survey, C&C, POOH. MW – 8.8, Vis. – 44, FL – 13. Surveys: 4.9° @ 6830'.

5 April 2011

Depth 6995' DF, 13. @ 3769' DF. POOH, change bit and stabilizers, GIH, ream to btm, drill to 6995. MW – 8.8, Vis. – 41, FL – 12.6. Surveys: 5.1° @ 6915' & 5.19°@ 6924'.

6 April 2011

Depth 7080' DF, 13. @ 3769' DF. Drill & survey. MW – 8.9, Vis. – 48, FL – 9.2. Surveys: 5.01° @ 7016'.

7 April 2011

Depth 7197' DF, 13. @ 3769' DF. Drill & survey. MW -8.95, Vis. -48, FL -9. Surveys: 4.92° @ 7117'.

8 April 2011

Depth 7258' DF, 13. @ 3769' DF. Drill & survey, TFNB. MW – 8.8, Vis. – 51, FL – 6. Surveys: 4.92° @ 7246'.

9 April 2011

Depth 7323' DF, 13. @ 3769' DF. GIH, ream to bottom, drill. MW -8.8, Vis. - 50, FL - 7.8. Surveys: none.

10 April 2011

Depth 7412' DF, 13. @ 3769' DF. Drill & survey. MW – 8.8, Vis. – 63, FL – 7.6. Surveys: 5.1° @ 7313'.

11 April 2011

Depth 7531' DF, 13. @ 3769' DF. Drill & survey. MW – 8.8, Vis. – 75, FL – 7.4. Surveys: 5.32°@ 7408'.

12 April 2011

Depth 7596' DF, 13. @ 3769' DF. Drill & survey, POOH. MW – 8.8, Vis. – 67, FL – 7.2. Surveys: 5.8° @ 7568'.

13 April 2011

Depth 7596' DF, 13. @ 3769' DF. PU bit, IBS & reamer, GIH, ream to bottom. MW –8.7, Vis. – 56, FL – 7.5. Surveys: none.

14 April 2011

Depth 7665' DF, 13. @ 3769' DF. Ream to bottom, drill & survey. MW – 8.9, Vis. – 53, FL – 7. Surveys: 5.8° @ 7596'.

15 April 2011

Depth 7766' DF, 13. @ 3769' DF. Drill & survey. MW -8.8, Vis. -67, FL -6. Surveys: 5.8° @ 7691'.

16 April 2011

Depth 7794' DF, 13. @ 3769' DF. Drill & survey, POOH, PU new bit, pump service. MW – 8.8, Vis. – 58, FL – 6.8. Surveys: 5.8° @ 7741'.

17 April 2011

Depth 7825' DF, 13. @ 3769' DF. Pump service, GIH, drill & survey. MW – 8.8, Vis. – 60, FL – 7. Surveys: 5.89°@ 7786'.

18 April 2011

Depth 7844' DF, 13. @ 3769' DF. Drill & survey, TFNB, drill. MW – 8.8, Vis. – 52, FL – 6.5. Surveys: 5.89°@ 7775'.

19 April 2011

Depth 8011' DF, 13. @ 3769' DF. Drill & survey. MW – 8.8, Vis. – 52, FL – 6.8. Surveys: 6° @ 7880'.

20 April 2011

Depth 8174' DF, 13. @ 3769' DF. Drill & survey. MW -8.9, Vis. -60, FL -6.5. Surveys: 6.4° @ 8071'.

21 April 2011

Depth 8331' DF, 13. @ 3769' DF. Drill & survey. MW – 8.8, Vis. – 64, FL – 7. Surveys: 7.1° @ 8165' & 7.9° @ 8260'.

22 April 2011

Depth 8424' DF, 13. @ 3769' DF. Drill & survey, C&C, POOH. MW -8.8, Vis. -50, FL -6. Surveys: 8.8° @ 8351'.

23 April 2011

Depth 8438' DF, 13. @ 3769' DF. POOH, change BHA, GIH, drill. MW - 8.8, Vis. - 62, FL - 6.4. Surveys: none.

24 April 2011

Depth 8439' DF, 13. @ 3769' DF. Drill, C&C, POOH, change BHA, GIH, W&R to bottom. MW - 8.8, Vis. -50, FL - 7. Surveys: none.

25 April 2011

Depth 8542' DF, 13. @ 3769' DF. Drill & survey. MW – 8.8, Vis. – 58, FL – 6.8. Surveys: 9°@ 8396' & 9° @ 8481'.

26 April 2011

Depth 8619' DF, 13. @ 3769' DF. Drill & survey. MW – 8.8, Vis. – 55, FL – 7. Surveys: 9.4° @ 8541'.

27 April 2011

Depth 8619' DF, 13. @ 3769' DF. Drill & survey, TFNB, GIH. MW –8.8, Vis. – 52, FL – 7.1. Surveys: 9.4° @ 8541'.

28 April 2011

Depth 8772' DF, 13. @ 3769' DF. Drill & survey. MW – 8.8, Vis. – 60, FL – 6.7. Surveys: 9.49° @ 8641' & 9.71° @ 8721'.

29 April 2011

Depth 8863' DF, 13. @ 3769' DF. Drill & survey. MW -8.8, Vis. -57, FL -7. Surveys: 9.89° @ 8812'.

30 April 2011

Depth 8966' DF, 13. @ 3769' DF. Drill & survey. MW – 8.8, Vis. – 54, FL – 7.9. Surveys: 10.11° @ 8907'.

1 May 2011

Depth 9056' DF, 13. @ 3769' DF. Drill & survey. MW - 8.8, Vis. - 43, FL - 7.8. Surveys: 10.5° @ 9002'.

2 May 2011

Depth 9143' DF, 13. @ 3769' DF. Drill & survey, TFNB. MW – 8.8, Vis. – 61, FL – 8.9. Surveys: 10.9°@ 9096'.

3 May 2011

Depth 9192' DF, 13. @ 3769' DF. TFNB, ream to bottom, drill. MW – 8.8, Vis. – 45, FL – 9.1. Surveys: none.

4 May 2011

Depth 9287' DF, 13. @ 3769' DF. Drill & survey. MW -8.8, Vis. - 51, FL - 7.5. Surveys: 10.7° @ 9205'.

5 May 2011

Depth 9351' DF, 13. @ 3769' DF. Drill & survey. MW – 8.9, Vis. – 49, FL – 5.1. Surveys: 10.9° @ 9286'.

6 May 2011

Depth 9398' DF, 13. @ 3769' DF. Drill to 9366', 15 stand short trip, drill. MW -8.8, Vis. -51, FL -8. Surveys: none.

7 May 2011

Depth 9480' DF, 13. @ 3769' DF. Drill & survey. MW – 8.8, Vis. – 54, FL – 7.5. Surveys: 10.8° @ 9378'.

8 May 2011

Depth 9482' DF, 13. @ 3769' DF. Drill, POOH for logs & casing. MW - 8.8, Vis. -52, FL - 7.5. Surveys: none.

9 May 2011

Depth 9482' DF, 13. @ 3769' DF. Left cones in hole, magnet run, log w/ Halliburton, GIH w/ concave mill and junk baskets. MW - 8.75, Vis. -58, FL - 6.6. Surveys: none.

10 May 2011

Depth 9482' DF, 13. @ 3769' DF. Ream tight spots, mill on junk, POOH, work tight spots, POOH, rig repair. MW - 8.8, Vis. -47, FL - 7.5. Surveys: none.

11 May 2011

Depth 9483' DF, 13. @ 3769' DF. GIH for C&C, C&C, POOH, LD jars & x-o's, RU casers, run 9-5/8" casing. MW – 8.8, Vis. – 64, FL – 7.5. Surveys: none.

12 May 2011

Depth 9483' DF, 13. @ 3769' DF. Damaged shoe jt during make up, wait on replacement cementing shoe, run 9-5/8 casing. MW - 8.8, Vis. - 47, FL - 8. Surveys: none.

13 May 2011

Depth 9483' DF, 9. @ 9470' DF. Run 9. casing to 9469.52' DF, C&C, cement w/ Schlumberger. MW - 8.75, Vis. - 43, FL - 7.5. Surveys: none.

14 May 2011

Depth 9483' DF, 9. @ 9470' DF. WOC, cut off pipe, weld on bradenhead, NU BOP's. MW -8.75, Vis. -44, FL - 8. Surveys: none.

15 May 2011

Depth 9494' DF, 9. @ 9470' DF. Test BOP's, lay out & strap BHA, GIH to 3489', drill stage collar, GIH, drill cmt collar, shoe its and shoe, drill to 9494' DF. MW – 8.7, Vis. – 44, FL – 8. Surveys: none.

16 May 2011

Depth 9494' DF, 9. @ 9470' DF. C&C, conduct leak-off test to 14.2 ppg EMW, pump pill, POOH, RU Baker truck, run Gyrodata gyro survey 4200' to 2000', RU Baker seismic, run VSP log. MW - 8.8, Vis. - 52, FL - 7.5. Surveys: none.

17 May 2011

Depth 9494' DF, 9. @ 9470' DF. Run VSP open hole log, RU Zeco solids control eqip, RU Katch Kan equip, PU BHA, move OBM to active system, GIH. MW – 11.6, Vis. – 78, FL – 9.8. Surveys: none.

18 May 2011

Depth 9494' DF, 9. @ 9470' DF. Displace WBM w/ OBM, run leak-off test to 13 ppg, lost returns, lost 120 bbl OBM, POOH, stand back directional tools, GIH w/ packer, set at 3657', test annulus to 750 psi/30 min, OK, test drill pipe, losing mud, GIH w/ pkr. MW – 11.2, Vis. – 46, FL – 8.2. Surveys: none.

19 May 2011

Depth 9494' DF, 9. @ 9470' DF. Set pkr at 9362' DF, test csg to 700 psi/30min, OK, C&C, reduce MW from 11.6 to 10.6 ppg, POOH, LD pkr, GIH w/ directional tools. MW - 10, Vis. -49, FL - 6.4. Surveys: none.

20 May 2011

Depth 9498' DF, 9. @ 9470' DF. Test MWD, GIH, drill, losing 10 bbl mud/hr, lower MW to 10.2 ppg, work on mud losses, POOH, LD BHA, PU tooth bit & junk basket. MW –10, Vis. – 36, FL – 6.8. Surveys: none.

21 May 2011

Depth 9498' DF, 9. @ 9470' DF. GIH, build LCM pill, spot on bottom, monitor well, C&C, . MW - 9.2, Vis. -48, FL - nil. Surveys: none.

22 May 2011

Depth 9505' DF, 9. @ 9470' DF. C&C, drill, spot pill, POOH, PU directional BHA, GIH. MW – 9, Vis. – 47, FL – nil. Surveys: none.

23 May 2011

Depth 9576' MD, 9% @ 9470' DF. Drill & survey. MW - 9, Vis. - 46, FL - nil. Surveys: 11.1° @ 9487'.

24 May 2011

Depth 9650' MD, 9% @ 9470' DF. Drill & survey. MW – 9, Vis. – 47, FL – nil. Surveys: 11.3° @ 9520' & 11.1° @ 9574'.

25 May 2011

Depth 9654' MD, 9% @ 9470' DF. Drill, mud losses unsustainable, POOH, RU Schlumberger loggers, run cement imaging log over length of 9-5/8 casing. MW – 9, Vis. – 51, FL – nil. Surveys: none.

26 May 2011

Depth 9654' MD, 9% @ 9470' DF. GIH w/ Halliburton pkr, set pkr at 3422', test back side to 700 psi/30 min, held ok, losing mud below pkr, move pkr to 5029', test annulus to 700 psi/30 min, held ok, losing mud below pkr, POOH w/ pkr, GIH open ended. MW –9.1, Vis. – 52, FL – nil. Surveys: none.

27 May 2011

Depth 9654' MD, 9% @ 9470' DF. GIH open ended to 9632', spot cement pill, pump 15 bbl spacer, 35.3 bbl cement, 5.7 bbl spacer, displace w/ 126 bbl OBM, POOH 30 stands, fill hole w/ OBM, shut in well and pressure up to 350 psi, pressure bled off to 324 psi, WOC. MW – 9, Vis. – 51, FL – nil. Surveys: none

28 May 2011

Depth 9654' MD, 9% @ 9470' DF. Hold pressure, pressure dropped to 312 psi, bleed off pressure, POOH, GIH w/ mill tooth bit slick, W&R, circulate at 420 gpm, losing mud at 33 bph, C&C @ 210 gpm, losing mud at 0 bph, spot 60 bbl Strata Vanguard LCM pill, wait on LCM pill to soak, GIH to 9600'. MW – 9.1, Vis. – 48, FL – nil. Surveys: none.

29 May 2011

Depth 9660' DF, 9% @ 9470' DF. Drill, still losing mud, reduce MW to 8.5 ppg, drill, POOH, PU directional tools, GIH. MW – 8.5, Vis. – 46, FL – nil. Surveys; none.

30 May 2011

Depth 9771' DF, 9% @ 9470' DF. GIH, W&R, drill & survey. MW – 8.5, Vis. – 46, FL – nil. Surveys: 11.1° @ 9603', 10.9° @ 9634', 11.3° @ 9666' & 11.1° @ 9698'.

31 May 2011

Depth 9901' MD, 9% @ 9470' DF. Drill & survey. MW – 8.5, Vis. – 44, FL – nil. Surveys: 11.2° @ 9730', 11.3° @ 9762', 11.2° @ 9793' & 11.2° @ 9825'.

1 June 2011

Depth 10,039' MD, 9. @ 9470' DF. Drill & survey. MW – 8.5, Vis. – 44, FL – nil. Surveys: 11.4° @ 9857', 12.4° @ 9888', 13.3° @ 9920' & 14.5° @ 9951'.

2 June 2011

Depth 10,151' MD, 9. @ 9470' DF. Drill & survey. MW – 8.5, Vis. – 47, FL – nil. Surveys: 15.4° @ 9983', 16.1° @ 10015', 16.6° @ 10047' & 17.8° @ 10079'.

3 June 2011

Depth 10,229' MD, 9. @ 9470' DF. Drill & survey, C&C, POOH. MW -8.5, Vis. -53, FL - nil. Surveys: 18.5° @ 10111' & 19.4° @ 10142'.

4 June 2011

Depth 10,285' MD, 9. @ 9470' DF. PU new bit & BHA, GIH, drill & survey. MW – 8.5, Vis. – 61, FL – nil. Surveys: 20.9° @ 10172' & 21.3° @ 10203'.

5 June 2011

Depth 10,481' MD, 9. @ 9470' DF. Drill & survey. MW – 8.5, Vis. – 53, FL – nil. Surveys: 23.6° @ 10235', 25.4° @ 10266', 26.8' @ 10298', 27.7° @ 10329', 29.3° @ 10361' & 29.9° @ 10392'.

6 June 2011

Depth 10,542' DF, 9. @ 9470' DF. Drill & survey, mud losses, pull into csg shoe, build mud volume, GIH, fill hole, drill, mud losses, pull into csg shoe. MW - 8.3, Vis. - 45, FL - nil. Surveys: 31.6° @ 10424'.

7 June 2011

Depth 10,588' MD, 9. @ 9470' DF. Wait on LCM soak, GIH, mix LCM pill, GIH, drilling. MW – 8.3, Vis. – 45, FL – nil. Surveys: none.

8 June 2011

Depth 10,685' MD, 9. @ 9470' DF. Drill & survey, POOH. MW – 8.5, Vis. – 47, FL – nil. Surveys: 35.3° @ 10520'.

9 June 2011

Depth 10,715' MD, 9. @ 9470' DF. POOH, change BHA, GIH, drill & survey. MW – 8.6, Vis. – 53, FL – nil. Surveys: 39.6° @ 10627' & 40.2° @ 10646'.

10 June 2011

Depth 10,855' MD, 9. @ 9470' DF. Drill & survey. MW -8.4, Vis. -49, FL - nil. Surveys: 41.3° @ 10678', 41° @ 10741 & 40.5° @ 10772'.

11 June 2011

Depth 10,967' MD, 9. @ 9470' DF. Drill & survey, short trip, drill & survey. MW – 8.3, Vis. – 49, FL – nil. Surveys: 38.6° @ 10867' & 38.5° @ 10899'.

12 June 2011

Depth 10,972' MD, 9. @ 9470' DF. Drill, POOH, PU new bit, test BOP's, GIH. MW – 8.3, Vis. – 55, FL – nil. Surveys: none.

13 June 2011

Depth 11,085' DF, 9. @ 9470' DF. GIH, drill & survey. MW – 8.3, Vis. – 53, FL – nil. Surveys: 38.8° @ 10930', 38.7° @ 10962' & 38.8° @ 10994'.

14 June 2011

Depth 11,173' MD, 9. @ 9470' DF. Drill & survey, short trip, drill, spot LCM pill, drill& survey. MW – 8.2, Vis. – 47, FL – nil. Surveys: 38.8° @ 11025' & 39.4° @ 11089'.

15 June 2011

Depth 11,204' MD, 9. @ 9470' DF. Spot LCM pill, drill, C&C, POOH for logs. MW - 8.3, Vis. -46, FL - nil. Surveys: none.

16 June 2011

Depth 11,204' MD, 9. @ 9470' DF. POOH, LD BHA, run open hole logs, GIH w/ bit to 2000', WOO. MW - 8.3, Vis. - 47, FL - nil. Surveys: none.

17 June 2011

Depth 11,204' MD, 9. @ 9470' DF. WOO, POOH, LDDP, clean mud tanks, PU Halliburton retainer, GIH. MW –8.3, Vis. – 43, FL – nil. Surveys: none.

18 June 2011

Depth 11,204' MD, 9. @ 9470' DF. GIH, set retainer @ 9385' MD, displace OBM out of hole w/ 9 ppg fresh water mud, pump plug #1 under retainer, pumped 17 bbl of cement. MW – 9, Vis. – 43, FL – not reported. Surveys: none.

19 June 2011

Depth 11,204' MD, 9. @ 9470' DF. POOH, LD Howco tools, GIH, pressure test csg to 750 psi, ok, set plug 2 @ 6500' 10 bbl cement, set plug 3 @ 3845' 10 bbl cement, set plug 4 @ 1485' 8 bbl cement, LDDP to 765'. MW-9, Vis.-43, FL-not reported. Surveys: none.

20 June 2011

Depth 11,204' MD, 9. @ 9470' DF. Pump surface plug cement, clean up, rig down rig equipment, rig released 18:00 hrs 19 June 2011, final report. MW – not reported, Vis. – not reported, FL – not reported. Surveys: none.

21 - 23 June 2011

Depth 11,204' MD, 9. @ 9470' DF. Rig down, move out rotary tools. MW – not reported, Vis. – not reported, FL – not reported. Surveys: none.

Form 3160-5

UNITED STATES

	DEPARTMENT OF THE BUREAU OF LAND MAN.	Expires: No.	March 31, 2007			
SUNDRY Do not use th abandoned we	UTU-852536 6. If Indian, Allottee N/A	or Tribe Name				
SUBMIT IN TR	7. If Unit or CA/Agreement, Name and/or No. N/A					
	Gas Well Other			8. Well Name and No. Rough Canyon Federal 30-1 9. API Well No. 43039500030000 10. Field and Pool, or Exploratory Area		
2. Name of Operator Wolverine O	perating Company of Utah, Ll	,				
3a. Address 55 Campau NW, Grand Rapid	ls, MI 49503	3b. Phone No. (include of 616-458-1150	area code)			
 Location of Well (Footage, Sec., SHL: 288' FNL, 452' FWL, S BHL: 149'FNL, 390' FEL, Se 	ec 32, T17S, R1E, NWNW			Exploratory 11. County or Parish. Sanpete, Utah	, State	
12. CHECK A	PPROPRIATE BOX(ES) TO			EPORT, OR OTHE	R DATA	
TYPE OF SUBMISSION		TYP	E OF ACTION			
Notice of Intent Subsequent Report Final Abandonment Notice	Acidize Alter Casing Casing Repair Change Plans Convert to Injection	Deepen Fracture Treat New Construction Plug and Abandon Plug Back	Production (Statement of Statement of Statem	□ We	nter Shut-Off ell Integrity ner Drilling highlights	
12 Describe Proposed or Complet	ed Operation (clearly state all perti	nent details including estin	nated starting date of a	ny proposed work and ar	proximate duration thereof	

If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Please see attached document detailing the main highlights experienced from the actual drilling of the Rough Canyon Federal 30-1 from spud to abandonment, as requested by Marvin Hendricks, BLM,

> RECEIVED NOV 2 9 2011

FORM APPROVED

DIV. OF OIL, GAS & MINING

14. I hereby certify that the foregoing is true and correct Name (Printed/Typed) Edward A. Higuera Tit	le Manager - Development							
Signature Da	ate 11/18/2011							
THIS SPACE FOR FEDERAL OR STATE OFFICE USE								
Approved by	Title	Date						
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.	Office							
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212 make it a crime for any pers	son knowingly and willfully to make to	any department or agency of the United						

States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.





Operator:

Wolverine Operating Company of Utah, LLC

Well:

Rough Canyon Federal 30-1

Surface Location:

Section 32, T17S, R1E

API Number:

43039500030000

Lease:

UTU-82536

County/State:

Sanpete, UT

Re:

Summary of Drilling Operations

The purpose of this document is to satisfy a request by the BLM to summarize the main highlights experienced at this well as compared to the permitted APD and subsequent sundries.

The Rough Canyon Federal 30-1 was originally permitted to test the Navajo, with a projected total depth of 12,800' MD. Several changes to the original APD were needed to accomplish the drilling of this well, such as changes to the casing program and the drilling fluid systems, which will be discussed below.

The biggest geological factor that impacted drilling was the much thicker North Horn and Indianola conglomerates. Table 1 is a comparison of the anticipated formation tops and the actual tops encountered in the well.

Table 1 - Comparison of Geologic Prog and Actual formation Tops

Age	Formation	Prog, TVD/MD	Actual , TVD/MD
Tertiary	Colton	Surface	surface
Tertiary	Flagstaff	56'	56'
Tertiary	North Horn	156'	290′
Cretaceous	Indianola	356'	3195/3200'
Cretaceous	Cedar Mountain		6963/6981'
Jurassic	Twist Gulch	2800/2800'	Not identified*
Triassic	Triassic (unidentified)*		7934/7959'
	Thrust		9741/9790'
Jurassic	Arapien	3863/3940'	9741/9790'
Jurassic	Twin Creek	9765/10100′	10373/10470'
Jurassic	Navajo	10079/10420'	10687/10873'
	TD	12400/12800'	

^{*}The interval below the Cedar Mountain has not been confirmed as Twist Gulch. Sample descriptions suggest it could be Twist Gulch, but palynogical data indicates it is Triassic age, meaning a thrust was cut.

The conglomerates are slow drilling, cannot support a full liquid column, and are sensitive to changes in hydrostatic pressure, yielding larger volumes of water when underbalanced and incurring large mud losses when slightly overbalanced. LCM appeared to have limited impact on controlling losses. Successful drilling was found within a very narrow operating range. This was initially addressed with Boart's reverse circulation method, and then with an aerated fresh water mud, once Patterson rig #304 was mobilized to the site. The thicker conglomerates resulted in the Boart rig being on location much longer than anticipated.





Rough Canyon Federal, Sanpete Co., UT Summary of Drilling Operations Page 2

Originally Boart Rig LK-12 was programmed to drill the 36" hole and set 32" conductor at 50' GL and then drill and set the 20" conductor to 1200' which was intended to cover the Colton, Flagstaff, North Horn and the upper part of the Indianola. After setting the 20", Boart would be rigged down and Patterson rig #304 would be moved in to the finish the hole. When the North Horn and, in particular, the Indianola, were not encountered near prog depth, coupled with the issues encountered at Painted Rock Federal 29-1 drilling the same rocks, Wolverine decided to increase the conductor size to 22" and set it to 1425' (weight limit for this Boart rig), and then move in a larger Boart rig to set the 13-3/8" casing into the Arapien, which was anticipated near 4000'. The 22" conductor was set instead of the programmed 20" to allow the use of the 19" bit, which would facilitate cementing with Boart's tremie pipe and allow the use of parasite string (to be run on the outside of the 13-3/8" casing).

This decision to use the larger Boart rig and continue drilling to the Arapien was made to take advantage of the Boart reverse circulation method and minimize the problems that were encountered in the Painted Rock well. This decision was also predicated with reaching the Arapien near the prog depth of 4000'.

Drilling continued to 3829', where it was decided to set 13-3/8 casing because of deteriorating hole conditions (bit/pipe was stuck and worked free) which could not be improved. Rigged up and ran 13-3/8", 68 #/ft J-55 BTC (report date December 5, 2010) with a 1.9" parasite string. The casing was landed at 3769' (tagged fill at 3770') and cemented down casing with 1450 sacks 14.4 ppg, yield 1.05 cu. Ft/sack, 35:65 Poz mix . During cementing, the casing moved and investigations were undertaken to diagnose the problem. It was determined the casing parted at the air injection sub (part of the parasite assembly) coupling. The casing alignment assembly was run and the casing "re-aligned" and the annulus was cemented to surface with tremie pipe in multiple batches (total of 3170 sacks) of 15.6 ppg class "G" cement until cement was at surface. The injection sub/parasite string had likely separated and had to be squeezed to get a pressure test on the casing rendering the parasite string unavailable for future operations.

Drilling operations continued with Boart with a 12.25" bit to a depth of 6502', at which, not having reached Arapien, Boart was rigged down and moved off and Patterson rig #304 was moved-in to finish the well. Patterson commenced drilling with an aerated fresh water mud and drilled to 9482', where openhole logs were run. The 9-5/8" casing was run and landed at 9470' and cemented with a two stage cement job, as follows: Stage1: Lead-1320 sacks, 12.5 ppg, yield 2.12 cu. Ft/sack Class "G" plus additives followed by 625 sacks, 13.5 ppg, yield 1.26 cu./sack TXI-lite. Stage 2: Lead-625 sacks, 12.5 ppg, yield 2.12 cu. Ft/sack Class "G". Stage 2 was circulated to surface.

Table 2- Casing Setting Depths

	Hole Size	Proposed	Actual	Comment
		Depth	Depth	
32" conductor, 126.7#/ft, 0.375	38"	72'	72'	Ran 32" conductor
wall				
20" conductor, 106.5 #/ft	26"	1200'	1424'	Ran 22" conductor
13-3/8", 68#/ft casing	19" ⁽¹⁾	4000′	3769'	Ran 13-3/8", 68# J55 BTC
9-5/8", 53.5 #/ft casing	12.25"	10,100'	9470'	Ran 9-5/8 53.3 # L-80
5-1/2" 20 #/ft casing	8.5"	12800′	NA	Did not run
				1171
				CONT IVE
		(6)		(:Ola .
		The same of the same of	in conti	O ^o

Rough Canyon Federal, Sanpete Co., UT Summary of Drilling Operations Page 3

 $^{(1)}$ Hole size was increased to 19" from 17.5" to accommodate parasite string on 13-38" casing.

After setting the 9-5/8' casing, shoe was drilled out, and the mud was swapped out for oil-based mud ("OBM"). The well was drilled with an OBM to TD of 11,204, where openhole logs were run. Wolverine decided to plug and abandon the well as a dry hole. Plugging requirements were obtained from Marvin Hendrick, BLM, and the following abandonment plugs were set in the well:

Plug1: Set cement retainer at 9385' MD (displaced OBM out of hole with 9 ppg fresh water mud) and pumped plug #1 under retainer with 10 bbls water spacer, 17 bbls/84 sacks, 15.8 ppg, yield 1.16 cu. Ft/sack Class "G" cement, 10 bbls water spacer, then 124 bbls 9 ppg water based mud. Displaced 15 bbls below retainer and left 2 bbls cement on top of retainer. Pressure tested casing to 750 psi.

Plug 2: Set plug 2 at 6500'-6350 with 10 bbls water spacer, 10.6 bbls/52 sacks, 15.8 ppg, yield 1.16 cu. Ft/sack Class "G" cement (equivalent to 150 foot plug), and 3 bbls water spacer followed by 9 ppg FW mud.

Plug 3: Set 140-ft plug from 3845'-3705' with 10 bbls water spacer, 9.9 bbs/48 sacks, 15.8 ppg, yield 1.16 cu. Ft/sack Class "G" cement, 3 bbls water spacer followed by FW mud.

Set plug 4 at 1485' with 10 bbls water spacer, 7.8 bbls/38 sacks, 15.8 ppg, yield 1.16 cu. Ft/sack Class "G" cement, 3 bbls water followed by FW mud.

Set Plug 5 at surface with 3.2 bbls/16 sacks, 15.8 ppg, yield 1.16 cu.ft/sack Class G cement.

An above-ground post marker has been installed on the well location.

The OBM pit has been treated with Soli-bond and closed. The water based cutting has been closed; final surface reclamation should be finished fall 2011.





Form 3160-5 (April 2004)

UNITED STATES

E		Expires: March 31, 2007 5. Lease Serial No.		
SUNDRY Do not use the abandoned we	6. If Indian, Allottee or Tribe Name N/A			
SUBMIT IN TRI	7. If Unit or CA/Agreement, Name and/or No. N/A			
1. Type of Well Oil Well □ □	Gas Well□□ Cther			8. Well Name and No. Rough Canyon Federal 30-1
Name of Operator Wolverine Operator Address	perating Company of Utah, Ll	LC 3b. Phone No. (include	area code)	9. API Well No. 43039500030000
55 Campau NW, Grand Rapid 4. Location of Well (Footage, Sec., SHL: 288' FNL, 452' FWL, Se BHL: 149' FNL, 390' FEL, See		10. Field and Pool, or Exploratory Area Exploratory 11. County or Parish, State Sanpete, Utah		
12. CHECK AI	PPROPRIATE BOX(ES) TO	INDICATE NATUR	E OF NOTICE, R	EPORT, OR OTHER DATA
TYPE OF SUBMISSION		TYI	PE OF ACTION	
Notice of Intent ✓ Subsequent Report Final Abandonment Notice	Acidize Alter Casing Casing Repair Change Plans Convert to Injection	Deepen Fracture Treat New Construction Plug and Abandon Plug Back	Production (Statement of the Production (Stat	Well Integrity Other

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Please see attached report for plugging details.

RECEIVED NOV 29 2011

DIV. OF OIL, GAS & MINING

14. I hereby certify that the foregoing is true and correct Name (Printed/Typed)		
Edward A. Higuera Title	Manager - Development	
Signature Date	11/18/2011	
THIS SPACE FOR FEDERAL OR	STATE OFFICE USE	
Approved by	Title	Date
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.	Office	e 7
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person States any false, fictitious or fraudulent statements or representations as to any matter within	knowingly and willfully to make to a its jurisdiction.	any department or agency of the United
(Instructions on page 2)	(CONFIDENTIL

Operator:

Wolverine Operating Company of Utah, LLC

Well:

Rough Canyon Federal 30-1

Surface Location:

Section 32, T17S, R1E

API Number:

43039500030000

Lease:

UTU-82536

County/State:

Sanpete, UT

Re:

Plugging/Cement Plug Record

Plugging requirements were obtained from Marvin Hendrick, BLM, and the following abandonment plugs were set in the well:

Plug1: Set cement retainer at 9385' MD (displaced OBM out of hole with 9 ppg fresh water mud) and pumped plug #1 under retainer with 10 bbls water spacer, 17 bbls/84 sacks, 15.8 ppg, yield 1.16 cu. Ft/sack Class "G" cement, 10 bbls water spacer, then 124 bbls 9 ppg water based mud. Displaced 15 bbls below retainer and left 2 bbls cement on top of retainer. Pressure tested casing to 750 psi.

Plug 2: Set plug 2 at 6500'-6350 with 10 bbls water spacer, 10.6 bbls/52 sacks, 15.8 ppg, yield 1.16 cu. Ft/sack Class "G" cement (equivalent to 150 foot plug), and 3 bbls water spacer followed by 9 ppg FW mud.

Plug 3: Set 140-ft plug from 3845'-3705' with 10 bbls water spacer, 9.9 bbs/48 sacks, 15.8 ppg, yield 1.16 cu. Ft/sack Class "G" cement, 3 bbls water spacer followed by FW mud.

Set plug 4 at 1485' with 10 bbls water spacer, 7.8 bbls/38 sacks, 15.8 ppg, yield 1.16 cu. Ft/sack Class "G" cement, 3 bbls water followed by FW mud.

Set Plug 5 at surface with 3.2 bbls/16 sacks, 15.8 ppg, yield 1.16 cu.ft/sack Class G cement.

An above-ground post marker has been installed on the well location.



CONFIDENTIAL



Actual Wellpath Report Rough Canyon Federal #30-1 awp Page 1 of 6



REFERENCE WELLPATH IDENTIFICATION						
Operator	WOLVERINE GAS & OIL COMPANY	Slot	Slot #01 Rough Canyon Federal #30-1 (288'FNL & 452'FWL,SEC.32)			
Area	UTAH	Well	Rough Canyon Federal #30-1			
Field	SANPETE COUNTY	Wellbore	Rough Canyon Federal #30-1 AWB			
Facility	SEC.32-T17S-R1E					

REPORT SETUP INFORMATION						
Projection System	NAD83 / UTM Zone 12 North, US feet	Software System	WellArchitect® 3.0.0			
North Reference	True	User	Balldoun			
Scale	0.999664	Report Generated	6/15/2011 at 10:48:45 AM			
Convergence at slot	0.53° West	Database/Source file	WellArchitectDB/Rough_Canyon_Federal_#30-1_AWB.xml			

	Local coo	rdinates	Grid co	ordinates	Geographic coordinates	
	North[ft]	East[ft]	Easting[US ft]	Northing[US ft]	Latitude	Longitude
Slot Location	0.00	0.00	1403147.25	14270941.25	39°17'40.135"N	111°50'19.188"W
Facility Reference Pt		1	1403147.25	14270941.25	39°17'40.135"N	111°50'19.188"W
Field Reference Pt		I I	1403147.25	14270941,25	39°17'40.135"N	111°50'19.188"W

WELLPATH DATUM							
Calculation method	Minimum curvature	Rig on Slot #01 Rough Canyon Federal #30-1 (288'FNL & 452'FWL,SEC.32) (RT) to Facility Vertical Datum					
Horizontal Reference Pt	Slot	Rig on Slot #01 Rough Canyon Federal #30-1 (288 FNL & 452 FWL, SEC.32) (RT) to Mean Sea Level					
Vertical Reference Pt	Rig on Slot #01 Rough Canyon Federal #30-1 (288'FNL & 452'FWL,SEC.32) (RT)	Rig on Slot #01 Rough Canyon Federal #30-1 (288'FNL & 452'FWL,SEC.32) (RT) to Mud Line at Slot (Slot #01 Rough Can					
MD Reference Pt	Rig on Slot #01 Rough Canyon Federal #30-1 (288'FNL & 452'FWL,SEC.32) (RT)	Section Origin					
Field Vertical Reference	Mean Sea Level	Section Azimuth					

RECEIVED NOV 2 9 2011



Actual Wellpath Report Rough Canyon Federal #30-1 awp Page 2 of 6



REFERENCE WELLPATH IDENTIFICATION						
Operator	WOLVERINE GAS & OIL COMPANY	Slot	Slot #01 Rough Canyon Federal #30-1 (288'FNL & 452'FWL,SEC.32)			
Area	UTAH	Well	Rough Canyon Federal #30-1			
Field	SANPETE COUNTY	Wellbore	Rough Canyon Federal #30-1 AWB			
Facility	SEC.32-T17S-R1E					

MID [ft]	Inclination [°]	Azimuth [°]	TVD [ft]	Vert Sect [ft]	North [ft]	East [ft]	DLS [°/100ft]
0.00	0.000	225.900	0.00	0.00	0.00	0.00	[/zoutj
50.00	0.590	225.900	50.00	-0.02	-0.18	-0.18	
100.00	0.610	222.450	100.00	-0.07	-0.55	-0.55	
150.00	0.580	223.060	149.99	-0.13	-0.94	-0.90	
200.00	0.620	220,530	199.99	-0.20	-1.33	-1.25	
250.00	0.690	222,770	249.99	-0.28	-1.75	-1.63	
300.00	0.720	220.370	299.98	-0.37	-2.21	-2.04	
350.00	0.840	227.710	349.98	-0.43	-2.70	-2.51	
400.00	0.950	226.920	399.97	-0.47	-3.23	-3.09	
450.00	1.110	226.220	449.97	-0.52	-3.85	-3.74	
500.00	1.120	225.430	499.96	-0.58	-4.53	-4.44	
550.00	1.320	225.160	549.94	-0.66	-5.27	-5.19	
600.00	1.400	225.010	599.93	-0.76	-6.11	-6.03	
650.00	1.520	225.800	649.91	-0.85	-7.01	-6.94	
700.00	1.580	225.220	699.90	-0.95	-7.95	-7.91	****
750.00	1.630	226.080	749.88	-1.05	-8.93	-8.91	
800.00	1.640	224.280	799.86	-1.16	-9.94	-9.92	
850.00	1.720	225.350	849.83	-1.29	-10.98	-10.95	
900.00	1.730	224.500	899.81	-1,41	-12.04	-12.02	
950.00	1.750	223.580	949.79	-1.56	-13.14	-13.07	
1000.00	1.830	224.260	999.76	-1.72	-14.26	-14.15	
1050.00	1.900	225.600	1049.74	-1.86	-15.41	-15.30	
1100.00	2.140	228.150	1099.71	-1.94	-16.61	-16.59	
1150.00	2.070	226.380	1149.67	-2.02	-17.86	-17.94	
1200.00	2.170	227.330	1199.64	-2.11	-19.12	-19.29	
1250.00	2.180	227.020	1249.60	-2.19	-20.41	-20.68	,
1300.00	2.250	226.390	1299.57	-2.29	-21.74	-22.09	
1350.00	2.370	227.650	1349.52	-2.39	-23.11	-23.56	
1400.00	2.340	228.880	1399.48	-2.44	-24.48	-25.10	
1450.00	2.440	229.900	1449.44	-2.45	-25.84	-26.68	
1500.00	2.450	229.790	1499.39	-2.44	-27.21	-28.31	
1550.00	2.560	228.330	1549.35	-2.47	-28.65	-29.96	
1600.00	2.600	228.870	1599.29	-2.51	-30.13	-31.65	
1650.00	2.600	229.850	1649.24	-2.53	-31.61	-33.37	
1700.00	2.760	230.830	1699.19	-2.50	-33.10	-35.17	
1750.00	2.930	229.240	1749.13	-2.49	-34.70	-37.07	
1800.00	2.950	228.980	1799.06	-2.51	-36.38	-39.01	
1850.00	3.070	229.550	1848.99	-2.53	-38.09	-41.00	
1900.00	3.170	229.290	1898.92	-2.55	-39.86	-43.07	
2000.00	3.140	232.410	1998.77	-2.44	-43.33	-47.33	
2100.00	3.350	235.870	2098.61	-1.99	-46.64	-51.92	
2200.00	3.580	241.570	2198.42	-1.04	-49.77	-57.08	
2300.00	3.730	233,090	2298.22	-0.20	-53.21	-62.43	
2400.00	4.030	227.040	2397.99	-0.17	-57.56	-67.60	
2500.00	4.600	231.180	2497.71	-0.23	-62.47	-73.30	



Actual Wellpath Report Rough Canyon Federal #30-1 awp Page 3 of 6



REFERENC	CE WELLPATH IDENTIFICATION		
Operator	WOLVERINE GAS & OIL COMPANY	Slot	Slot #01 Rough Canyon Federal #30-1 (288'FNL & 452'FWL,SEC.32)
Area	UTAH	Well	Rough Canyon Federal #30-1
Field	SANPETE COUNTY	Wellbore	Rough Canyon Federal #30-1 AWB
Facility	SEC.32-T17S-R1E		

MD [ft]	Inclination (°)	Azimuth [°]	TVD [ft]	Vert Sect	North [ft]	East [ft]	DLS [°/100ft]
2600.00	4.560	231.270	2597.39	-0.02	-67.47	-79.52	[/20026]
2700.00	4.470	229.970	2697.08	0.11	-72.46	-85.61	
2800.00	4.720	229.250	2796.76	0.09	-77.65	-91.71	
2900.00	4.700	230.030	2896.42	0.09	-82.97	-97.97	
3000.00	4.580	230.110	2996.09	0.14	-88.16	-104.17	
3100.00	4.890	229.190	3095.75	0.13	-93.51	-110.46	
3200.00	4.840	226.960	3195.39	-0.11	-99.17	-116,77	
3300.00	4.920	228.910	3295.03	-0.37	-104.87	-123.08	
3400.00	4.920	229.820	3394.66	-0.42	-110.46	-129.59	
3500.00	4.780	228.130	3494.30	-0.53	-116.00	-135.97	
3600.00	4.920	228.290	3593.94	-0.75	-121.64	-142.27	
3700.00	5.010	228.740	3693.57	-0.93	-127.37	-148.76	
3800.00	4.710	223,520	3793.21	-1.44	-133.23	-154.87	
3883.00	4.700	218.500	3875.93	-2.47	-138.36	-159.33	
3955.00	4.790	218.810	3947.68	-3.61	-143.01	-163.05	
4040.00	4.570	219.910	4032.40	-4.86	-148.37	-167.45	****
4135.00	4.790	218.190	4127.08	-6.29	-154.39	-172.33	
4227.00	4.920	218.980	4218.75	-7.79	-160.48	-177.19	•
4336.00	4.790	217.710	4327.36	-9.61	-167.71	-182.91	
4429.00	4.700	218.410	4420.04	-11.16	-173.77	-187.65	
4522.00	4.700	218.410	4512.73	-12.65	-179.74	-192.39	
4616.00	4.610	218.900	4606.42	-14.11	-185.70	-197.15	
4716.00	4.610	219.200	4706.10	-15.60	-191.94	-202.21	
4810.00	4.480	219.510	4799.80	-16.94	-197.70	-206.94	
4903.00	4.610	218.280	4892.51	-18.32	-203.44	-211.56	
4997.00	4.480	218.500	4986.21	-19.78	-209.28	-216.19	,
5028.00	4.480	218.280	5017.12	-20.25	-211.17	-217.69	
5122.00	4.790	218.980	5110.81	-21.71	-217.11	-222.44	
5214.00	4.700	218.800	5202.50	-23.14	-223.03	-227.21	
5307.00	4.480	219.200	5295.20	-24.52	-228.81	-231.90	
5413.00	4.480	218.980	5400.87	-26.04	-235.24	-237.12	
5505.00	4.790	223.200	5492.57	-27.15	-240.83	-242.01	
5598.00	4.790	224.080	5585.25	-27.97	-246.45	-247.37	
5690.00	4.790	226.300	5676.93	-28.57	-251.87	-252.82	
5782.00	4.790	227.300	5768.61	-28.96	-257.13	-258.42	
5875.00	5.010	228.100	5861.27	-29.24	-262.47	-264.29	
5968.00	5.010	227.910	5953.91	-29.48	-267.90	-270.33	
6067.00	5.010	227.910	6052.53	-29.75	-273.70	-276.74	
6162.00	5.010	229.500	6147.17	-29.89	-279.17	-282.98	
6255.00	5.010	230.100	6239.81	-29.88	-284.42	-289.18	
6350.00	5.100	229.090	6334.44	-29.89	-289.84	-295.55	
6420.00	5.100	229.050	6404.17	-29.96	-293.92	-300.26	
6551.00	4.790	230.720	6534.68	-29.93	-301.20	-308.89	
6640.00	5.010	231.590	6623.35	-29.74	-305.97	-314.81	
6738.00	4.920	235.290	6720.99	-29.18	-311.02	-321.62	



Actual Wellpath Report Rough Canyon Federal #30-1 awp Page 4 of 6



REFERENCE WELLPATH IDENTIFICATION						
Operator	WOLVERINE GAS & OIL COMPANY	Slot	Slot #01 Rough Canyon Federal #30-1 (288 FNL & 452 FWL, SEC.32)			
Area	UTAH	Well	Rough Canyon Federal #30-1			
Field	SANPETE COUNTY	Wellbore	Rough Canyon Federal #30-1 AWB			
Pacility	SEC.32-T17S-R1E					

MD	Inclination	Azimuth	TVD	Vert Sect	North	East	DLS
[ft]	[*]	(°)	[ft]	[ft]	[ft]	[ft]	[°/100ft]
6832.00 6924.00	4.920	238.100	6814.64	-28.20	-315.44	-328.35	0.:
	5.190	241.570	6906.28	-26.77	-319.51	-335.36	0.
7016.00	5.010	241.570	6997.92	-25.09	-323.40	-342.55	0.:
7117.00 7207.00	4.920	244.470	7098.54	-23.08	-327.37	-350.34	0.:
7207.00	4.920	243.290	7188.21	-21.19	-330.77	-357.27	0.
7313.00	5.100	247.680	7293.80	-18.66	-334.60	-365.69	0.
7503.00	5.320 5.710	248.080	7388.41	-15.97	-337.85	-373.68	0
7568.00	5.800	246.800 246.190	7482.97	-13.19	-341.35	-382.11	0
7596.00	5.800	245.480	7547.64 7575.50	-11.31	-343.95	-388.09	0
7691.00	5.890	243.480	7575.50	-10.52	-345.11	-390.67	0.
7741.00	5.800	245.470	7719.75	-8.02	-349.25	-399.41	0.
7742.00	5.890	244.780	7719.73	-6.71 -6.68	-351.42 -351.47	-404.01	0.
7775.00	5.890	244.600	7753.57	-5.80	-351.47	-404.11	11.
7871.00	6.020	245.310	7849.05	-3.18	-352.91 -357.13	-407.17	0.
7967.60	6.200	243.990	7945.10	-0.53	-361.53	-416.19 -425.48	0.
8071.00	6,420	242.010	8047.87	2.08	-366.70	-425.48 -435.60	0.
8250.00	7.910	234,100	8225.47	5.16	-378.62	-435.60 -454.42	0.
8351.00	8.790	234.100	8325.40	6.29	-3/8.62	-454.42 -466.31	1
8389.00	9.010	234.670	8362.95	6.78	-387.21	-406.31 -471.09	0
8396.00	9.010	234.500	8369.86	6.87	-391.26	-471.09 -471.98	0
8446,00	9.010	234.890	8419.24	7.55	-395.79	-471.98 -478.37	0.
8541.00	9,400	233.000	8513.02	8.67	-404.73	-490.66	0.
8610.00	9.400	234.590	8581.09	9.48	-411.39	-499.75	0
8641.00	9.490	234.500	8611.67	9.91	-414.34	-503.89	
8721.00	9.710	233.000	8690.55	10.85	-422.23	-514.65	0
8812.00	9.890	232.870	8780,22	11.72	-431.57	-527.01	0
8907.00	10.110	232.870	8873.78	12.63	-441.52	-540.16	0
9002.00	10,500	231,900	8967.25	13.43	451.90	-553,62	
9096.00	10.810	230,980	9059.63	13.95	-462.73	-567.21	
9205.00	10.680	231.680	9166.72	14.53	-475.43	-583.07	0
9286.00	10.900	231.770	9246.28	15.07	-484.82	-594.98	0
9378.00	10.810	232,300	9336.64	15.77	-495,48	-608.64	- 0
9487.00	11.100	231.300	9443.65	16.53	-508.29	-624.91	
9520.00	11.140	232.640	9476.03	16.78	-512.21	-629.93	
9540.00	11.250	237.470	9495.65	17.14	-514,44	-633.11	4
9574.00	11.150	243.950	9529.01	18.40	-517.66	-638.86	3
9603.00	11.060	249.120	9557.46	20.02	-519.89	-643.98	
9634.00	10.930	257.580	9587.90	22.38	-521.58	-649.62	
9666.00	11.300	260.970	9619.30	25.43	-522.72	-655,68	
9698.00	11.080	266.730	9650.69	28.91	-523,39	-661.85	
9730.00	11.220	272.220	9682.09	32.86	-523,44	-668.03	
9762.00	11.290	278.560	9713.47	37.32	-522.86	-674.24	
9793.00	11.240	284,720	9743.88	42.09	-521.64	-680.16	3
9825.00	11.190	295.800	9775.27	47.48	-519.49	-685.98	



Actual Wellpath Report Rough Canyon Federal #30-1 awp Page 5 of 6



REFEREN	CE WELLPATH IDENTIFICATION		
Operator	WOLVERINE GAS & OIL COMPANY	Slot	Slot #01 Rough Canyon Federal #30-1 (288'FNL & 452'FWL,SEC.32)
Area	UTAH	Weli	Rough Canyon Federal #30-1
Field	SANPETE COUNTY	Wellbore	Rough Canyon Federal #30-1 AWB
Facility	SEC.32-T17S-R1E		

MD [ft]	Inclination [°]	Azimuth [°]	TVD [ft]	Vert Sect [ft]	North [ft]	East [ft]	DLS [°/100ft]
9857.00	11.420	303.570	9806.65	53.36	-516.39	-691.41	
9888.00	12.430	306.650	9836.98	59.56	-512.70	-696.64	
9920.00	13.320	306.420	9868.18	66.50	-508.46	-702.37	
9951.00	14.510	306.600	9898.27	73.76	-504.02	-708.37	
9983.00	15.440	307.760	9929.18	81.83	-499.02	-714.95	
10015.00	16.140	313.810	9959.97	90.43	-493.34	-721.53	4,
10047.00	16.570	320.580	9990.68	99.41	-486.73	-727.64	
10079.00	17.770	325.260	10021.26	108.84	-479.19	-733.32	
10111.00	18.500	328.250	10051.67	118.72	-470.86	-738.77	
10142.00	19.390	331.870	10080.99	128.61	-462.14	-743.79	
10172.00	20.060	335.950	10109.23	138.42	-453.05	-748.23	
10203.00	21.330	338.810	10138.23	148.85	-442.94	-752.44	
10235.00	23.610	341.570	10167.80	160.30	-431.43	-756.57	
10266.00	25.410	343.710	10196.00	172.14	-419.16	-760.40	
10298.00	26.790	345.360	10224.74	184.91	-405.59	-764.14	
10329.00	27.710	346.790	10252.30	197.63	-391.81	-767,56	
10361.00	29.270	347.790	10280.42	211.15	-376.92	-770.91	
10392.00	29.940	347.260	10307.38	224.70	-361.97	-774.22	
10424.00	31.600	347.560	10334.87	239.19	-345.99	-777,79	
10520.00	35.250	345.940	10414.98	286.29	-294.54	-789.94	
10627.00	39.550	349.120	10499.97	343.69	-231.10	-803.88	
10646.00	40.170	347.360	10514.56	354.39	-219.18	-806,36	
10678.00	41.310	350.880	10538.81	372.57	-198.67	-810.30	
10741.00	41.130	352.280	10586.19	407.82	-157.61	-816.38	****
10772.00	40.520	348.770	10609.66	425.21	-137.63	-819.71	
10836.00	39.640	345.950	10658.63	461.70	-97.43	-828.71	
10867.00	38.670	347.710	10682.67	479.12	-78.37	-833.18	
10899.00	38.580	348.770	10707.67	496.67	-58.81	-837,25	
10930.00	38.850	354.390	10731.86	513.11	-39.65	-840.08	
10962.00	38.760	356.500	10756.80	529.39	-19.66	-841.67	
10994.00	38.850	353.690	10781.74	545.73	0.31	-843,39	
11025.00	38.850	353.340	10805.88	561.89	19.63	-845,58	
11057.00	39.460	0.020	10830.71	578.01	39.78	-846.74	
11089.00	40.340	2.130	10855.26	593.40	60.30	-846.36	
11204.00	40.000	2.000	10943.13	648.21	134.43	-843.68	



Actual Wellpath Report Rough Canyon Federal #30-1 awp Page 6 of 6



REFERENCE WELLPATH IDENTIFICATION						
Operator	WOLVERINE GAS & OIL COMPANY	Slot	Slot #01 Rough Canyon Federal #30-1 (288'FNL & 452'FWL,SEC.32)			
Атеа	UTAH	Well	Rough Canyon Federal #30-1			
Field	SANPETE COUNTY	Wellbore	Rough Canyon Federal #30-1 AWB			
Facility	SEC.32-T17S-R1E					

TARGETS									
Name	MD [ft]	TVD [ft]	North [ft]	East [ft]	Grid East [US ft]	Grid North [US ft]	Latitude	Longitude	Shape
Rough Canyon Federal #30-1 Crosses Section Line at 11448'MD		0.00	288.00	-905.00	1402245.26	14271237.53	39°17'42.981"N	111°50'30.700"W	point
Rough Canyon Federal #30-1 BHL REV-1 (1830'FSL & 810'FEL,30)	_ · · · · ·	10785.00	2112.06	-1261.36	1401905.94	14273064.20	39°18'01.009''N	111°50'35.234"W	point
Rough Canyon Federal #30-1 BHL REV-2 (1830'FSL & 810'FEL,SEC 30)		12400.00	2112.06	-1261.36	1401905.94	14273064.20	39°18'01.009''N	111°50'35.234''W	point
Rough Canyon Federal #30-1 BHL Rev-3 (644'FSL & 514'FEL Sec 30)		12400.00	926.94	-966.02	1402190.19	14271876.79	39°17'49.296"N	111°50'31.476"W	point
Rough Canyon Federal #30-1 BHL Rev-4 (532'FSL & 584'FEL Sec 30)		12400.00	814.97	-1035.68	1402119.52	14271765.51	39°17'48.189"N	111°50'32.362"W	point
Rough Canyon Federal #30-1 BHL Rev-5 (1044'FSL & 650'FEL Sec 30)		12400.00	1326.95	-1101.51	1402058.46	14272277.90	39°17'53.249"N	111°50'33.200"W	point
Rough Canyon Federal #30-1 BHL Rev-6 (1045'FSL & 674'FEL Sec. 30)	Ш	12400.00	1327.65	-1125.83	1402034.15	14272278.83	39°17'53.256"N	111°50'33.509"W	point

WELLPATH COMPOSITION - Ref Wellbore: Rough Canyon Federal #30-1 AWB Ref Wellpath: Rough Canyon Federal #30-1 awp							
Start MD	End MD [ft]	Positional Uncertainty Model	Log Name/Comment	Wellbore			
0.00		Gyrodata standard - Continuous gyro	Gyro Data Actual Surveys <0' - 1900'>	Rough Canyon Federal #30-1 AWB			
1900.00	3800.00	Gyrodata standard - Continuous gyro	GYRODATA SURVEYS <2000-3800>	Rough Canyon Federal #30-1 AWB			
3800.00	11089.00	ISCWSA MWD, Rev. 2 (Standard)	EXTREME MWD SURVEYS <3883-9378>	Rough Canyon Federal #30-1 AWB			
11089.00	11204.00	Blind Drilling (std)	Projection to bit	Rough Canyon Federal #30-1 AWB			

T125 ROLE 5-32

43-039-50003

From:

"Bill Donovan" <boart@drillmail.net>

To:

"Allen, Geoff" <geoff.allen@fmcti.com>, "'Arthurs, Shane" <DArthurs@s...

Date:

1/9/2011 6:32 AM

Subject:

Rough Canyon Federal 30-1 Update

1/9/2011 5:18 AM

CONFIDENTIAL

Trip for new bit. Hole depth 5,093'

Bill Donovan

Wolverine Operating Company of Utah, LLC

Rough Canyon Federal 30-1

AFE 224 API 43-039-50003-00-00

Rig (970) 361-3276

boart@drillmail.net

Cell (720) 351-7470

donovan@petroleum-eng.com

RECEIVED
JAN 1 0 2011

T195 ROIE 5-32 43-039-50003

From:

"Bill Donovan" <boart@drillmail.net>

To:

"'Allen, Geoff" <geoff.allen@fmcti.com>, "'Arthurs, Shane" <DArthurs@s...

Date:

1/8/2011 9:51 AM

Subject:

Rough Canyon Federal 30-1 Update

1/8/2011 9:49 AM

CONFIDENTIAL

Drilling at 5,027', PR 6 fph

Bill Donovan

Wolverine Operating Company of Utah, LLC

Rough Canyon Federal 30-1

AFE 224 API 43-039-50003-00-00

Rig (970) 361-3276

boart@drillmail.net

Cell (720) 351-7470

donovan@petroleum-eng.com

RECEIVED
JAN 1 0 2011

T175 ROLE 5-32 43-039-50003

From:

"Bill Donovan" <boart@drillmail.net>

To:

"'Allen, Geoff" <geoff.allen@fmcti.com>, "'Arthurs, Shane" <DArthurs@s...

Date:

1/7/2011 7:16 AM

Subject:

Rough Canyon Federal 30-1 Update

1/7/2011 7:13 AM

CONFIDENTIAL

Drilling at 4,932', 3 fph

Bill Donovan

Wolverine Operating Company of Utah, LLC

Rough Canyon Federal 30-1

AFE 224 API 43-039-50003-00-00

Rig (970) 361-3276

boart@drillmail.net

Cell (720) 351-7470

donovan@petroleum-eng.com

RECEIVED JAN 1 0 2011

T175 ROIE 5-32 43-039-50003

From:

"Bill Donovan" <boart@drillmail.net>

To:

"'Allen, Geoff'" <geoff.allen@fmcti.com>, "'Arthurs, Shane'" <DArthurs@s...

Date:

1/10/2011 4:49 AM

Subject:

Rough Canyon Federal 30-1 Update

1/10/2011 4:35 AM

Drilling at 5,110', PR 5 fph

CONFIDENTIAL

Bill Donovan

Wolverine Operating Company of Utah, LLC

Rough Canyon Federal 30-1

AFE 224 API 43-039-50003-00-00

Rig (970) 361-3276

boart@drillmail.net

Cell (720) 351-7470

donovan@petroleum-eng.com

RECEIVED
JAN 1 0 2011



Carol Daniels - Wolverine Rough Canyon Federal 30-1 update

TI75 ROLE 5-32 43-039-50003

From:

"Wolverine Exploration Rig"

To:

"Ainge, Jeff", "Allen, Geoff", "Arthurs, Shane", "Blair, Richard", "Brock Pope", "Chamberlain, Don", "Childers, Eli", "Chris Schaugaard", "Daniel Jenkins", "Daniels, Carol", "De la Torre, Juan C", "Dennis", "Denton, Derek", "Dieste, Bobby", "Doucet, Dustin", "Dustin Dunning", "Foreman, Ron", "George Zamantakis", "Hall, Denise", "Hammell, Hank", "Harry Melnikoff", "Hendricks, Marvin", "Hutcinson, Clayton", "Jim Barry", "Jimmy Germon", "Jones, Mark", "KC Schultz", "Kent Donner", "Kulow, Kyle", "Kyle Cox", "LaDee Roundy", "Larimore, Mark", "Lewis, John", "Martin Pete", "Marvin Hendricks", "Matt Harmon", "McCoy, Charlene", "McCoy, Tim", "Nilles, Chris",

"O'Connell, David", "Perry, Bud (Smith Bits)", "Pickup, Marc", "Rees, John M", "Revert, Scott", "Robinson, Darin", "Ryan Thomas", "Shaun Burns", "Shawn Moulton", "Shelton, Shorty", "Steffen, Dana", "Tujillo, Chris", "Tyler Ross", "Willis, Walton", "Willis,

Walton Home", "Winkler, Matt", "Zimmerman, Bill"

Date:

2/14/2011 7:29 AM

Subject: Wolverine Rough Canyon Federal 30-1 update

2/14/2011 7:26 AM

Rig Repair

Tom Zupan **Drilling Supervisor** Wolverine Gas and Oil Company of Utah, LLC Ria (970) 812-0022 Cell (970) 314-8219 Fax (435) 304-1222 wolvexpl@drillmail.net

> RECEIVED FEB 1 4 2011



Carol Daniels - Wolverine Rough Canyon Federal 30-1 update

T 115 ROLE 5-32 43-039-50023

From:

"Wolverine Exploration Rig"

To:

"Ainge, Jeff", "Allen, Geoff", "Arthurs, Shane", "Blair, Richard", "Brock Pope", "Chamberlain, Don", "Childers, Eli", "Chris Schaugaard", "Daniel Jenkins", "Daniels, Carol", "De la Torre, Juan C", "Dennis", "Denton, Derek", "Dieste, Bobby", "Doucet, Dustin", "Dustin Dunning", "Foreman, Ron", "George Zamantakis", "Hall, Denise", "Hammell, Hank", "Harry Melnikoff", "Hendricks, Marvin", "Hutcinson, Clayton", "Jim Barry", "Jimmy Germon", "Jones, Mark", "KC Schultz", "Kent Donner", "Kulow, Kyle", "Kyle Cox", "LaDee Roundy", "Larimore, Mark", "Lewis, John", "Martin Pete", "Marvin Hendricks", "Matt Harmon", "McCoy, Charlene", "McCoy, Tim", "Nilles, Chris",

"O'Connell, David", "Perry, Bud (Smith Bits)", "Pickup, Marc", "Rees, John M", "Revert, Scott", "Robinson, Darin", "Ryan Thomas", "Shaun Burns", "Shawn Moulton", "Shelton, Shorty", "Steffen, Dana", "Tujillo, Chris", "Tyler Ross", "Willis, Walton", "Willis,

Walton Home", "Winkler, Matt", "Zimmerman, Bill"

Date:

2/12/2011 7:08 AM

Subject: Wolverine Rough Canyon Federal 30-1 update

2/12/2011 7:06 AM Rig Repair

Tom Zupan Drilling Supervisor Wolverine Gas and Oil Company of Utah, LLC Ria (970) 812-0022 Cell (970) 314-8219 Fax (435) 304-1222 wolvexpl@drillmail.net

> RECEIVED FEB 1 4 2011



Carol Daniels - Wolverine Rough Canvon Federal 30-1 update

TITS ROIE 5-32 43-039-50003

From:

"Wolverine Exploration Rig"

To:

"Ainge, Jeff", "Allen, Geoff", "Arthurs, Shane", "Blair, Richard", "Brock Pope", "Chamberlain, Don", "Childers, Eli", "Chris Schaugaard", "Daniel Jenkins", "Daniels, Carol", "De la Torre, Juan C", "Dennis", "Denton, Derek", "Dieste, Bobby", "Doucet, Dustin", "Dustin Dunning", "Foreman, Ron", "George Zamantakis", "Hall, Denise", "Hammell, Hank", "Harry Melnikoff", "Hendricks, Marvin", "Hutcinson, Clayton", "Jim Barry", "Jimmy Germon", "Jones, Mark", "KC Schultz", "Kent Donner", "Kulow, Kyle", "Kyle Cox", "LaDee Roundy", "Larimore, Mark", "Lewis, John", "Martin Pete", "Marvin Hendricks", "Matt Harmon", "McCoy, Charlene", "McCoy, Tim", "Nilles, Chris",

"O'Connell, David", "Perry, Bud (Smith Bits)", "Pickup, Marc", "Rees, John M", "Revert, Scott", "Robinson, Darin", "Ryan Thomas", "Shaun Burns", "Shawn Moulton", "Shelton, Shorty", "Steffen, Dana", "Tujillo, Chris", "Tyler Ross", "Willis, Walton", "Willis,

Walton Home", "Winkler, Matt", "Zimmerman, Bill"

Date:

2/10/2011 8:01 AM

Subject: Wolverine Rough Canyon Federal 30-1 update

2/10/2011 7:58 AM

Rig Repair

Tom Zupan Drilling Supervisor Wolverine Gas and Oil Company of Utah, LLC Ria (970) 812-0022 Cell (970) 314-8219 Fax (435) 304-1222 wolvexpl@drillmail.net

RECEIVED

FEB 1 4 2011